

LKK:  
IDAC:

Surveyor:

DOI:

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. \_\_\_\_\_

Name of Insured

Insured Tel No.

**Excess Sec II :SS**

Is driver the owner?

( YES / NO )

Nature of Accident :

If **NO**, Driver Name / Age :

Driver Tel No. :

(V/L: ~~YES~~ / NO)

Claim No. \_\_\_\_\_

Policy No.

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :	%	Final ? Yes / No
1. General Liability		
2. Professional Liability		
3. Directors and Officers		
4. Employment Practices		
5. Automobile Liability		
6. Aircraft Liability		
7. Watercraft Liability		
8. Umbrella Liability		
9. Other		



INSRS:

WSP:

Tel :

**Liability :**

RMKS:



INSRS:

WSP:

Tel :

**Liability :**

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time		STAGE	DATE / PIC
5/4/18 vinam	SJY VISA - X SPECIFIC - AM/PM/TH/SSG/US DON-14/M/12	Non-Reporting ltr (1st); Non-Reporting ltr (2nd); Non-Reporting ltr (Final); Notification ltr (if non-pickup); Call OI; After call ltr to OI;	
4/6/18	email workshop liability clear. O2D collided # Parked TP-	<b>Documentation Check List:</b> Handler Typist	
9/11/18	File pass to typist type report.	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
13/12/18	See Email to CPC to seek mandate	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
17/12/18	Email From LPC approve mandate	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Towing Invoice	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
		Others:	<input type="checkbox"/> <input type="checkbox"/>
<b>PRELIMINARY ADVICE</b> Date/Time:	A.T.	Sent By:	

<b>FINALIZATION</b>	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S\$ ( days) Reduction: %		Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>	Date/Time: 1-1-19	Confirm with: CANALINE	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : N/A	If NO or B 28, Ass. Lia :	
Repair Cost:	S\$ 2317.75		
Loss of Rental (LOR):	S\$ ( days)		
Loss of Use (LOU):	S\$ 300.00 (\$100 x 3 days)		
Loss of Income (LOI):	S\$ (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]			
GIA/LTA Search	S\$ 2.00		
Medical:	S\$	1) Claim status: Normal/Reject/Private Settle	
Disbursement:	S\$ (e.g. Tow/ Independent )	2) Report Format:	
Legal Cost	S\$	3) Survey fee:	
<b>Total:</b>	S\$ 2617.75	<b>Global Sum S\$:</b>	
<b>FINAL PAYMENT</b>	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	S\$ 2617.75	Name 1:	Performance Motors Ltd
Payee 2: (Strike if N.A.)	S\$ X	Name 2:	X
Payee 3: (Strike if N.A.)	S\$ X	Name 3:	X

Signature

Paul

REF: LPC

5607F

## ASSIGNMENT

From:

Date:

9/04/18

Estimated Cost:

OD ☒ TP ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLJ 2818A

at Workshop m/s

Performance

of

303 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Han

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

2-B-2

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>(wps)</sup>

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLJ 2818A

Yr Regn:

2016 / Per

Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W 2160 GT

C.C

1496

Colour:

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading:

34197

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA2E320105645446

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ R/Rim / STD A/Rim or

Tyre Size:

F:

205/55R17

R:

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/03/18

D.O.I.

09/04/18

Survey held at

Performance

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/4/18 Confirm 2-B-2 B2164.25 with 3 working days

1260-1962.53  
48.1)

Date/Time. File Pass to?



Preli. Report

1)



Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + PS ) SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC4/LPC18005944/R1wb3

Date: 12.04.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLJ2818A**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09.04.2018 at the premises of M/s Performance Motors Limited and have the following to report:-

Workshop Estimate Amount	: S\$	3,856.80
Revised Estimate Amount	: S\$	1,934.00
"Check" Items Amount	: S\$	347.80
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
Rear O/S Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

MOHD. RASUL  
Licensed Appraiser




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18005944/wb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 02-04-2018	
			Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKS 7191E	Veh. Inspected	SLJ 2818A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	29/03/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Mon 09/04 @ read  
PQR

SLJ2818A

BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159541  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159544  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796801 (AfterSales)  
64796824 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

02 APR 2018

Estimate No. : b1 46438  
Date Estimated : 31/03/2018  
Prepared By : Han Kwan Yong

Page No. : 1 of 2

### - ESTIMATE REPAIR FOR -

Ho Hai Wee (He Haiwei)  
12C Hougang Street 11  
#14-65

Singapore 534072

- ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLJ2818A	5B45446	02/12/2016	216d G TOURER	0

### DESCRIPTION

To replace front bumper & attachments including to knock out dented area caused by the accident

850 ~~1,275.00~~

To respray front bumper

934 ~~1,038.00~~

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 ~~177.00~~

To remove old PDC assembly, and reconnect to new bumper including conduct checks for proper function.

177 ~~177.00~~

Sundries. *Me*

7. 80.00

Total Labour 1: 2,747.00

### DESCRIPTION

FRT IMPACT ABSORBER  
RH FINISHER (LUXURY LINE)  
RH SUPPORT FOG LAMP (GESCHLOSSEN)  
FRT BUMPER PANEL PRIMED (PMA)  
# GRILLE SIDE OPEN RH (LUXURY CLIP

QTY	PRIC
1	47.80
1	60.20
1	50.95
1	842.00
1	95.85
10	1.30

1,900.75  
1,900.75  
50.95  
842.00  
95.85  
13.00

Total Parts : 1,109.80

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 46438  
Date Estimated : 31/03/2018  
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLJ2818A	5B45446	02/12/2016	216d G TOURER	0

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims GD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date &amp; Time 09/04/16 @ 1400 Excess S\$ \_\_\_\_\_

Surveyor's Name P. K. S. Sign \_\_\_\_\_

Surveyor's Tel 90010068 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 3 days

Resurvey after repair

3986.85

Labour 1	:	2,747.00
Parts	:	1,109.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	269.98
Grand Total	:	4,126.78

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 46438  
Date Estimated : 31/03/2018  
Prepared By : Han Kwan Yong

Page No. :

**REPAIR FOR -**  
Ho Hai Wee (He Haiwei)  
12C Hougang Street 11  
#14-65

Singapore 534072

**- ACCOUNT - 158**  
Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLJ2818A	5B45446	02/12/2016	216d G TOURER	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
To make good front bumper include replacement of damaged parts and knocking out dents caused by the accident		850.00		850.00 ✓
To respray front bumper		934.00		934.00 ✓
To check electrical wiring systems at the front section for proper function including adjustments of headlights.		150.00		150.00 ✓
Sundries.		40.00		40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RH FINISHER (LUXURY LINE)	60.20	1.00		60.20
# WINDSHIELD CLEANING CONTAINER *	126.45	1.00		126.45
# (S/L) WASHER ADDITIVES (250ML) *	3.60	1.00		3.60

### # SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	190.25
Total Labour & Parts :	2,164.25
Deduction for Excess :	0.00
Total Repair Costs less Excess:	2,164.25
GST @7%:	151.50
Grand Total :	2,315.75

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 46438  
Date Estimated : 31/03/2018  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Ho Hai Wee (He Haiwei)  
12C Hougang Street 11  
#14-65

Singapore 534072

- ACCOUNT - 158  
Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLJ2818A	5B45446	02/12/2016	216d G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# WINDSHIELD CLEANING CONTAINER *	126.45	1.00		126.45 ✓
# (S/L) WASHER ADDITIVES (250ML) *	3.60	1.00		3.60 ✓

Total Labour :	
Total Parts :	130.05
Total Labour & Parts :	130.05



**Catherine Chong (LKK Auto)**

---

**From:** ERIC WOO JUN KIAT <ericwoo@lonpac.com>  
**Sent:** Monday, 2 April, 2018 3:46 PM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG; pml-pbsp@simedarby.com.sg  
**Subject:** FW: Our Ref: 17/18/18/VP05/020502 REQ FOR DIRECT SETTLEMENT- SLJ2818A AND SKS7191E(LONPAC) ON 29/03/2018  
**Attachments:** img-402122527-ApeosPort-IV 3070(122003)-6042-180402122532.tif; SLJ2818A.PDF

Dear Catherine / Nivitha,

Kindly refer to our attachment and email below.

Please proceed to conduct a survey of the vehicle SLJ 2818A on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

*02042018 @ 4:03pm  
Caroline wch action*

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

---

**From:** GERALD POH WEE BIN  
**Sent:** Monday, 2 April, 2018 12:41 PM  
**To:** PBSP  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SLJ2818A AND SKS7191E(LONPAC) ON 29/03/2018

WITHOUT PREJUDICE

Dear Caroline,

Our insured has yet to lodge a report and we are unable to comment on liability.

We shall proceed to appoint our surveyor to survey the vehicle.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** PBSF [mailto:pml-pbsp@sime-darby.com.sg]

**Sent:** Monday, 2 April, 2018 12:31 PM

**To:** GERALD POH WEE BIN; ERIC WOO JUN KIAT; 甯璿 ©; CS A Team

**Subject:** REQ FOR DIRECT SETTLEMENT- SLJ2818A AND SKS7191E(LONPAC) ON 29/03/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## Shu Pei (LKKAUTO)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Wednesday, 4 April 2018 11:01 AM  
**To:** Shu Pei (LKKAUTO); GERALD POH WEE BIN; ERIC WOO JUN KIAT  
**Cc:** MT\_Claim\_SG; Admin A; Vivian Lau (LKKAUTO)  
**Subject:** RE: Direct Settlement - Accident Involving SKS7191E (OI : LPC - 17/18/18/VP05/020502) AND SLJ2818A (TP : LKK REF -CC3/LPC18005944/wb3 ) on 29.03.2018  
**Attachments:** SKS7191E 290318.PDF

Dear Shu Pei

Please see our Insured's GIA report attached.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]  
**Sent:** Wednesday, 4 April, 2018 10:29 AM  
**To:** GERALD POH WEE BIN; ERIC WOO JUN KIAT; ONG LI LI  
**Cc:** MT\_Claim\_SG; Admin A; Vivian Lau (LKKAUTO)  
**Subject:** RE: Direct Settlement - Accident Involving SKS7191E (OI : LPC - TBA) AND SLJ2818A (TP : LKK REF - CC3/LPC18005944/wb3 ) on 29.03.2018

### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shu Pei (LKKAUTO)  
**Sent:** Monday, 2 April 2018 2:59 PM  
**To:** 'GERALD POH WEE BIN' <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)>; 'ERIC WOO JUN KIAT' <[ericwoo@lonpac.com](mailto:ericwoo@lonpac.com)>; ONG LI LI <[llong@lonpac.com](mailto:llong@lonpac.com)>  
**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Vivian Lau (LKKAUTO) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>

**Subject:** Direct Settlement - Accident Involving SKS7191E (OI : LPC - TBA) AND SLJ2818A (TP : LKK REF - CC3/LPC18005944/wb3 ) on 29.03.2018

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case from M/s Performance Motors Limited.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- TP's GIA report

Please be informed that preliminary advice is not ready yet.

Our case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LK K - Asher Ing

Lonpac Insurance Bhd  
300 Beach Road  
#17- 04/07 The Concourse  
Singapore 199555  
Attention: Motor Claims



Your Ref :

Our Ref :

Date :

Subject :

08 January 2019

**ACCIDENT INVOLVING SLJ2818A AND SKS7191E ON 29.03.2018**

Dear Sirs

We refer to the above matter.

We are pleased to enclose the Discharge Voucher duly executed by our client.

Please let us have your settlement cheque made in favour of "Performance Motors Limited" within the next 14 days.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to [pml-pbsp@sime-darby.com.sg](mailto:pml-pbsp@sime-darby.com.sg).

Performance Motors  
Limited  
1800-Call-BMW  
(1800-2255-269)

[www.pml.com.sg](http://www.pml.com.sg)

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel After-sales:  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
#01-01  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel After-sales:  
6319 0527  
Fax 6479 6624

280  
Kampong Arang Rd  
East Coast Centre  
Singapore 438180  
Tel After-sales:  
6319 0888  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No:  
197401559W

Yours sincerely

Teng Wai Khan  
Customer Service Manager, Body & Paint




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18005944/R1jb3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 02-07-2019		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKS 7191E	Veh. Inspected	SLJ 2818A	
Policy No.	Z17VP05016767	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020502	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	02/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	BMW 216D GT	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBA2E320105B45446	Colour	WHITE	
Odometer	34197	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	205/55 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/55 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R17	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/03/2018	Inspection Date	09/04/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 2818A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SUNDRIES (SN)	NECESSARY	80.00	40.00
1	FRT IMPACT ABSORBER (SN)	SERVICEABLE	47.80	-
1	RH FINISHER (LUXURY LINE) (SN)	CRACKED	60.20	60.20
1	RH SUPPORT FOG LAMP (GESCHLOSSEN)(SN)	SERVICEABLE	50.95	-
1	FRT BUMPER PANEL PRIMED (PMA) (SN)	TO REPAIR SEE LABOUR	842.00	-
1	GRILLE SIDE OPEN RH (LUXURY) (SN)	SERVICEABLE	95.85	-
10	CLIP (SN)	SERVICEABLE	13.00	-
1	WINDSHIELD CLEANING CONTAINER (ADDITIONAL) (SN)	DEFORMED	126.45	126.45
1	(S/L) WASHER ADDITIVES (250ML) (ADDITIONAL) (SN)	NECESSARY	3.60	3.60
			1,319.85	230.25
<b>LABOUR</b>				
TO REPLACE FRONT BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRT BUMPER PANEL PRIMED (PMA) .			1,275.00	850.00
TO RESPRAY FRONT BUMPER.			1,038.00	934.00
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.			177.00	150.00
TO REMOVE OLD PDC ASSEMBLY AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		NOT NECESSARY	177.00	-
			2,667.00	1,934.00
<b>GRAND TOTAL</b>			<b>3,986.85</b>	<b>2,164.25</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,164.25</b>

Report Ref No. CC4/LPC18005944/R1jb3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.