

SS-REC-BY:

REF: 13/FWD 18005948 / Airbed

Special Instruction:

SUPERVISOR

RASHA

ASSIGNMENT (Office)

From (Person):

Clara Li

of

FWD

Date/Time:

02042018 1123am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FY 24D

Insured:

at Workshop m/s

Performance

Tel:

9632 8105

of

313 Alexandra Rd

Policy No:

Claim No:

1201800003314

Sum Insured:

Excess:

\$ 1000.00

Make of Veh:

(Client's Record)

D.O.A.

14032018

CA / REV / REP. / REV 24 HRS

04-04-2018

H.O.D. Endorsement:

Date/Time:

02042018 11.58am

Person Contacted:

William

Vehicle IN/OUT

Date/Time

Action/Instruction (✓)

Estimate

motorcycle rear tyre burst & lost control

FY 24D - X

05/04/18

Revert thru merimen

9/4/18

Authorise repair and inform repairer to proceed

Supplementary received, minutes approval

SIRNAME

REF: FWD

8432A

ASSIGNMENT

From:

Date: 04042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

FY 24D

at Workshop m/s

Performanc

of

315 Alexandra Rd.

Insured

Policy No.

Claims No.

Sum Insured:

Excess: \$1000.00

(Client's Record)

Make of Veh:

Motorcycle rear tyre burst & lost control

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

45K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FY 24D

Yr Regn:

2016 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

P.M.W R1200GSA

c.c

1170

Colour:

Multi

A/C:

Insured / Std / NI / NA

Sp. Reading

28605

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WB10A020162172083

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70 R18

R:

120/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A

14/03/18

D.O.I.

04/04/18

Survey held at

PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Confirm \$11,061.90, 5 days
 Red. \$3659.44, 25%.

RECEIVED 28 MAY 2018

Date/Time, File Pass to?



Preli. Report



Final Report

1) typet

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation

3 - PR - \$

1 Photo

1 Follow

1

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Report Format:

OD

Lump Sum / I.B.I. (\$)

11061.90

250

50+50

10

360


LIMRA PTE LTD 凌瑞私人有限公司
INSURANCE AGENCY

BLK 9, KALLANG PLACE, #06-10 KALLANG BASIN IND. ESTATE
SINGAPORE 339154. TEL: 62966166 FAX: 62966766
E-mail: limra@limra.com.sg Co. Regn. No.: 198105491G

35 YEARS OF EXCELLENCE SERVICE

TO: EZ HOME PRODUCTS PTE LTD
202B SENGKANG EAST ROAD,
#14-74
SINGAPORE 542202

DEBIT NOTE
NOTE NO. 160777
DATE: 19/07/2016
AGENT: -/JT/SLC

26 JUL 2016

POLICY NUMBER: VA1/GA115615
INSURER: AXA INSURANCE SINGAPORE P/L
CLASS OF INSURANCE: MOTOR
PERIOD COVERED/VOYAGE: 19/07/2016 TO 18/07/2017
SUM INSURED: MARKET VALUE
NETT PREMIUM: 2,286.75 (A6666 10.000% NCB)
GST @ 7%: 160.07
AMP DUTY: 2,446.85
AMOUNT DUE: 2,446.85
COVERING: ON COMPREHENSIVE COVER
FOR VEHICLE NO. SKS2762R (ANY WORKSHOP).

Cheque should be crossed and made payable to "LIMRA PTE LTD"
支票開單應註明付於 "凌瑞私人有限公司"

IMPORTANT NOTICE
THIS PREMIUM SHOULD BE PAID WITHIN 60 DAYS FROM INCEPTION
DATE OTHERWISE POLICY WILL BE AUTOMATICALLY CANCELLED
投保者須在享有信貸的保單承保開始之日的60天內付清保費，否
則保單自動失效。

E & O. E.

LIMRA PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS/FWD18005948/R1rb

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 02-04-2018



Code : FWD

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	FY 24D
Policy No.	Coverage (\$)	0.00
Claim No. 1201800003314	Excess (\$)	1,000.00
Assign From CLARA LI	Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 14/03/2018	Inspection Date 04/04/2018
Survey held at 315 ALEXANDRA ROAD	
Repairer PERFORMANCE MOTORS LTD	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: motorclaims.sg@fwd.com
Sent: Monday, 2 April, 2018 11:23 AM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Subject: FW: FY24D - Accident bike on 14/03/2018 0545hrs at Malaysia North South Highway near Sungka, Perak - OD claim(FWD insurance Singapore) Our Ref: 1201800003314
Attachments: FY24D Insurance cert.pdf; FY24D Repair estimate.pdf; GIA REPORT - FY24D.pdf
Importance: High

Hi LKK team,

Please refer to the email below and liaise with the repairer for OD survey. Policy excess \$1K.

Attached is the repair estimate & OI GIA report.

Please create the case in Merimen and revert to us with preliminary report.

Thank you.

Note ***Insured motorcycle rear tyre burst and lost control***

Kind Regards
Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
--	--	--	--

From: Teh Hooi Teik [mailto:teh.hooi.teik@simedarby.com.sg]
Sent: Monday, 2 April, 2018 11:01 AM
To: Motor Claims SG - SG Common
Cc: Kris Chew L C; Elaine Wong

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 05 Apr 2018

Preliminary Advice

Vehicle No	: FY24D	Accident Date	: 14/03/2018
Make	: BMW R1200 GSA	Policy No.	: PNMC2017-50748
Assignment Date	: 02/04/2018	Excess	: S\$1,000.00
Date of Inspection	: 04/04/2018	Est. Duration of Repair	: 5.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion, o/s and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,073.75
Revised Amount	:S\$	10,325.13
Check Items (Estimated)	:S\$	161.66
Total	:S\$	10,486.79

1472134

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	5,273.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,727.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

VEHICLE'S TOP VIEW

FRONT PORTION

REAR PORTION

	FRONT BUMPER	RADIATOR, PANEL, CONDENSER, HEADLAMP	FRONT FENDER			SPARE TYRE PANEL	REAR FENDER	REAR PANEL	REAR BUMPER
PRS PRICE GUIDE	\$3 500	\$7,000	\$9,000			\$9,800	\$7500	\$3500	\$2500

FOR NON JAPAN MODEL ADD 20%

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 17 May 2018

Preliminary Advice

Vehicle No	: FY24D	Accident Date	: 14/03/2018
Make	: BMW R1200 GSA	Policy No.	: PNMC2017-50748
Assignment Date	: 02/04/2018	Excess	: S\$1,000.00
Date of Inspection	: 04/04/2018	Est. Duration of Repair	: 5.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion, o/s and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,721.34	(Include Supplementary \$647.59)
Revised Amount	:S\$	10,972.72	(Include Supplementary \$647.59)
Check Items (Estimated)	:S\$	161.66	
Total	:S\$	11,134.38	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	5,273.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,727.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

AUTHORISATION TO ACT
(Chartis Express Third Party Claim)

I, SMART TAXIS PTE LTD (the third party claimant") of 60 WOODLANDS INDUSTRIAL PARK
E4, S(757705) (address), owner of SHB 5294E (vehicle no.) hereby authorize SMART
AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SHB 5294E that was
damaged pursuant to the accident which occurred on 04/11/2012 (date) along COLLYER QUAY
ROAD TOWARDS ESPLANADE ROAD (location) involving vehicle no/s SIL 1311P ("the
accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 16 (day) of Jan (month) 2013 (year)

Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8432A
Vehicle Details	
Vehicle No.:	FY24D
Vehicle to be Exported:	No
Intended De-registration Date:	05 Apr 2018
Vehicle Make:	B.M.W.
Vehicle Model:	R1200GSA
Primary Colour:	Blue
Secondary Colour:	Black
Manufacturing Year:	2016
Engine No.:	122EN20160130
Chassis No.:	WB10A0201GZ772083
Maximum Power Output:	-
Open Market Value:	\$19,668.00
Original Registration Date:	19 Aug 2016
First Registration Date:	19 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$2,951.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Aug 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,302.00
COE Rebate Amount:	\$5,273.00
Total Rebate Amount:	\$5,273.00

The information contained herein is correct as at 05 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/03/2018 15:58
Date Of Accident	14/03/2018 05:45
Exact Location Of Accident	ALG NORTH SOUTH EXPRESSWAY MALAYSIA NEAR TO SUNGKA
Country/State of Loss	MALAYSIA/PERAK DARUL RIDZUAN

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FY24D
Insured/Policyholder	
Name Of Registered Owner	NUR MUHAMMAD SUFI BIN SAPI'EE
NRIC No	S8118432A
Email Address	NMSUFI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98711455
Alternative Phone No	OFFICE-98711455

Vehicle Particulars

Manufacturer	BMW
Model	R1200GSA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own Insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNMC2017-50748
Cover Note Number	

Driver

Name of Driver	NUR MUHAMMAD SUFI BIN SAPI'EE
NRIC No	S8118432A
Date Of Birth	28/06/1981
Occupation	INDOOR
Date Of Driving Pass	13/10/1999
Driving Experience	18 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98711455
Fax Number	
Contact Number	OFFICE-98711455
Email Address	NMSUFI@GMAIL.COM

Address BLK 634 WOODLANDS RING ROAD #03-127 SINGAPORE 730634
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident NO COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? NO
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : ZOOM ZAKARIAH @SITI ZUMRAH BINTE ZAKARIAH
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] TRAFIK TAPAH
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE POLICE REPORT, TRAFFIC TAPAH/000942/18 TRANSLATED TO ENGLISH. ON 14/03/2018 AT ABOUT 5AM I RIDING MY MOTORCYCLE E NUMBER FY24D WITH MY FIANCE FROM SINGAPORE TO THAILAND, UPON ARRIVING AT KM 349 NORTH-SOUTH HIGHWAY, HEADING TOWARDS NORTHWARDS WHEN SUDDENLY MY REAR TYRE BURST. I LOST CONTROL OF MY MOTORCYCLE AND SKIDDED/ FELL ON THE ROAD AND SUFFERED INJURES TO MY WAIST/HIP, HAND, ARM, RIGHT THUMB. MY FIANCE, ZOOM ZAKARIA SUFFERED INJURIES TO HER RIGHT HAND, RIGHT ARM, RIGHT LEG. MY MOTORCYCLE SUFFERED DAMAGES TO ITS REAR RIM (BENT), BENT FORK, BENT HDNALE AND BROKEN COVER SET.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF INJURED PERSON 1

Name NUR MUHAMMAD SUFI BIN SAPI'EE
 Approximate Age
 Injuries Sustain
 Injured person in which vehicle? FY24D
 Were seat belts worn? NO
 Was this injured conveyed to hospital by ambulance? NO
 Address

Postcode

DETAILS OF INJURED PERSON 2

Name	ZOOM ZAKARIAH @SITI ZUMRAH BINTE ZAKARIAH
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FY24D
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Handwritten signature
3:21pm
15/3/18


VERIFIED BY AJAX MARS
REPORTING OFFICER
THOMAS NG CHIN CHUN

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan





POLIS DIRAJA MALAYSIA REPOT POLIS

Balai : TRAFIK TAPAH
 Daerah : TAPAH
 Kontinjen : PERAK
 No Repot : TRAFIK TAPAH/000942/18
 Tarikh : 14/03/2018
 Waktu : 1033 AM
 Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R190050

Butir-butir Penerima Repot

Nama : MOHAMAD ZAINI BIN (BAI)ARI

No Personel : R121900

Pangkat : KPL

Butir-butir Jurubahasa (Jika Ada)

Nama : —

No K/P (Baru) : —

No Polis/Tentera : —

No Paspot : —

Bahasa Asal : —

Alamat : —

Butir-butir Pengadu

Nama : NUR MUHAMMAD SUFI BIN SAHI

No K/P (Baru) : —

No Polis/Tentera : —

No Paspot : E6950525J

No Sijil Boranak : —

Jantina : Lelaki

Tarikh Lahir : 28/06/1981

Umur : 36 tahun 8 bulan

Keturunan : Melayu

Warganegara : Singapore

Pekerjaan : POLIS SINGAPORE

Alamat Tempat Tinggal : BLK 634 WOODLANDS RING ROAD SINGAPORE, 730634

Alamat Ibu/Bapa : —

Alamat Pejabat : —

No Tel (Rumah) : —

No Tel (Pejabat) : —

No Tel (HP) : 98711455

Emel : —

Pengadu Menyatakan:-

PADA 14/03/2018 JAM LEBIH KURANG 5:00 PAGI SEMASA SAYA SEDANG MENUNGGANG M/SIKAL NO.FY24D BERSAMA TUNANG SAYA DARI SINGAPORE HENDAK PERGI THAILAND,KELIKA SAYA SAMPAI DI KM 349 11:BUH RAYA UTARA SELATAN,ARAH UTARA TIBA-TIBA TAYAR BELAKANG M/SIKAL SAYA MELI:TUP M/SIKAL SAYA HILANG KAWALAN TERBABAS,SAYA BERSAMA M/SIKAL TERJATUH DI ATAS JALAN DAN MENIDAPAT KECEDERAAN,PINGGANG LUKA,TANGAN LUKA,LENGAN LUKA,IRU JARI KANAN CEDERA,TUNANG SAYA NAMA ZOOM ZAKARIA,CEDELA DI TANGAN KANAN,LENGAN KANAN LUKA,KAKI KANAN LUKA,KEROSAK M/SIKAL,RIM BELAKANG BENGKOK,BOX BENGKOK,HENDEL BENGKOK,COVER SET PECAH.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

: R121900 | 14/03/2018 10:56:16 AM

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : w5 46425
Date Estimated : 29/03/2018
Prepared By : Elaine Wong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Nur Muhammad Sufi Bin Sapiiee
Block 634 Woodlands Ring Road
#03-127

Singapore 730634

- ACCOUNT - 163385
FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
FY24D	Z772083	19/08/2016	R 1200 GSA	0

DESCRIPTION

Replacing damaged parts cause by accident.

VALUE

2400 3,280.00

Pirelli Scorpion Trail 2 170/60/R17

burst 350.00

Accident on 14/03/2018 0545hrs at Along North South Highway
Malaysia Near to Sungka, Perak

0.00

OD claim-FWD Singapore Pte Ltd Insurance policy - PNMC2017-
50748

0.00

This estimate is based on visual inspection only.
Additional fees and parts may be required during the course
of repair.

0.00

All parts price are subject to change without prior notice.

0.00

Total Labour 1: 3,600.00

PART NUMBER DESCRIPTION

PART NUMBER	DESCRIPTION
07119904950	O-RING (27X3.2)
07119907438	CSK FILLISTER HEAD SCREW M3.5X30
07119907874	O RING 24X3
07119963073	GASKET RING
07119963252	GASKET RING
07119963342	WASHER*
07129907390	FILLISTER HEAD SCREW M10X50
11128382758	CYLINDER HEAD GASKET 3 LAYER RH
11128523552	SCREW WITH BUSH
11128532975	IGNITION COIL COVER LH
11128532976	IGNITION COIL COVER RH
11128542058	RH SEALING KIT CYLINDER HEAD COVER
11128546332	RH CYLINDER HEAD BLACK
11128549654	CYLINDER HEAD COVER ASPHALT GRAU RH
11317710485	REPAIR KIT VALVE SEAL RING
11318523261	CLAMPING BOLT
11318546712	GEAR WHEEL 3=+0.04MM

QTY	PRIC	DISC	VALUE
1	4.38	0.00	4.38
1	7.24	0.00	7.24
1	3.80	0.00	3.80
1	0.50	0.00	0.50
1	2.95	0.00	2.95
1	1.25	0.00	1.25
2	9.11	0.00	18.22
1	92.27	0.00	92.27
3	25.99	0.00	77.97
1	35.78	0.00	35.78
1	35.78	0.00	35.78
1	97.09	0.00	97.09
1	1,808.43	0.00	1,808.43
1	315.39	0.00	315.39
1	120.33	0.00	120.33
1	3.13	0.00	3.13
2	184.14	0.00	368.28

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401359W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

289, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : w5 46425
Date Estimated : 29/03/2018
Prepared By : Elaine Wong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
FY24D	Z772083	19/08/2016	R 1200 GSA	0

PART NUMBER	DESCRIPTION	QTY	PRIC	DISC	VALUE
11347718103	ADJUSTING PLATE 2.44 MM	2	9.49	0.00	18.98
11347719100	ADJUSTING PLATE 2.42 MM	2	9.49	0.00	18.98
12531721040	BRACKET CABLE HARNESS	6	5.03	0.00	30.18
18517726822	EXHAUST SEAL	2	15.08	0.00	30.16
32718556251	HANDLEBAR	1	359.13	0.00	359.13
32728525826	CLUTCH LEVER	1	102.63	0.00	102.63
32728533739	HANDBRAKE LEVER	1	102.63	0.00	102.63
36317673903	WHEEL BOLT	5	8.53	0.00	42.65
36317720640	BALANCE WEIGHT (30 GR)	2	4.05	0.00	8.10
36318520871	REPAIR KIT TIRE PRESSURE MONITOR VA	1	32.24	0.00	32.24
36318526651	SPOKE WHEEL REAR 4.5X17	1	1,738.45	0.00	1,738.45
36318532731	SENSOR WITH VALVE	1	161.19	0.00	161.19
46548520068	CASE CARRIER RH	1	310.50	0.00	310.50
46548520069	CROSS BRACE	1	91.53	0.00	91.53
46628536970	REAR CARRIER PART	1	480.06	0.00	480.06
46638523431	HAND PROTECTOR LH	1	53.22	0.00	53.22
46638523432	HAND PROTECTOR RH	1	53.22	0.00	53.22
46638523433	BRACKET HAND PROTECTOR LH	1	22.39	0.00	22.39
46638523435	BUSH	1	15.41	0.00	15.41
46638538035	TANK PROTECTOR LH	1	421.50	0.00	421.50
46638538036	TANK PROTECTOR RH	1	421.50	0.00	421.50
46638538037	HOLDER TANK PROTECTION LH	1	68.10	0.00	68.10
46638538038	HOLDER TANK PROTECTION RH	1	68.10	0.00	68.10
51168567447	MIRROR LH	1	115.45	0.00	115.45
51168567448	MIRROR RH	1	115.45	0.00	115.45
61318567720	COMBINATION SWITCH RH (LIN BUS)	1	236.71	0.00	236.71
63138522499	LED FLASHER	1	83.88	0.00	83.88
71217698971	LABEL	1	4.25	0.00	4.25
71248523443	LABEL TYRES ECE	1	21.10	0.00	21.10
77148565802	RH ENGINE PROTECTION BAR	1	301.81	0.00	301.81
77412455445	LH ALUMINIUM CASE BLACK	1	804.44	0.00	804.44
77412455446	RH ALUMINIUM CASE BLACK	1	804.44	0.00	804.44
77498544517	REPAIR KIT LOCK CYLINDER	6	50.93	0.00	305.58
83192385214	(DG/SL) BRAKE CLEANER 500 ML	1	17.25	0.00	17.25
83512355290	ANTI-FREEZE 1.5 LITRES	1	19.75	0.00	19.75

RASIL

Hp 900/10068

5 days

P/P

04/04/18 @ 1100

EXCESS: 1000

REVERT

Resurvey after repair

(include damage photos & new parts)

Total Parts : 10,473.75

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

Labour 1	: 14,073.75	3,600.00
Parts	:	10,473.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	985.16
Grand Total	:	15,058.91

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

16721-34

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740199W GST Reg. No M2-0020081-X



309, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747735

139, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796501 (AfterSales)
64796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : w5 46740
Date Estimated : 26/04/2018
Prepared By : William Teh Hooi Teik

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -
Nur Muhammad Sufi Bin Sapiee
Block 634 Woodlands Ring Road
#03-127
Singapore 730634

- ACCOUNT - 163385
FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
FY24D	2772083	19/08/2016	R 1200 GSA	28605

DESCRIPTION

Supplementary parts for FY24D accident repair.

VALUE

0.00

Total Labour 1: 0.00

PART NUMBER DESCRIPTION

PART NUMBER	DESCRIPTION
11128523552	SCREW WITH BUSH
11128542057	LH SEALING KIT CYLINDER HEAD COVER
11128549653	CYLINDER HEAD COVER ASPHALT GRAU LH
46628546508	REAR WHEEL COVER

QTY	PRIC	DISC	VALUE
3	25.99	0.00	77.97
1	97.09	0.00	97.09
1	315.39	0.00	315.39
1	157.14	0.00	157.14

Total Parts : 647.59

Labour 1	:	0.00
Parts	:	647.59
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	45.33
Grand Total	:	692.92

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report **correctly** the details of the accident to speed up the claims process
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may show insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the G/A Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan

Refer attached

Describe Circumstances of the Accident

Refer Police Report T/m12

Declaration

We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature / Date & 	Driver's Signature (if driver is not the policyholder) / Date & 	Witnessed by Reporting Centre (Personnel)
---	---	--

19-1-12

SM

1504

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740199W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190112 (AfterSales)
Fax. 64747770

199, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/510 (Motorrad)
Fax. 64796401 (AfterSales)
64796424 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : w5 46425
Date Estimated : 29/03/2018
Prepared By : Elaine Wong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Nur Muhammad Sufi Bin Sapiee
Block 634 Woodlands Ring Road
#03-127
Singapore 730634

- ACCOUNT - 163385
FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
FY24D	2772083	19/08/2016	R 1200 GSA	28605

DESCRIPTION

VALUE

Replacing damaged parts cause by accident.

2,400.00

Michelin Anakee 3 Rear - 170/60/R17

350.00

Accident on 14/03/2018 0545hrs at Along North South Highway
Malaysia Near to Sungka, Perak

0.00

OD claim-FWD Singapore Pte Ltd Insurance policy - PNMC2017-
50748

0.00

Total Labour 1: 2,750.00

PART NUMBER DESCRIPTION

QTY	PRIC	DISC	VALUE
1	7.24	0.00	7.24
2	9.11	0.00	18.22
6	25.99	0.00	155.94
1	35.78	0.00	35.78
1	35.78	0.00	35.78
1	97.09	0.00	97.09
1	97.09	0.00	97.09
1	315.39	0.00	315.39
1	315.39	0.00	315.39
6	5.03	0.00	30.18
1	359.13	0.00	359.13
1	102.63	0.00	102.63
1	102.63	0.00	102.63
5	8.53	0.00	42.65
2	4.05	0.00	8.10
1	32.24	0.00	32.24
1	1,738.45	0.00	1,738.45
1	161.19	0.00	161.19
1	310.50	0.00	310.50
1	91.53	0.00	91.53
1	480.06	0.00	480.06
1	157.14	0.00	157.14
1	53.22	0.00	53.22

07119907438 CSK FILLISTER HEAD SCREW M3.5X30
07129907390 FILLISTER HEAD SCREW M10X50
11128523552 SCREW WITH BUSH
11128532975 IGNITION COIL COVER LH
11128532976 IGNITION COIL COVER RH
11128542057 LH SEALING KIT CYLINDER HEAD COVER
11128542058 RH SEALING KIT CYLINDER HEAD COVER
11128549653 CYLINDER HEAD COVER ASPHALT GRAU LH
11128549654 CYLINDER HEAD COVER ASPHALT GRAU RH
12531721040 BRACKET CABLE HARNESS
32718556251 HANDLEBAR
32728525826 CLUTCH LEVER
32728533739 HANDBRAKE LEVER
36317673903 WHEEL BOLT
36317720640 BALANCE WEIGHT (30 GR)
36318520871 REPAIR KIT TIRE PRESSURE MONITOR VA
36318526651 SPOKE WHEEL REAR 4.5X17
36318532731 SENSOR WITH VALVE
46548520068 CASE CARRIER RH
46548520069 CROSS BRACE
46628536970 REAR CARRIER PART
46628546508 REAR WHEEL COVER
46638523431 HAND PROTECTOR LH

4747.59

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 43190120 (Sales & Admin)
43190111 (AfterSales)
Fax. 44747770

180, Kampong Arang Road
East Coast Centre
Singapore 438190
Tel. 43190888 (AfterSales)
Fax. 43449773

319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 43190528 (AfterSales)
43190533/530 (Motorrad)
Fax. 44796521 (AfterSales)
44796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : w5 46425
Date Estimated : 29/03/2018
Prepared By : Elaine Wong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
FY24D	2772083	19/08/2016	R 1200 GSA	28605

PART NUMBER	DESCRIPTION	QTY	PRIC	DISC	VALUE
46638523432	HAND PROTECTOR RH	1	53.22	0.00	53.22
46638523433	BRACKET HAND PROTECTOR LH	1	22.39	0.00	22.39
46638523435	BUSH	1	15.41	0.00	15.41
46638538035	TANK PROTECTOR LH	1	421.50	0.00	421.50
46638538036	TANK PROTECTOR RH	1	421.50	0.00	421.50
46638538037	HOLDER TANK PROTECTION LH	1	68.10	0.00	68.10
61318567720	COMBINATION SWITCH RH (LIN BUS)	1	236.71	0.00	236.71
63138522499	LED FLASHER	1	83.88	0.00	83.88
71217698971	LABEL	1	4.25	0.00	4.25
71248523443	LABEL TYRES ECE	1	21.10	0.00	21.10
77148565802	RH ENGINE PROTECTION BAR	1	301.81	0.00	301.81
77412455445	LH ALUMINIUM CASE BLACK	1	804.44	0.00	804.44
77412455446	RH ALUMINIUM CASE BLACK	1	804.44	0.00	804.44
77498544517	REPAIR KIT LOCK CYLINDER	6	50.93	0.00	305.58
Total Parts :					8,311.90

Labour 1	:	2,750.00
Parts	:	8,311.90
Labour 2	:	0.00
Excess	:	1,000.00
Total GST @ 7%	:	704.33
Grand Total	:	10,766.23

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Janice Lee (LKKAUTO)

From: clara.li@fwd.com
Sent: Wednesday, May 09, 2018 5:19 PM
To: SUR; assignments
Cc: motorclaims.sg@fwd.com
Subject: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314
Importance: High

Hi Mohd Rasul,

We refer to the above OD claim which surveyed by you at Performance Motors Limited.

Please refer to our insured's email below and advise the damaged items mentioned were due to the accident.

Quote

Hi,

I have collected my motorcycle and excess paid to Performance Motor Limited. I found that the left side of my crash the left with photos of my damaged accessories (not claimable) totally unusable. Performance Motors explained that the rigidity of the crash bars and luggage carrier both on the left side is not compromised from the accident?

Please revert to us by EOB 10 May 2018.

Thank you.

Kind Regards
Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



Hi clara, this photo was taken directly on the damage photo without display the veh. no. plate. ~~moreover~~, kindly, show the part located of this bike on general

Unquote

right side

Janice Lee (LKKAUTO)

From: clara.li@fwd.com
Sent: Wednesday, May 09, 2018 6:26 PM
To: SUR; assignments
Cc: motorclaims.sg@fwd.com
Subject: RE: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314
Attachments: Mud guard.jpg

Hi Mohd Rasul,

Additional item mentioned by our policyholder, please refer to the attached photo and advise us it's due to the accident.

Thank you.

Kind Regards
Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

This damage mudguard was given and replace by the repairer, but the part was not concluded inside the estimate finance invoice. Repairer did inform owner that parts currently no stock available. Need to wait part to arrive.

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



Endowment Plan

Get the biggest guaranteed return for a 3 year plan available online.

Limited time offer!



2.02%
p.a.
fwd.com.sg

save now

From: Clara Li Zirong - SGUser
Sent: Wednesday, 9 May, 2018 5:19 PM
To: 'sur@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Motor Claims SG - SG Common
Subject: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314
Importance: High

Hi Mohd Rasul,

We refer to the above OD claim which surveyed by you at Performance Motors Limited.

Please refer to our insured's email below and advise the damaged items mentioned were due to the accident.

It's good to have what you want faster

Introducing weekend processing of auto financing applications*

Find out more

* Terms and conditions apply

Standard Chartered

More for good

ARWIN

> over 300 Commercial Vehicles

> Our own workshop

> In-house Loan

With our vehicles

03/2009 Odyssey 2.4A EXV Premium Selling At \$119.8K

High Specification, Irrevocable Condition, Accident Free, Low Mileage

Tan Motor (Sole)

Post an Advertisement

Sell it yourself! Advertise it at just \$48 for 6 weeks.

Post an Ad

Advertiser Login

Ways of Selling

Compare listed cars

Search Selection

Honda Civic 1.8

Make

Model

Price

Reg Date

Gear

Eng Cap

Mileage

Veh Type

Status

Advanced Search

Submit

Honda Civic 1.8A

Posted: 07-Aug-2012

Tag: 2007 Honda Civic, Honda Civic, Used Honda

Available

Sedan

1,799 cc

Auto

02-Oct-2007

\$60,800

Honda Civic 1.8A (OPC)

Posted: 06-Aug-2012

Tag: 2007 Honda Civic, Honda Civic, Used Honda

Available

Sedan

48,215 km

1,799 cc

Auto

18-Dec-2007

\$52,800

Extra 10% Insurance Discount, GPS, Camera On Board, Mute Socket with USB, 1 Year Warranty, Normal At \$61800.

Honda Civic 1.8A

Posted: 06-Aug-2012

Tag: 2007 Honda Civic, Honda Civic, Used Honda

Available

Sedan

1,799 cc

Auto

08-Jun-2007

\$56,000

Low Mileage, Accident Free, Well Kept By Previous Owner, \$0 Driveaway Available, Bank And In House Loan Available, Monthly Instalment \$359 With Balloon Scheme

Honda Civic 1.8A

Posted: 06-Aug-2012

Tag: 2007 Honda Civic, Honda Civic, Used Honda

Available

Sedan

1,799 cc

Auto

08-Jun-2007

\$56,000

Black Sporting Car, Well Maintained, Showroom Condition, Full In House Loan Available, Call Now For Viewing.

Car Buying

Car Selling

Car Aftermarket

Men's Interest

Honda Civic VTI-S 1.8A

Posted: 05-Aug-2012

Tag: 2007 Honda Civic, Honda Civic, Used Honda

Available

Sedan

105,000 km

1,799 cc

Auto

28-May-2007

\$56,899

1 Owner, Accident Free, Full Agent Service, Paddle Shift, Mileage Done At 2000km Per Year, Good Condition.

Honda Civic 1.8A (OPC)

Posted: 05-Aug-2012

Tag: 2007 Honda Civic, Honda Civic, Used Honda

Available

Sedan

46,000 km

1,799 cc

Auto

03-Dec-2007

\$52,800

Full Serviced With Kan Motors, Full Mugen Bodykit, Twin Lowering Spring, Mugen Exhaust, Throttle Controller, Sport Booster, Worth \$5k! Hurry Call Now!

Honda Civic 1.8A

Posted: 05-Aug-2012

Tag: 2007 Honda Civic, Honda Civic, Used Honda

Available

Sedan

46,000 km

1,799 cc

Auto

03-Dec-2007

\$52,800

Full Serviced With Kan Motors, Full Mugen Bodykit, Twin Lowering Spring, Mugen Exhaust, Throttle Controller, Sport Booster, Worth \$5k! Hurry Call Now!

Janice Lee (LKKAuto)

From: motorclaims.sg@fwd.com
Sent: Thursday, May 10, 2018 1:52 PM
To: Janice Lee (LKKAuto); SUR
Subject: RE: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314

Hi Janice,

I do not have any other photos as it is provided by our insured. Please inform the surveyor to compare with the survey photos which he had taken during inspection.

Thank you.

Regards,
Clara

From: Janice Lee (LKKAuto) [mailto:JaniceLee@lkkauto.com]
Sent: Thursday, 10 May, 2018 1:48 PM
To: Clara Li Zirong - SGUser; SUR
Cc: Motor Claims SG - SG Common
Subject: RE: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314

Hi Clara,

This photo was taken directly on the damage without displaying the vehicle number plate. Kindly send us the photo where the damage parts located on the bike on general.

kindly contact me at 6256 3561 for further clarification

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler (On behalf of Rasul)

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: clara.li@fwd.com [mailto:clara.li@fwd.com]
Sent: Wednesday, May 09, 2018 6:26 PM
To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: motorclaims.sg@fwd.com
Subject: RE: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314

Hi Mohd Rasul,

Additional item mentioned by our policyholder, please refer to the attached photo and advise us it's due to the accident.

Janice Lee (LKKAUTO)

From: clara.li@fwd.com
Sent: Tuesday, May 15, 2018 6:01 PM
To: Janice Lee (LKKAUTO)
Cc: SUR; motorclaims.sg@fwd.com; josey.loh@fwd.com
Subject: RE: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314
Attachments: Email from OI 2.PNG; Email from OI 3.PNG; Email from OI.PNG

Hi Janice,

Please inform the surveyor to take note of our insured's concern in the attached email and try to resolve the issue during the resurvey tomorrow.

Please keep us updated.

Thank you.

Regards,
Clara

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Tuesday, 15 May, 2018 3:58 PM
To: Clara Li Zirong - SGUser
Cc: SUR; Motor Claims SG - SG Common
Subject: RE: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314

Hi Clara,

Owner is sending his bike for resurvey tomorrow. We will keep you posted.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: clara.li@fwd.com [mailto:clara.li@fwd.com]
Sent: Tuesday, May 15, 2018 3:33 PM
To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; motorclaims.sg@fwd.com
Subject: RE: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314

Hi Janice,

Can we have an update on our email sent on 09 May 2018?

LETTER OF DISCHARGE

We, KAN FOK SING MOTOR WORKSHOP (workshop), hereby agreed and confirmed that we are authorized by the owner of motor vehicle EE1388P to accept the sum of \$ 487.93 (inclusive of inte alia, damages, interests, loss of use, costs and disbursements) from M/s LKK Auto Consultants Pte Ltd, the authorized surveyors of M/s AXA Insurance Singapore Pte Ltd, the Third Party's insurers, on this matter.

This acceptance is in full and final settlement of any claim made against SKA 4819T pursuant to the road accident which occurred along VOLKSWAGEN GOLF CARPARK on 20/12/2012.

We KAN FOK SING MOTOR WORKSHOP (workshop) are further authorized by the said owner that this settlement is reached on a strictly without prejudice basis on the part of M/s AXA Insurance Singapore Pte Ltd. And or their insured or other person or persons arising out of this said accident.

In consideration of the said payment by the said M/s AXA Insurance Singapore Pte Ltd, we, the said authorized workshop, shall fully discharge them from any further claim whatsoever in respect of the said accident.

We also declare that we are authorized by the said owner to receive the said settlement sum and hereby undertake to indemnify M/s AXA Insurance Pte Ltd, against any claim made or which may be made in respect of this matter.

For and on behalf of the owner of
(CLIFFORD NG CHUAN BONG EE1388P)
(workshop stamp and authorized signature)



For and on behalf of M/s AXA
Insurance Singapore Pte Ltd
(LKK stamp and authorized
signature)





Tue 15/5/2018 5:13 PM

nmsufi@gmail.com

RE: FWD Motorcycle Insurance Policy | Claim 1201800003314 | Enquiry

To: Clara Li Zhenq - SGLuser; hordan_71@yahoo.com.sg

Cc: CRM and all customer engagements - SG Common; Motor Claims SG - SG Common; Josey Loh Kah Wai - SGLuser

Hi,

Noted on preceding email. Kindly inform my travel insurance to omit the telephone charges claim as well.

As spoken earlier, the following are some of the issues raised:



Dented panniers

Luggage holder not changed as PML says its still usable even though my first impact of accident was on the left of bike and dented the panniers.

- The left luggage rack are not changed and reused even though the panniers are dented from the accident (First impact was on the left side of bike)

my receipts and the link I purchased my Wunderlich Highway pegs:



reinforcement Bracket (For lower crash bar) - SGD\$170



valve cover guards- SGD \$270

Touratech reinforcement crash bar – unusable with replaced new lower crash bar.

Totally unusable Wunderlich valve covers (right and left).



Totally unusable Wunderlich highway pegs (right and left)

Old crash bar used again as PML says there is no damage, even though it's the first point of impact during accident.

- For my accessories that were damaged, the Wunderlich valve guards purchased from Mitekrak at \$60-\$79 are both damaged.
- The highways pegs purchased online via rippymans.com at \$136 pounds (UK) are both damaged.
- For my Touratech reinforcement bracket purchased from Mitekrak at \$60-\$130, according to PML, the new version of the crash bars is not compatible with my old reinforcement crash bar.
- PML is currently trying to get me a used lower right crash bar (old model) to see if the Touratech reinforcement bracket is still usable. I will have no issue if PML confirms that my Touratech reinforcement bars are still usable and there are no damages with the used and older version of my lower crash bars. But if not, Touratech also has a new version of the reinforcement bracket, 2018 version, (<http://touratech-usa.com/11026/MTW-Crash-Bar-Reinforcement-2013-on>) that is compatible to the new version lower crash bar (only if I get the left side lower crash bar replaced too).

Janice Lee (LKKAUTO)

From: clara.li@fwd.com
Sent: Thursday, May 17, 2018 9:57 AM
To: Janice Lee (LKKAUTO)
Cc: SUR; motorclaims.sg@fwd.com; josey.loh@fwd.com; belliana@fwd.com
Subject: RE: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314

Hi Janice,

Resurvey has been conducted yesterday.

Please let us have your surveyor's finding on our insured's concerns/issues during the inspection by **EOB today** as we need to get back to our insured.

Thank you.

Kind Regards

Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg SAVE NOW
--	--	---	--

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Tuesday, 15 May, 2018 6:04 PM
To: Clara Li Zirong - SGUser
Cc: SUR; Motor Claims SG - SG Common; Josey Loh Kah Wai - SGUser
Subject: RE: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314

Hi Clara,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG12019538/Anlt2

22/10/2012

CHEE BOON HEE LIONEL
1 JALAN SELANTING
#09-07
SINGAPORE 598368

Dear Sir/Madam,

ACCIDENT INVOLVING SFZ 6291D AND SKE 8002K ON 06/10/2012

We refer to the above accident where we are acting for Chartis Singapore Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Davion Ho
Case Handler
E-mail: Davionho@lkkauto.com
DID: 67491316 / FAX: 6741 4108

Case Handler

c.c. *Chartis Singapore Insurance Pte Ltd*
(Motor Claims Dept)

Janice Lee (LKKAUTO)

To: clara.li@fwd.com
Cc: SUR; motorclaims.sg@fwd.com; josey.loh@fwd.com; belliana@fwd.com
Subject: RE: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314

Dear Clara,

The repairer has resolve the ^{insured} queries regarding the crash bar, luggage carrier ^{and} the ^{no claim will be} ~~mug guard~~ ^{made} ~~made~~ under these 2

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: clara.li@fwd.com [mailto:clara.li@fwd.com]

Sent: Thursday, May 17, 2018 9:57 AM

To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; motorclaims.sg@fwd.com; josey.loh@fwd.com; belliana@fwd.com

Subject: RE: OD - Vehicle Number: FY24D DOA: 14/03/2018 Our Ref: 1201800003314

Hi Janice,

Resurvey has been conducted yesterday.

Please let us have your surveyor's finding on our insured's concerns/issues during the inspection by EOB today as we need to get back to our insured.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan 15 SEP 12 19:05

A. SFRQ42LL

B. SHC 500R

MS NG CHEONG CHING



Describe Circumstances of the Accident:

AFTER TURNING INTO PENANG ROAD FROM PENANG LANE, OUR VEHICLE WAS STRUCK ON THE DRIVER SIDE DOOR BY A TRANS CAR TAXI.

THERE WERE NO INJURIES AND THE DRIVER OF THE TAXI APPEARS TO BE AT FAULT DUE TO ANGLE OF DAMAGE TO BOTH VEHICLES.

PROVIDING DETAILED REPORT SEPARATELY.

MR TAN INDICATED HE HAS FOUR EYE-SIGHT.

Declaration

We declare the foregoing particulars are true in every respect.

[Signature] 17 SEP 12
 Policyholder's Signature / Date & Time

[Signature] 17/9/12
 Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature] 17/9/12
 Witnessed by Reporting Centre Personnel

Performance Motors Limited

A member of the Sime Darby Group
Co Reg No: 197401559W

**DISCHARGE / SATISFACTION CERTIFICATE**

Vehicle No.	:	<u>FY24D</u>
Make / Model	:	<u>BMW (K51) R1200GSA</u>
Accident Location	:	<u>Along North-South Highway Malaysia</u> <u>Near to Sungka exit.</u>
Date of Accident	:	<u>14/03/2018</u>
Name of Owner / Insured	:	<u>Nur Muhammad Sufi Bin Sap'ee</u>
Repairer	:	<u>Performance Motors Limited</u>
Own Insurer	:	<u>FWD Singapore Pte Ltd</u>
Motor Insurance Policy No.	:	<u>PNMC2017-50748</u>
Claim Reference No.	:	<u></u>
Policy Excess (W/GST)	:	<u>\$1,070.00</u>
Official Receipt No.	:	<u></u>

I/We hereby declare and confirm that I have received from the Repairers my/our Vehicle and that the repairs have been carried out to my/our entire satisfaction. I/We agree that the settlement of the cost of repairs by the Insurance Company to the account of the Repairers for the repairs shall be in full discharge of all claims under the Motor Insurance Policy in respect of damage to my/our vehicle resulting from the Accident/Loss on the Date of Accident/Loss.

Signature of Owner / Insured	:	<u></u>
Date	:	<u>02/05/2018</u>

≡ Without Prejudice for any
Personal Injury Claim

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 137401355W GST Reg. No M2-0020081-X



301, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

289, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190527 (AfterSales)
63190533/630 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : W5 1267777	Page No. : 1 of 3
Date IN : 12/04/2018	Invoice Number : 1965515 / WSB
Cust. Svc. Advisor : William Teh Hooi Teik	Invoice Date : 16/05/2018
	Payment Term : 30 Days From Invoice
	Invoice By : William Teh Hooi Teik

- CUSTOMER INFORMATION -

Mr Nur Muhammad Sufi Bin Sapiiee
Block 634 Woodlands Ring Road
#03-127
Singapore 730634

- INVOICE TO - 163385

FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

REGN. NO. FY24D	CHASSIS NO. Z772083	REGN. DATE 19/08/2016	MODEL R 1200 GSA	MILEAGE 28605
--------------------	------------------------	--------------------------	---------------------	------------------

CODE	DESCRIPTION	UNITS	NETT
0099000	Replacing damaged parts cause by accident.	1.00	2,400.00
	Accident on 14/03/2018 0545hrs at along North South Highway Malaysia near to Sungka, Perak.	1.00	0.00
	OD Claim - FWD Singapore Pte Ltd.	1.00	0.00
	Insurance policy - PNM2017-50748		
	-Bike survey by Rasul from LKK Auto Consultants Pte Ltd on 04/04/2018. -Repair authorised by Janice Lee from LKK Auto Consultants Pte Ltd on 09/04/2018.	1.00	0.00
	Michelin Anakee 3 Rear - 170/60/R17	0.00	350.00
	Sub-Total :		2,750.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

289, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63398888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190527 (AfterSales)
63190533/530 (Motorrad)
Fax: 64794601 (AfterSales)
64794624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : W5 1267777	Page No. : 2 of 3
Date IN : 12/04/2018	Invoice Number : 1965515 / WSB
Cust. Svc. Advisor : William Teh Hooi Teik	Invoice Date : 16/05/2018
	Payment Term : 30 Days From Invoice
	Invoice By : William Teh Hooi Teik

CODE	DESCRIPTION	UNITS	NETT
07119907438	CSK FILLISTER HEAD SCREW M3.5X30	1.00	7.24
07129907390	FILLISTER HEAD SCREW M10X50	2.00	18.22
11128532975	IGNITION COIL COVER LH	1.00	35.78
11128549654	CYLINDER HEAD COVER ASPHALT GRAU RH	1.00	315.39
32718556251	HANDLEBAR	1.00	359.13
32728525826	CLUTCH LEVER	1.00	102.63
36317673903	WHEEL BOLT	5.00	42.65
36318526651	SPOKE WHEEL REAR 4.5X17	1.00	1,738.45
46638523431	HAND PROTECTOR LH	1.00	53.22
46638523432	HAND PROTECTOR RH	1.00	53.22
46638523433	BRACKET HAND PROTECTOR LH	1.00	22.39
46638523435	BUSH	1.00	15.41
46638538035	TANK PROTECTOR LH	1.00	421.50
46638538037	HOLDER TANK PROTECTION LH	1.00	68.10
11128532976	IGNITION COIL COVER RH	1.00	35.78
11128542058	RH SEALING KIT CYLINDER HEAD COVER	1.00	97.09
12531721040	BRACKET CABLE HARNESS	6.00	30.18
32728533739	HANDBRAKE LEVER	1.00	102.63
36317720640	BALANCE WEIGHT (30 GR)	2.00	8.10
36318532731	SENSOR WITH VALVE	1.00	161.19
46548520068	CASE CARRIER RH	1.00	310.50
46548520069	CROSS BRACE	1.00	91.53
46628536970	REAR CARRIER PART	1.00	480.06
46638538036	TANK PROTECTOR RH	1.00	421.50
61318567720	COMBINATION SWITCH RH (LIN BUS)	1.00	236.71
63138522499	LED FLASHER	1.00	83.88
71217698971	LABEL	1.00	4.25
77148565802	RH ENGINE PROTECTION BAR	1.00	301.81
77412455445	LH ALUMINIUM CASE BLACK	1.00	804.44
77412455446	RH ALUMINIUM CASE BLACK	1.00	804.44
77498544517	REPAIR KIT LOCK CYLINDER	6.00	305.58
11128523552	SCREW WITH BUSH	3.00	77.97
11128523552	SCREW WITH BUSH	3.00	77.97
11128549653	CYLINDER HEAD COVER ASPHALT GRAU LH	1.00	315.39
11128542057	LH SEALING KIT CYLINDER HEAD COVER	1.00	97.09
36318520871	REPAIR KIT TIRE PRESSURE MONITOR VA	1.00	32.24
71248523443	LABEL TYRES ECE	1.00	21.10
46628546508	REAR WHEEL COVER	1.00	157.14

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401555W GST Reg. No. M2-0020081-m



301, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

288, Kembangan Road
East Coast Centre
Singapore 418180
Tel. 63190888 (AfterSales)
Fax. 63443773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190527 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : W5 1267777	Page No. : 3 of 3
Date IN : 12/04/2018	Invoice Number : 1965515 / WSB
Cust. Svc. Advisor : William Teh Hooi Teik	Invoice Date : 16/05/2018
	Payment Term : 30 Days From Invoice
	Invoice By : William Teh Hooi Teik

Sub-Total : 8,311.90

Labour Charges : 2,750.00	Total Labour & Parts Charges : S\$ 11,061.90
Parts Charges : 8,311.90	Less Insurance Excess : S\$ 1,000.00
Lubricant/Misc : 0.00	Invoice Total Amount Exclude GST : S\$ 10,061.90
	GST @ 7% : S\$ 704.33
	Invoice Total Amount Include GST : S\$ 10,766.23

Computer generated invoice. No signature is required. Amount Payable Include GST: **S\$ \$10,766.23**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2018 Edit Reg		02 Apr 2018 00:00 Edit Adj Rpt	S\$11,061.90 Edit Estimates	S\$11,061.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	NUR MUHAMMAD SUFI BIN SAPI'EE, ID: S8118432A		
Vehicle Reg. No.:	FY24D	Date of Loss:	14/03/2018 05:00 - :59 [18 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800003314	Policy/Cover Note No.:	PNMC2017-50748 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 11/04/2018]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- FWD_SG (17/05/2018): Alert - Adj Mandate Approved (S\$11134.38) - FY24D - Claim Handler: Clara Li Zi R...
- FWD_SG (05/04/2018): Alert - Adj Mandate Approved (S\$10486.79) - FY24D - Claim Handler: Clara Li Zi R...

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FY24D (1201800003314)
OD
Mar 14 2018 5:00AM
[NUR MUHAMMAD SUFI BIN SAPI'EE]
Performance Motors Limited

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View In Browser

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/04/18 14:53	Adjuster Immediate Advice	1	Load HTM	
2	17/05/18 15:18	Adjuster Immediate Advice	1	Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/04/18 14:58	General View	1	Load JPG	☒
2	05/04/18 14:58	General View	1	Load JPG	☒
3	05/04/18 14:58	General View	1	Load JPG	☒
4	05/04/18 14:58	General View	1	Load JPG	☒
5	05/04/18 14:58	General View	1	Load JPG	☒
6	05/04/18 14:58	General View	1	Load JPG	☒
7	05/04/18 14:58	General View	1	Load JPG	☒
8	05/04/18 14:58	General View	1	Load JPG	☒
9	05/04/18 14:58	General View	1	Load JPG	☒
10	05/04/18 14:58	General View	1	Load JPG	☒
11	05/04/18 14:58	General View	1	Load JPG	☒
12	05/04/18 14:58	General View	1	Load JPG	☒
13	05/04/18 14:58	General View	1	Load JPG	☒
14	05/04/18 14:58	General View	1	Load JPG	☒
15	05/04/18 14:58	General View	1	Load JPG	☒
16	05/04/18 14:58	General View	1	Load JPG	☒
17	05/04/18 14:58	General View	1	Load JPG	☒
18	05/04/18 14:58	General View	1	Load JPG	☒
19	05/04/18 14:58	General View	1	Load JPG	☒
20	05/04/18 14:58	General View	1	Load JPG	☒
21	05/04/18 14:58	General View	1	Load JPG	☒
22	05/04/18 14:58	General View	1	Load JPG	☒
23	05/04/18 14:58	General View	1	Load JPG	☒
24	05/04/18 14:58	General View	1	Load JPG	☒
25	05/04/18 14:58	General View	1	Load JPG	☒
26	05/04/18 14:58	General View	1	Load JPG	☒
27	05/04/18 14:58	General View	1	Load JPG	☒
28	05/04/18 14:58	General View	1	Load JPG	☒
29	05/04/18 14:58	General View	1	Load JPG	☒
30	05/04/18 14:58	General View	1	Load JPG	☒
31	05/04/18 14:58	General View	1	Load JPG	☒
32	05/04/18 14:58	General View	1	Load JPG	☒
33	05/04/18 14:58	General View	1	Load JPG	☒
34	05/04/18 14:58	General View	1	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	05/04/18 14:58	General View	 Load JPG	☒
36	05/04/18 14:58	General View	 Load JPG	☒
37	05/04/18 14:58	General View	 Load JPG	☒
38	05/04/18 14:58	General View	 Load JPG	☒
39	05/04/18 14:58	General View	 Load JPG	☒
40	05/04/18 14:58	General View	 Load JPG	☒
41	05/04/18 14:58	General View	 Load JPG	☒
42	05/04/18 14:58	General View	 Load JPG	☒
43	05/04/18 14:58	General View	 Load JPG	☒
44	05/04/18 14:58	General View	 Load JPG	☒
45	05/04/18 14:58	General View	 Load JPG	☒
46	05/04/18 14:58	General View	 Load JPG	☒
47	05/04/18 14:58	General View	 Load JPG	☒
48	05/04/18 14:58	General View	 Load JPG	☒
49	05/04/18 14:58	General View	 Load JPG	☒
50	05/04/18 14:58	General View	 Load JPG	☒
51	05/04/18 14:58	General View	 Load JPG	☒
52	05/04/18 14:58	General View	 Load JPG	☒
53	05/04/18 14:58	General View	 Load JPG	☒
54	05/04/18 14:58	General View	 Load JPG	☒
55	05/04/18 14:58	General View	 Load JPG	☒
56	05/04/18 14:58	General View	 Load JPG	☒
57	05/04/18 14:58	General View	 Load JPG	☒
58	05/04/18 14:58	General View	 Load JPG	☒
59	05/04/18 14:58	General View	 Load JPG	☒
60	05/04/18 14:58	General View	 Load JPG	☒
61	05/04/18 14:58	General View	 Load JPG	☒
62	05/04/18 14:58	General View	 Load JPG	☒
63	05/04/18 14:58	General View	 Load JPG	☒
64	05/04/18 14:58	General View	 Load JPG	☒
65	05/04/18 14:58	General View	 Load JPG	☒
66	05/04/18 14:58	General View	 Load JPG	☒
67	05/04/18 14:58	General View	 Load JPG	☒
68	05/04/18 14:58	General View	 Load JPG	☒
69	05/04/18 14:58	General View	 Load JPG	☒
70	05/04/18 14:58	General View	 Load JPG	☒
71	05/04/18 14:58	General View	 Load JPG	☒
72	05/04/18 14:58	General View	 Load JPG	☒
73	05/04/18 14:58	General View	 Load JPG	☒
74	05/04/18 14:58	General View	 Load JPG	☒
75	05/04/18 14:58	General View	 Load JPG	☒
76	05/04/18 14:58	General View	 Load JPG	☒
77	05/04/18 14:58	General View	 Load JPG	☒
78	05/04/18 14:58	General View	 Load JPG	☒
79	05/04/18 14:58	General View	 Load JPG	☒
80	05/04/18 14:58	General View	 Load JPG	☒
81	05/04/18 14:58	General View	 Load JPG	☒
82	05/04/18 14:58	General View	 Load JPG	☒
83	05/04/18 14:58	General View	 Load JPG	☒
84	05/04/18 14:58	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
85	05/04/18 14:58	General View	 Load JPG	☒
86	05/04/18 14:58	General View	 Load JPG	☒
87	05/04/18 14:58	General View	 Load JPG	☒
88	05/04/18 14:58	General View	 Load JPG	☒
89	05/04/18 14:58	General View	 Load JPG	☒
90	05/04/18 14:58	General View	 Load JPG	☒
91	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
92	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
93	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
94	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
95	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
96	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
97	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
98	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
99	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
100	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
101	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
102	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
103	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
104	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
105	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
106	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
107	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
108	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
109	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
110	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
111	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
112	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
113	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
114	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
115	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
116	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
117	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
118	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
119	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
120	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
121	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
122	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
123	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
124	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
125	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
126	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
127	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
128	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
129	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
130	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
131	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
132	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
133	17/05/18 15:45	Reinspection Photo	 Load JPG	☒
134	17/05/18 15:45	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
135	17/05/18 15:45	Reinspection Photo		☒
136	17/05/18 15:45	Reinspection Photo		☒
137	17/05/18 15:45	Reinspection Photo		☒
138	17/05/18 15:45	Reinspection Photo		☒
139	17/05/18 15:45	Reinspection Photo		☒
140	17/05/18 15:45	Reinspection Photo		☒
141	17/05/18 15:45	Reinspection Photo		☒
142	17/05/18 15:45	Reinspection Photo		☒
143	17/05/18 15:45	Reinspection Photo		☒
144	17/05/18 15:45	Reinspection Photo		☒
145	17/05/18 15:45	Reinspection Photo		☒
146	17/05/18 15:45	Reinspection Photo		☒
147	17/05/18 15:45	Reinspection Photo		☒
148	17/05/18 15:45	Reinspection Photo		☒
149	17/05/18 15:45	Reinspection Photo		☒
150	17/05/18 15:45	Reinspection Photo		☒
151	17/05/18 15:45	Reinspection Photo		☒
152	17/05/18 15:45	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/18 14:56	FY 24D ESTIMATE		☐
2	17/05/18 15:46	FY 24D SUPPLEMENTARY ESTIMATE		☐
3	01/06/18 12:24	Workshop Invoice		☐
4	01/06/18 12:24	Discharge Voucher		☐
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	02/04/18 15:49	OI GIA Report		☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18005948/R1RBE2

Date: 01/06/2018

REFERENCE

Insured/Claimant: NUR MUHAMMAD SUFI BIN SAPI'EE Policy No: PNMC2017-50748
Date of Loss: 14/03/2018 Nature of Claim: OD Claim No: 1201800003314

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FY24D**
Make & Model: BMW R1200 GSA, 1.2 Engine No: 122EN20160130
Reg. Date: 19/08/2016 (Man. Year: 2016) Chassis No: WB10A0201GZ772083
Colour: Multi-colour Odometer: 28605 km
Engine Capacity: 1170 cc
Market Value/New Car Price: S\$45,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R18 Rear Tyre Size: 170/60 R17
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,471.34	8,661.90	2,809.44	24.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	2,400.00	850.00	26.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,721.34	11,061.90	3,659.44	24.86
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	13,721.34	10,061.90	3,659.44	26.67
+ GST 7.00/7.00% (S\$)	960.49	704.33	256.16	26.67
Nett Amount (S\$)	14,681.83	10,766.23	3,915.60	26.67

INSPECTION

Date of Assignment: 02/04/2018
Date Inspected: 04/04/2018 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Jun 2018)	
Parts:	N/A	BMW R1200 GSA 1.2 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FY24D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PIRELLI SCORPION TRAIL 2 170/60/R17	Burst	350.00 FS	*350.00 FS
2	1		*O-RING (27X3.2)	Not Necessary	4.38 FS	*- FS
3	1		*CSK FILLISTER HEAD SCREW M3.5X30	Necessary	7.24 FS	*7.24 FS
4	1		*O RING 24X3	Not Necessary	3.80 FS	*- FS
5	1		*GASKET RING	Not Necessary	0.50 FS	*- FS
6	1		*GASKET RING	Not Necessary	2.95 FS	*- FS
7	1		*WASHER	Not Necessary	1.25 FS	*- FS
8	2		*FILLISTER HEAD SCREW M10X50	Necessary	18.22 FS	*18.22 FS
9	1		*CYLINDER HEAD GASKET 3 LAYER RH	Not Necessary	92.27 FS	*- FS
10	3		*SCREW WITH BUSH	Necessary	77.97 FS	*77.97 FS
11	1		*IGNITION COIL COVER LH	Cut	35.78 FS	*35.78 FS
12	1		*IGNITION COIL COVER RH	Cut	35.78 FS	*35.78 FS
13	1		*RH SEALING KIT CYLINDER HEAD COVER	Necessary	97.09 FS	*97.09 FS
14	1		*RH CYLINDER HEAD BLACK	Not Necessary	1,808.43 FS	*- FS
15	1		*CYLINDER HEAD COVER ASPHALT GRAU RH	Cracked	315.39 FS	*315.39 FS
16	1		*REPAIR KIT VALVE SEAL RING	Not Necessary	120.33 FS	*- FS
17	1		*CLAMPIN BOLT	Not Necessary	3.13 FS	*- FS
18	2		*GEAR WHEEL 3=+0.04MM	Serviceable	368.28 FS	*- FS
19	2		*ADJUSTING PLATE 2.44MM	Serviceable	18.98 FS	*- FS
20	2		*ADJUSTING PLATE 2.42MM	Serviceable	18.98 FS	*- FS
21	6		*BRACKET CABLE HARNESS	Necessary	30.18 FS	*30.18 FS
22	2		*EXHAUST SEAL	Not Necessary	30.16 FS	*- FS
23	1		*HANDLEBAR	Bent	359.13 FS	*359.13 FS
24	1		*CLUTCH LEVER	Broken	102.63 FS	*102.63 FS
25	1		*HANDBRAKE LEVER	Bent	102.63 FS	*102.63 FS
26	5		*WHEEL BOLT	Necessary	42.65 FS	*42.65 FS
27	2		*BALANCE WEIGHT (30 GR)	Necessary	8.10 FS	*8.10 FS
28	1		*REPAIR KIT TIRE PRESSURE MONITOR VA	Necessary	32.24 FS	*32.24 FS
29	1		*SPOKE WHEEL REAR 4.5X17	Scratched	1,738.45 FS	*1,738.45 FS
30	1		*SENSOR WITH VALVE	Necessary	161.19 FS	*161.19 FS
31	1		*CASE CARRIER RH	Bent	310.50 FS	*310.50 FS
32	1		*CROSS BRACE	Bent	91.53 FS	*91.53 FS
33	1		*REAR CARRIER PART	Cut	480.06 FS	*480.06 FS
34	1		*HAND PROTECTOR LH	Scratched	53.22 FS	*53.22 FS
35	1		*HAND PROTECTOR RH	Scratched	53.22 FS	*53.22 FS
36	1		*BRACKET HAND PROTECTOR LH	Scratched	22.39 FS	*22.39 FS
37	1		*BUSH	Scratched	15.41 FS	*15.41 FS
38	1		*TANK PROTECTOR LH	Scratched	421.50 FS	*421.50 FS
39	1		*TANK PROTECTOR RH	Scratched	421.50 FS	*421.50 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*HOLDER TANK PROTECTION LH	Cut	68.10 FS	*68.10 FS
41	1		*HOLDER TANK PROTECTION RH	Serviceable	68.10 FS	*- FS
42	1		*MIRROR LH	Serviceable	115.45 FS	*- FS
43	1		*MIRROR RH	Serviceable	115.45 FS	*- FS
44	1		*COMBINATION SWITCH RH (LIN BUS)	Necessary	236.71 FS	*236.71 FS
45	1		*LED FLASHER	Cut	83.88 FS	*83.88 FS
46	1		*LABEL	Necessary	4.25 FS	*4.25 FS
47	1		*LABEL TYRES ECE	Necessary	21.10 FS	*21.10 FS
48	1		*RH ENGINE PROTECTION BAR	Scratched	301.81 FS	*301.81 FS
49	1		*LH ALUMINIUM CASE BLACK	Deformed	804.44 FS	*804.44 FS
50	1		*RH ALUMINIUM CASE BLACK	Scratched	804.44 FS	*804.44 FS
51	6		*REPAIR KIT LOCK CYLINDER	Necessary	305.58 FS	*305.58 FS
52	1		*(DG/SL) BRAKE CLEANER 500 ML	Not Necessary	17.25 FS	*- FS
53	1		*ANTI-FREEZE 1.5 LITRES	Not Necessary	19.75 FS	*- FS
54	3		*SCREW WITH BUSH	Necessary	77.97 FS	*77.97 FS
55	1		*LH SEALING KIT CYLINDER HEAD COVER	Necessary	97.09 FS	*97.09 FS
56	1		*CYLINDER HEAD COVER ASPHALT GRAU LH	Deformed	315.39 FS	*315.39 FS
57	1		*REAR WHEEL COVER	Cracked	157.14 FS	*157.14 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					11,471.34	8,661.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACING DAMAGED PARTS CAUSE BY ACCIDENT	New	3,250.00	2,400.00
2	ACCIDENT ON 14/03/2018 0545HRS AT ALONG NORTH SOUTH HIGHWAY MALAYSIA NEAR TO SUNGKA, PERAK (NPA)	New	0.00	0.00
3	OD CLAIM-FWD SINGAPORE PTE LTD INSURANCE POLICY - PNMC2017-50748 (NPA)	New	0.00	0.00
4	THIS ESTIMATE IS BASED ON VISUAL INSPECTION ONLY. ADDITIONAL FEES AND PARTS MAY BE REQUIRED DURING THE COURSE OF REPAIR (NPA)	New	0.00	0.00
5	ALL PARTS PRICE ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			3,250.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >