

22/03/2002

ASS. REC. BY:

REF:

CS/msh18005557/11bez

Special Instruction

Surveyor:

marins.

ASSIGNMENT (Office)

merimen

From (Person):

Fidel Foo

of

msh

Date/Time:

02042018 11:21am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 72103

Insured:

WC 28493

at Workshop m/s

Vix Auto

Tel:

of

60 Kaki Bukit Ave 6

Policy No:

B28 600714 MKC

Claim No:

593996

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28032018

CA / REV / REP. / REV 24 HRS wp.

H.O.D. Endorsement:

Date/Time:

02042018 11:35am

Person Contacted:

Jouma

Vehicle: IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

11/3/18 - ✓

11/3/18 - 10:15 AM 13212

14002

11/3/18 10:15 AM

Dismantle: 6/4/18

Reassembly: 9/4/18

After repair: 20/4/18

(08/11/13) wef

REF:

ASS. REC. BY: *Marius*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: *Y 7210J*at Workshop m/s *1-fx*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *15* days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *Y 7210J*Yr Regn: *8, 17*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *(m)*Make: *Isuzu NPR85*

c.c

*2999*Colour: *white*

A/C: Insured / Std / NI / NA

Sp. Reading: *18172*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JAANPR85HH7100779*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nit / S/Rim* / STD A/Rim or

Tyre Size: F: _____

R: *195/85R16*☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mmR/Bal. *6/6* mmL/Bal. *6* mmL/Bal. *6/6* mmD.O.A. *28/3/18*D.O.I. *2/4/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*No signif. PRS**12-15h.**11/5 Submit PRS report.*

RECEIVED 1 MAY 2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: *15*Resurvey No. of Trip: *3*

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ ~ RS, \$

Photos

Others

TOTAL

Report Format : *PRS*

Lump Sum / I.B.I: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2018		02 Apr 2018 11:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SAMWOH READY MIX PTE LTD, Co. Reg. No.: 200409069N								
Main Claimant:	Hoe Huat Equipment Pte Ltd, Co. Reg. No.: 201615389H								
Vehicle Reg. No.:	YP7210J	Date of Loss:	28/03/2018 19:00 - :59						
Claim Type:	TP / 553996	Policy/Cover Note No.:	B28600714MKC (Comprehensive) Coverage: 24/09/2017 - 23/09/2018						
Vehicle Reg. No. (Insured):	WC2849S	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	Vfix Auto Services Pte Ltd (HQ) 60 Kaki Bukit Ave 6 Ark@KB, 417892 Kaki Bukit - Tel: +65 64552957								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Flevel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/04/2018]								
Driver/Custodian (Insured):	REN ZEMIN (), NRIC: G2649641T, Tel: +6581559444								
Adj Asg. Remarks:	Please survey vehicle by today. Thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

10/11/2018 @ 11:30 AM
 10/11/2018 @ 11:30 AM
 10/11/2018 @ 11:30 AM

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:Company

Owner ID:5389H

Vehicle Details

Vehicle No.:YP7210J

Vehicle to be Exported:No

Intended De-registration Date:02 Apr 2018

Vehicle Make:ISUZU

Vehicle Model:NPR85UH5A

Primary Colour:White

Manufacturing Year:2017

Engine No.:4JJ13C3801

Chassis No.:JAANPR85HH7100779

Maximum Power Output:-

Open Market Value:\$29,756.00

Original Registration Date:16 Aug 2017

First Registration Date:16 Aug 2017

Transfer Count:0

Actual ARF Paid:\$1,488.00

Intended PARF Rebate Details

PARF Eligibility:No

PARF Eligibility Expiry Date:-

PARF Rebate Amount:\$0.00

Intended COE Rebate Details

COE Expiry Date:15 Aug 2027

COE Category:C - Goods Vehicle & Bus

COE Period(Years):10

QP Paid:\$30,600.00

COE Rebate Amount:\$28,666.00

Total Rebate Amount:\$28,666.00

The information contained herein is correct as at 02 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/03/2018 09:08
Date Of Accident	28/03/2018 19:30
Exact Location Of Accident	SELETAR NORTH LINK (LAMP POST 228)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP7210J
Insured/Policyholder	
Name Of Registered Owner	HOE HUAT EQUIPMENT PTE. LTD.
Co Reg No	201615389H
Email Address	HEOHUATEPL@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-98533838
Vehicle Particulars	
Manufacturer	ISUZU
Model	NPR85UH5A
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093475770
Cover Note Number	
Driver	
Name of Driver	IBRAHIM PATWARY
Passport No/FIN	G7646475N
Date Of Birth	10/02/1982
Occupation	OUTDOOR
Date Of Driving Pass	24/11/2014
Driving Experience	3 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98960405
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	15 CHANGI NORTH STREET 1 #01-03 I-LOFTS @ CHANGI
Postcode	498765
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : BIPLAB SM SABUJ GENDER: : MALE
Passenger 2	NAME: : ISLAM AKIDUL GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC2849S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	REN ZEMIN
NRIC/Passport Number	G2649641T
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


30 MAR 2018

IDAC KAKI BUKIT (VAC)

23 KAKI BUKIT AVE 4
Reporting Centre Personnel's Signature
Singapore 415933
Name: Tel: 67416697
NRIC/FIN No. Fax: 67492305
Email: vackb@singnet.com.sg

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28/03/2018 at about 1730 hrs. I was stationary at Seletar North Link waiting for traffic light. Suddenly I felt an impact on my rear. Vehicle B had collided on to the rear of my lorry.

No injury involved.

DECLARATION
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

30 MAR 2018

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4

Reporting Centre Singapore 415933
Name: Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@singnet.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2018		02 Apr 2018 11:21 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SAMWOH READY MIX PTE LTD , Co. Reg. No.: 200409069N									
Main Claimant: Hoe Huat Equipment Pte Ltd , Co. Reg. No.: 201615389H									
Vehicle Reg. No.: YP7210J		Date of Loss: 28/03/2018 19:00 - :59 [7 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 553996		Policy/Cover Note No.: B28600714MKC (Comprehensive) Coverage: 24/09/2017 - 23/09/2018							
Vehicle Reg. No. (Insured): WC2849S		Policy No. (Claimant):							
		Excess: S\$2,000.00							
Repairer: Vfix Auto Services Pte Ltd (HQ) 60 Kaki Bukit Ave 6 Ark@KB, 417892 Kaki Bukit - Tel: +65 64552957									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 03/04/2018]									
Driver/Custodian (Insured): REN ZEMIN () , NRIC: G2649641T, Tel: +6581559444									
Adj Asg. Remarks: Please survey vehicle by today. Thank you.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents



















































***YP7210J (553996)**
[WC2849S]
TP
Hoe Huat Equipment Pte Ltd
Mar 28 2018 7:00PM
[SAMWOH READY MIX PTE LTD]
Vfix Auto Services Pte Ltd



















































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)



















































View View in Browser












































Assessment Reports				1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail		Print
1	02/04/18 10:55	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement <small>From: SC - Reg. No: WC2849S, Claimant: SAMWOH READY MIX PTE LTD</small>		Load HTM	

Photos/Images				3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail		Print
1	02/04/18 18:23	Odometre Reading		Load JPG	<input checked="" type="checkbox"/>
2	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
3	02/04/18 18:23	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
4	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
5	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
6	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
7	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
8	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
9	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
10	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
11	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
12	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
13	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
14	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
15	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
16	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
17	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
18	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
19	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
20	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
21	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
22	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
23	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
24	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
25	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
26	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
27	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
28	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
29	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
30	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
31	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
32	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
33	02/04/18 18:23	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
38	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
40	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
41	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
42	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
43	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
44	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
45	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
46	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
47	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
48	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
49	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
50	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
51	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
52	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
53	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
54	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
55	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
56	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
57	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
58	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
59	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
60	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
61	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
62	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
63	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
64	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
65	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
66	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
67	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
68	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
69	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
70	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
71	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
72	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
73	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
74	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
75	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
76	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
77	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
78	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
79	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
80	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
81	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
82	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
83	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
85	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
86	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
87	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
88	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
89	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
90	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
91	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
92	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
93	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
94	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
95	02/04/18 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
96	07/04/18 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	07/04/18 11:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
134	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	07/04/18 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	07/04/18 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	07/04/18 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	07/04/18 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	09/04/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
184	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
190	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
191	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
192	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
193	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
194	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
195	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
196	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
197	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
198	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
199	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
200	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
201	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
202	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
203	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
204	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
205	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
206	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
207	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
208	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
209	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
210	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
211	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
212	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
213	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
214	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
215	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
216	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
217	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
218	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
219	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
220	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
221	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
222	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
223	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
224	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
225	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
226	21/04/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18005957/UBE2

Date: 11/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B28600714MKC
 Claimant Vehicle No : YP7210J Insured Vehicle No : WC2849S
 Date of Loss: 28/03/2018 Nature of Claim: TP Claim No: 553996

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP7210J
 Make & Model: ISUZU NPR85UH5A, 3.0 D (M) Engine No: 4JJ13C3801
 Reg. Date: 16/08/2017 (Man. Year: 2017) Chassis No: JAANPR85HH7100779
 Colour: White Odometer: 18172 km
 Engine Capacity: 2999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/85 R16 Rear Tyre Size: 195/85 R16 (D)
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/04/2018
 Date Inspected: 02/04/2018 Inspected At: Vfix Auto Services Pte Ltd (HQ)
 60 Kaki Bukit Ave 6 Ark@KB
 Singapore 417892
 Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$12,000.00 -\$15,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 11 May 2018)
Parts: N/A ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for YP7210J)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >