

SS. REC. BY:

REF:

CS / CTU 8003560 / Kvb22

Special Instruction:

Survivor:

K20024

ASSIGNMENT (Office)

merimen

From (Person):

Addline Omg

of

CTL

Date/Time:

02042018 10:10am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 466AS

Insured:

at Workshop m/s

S & H Motor

Tel:

6433 4730

of

160 Sin ming Dr + 0702

Policy No:

DMPCSN 3056941701

Claim No:

SNM18001638C01

Sum Insured:

Excess:

\$ 1000.00

Make of Veh:

(Client's Record)

D.O.A.

26032018

CA / REX / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

02042018 11:01am

Person Contacted:

Cynthia

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	20 2543 - x
3/4/18	Revert vehicle T/L by merimen
4/4/18	Submit ext T/L

REF: CTZ /

Kenn

Fr Date:

Estimate

On

ES/OD RES/ A/INV/MV

To

at V

of

Ins

Po

Cl

Sur

(C

Mal

(P

Rem

Commenced its
Inspection.

0

Bal

815k

IDAC Consistent? : Yes or No

GIA Consistent? : Yes or No

Est. Res.: Yes or No

Lum 3 Val.: Yes or No

CA

Date: Vehicle

Date

2/4 Boston 1101
3/4 Fire parts Centre

RECEIVED 3 4 2010

Date/Time Report

1) Report

Date/Time

2) 4/4 - typist

Report to mrmen-T/L

Lump Sum

S/C 45695 Yr Regn: 10, 08

Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Trailer or

For Mander c.c. 220

M. Green A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

WFODXG8807J0398

3/ Fair / Poor / Burnt

In / Jammed / Leaked / Burnt or

3/ Jammed / Leaked / Burnt or

In / STD / RIM or

215/55R17

MA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

7 mm Rear
7 mm R/Bal. 8 mm
2613118 L/Bal. 8 mm
D.O.I. 2/4/18

Front / Rear / O/S / N/S / U/C / Rooftop or

018 PM & 416

Frame / Body Structure affected due to collision.

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

220

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18005960/Kvb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-04-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.		Veh. Inspected	SLC 4569S
Policy No.	DMPCSN3056941701	Coverage (\$)	0.00
Claim No.	SNM18D01638C01	Excess (\$)	1,000.00
Assign From	MERIMEN (ADELINE CHNG)	Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/03/2018	Inspection Date	02/04/2018
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Mar 2018 Sendback Est	31 Mar 2018 11:10 S\$120.00	02 Apr 2018 10:10 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	MANSOR BIN RAWI, ID: S1483775B, Tel: +6590706754, Email: NOEMAIL		
Vehicle Reg. No.:	SLC4569S	Date of Loss:	26/03/2018 20:00 - :59
Claim Type:	OD / SNM18D01638C01	Policy/Cover Note No.:	DMPCSN3056941701 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/04/2018]		
Driver/Custodian:	MANSOR BIN RAWI (56 / Male), NRIC: S1483775B, Tel: +6590706754		
Adj Asg. Remarks:	PLEASE CHECK WHETHER ECONOMICAL TO REPAIR & REVERT		

ASSOCIATED MAIL RECEIVED

View All | Compose Case Mail

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS**

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

2042018 @ 10:10am
Chen Hui Wen in

View Received Message

This mail is associated with :

SLC4569S (SNM18D01638C01)

OD

Mar 26 2018 8:00PM

[MANSOR BIN RAWI]

S & H Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **03/04/2018 14:40 PM.**
To LKK_HQ
Subject Alert - Adj Mandate Revoked - SLC4569S - Claim Handler: Adeline Chng Pei Wen

Revoked.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte.
Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 03 Apr 2018

Preliminary Advice

Vehicle No	: SLC4569S	Accident Date	: 26/03/2018
Make	: FORD MONDEO	Policy No.	: DMPCSN3056941701
Assignment Date	: 02/04/2018	Excess	: S\$1,000.00
Date of Inspection	: 02/04/2018	Est. Duration of Repair	: 0.00
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ TOTAL LOSS
Revised Amount	:S\$ TOTAL LOSS
Check Items (Estimated)	:S\$ 0.00
Total	:S\$
Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 15,000.00
COE / PARF Rebate	:S\$ 11,946.00
Salvage Value	:S\$
Margin for Repair	:S\$ 3,054.00

Brake System	: In Order
Steering System	: Jammed
Tyre Condition (Front)	: 7/7 mm
Tyre Condition (Rear)	: 8/8 mm

Remarks

☐ () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☒ (x) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☐ () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3775B
Vehicle Details	
Vehicle No.:	SLC45695
Vehicle to be Exported:	No
Intended De-registration Date:	03 Apr 2018
Vehicle Make:	FORD
Vehicle Model:	MONDEO 2.3 AUTO 4DR
Primary Colour:	Green
Manufacturing Year:	2007
Engine No.:	7J03996
Chassis No.:	WF0DXXG8BD7J03996
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$22,376.00
Original Registration Date:	30 Oct 2008
First Registration Date:	30 Oct 2008
Transfer Count:	1
Actual ARF Paid:	\$22,376.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2018
PARF Rebate Amount:	\$11,188.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2018
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$14,889.00
COE Rebate Amount:	\$758.00
Total Rebate Amount:	\$11,946.00

The information contained herein is correct as at 03 Apr 2018

OK

Enquire Transfer Fee

Vehicle Details

Vehicle No.: SLC4569S
Vehicle Type: P10 - Passenger Motor Car
Vehicle Attachment 1: With Sun Roof
Vehicle Scheme: Normal
Vehicle Make: FORD
Vehicle Model: MONDEO 2.3 AUTO 4DR
Chassis No.: WF0DXXGBBD7J03996
Propellant: Petrol
Engine No.: 7J03996
Engine Capacity: 2261 cc
Maximum Power Output: 118.0 kW (158 bhp)
Maximum Laden Weight: 2165 kg
Unladen Weight: 1541 kg
Year Of Manufacture: 2007
Original Registration Date: 30 Oct 2008
Lifespan Expiry Date: -
COE Category: E - Open Category
Quota Premium: \$14,889.00
COE Expiry Date: 29 Oct 2018
Road Tax Expiry Date: 29 Apr 2018
PARF Eligibility Expiry Date: 29 Oct 2018
Inspection Due Date: 29 Oct 2019
Intended Transfer Date: 01 Apr 2018
CO2 Emission: -
CO Emission: -
HC Emission: -
NOx Emission: -
PM Emission: -

The current road tax expiry is 29 Apr 2018. You may renew the road tax from 30 Jan 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 29 Apr 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 30 Apr 2018 to 29 Oct 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	760.00	-	760.00
Total Amount Payable:			785.00

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/03/2018 14:19
Date Of Accident	26/03/2018 20:45
Exact Location Of Accident	PIE 27.5KM TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC4569S
Insured/Policyholder	
Name Of Registered Owner	MANSOR BIN RAWI
NRIC No	S1483775B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90706754
Alternative Phone No	OFFICE-90706754

Vehicle Particulars

Manufacturer	FORD
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3056941701
Cover Note Number	

Driver

Name of Driver	MANSOR BIN RAWI
NRIC No	S1483775B
Date Of Birth	26/12/1961
Occupation	INDOOR
Date Of Driving Pass	19/01/1982
Driving Experience	36 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90706754
Fax Number	
Contact Number	OFFICE-90706754
EMail Address	NOEMAIL


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	DMPCSN3056941701	Date of Loss:	3/10/2010
Vehicle Reg. No.:	SLC4569S	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	L / M
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MANSOR BIN RAWI	Contact No:	+6590706754
Driver:	MANSOR BIN RAWI		
Make/Model:	FORD MONDEO, 2.3 Ghia (A)	Vehicle Reg. Date:	30/10/2008
Vehicle Colour:	Metallic Green	Chassis No:	WF0DXXGGBD7J03996
Engine No:	7J03996		
Odometer:	0 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER ATTACHED REPORT.		
Present Location:	S & AMP; H MOTOR PTE LTD (SIN MING)		

*Not Authorised
Loss
Ex \$1000*

COST OF CLAIMS

Parts		<div><div>LKK Auto Consultants hence notify the Repairer of the following:</div><ul style="list-style-type: none">• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company<div>Acknowledged by Repairer</div><div>Signature: _____</div><div>Date: _____</div></div>	0.00
Miscellaneous Items			0.00
Labour			0.00
Paintwork Labour			0.00
Towing			120.00
Gross Total (S\$)			120.00
+ GST 7.00% (S\$)			8.40
Nett Amount (S\$)			128.40

This claim is handled by: LUM WEE KEAT

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

S & H Motor Pte Ltd/SLC4569S/31/03/2018 11:10. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

Workshop: 160 Sin Ming Drive #07-02, Sin Ming AutoCity, Sin Ming 575722 . Tel: 6453 4730 Fax: 6457 1931 E-mail: shmotor@singnet.com.sg
Co. Reg. No.: 198701322K GST Reg. No.: M2-0076269-0

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	31 Mar 2018	31 Mar 2018 11:10 S\$120.00	02 Apr 2018 10:10 Edit Adj Rpt	S\$120.00 Edit Estimates	S\$120.00 View Rpt	Pending for Survey Report

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: MANSOR BIN RAWI , ID: S1483775B, Tel: +6590706754, Email: NOEMAIL									
Vehicle Reg. No.: SLC4569S		Date of Loss: 26/03/2018 20:00 - :59 [112 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D01638C01		Policy/Cover Note No.: DMPCSN3056941701 (Comprehensive)							
		Excess: S\$1,000.00							
Repairer: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/04/2018]									
Driver/Custodian: MANSOR BIN RAWI (56 / Male) , NRIC: S1483775B, Tel: +6590706754									
Adj Asg. Remarks: PLEASE CHECK WHETHER ECONOMICAL TO REPAIR & REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> CHINA_TAIPIING (03/04/2018): Alert - Adj Mandate Revoked - SLC4569S - Claim Handler: Adeline Chng Pei Wen 									
ALL ASSOCIATED TASKS <input type="checkbox"/> View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLC4569S (SNM18D01638C01)





OD

Mar 26 2018 8:00PM













[MANSOR BIN RAWI]

S & H Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser
Assessment Reports		1 per page 1 <input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)
1	27/03/18 14:39	Accident Statement
2	31/03/18 11:10	Repairer Estimates
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)
1	03/04/18 11:05	Adjuster Immediate Advice
Photos/Images		3 per page 3 <input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)
1	27/03/18 14:26	Accident Photo [Linked Accident Report Documents]
2	27/03/18 14:26	Accident Photo [Linked Accident Report Documents]
3	27/03/18 14:26	Accident Photo [Linked Accident Report Documents]
4	27/03/18 14:26	Accident Photo [Linked Accident Report Documents]
5	27/03/18 14:26	Accident Photo [Linked Accident Report Documents]
6	27/03/18 14:26	Accident Photo [Linked Accident Report Documents]
7	27/03/18 14:26	Accident Photo [Linked Accident Report Documents]
8	27/03/18 14:26	Accident Photo [Linked Accident Report Documents]
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	03/04/18 11:07	General View
2	03/04/18 11:07	General View
3	03/04/18 11:07	General View
4	03/04/18 11:07	General View
5	03/04/18 11:07	General View
6	03/04/18 11:07	General View
7	03/04/18 11:07	General View
8	03/04/18 11:07	General View
9	03/04/18 11:07	General View
10	03/04/18 11:07	General View
11	03/04/18 11:07	General View
12	03/04/18 11:07	General View
13	03/04/18 11:07	General View
14	03/04/18 11:07	General View
15	03/04/18 11:07	General View
16	03/04/18 11:07	General View
17	03/04/18 11:07	General View
18	03/04/18 11:07	General View
Documentation		1 per page 1 <input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)
1	27/03/18 14:27	Sketch Plan

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
		[Linked Accident Report Documents]		
2	27/03/18 14:27	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	27/03/18 14:27	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/04/18 09:57	REPORT OF SJL1735A	 Load PDF	
2	02/04/18 10:01	REBATE FORM	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	27/03/18 14:39	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	27/03/18 14:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	27/03/18 14:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	27/03/18 14:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	27/03/18 14:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	27/03/18 14:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	27/03/18 14:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	27/03/18 14:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	27/03/18 14:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	27/03/18 14:27	Sketch Plan	 Load TIF	
2	27/03/18 14:27	Sketch Plan #2	 Load TIF	
3	27/03/18 14:27	Sketch Plan #3	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18005960/KVBE2

Date: 05/04/2018

REFERENCE

Insured/Claimant: MANSOR BIN RAWI Policy No: DMPCSN3056941701
Date of Loss: 26/03/2018 Nature of Claim: OD Claim No: SNM18D01638C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC4569S**
Make & Model: FORD MONDEO, 2.3 Ghia (A) Engine No: 7J03996
Reg. Date: 30/10/2008 (Man. Year: 2007) Chassis No: WF0DXXGBBD7J03996
Colour: Metallic Green Odometer: 0 km
Engine Capacity: 2261 cc
Market Value/New Car Price: S\$15,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 8 mm
Front Right Side: Goodyear 7 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	120.00	120.00	0.00	0.00
Calculated Gross Total (S\$)	120.00	120.00	0.00	0.00
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	120.00	-880.00	1,000.00	833.33
+ GST 7.00/7.00% (S\$)	8.40	-61.60	70.00	833.33
Nett Amount (S\$)	128.40	-941.60	1,070.00	833.33

INSPECTION

Date of Assignment: 02/04/2018 Present Location: S & H Motor Pte Ltd (Sin Ming)
Date Inspected: 02/04/2018 Inspected At: 160 Sin Ming Drive #07-02, Sin Ming
AutoCity
Singapore 575722
Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$15,000.00
OMV : \$22,376.00
PARF Rebate (1) : \$11,188.00
Quota Premium Paid : \$14,889.00
COE Rebate (2) : \$758.00
Total Rebate (1) + (2) = : \$11,946.00

The total amount incurred will be Market Value \$15,000.00 minus Total Rebate \$11,946.00 = \$3,054.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2018)
Parts: 143 FORD MONDEO 2.3 Ghia (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLC4569S)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >