

22/03/2018

ISS. REC. BY:

REF:

CS/MS618005663/Grb 9

Special Instruction:

5544

Surveyor

Melman

From (Person):

Elaire Ngu

of

MS618

Date/Time:

02042018 10:19am

Estimated Cost:

Bill to:

OD / ~~FI~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBC 75779

Insured:

SKS 1450Y

at Workshop n/s

Kivile Enterprise

Tel:

6748 8645

of

Blk 3007 Ubi Rd 1 #01-408

Policy No:

AS0395626 QMY

Claim No:

550804

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23022018

CA / REV / REP. / REV 24 HRS Wp

03042018 @ Morning

H.O.D. Endorsement:

Date/Time:

02042018 11:29am

Person Contacted:

Tune

Vehicle IN / ~~OUT~~

Date/Time

Action/Instruction (✓) Estimate

FBC 75779 x

SKS 1450Y - N/A / MS618003580/YI

DUP - 23/02/18

04/04/18

@ 4.11 p.m revised to Elaire Ngu Sau Mei via meimen.

Confirmed L/S \$1350.00 @ 3 days

Red: \$1820, 57%.

Insurance

XHQ

REF: MSIG


5659A

(-2018)

ASSIGNMENT

From: _____ Date: 3/1/18
 Estimated Cost: _____
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FBC 7577S
 at Workshop n/s: Kivile Enterprise
 of: Blk 3007, ubi Rd 1 # 01-108
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

Morning



(Policy Condition) _____
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$700
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / FR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS /wp
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: FBC7577S Yr Regn: 24 Jun 2008
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: SYM Fighter 4V 150
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 83804 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RT GUV 15V 075 013179
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or
 Brake: Insured / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 120/70-12
 R: 130/70-12
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: _____ mm L/Bal: _____ mm
 D.O.A: _____ D.O.I: 03-04-18
 Survey held at: w/s 12:20pm
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 07 SEP 2018

Date/Time: File Pass to? ☐ : Preli. Report
☒ : Final Report
 1) Typist
 Date/Time: File Return to? _____

Days Of Repair: 3
 Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Weekend (\$)

Survey Fee: _____
 Transportation: _____
 1) S-RE \$1
 2) Photos
 3) Others

Report Format: TP
 Lump Sum / L.S. (\$): 1350.00

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005963/Grb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 02-04-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 1450Y	Veh. Inspected	FBC 7577S
Policy No.	A80395626QMY	Coverage (\$)	0.00
Claim No.	550804	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/02/2018	Inspection Date	03/04/2018
Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2018		02 Apr 2018 10:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	POH QIAN YI, CORINA, ID: S8607970D, Tel: +6598636806, Email: poh.corina@yahoo.com								
Main Claimant:	TAN PENG SIANG, BENEDICT, ID: S8005659A								
Vehicle Reg. No.:	FBC7577S	Date of Loss:	23/02/2018 17:00 - :59						
Claim Type:	TP / 550804	Policy/Cover Note No.:	A80395626QMY (Comprehensive) Coverage: 27/03/2017 - 26/03/2018						
Vehicle Reg. No. (Insured):	SKS1450Y	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Kivile Enterprise (HQ) BLK 3007 UBI RD 1 #01-408, 408701 Ubi - Tel: 67488645, 67479547								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/04/2018]								
Driver/Custodian (Insured):	POH QIAN YI, CORINA (31 / Female), NRIC: S8607970D, Tel: +6598636806								
Adj Asg. Remarks:	SPECIAL REQUEST : TO INSPECT ON 03/04/18 @9.30AM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

02042018 @ 1129am

7mm2 veh in

but mileage 03042018 @mms

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 04 Apr 2018

Preliminary Advice

Insured Vehicle No	: SKS1450Y	Accident Date	: 23/02/2018
TP Vehicle No	: FBC7577S	Assignment Date	: 02/04/2018
Make	: SYM FIGHTER 150	Est. Duration of Repair	: 3 days
Date of Inspection	: 03/04/2018		
Inspection At	: Kivile Enterprise (HQ) BLK 3007 UBI RD 1 #01-408 Singapore 408701		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front, o/s and n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,170.00
Revised Amount	:S\$	1,725.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,725.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2018 12:08
Date Of Accident	23/02/2018 17:20
Exact Location Of Accident	ALONG TEMASEK AVENUE TWDS SUNTEC
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBC7577S
Insured/Policyholder	
Name Of Registered Owner	TAN PENG SIANG, BENEDICT
NRIC No	S8005659A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96665472
Alternative Phone No	OTHERS-96665472
Vehicle Particulars	
Manufacturer	SYM
Model	FIGHTER4V 150 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095562338
Cover Note Number	
Driver	
Name of Driver	TAN PENG SIANG, BENEDICT
NRIC No	S8005659A
Date Of Birth	27/02/1980
Occupation	OUTDOOR
Date Of Driving Pass	15/02/2001
Driving Experience	17 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96665472
Fax Number	
Contact Number	OTHERS-96665472
EMail Address	NOEMAIL



SINGAPORE POLICE FORCE



T/20180224/2061

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180224/2061

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/02/2018 13:38	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: TAN PENG SIANG BENEDICT			Address: APT BLK 618 HOUGANG AVE 8 #04-338 HDB-HOUGANG SINGAPORE 530618		
ID Type / ID No.: NRIC NO / S8005659A			Contact No.: Home/Office: Mobile: 96665472		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 37	Date of Birth: 27/02/1980	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SELF-EMPOLYED			Driving Licence Information: Class: 2B,2A Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/02/2018 17:20	Type of Location: Straight Road
Location: Along Road 1 TEMASEK AVENUE TEMASEK AVENUE TOWARD THE FOUNTAIN OF WEALTH				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBC7577S	Motorcycle	SYM	FIGHTER4V 150 A	Black	Slightly Damaged	0
SKS1450Y	Car				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBC7577S	NTUC Income Insurance Co-Operative Limited	5095562338	02/11/2017	01/11/2018



**SINGAPORE
POLICE FORCE**



T/20180224/2051

3 of 3

Report No. T/20180224/2061

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
KEE CHUAN JIA MARCUS

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sgt 2 LIM HONG LEE
Contact No.: 65476438

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:
24/02/2018 13:38

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature: 

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5659A
Vehicle Details	
Vehicle No.:	FBC7577S
Vehicle to be Exported:	No
Intended De-registration Date:	04 Apr 2018
Vehicle Make:	SYM
Vehicle Model:	FIGHTER4V 150 A
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	DN039357
Chassis No.:	RFGHV15V07S013179
Maximum Power Output:	-
Open Market Value:	\$1,960.00
Original Registration Date:	24 Jun 2008
First Registration Date:	24 Jun 2008
Transfer Count:	12
Actual ARF Paid:	\$294.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jun 2018
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,012.00
COE Rebate Amount:	\$22.00
Total Rebate Amount:	\$22.00

The information contained herein is correct as at 04 Apr 2018

OK



吉维利企业 KIVILE ENTERPRISE

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2553

EMAIL: KIVILEPC@GMAIL.COM WEBSITE: KIVILEPC.COM

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBC7577S

Mirror / Cut
Balance LH X NN, RH - Cut
Lever Set LH X NN, RH - Cut
Front RH Signal - Cut
Handle Cover Out - Cut
Bar Handle - BT
Steering Cone X - AC
Fork Under Bracket X NN
Fork Set - Cut
Front Cowling - Cut
Lower Fairing - Cut
Lower Side Fairing R/L - CRA
Centre Pedal X NN
Rear Footrest - Cut
RH Rear Cover - Cut
Exhaust Pipe Cover - CRA
Transport
Labour
body alightment } NN
fork alightment }

85 /
45 22.5
65 32.5
45 /
120 /
145 /
90 /
220 X
460 230
255 /
120 /
260 /
85 X
55 /
120 /
70 /
50 40
350 200
250 X
280 X
3170

1650
10%: 1485
+ 240

1725
20%: 1350

3 Days.

lump sum repair.

After repair photos.

Guo Qiang - 8288 0282

Guo Qiang @ lkk auto. com

03/4/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2018		02 Apr 2018 10:19 Edit Adj Rpt	S\$1,350.00 Edit Estimates	S\$1,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	POH QIAN YI, CORINA, ID: S8607970D, Tel: +6598636806, Email: poh.corina@yahoo.com								
Main Claimant:	TAN PENG SIANG, BENEDICT, ID: S8005659A								
Vehicle Reg. No.:	FBC7577S	Date of Loss:	23/02/2018 17:00 - :59 [115 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 550804	Policy/Cover Note No.:	A80395626QMY (Comprehensive) Coverage: 27/03/2017 - 26/03/2018						
Vehicle Reg. No. (Insured):	SKS1450Y	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Kivile Enterprise (HQ) BLK 3007 UBI RD 1 #01-408, 408701 Ubi - Tel: 67488645, 67479547								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 02/05/2018]								
Driver/Custodian (Insured):	POH QIAN YI, CORINA (31 / Female), NRIC: S8607970D, Tel: +6598636806								
Adj Asg. Remarks:	SPECIAL REQUEST : TO INSPECT ON 03/04/18 @9.30AM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBC7577S (550804)
[SKS1450Y]
TP
TAN PENG SIANG, BENEDICT
Feb 23 2018 5:00PM
[POH QIAN YI, CORINA]
Kivile Enterprise

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	29/03/18 11:45	Accident Statement <small>From: SC - Reg. No: SKS1450Y, Claimant: POH QIAN YI, CORINA</small>		<div>1</div> <div>Load HTM</div>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/04/18 16:11	Adjuster Immediate Advice		<div>1</div> <div>Load HTM</div>	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
2	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
3	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
4	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
5	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
6	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
7	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
8	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
9	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
10	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
11	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
12	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
13	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
14	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
15	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
16	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
17	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
18	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
19	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
20	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
21	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
22	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
23	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
24	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
25	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
26	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
27	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
28	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
29	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
30	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
31	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>
32	07/09/18 13:59	General View		<div>1</div> <div>Load JPG</div>	<div></div>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	07/09/18 13:59	General View	Load JPG	<input checked="" type="checkbox"/>
34	07/09/18 13:59	General View	Load JPG	<input checked="" type="checkbox"/>
35	07/09/18 13:59	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/03/18 11:44	TPD FBC7577S PRI & GIA REPORT.	Load PDF	
2	29/03/18 11:44	TPD FBC7577S GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005963/URBQ2

Date: 10/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80395626QMY

Claimant Vehicle No : FBC7577S

Insured Vehicle No : SKS1450Y

Date of Loss: 23/02/2018

Nature of Claim: TP

Claim No: 550804

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBC7577S**

Make & Model: SYM FIGHTER 150, 150cc (A)

Engine No: DN039357

Reg. Date: 24/06/2008 (Man. Year: 2007)

Chassis No: RFGHV15V07S013179

Colour: Black

Odometer: 83804 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-12

Rear Tyre Size: 130/70-12

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,240.00	1,485.00	755.00	33.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	240.00	690.00	74.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,170.00	1,725.00	1,445.00	45.58
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	3,170.00	1,350.00	1,820.00	57.41
+ GST 7.00/7.00% (S\$)	221.90	94.50	127.40	57.41
Nett Amount (S\$)	3,391.90	1,444.50	1,947.40	57.41

INSPECTION

Date of Assignment: 02/04/2018

Date Inspected: 03/04/2018 Inspected At:

Kivile Enterprise (HQ)
BLK 3007 UBI RD 1 #01-408
Singapore 408701

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Sep 2018)	
Parts:	N/A	SYM FIGHTER 150 150cc (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBC7577S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR	Cut	85.00 F	*85.00 FL
2	1		*BALANCE	N/S Not Necessary / O/S Cut	45.00 F	*22.50 FL
3	1		*SET LEVER	N/S Not Necessary / O/S Cut	65.00 F	*32.50 FL
4	1		*FRONT RH SIGNAL	Cut	45.00 F	*45.00 FL
5	1		*HANDLE COVER OUT	Cut	120.00 F	*120.00 FL
6	1		*BAR HANDLE	Bent	145.00 F	*145.00 FL
7	1		*STEERING CONE	Necessary	90.00 F	*90.00 FL
8	1		*FORK UNDER BRACKET	Not Necessary	220.00 F	*- FL
9	1		*SET FORK	Cut	460.00 F	*230.00 FL
10	1		*FRONT COWLING	Cut	255.00 F	*255.00 FL
11	1		*LOWER FAIRING	Cut	120.00 F	*120.00 FL
12	2		*LOWER SIDE FAIRING R/L	Cracked	260.00 F	*260.00 FL
13	1		*CENTRE PEDAL	Not Necessary	85.00 F	*- FL
14	1		*REAR FOOTREST	Cut	55.00 F	*55.00 FL
15	1		*RH REAR COVER	Cut	120.00 F	*120.00 FL
16	1		*EXHAUST PIPE COVER	Cracked	70.00 F	*70.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,240.00	1,650.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	165.00
Total Parts (\$\$)	2,240.00	1,485.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	50.00	40.00
2	LABOUR	New	350.00	200.00
3	BODY ALIGNMENT	New	250.00	0.00
4	FORK ALIGNMENT	New	280.00	0.00
Gross Labour Cost (S\$)			930.00	240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >