

22/03/2018

ASS. REC. BY:

REF: CS/msh18006006/Altber

Special Instruction:

## ASSIGNMENT (Office)

From (Person): Catherine Thiu of msh Date/Time: 02042018 938am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: STA 240Y Insured: SKS 3966M

at Workshop m/s MOVU Tel:

of Blk 1008 Bukit Meruh Lane 3 # 01-04

Policy No: 828 762234 MKF Claim No: 554005

Sum Insured: Excess:

Make of Veh: D.O.A. 27032018  
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time: 02042018 11:27am Person Contacted: Suzanne Vehicle: IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	STA 240Y - X
	SKS 3966M - NA/msh18005733/hu DOA: 27032018
9/4-	Revert via menimen
	Labour only \$650+ (1863.13, 74%)

Signature: *Rabe*

REF: MSIG

0231L

# ASSIGNMENT

From: \_\_\_\_\_ Date: **5/4/18**

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SFA 240 Y**

at Workshop m/s: **Mova Automotive**

of **BK 1008 BK Meruh Lane 3 #01-04**

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record) \_\_\_\_\_

Make of Veh: **3pm @ owner waiting**

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>wp</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SFA 240 Y** Yr Regn: **2013 / May**

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: **Volkswagen Jetta 1.4** c.c. **1320**

Colour: **Grey** A/C: Insured / Std / NI / NA

Sp. Reading: **72529** T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **WVW2221620M031592**

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Modi: Nil ☒ S/Rim / STD A/Rim or

Tyre Size: F: **205/55R16**

R: **-**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front		Rear	
R/Bal. <b>6</b>	mm	R/Bal. <b>6</b>	mm
L/Bal. <b>6</b>	mm	L/Bal. <b>6</b>	mm
D.O.A. <b>27/03/18</b>		D.O.I. <b>05/04/18</b>	

Survey held at **MOVA (BM)**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

**N/S Frt**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 14 JUN 2018

Date/Time. File Pass to?

**13/6 Typist**

Date/Time. File Return to?

☐ : Preli. Report

☒ : Final Report

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation

☐ S + RS ☐ SI

☐ Photos

☐ Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

**TP**

**650/-**

**150**

**10**

**160**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18006006/R1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 02-04-2018	
		Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKS 3966M	Veh. Inspected	SFA 240Y
Policy No.	B28762234MKF	Coverage (\$)	0.00
Claim No.	554005	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	02/04/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	27/03/2018	Inspection Date	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Mar 2018		02 Apr 2018 09:38 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

<b>Insured:</b>	UNISTRONG TECHNOLOGY (S) PTE LTD, Co. Reg. No.: 200717259G		
<b>Main Claimant:</b>	LOW KIAH PICK, ID: S1380231I		
<b>Vehicle Reg. No.:</b>	SFA240Y	<b>Date of Loss:</b>	27/03/2018 19:00 - :59
<b>Claim Type:</b>	TP / 554005	<b>Policy/Cover Note No.:</b>	B28762234MKF (Comprehensive) Coverage: 01/06/2017 - 31/05/2018
<b>Vehicle Reg. No. (Insured):</b>	SKS3966M	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	
<b>Repairer:</b>	Mova Automotive Pte Ltd (HQ) Block 1008 Bukit Merah Lane 3 #01-04/06/08/94, 159722 Bukit Merah - Tel:		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/04/2018]		
<b>Driver/Custodian (Insured):</b>	MUHAMMAD HANIF BIN RIZUAN (), NRIC: S9107184C		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

02042018 @ 1129am  
 scanned veh not in

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/03/2018 09:16
Date Of Accident	27/03/2018 19:25
Exact Location Of Accident	BALESTIER ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFA240Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOW KIAH PICK
NRIC No	S1380231I
Email Address	KPLOW123@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96212272
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA 1.4 TSI AT 1623Q5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1383473
Cover Note Number	

### Driver

Name of Driver	LOW KIAH PICK
NRIC No	S1380231I
Date Of Birth	08/10/1959
Occupation	INDOOR
Date Of Driving Pass	13/11/1979
Driving Experience	38 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96212272
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	KPLOW123@GMAIL.COM

Address	46 SPRINGSIDE AVENUE
Postcode	786988
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NG CHENG TIONG GENDER: : MALE
Passenger 2	NAME: : KOH KIAN GEOK GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS3966M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	HANIF
NRIC/Passport Number	
Contact Number	90114027
Address	
Postcode	
Insurance Company Name	

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.


Date & Time: 28/3/2018 9.30am

Date &amp; Time:

NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SFA 240 Y	ACCIDENT DATE & TIME: 27 Mar 2018 7.28pm
CONTACT NUMBER: 96212272	E-MAIL ADDRESS: kplow123@gmail.com
LOCATION: Balestiar Road.	
Weather: Drizzling Traffic: heavy	
: Night 7.28pm	
I was travelling along Balestiar Road at between 30-40 km/hr under heavy traffic condition and slight drizzle at night when an ambulance suddenly cut into my lane from my left and hit my front left car. Ambulance car plate: SKS 3966 M.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature

Date & Time:

28/3/2018 9.30am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

*[Signature]*

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

**Main Office:**  
 Mova Building  
 No. 22, Jalan Kilang,  
 Singapore 159419  
 Tel: (65) 6476 3333  
 Fax: (65) 6271 5891  
 www.mova.com.sg

**Workshop Dept:**  
 Block 1008,  
 Bukit Merah Lane 3,  
 #01-04/06/08/94  
 Singapore 159722

Tel: (65) 6272 3892  
 Fax: (65) 6270 8314  
 Co. Reg. 198904033G  
 GST Reg. M2-0088864-2

# Estimate

28/03/2018

**MSIG INSURANCE (S) PTE LTD (SGX CENTRE)**  
**16, RAFFLES QUAY**  
**#24-01 HONG LEONG BUILDING**  
**SINGAPORE 048581.**

Attention :- **XA013**

Page # :- 1

Veh # :- SFA240Y

Veh Model :- VOLKSWAGEN

Estimate# :- CK417288

Claim # :-

ACC. Date :- 27/03/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	FRONT FENDER LH	1 PC	540.85 <sup>R</sup>	540.85
2.	FRONT BUMPER	1 PC	1,140.60 <sup>R</sup>	1,140.60
3.	FRONT BUMPER SIDE BRACKET LH	1 PC	44.25 <sup>X</sup>	44.25
4.	HEAD LAMP LH- CHECK <sup>SCU</sup>	1 PC		
5.	FRONT FENDER INNER BRACKET- REPAIR	1 PC		
	LIST TOTAL S\$			1,725.70
	10% DISCOUNT S\$			-172.57
				1,553.13
<b>LABOUR :</b>				
	TO REPAIR FRONT INNER PANEL, TO REMOVE AND REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREA			
	TO SPRAY AFFECTED AREA			
	TO CHECK WHEEL ALIGNMENT			
	LABOUR TOTAL S\$			960.00

*Rasul*  
*Hp 9000068*  
*3 days*  
*05/04/18 @ 1500*  
*Ready after repair*

*250* ~~380.00~~  
*400* ~~580.00~~  
*X* 80.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 2,513.13

GST @ 7 % 175.92

AMOUNT DUE S\$ 2,689.05

Customer's Signature/Co. Stamp

MOVA AUTOMOTIVE PTE LTD

- I KK Auto Consultancy hereby certify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

# Estimate

28/03/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)  
16, RAFFLES QUAY  
#24-01 HONG LEONG BUILDING  
SINGAPORE 048581.

Attention :- XA013

Page # :- 1

Veh # :- SFA240Y

Veh Model :- VOLKSWAGEN

Estimate# :- CK417288

Claim # :-

ACC. Date :- 27/03/18

Terms :- C.O.D Days

Remarks :-



Automotive Pte Ltd

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	FRONT FENDER LH	1 PC	540.85 R	540.85
2.	FRONT BUMPER	1 PC	1,140.60 R	1,140.60
3.	FRONT BUMPER SIDE BRACKET LH	1 PC	44.25 Xsu	44.25
4.	HEAD LAMP LH- CHECK	1 PC		
5.	FRONT FENDER INNER BRACKET- REPAIR	1 PC		
LIST TOTAL S\$				1,725.70
10% DISCOUNT S\$				-172.57
				1,553.13
<b>LABOUR :</b>				
TO REPAIR FRONT INNER PANEL, TO REMOVE AND REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREA				
TO SPRAY AFFECTED AREA				
TO CHECK WHEEL ALIGNMENT				
LABOUR TOTAL S\$				960.00

Rasul  
Hp 9000068  
3 days  
05/04/18 @ 1500  
Resy after repair  
COR \$ 650.00  
3 days.

250 380.00  
400 580.00  
X 80.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

2,513.13

GST @ 7 %

175.92

AMOUNT DUE S\$

2,689.05

Customer's Signature: **MOVA AUTOMOTIVE PTE LTD**

- LKK Auto Consultants hereby certify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)
































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Mar 2018		02 Apr 2018 09:38 <a href="#">Edit Adj Rpt</a>	<b>S\$650.00</b> <a href="#">Edit Estimates</a>	<b>S\$650.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>UNISTRONG TECHNOLOGY (S) PTE LTD,</b> Co. Reg. No.: 200717259G									
Main Claimant: <b>LOW KIAH PICK,</b> ID: S1380231I									
Vehicle Reg. No.: <b>SFA240Y</b>		Date of Loss: 27/03/2018 19:00 - :59 [57 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 554005</b>		Policy/Cover Note No.: B28762234MKF (Comprehensive) Coverage: 01/06/2017 - 31/05/2018							
Vehicle Reg. No. (Insured): <b>SKS3966M</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Mova Automotive Pte Ltd (HQ)</b> No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Catherine Thia Shi Yi</b> - 6594 2545]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 02/05/2018]									
Driver/Custodian (Insured): MUHAMMAD HANIF BIN RIZUAN (), NRIC: S9107184C									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SFA240Y (554005)**  
**[SKS3966M]**  
**TP**  
**LOW KIAH PICK**  
**Mar 27 2018 7:00PM**  
**[UNISTRONG TECHNOLOGY (S) PTE LTD]**  
**Mova Automotive Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/04/18 09:24	<b>Accident Statement</b> From: SC - Reg. No: SKS3966M, Claimant: UNISTRONG TECHNOLOGY (S) PTE LTD	 Load HTM	
No	Finalized On	<b>LKK Auto Consultants Pte Ltd (HQ)</b>	Thumbnail	Print
1	09/04/18 17:26	<b>Adjuster Immediate Advice</b>	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	13/06/18 17:21	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	13/06/18 17:22	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
24	13/06/18 17:22	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
25	13/06/18 17:22	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
26	13/06/18 17:22	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/04/18 09:35	<b>SFA240Y E-FILE REPORT</b>	 Load PDF	
2	02/04/18 09:37	<b>TP agreed common SJE - assign LKK</b>	 Load PDF	
3	02/04/18 09:37	<b>TP ESTIMATE</b>	 Load PDF	

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006006/R1TBE2

Date: 18/06/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B28762234MKF  
 Claimant Vehicle No: SFA240Y Insured Vehicle No: SKS3966M  
 Date of Loss: 27/03/2018 Nature of Claim: TP Claim No: 554005

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFA240Y  
 Make & Model: VOLKSWAGEN JETTA, 1.4 TSI 1623Q5 (A) Engine No: CTH005446  
 Reg. Date: 30/05/2013 (Man. Year: 2012) Chassis No: WWWZZZ16ZDM031592  
 Colour: Grey Odometer: 72529 km  
 Engine Capacity: 1390 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,553.13	0.00	1,553.13	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	650.00	310.00	32.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,513.13</b>	<b>650.00</b>	<b>1,863.13</b>	<b>74.14</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>175.92</b>	<b>45.50</b>	<b>130.42</b>	<b>74.14</b>
<b>Nett Amount (S\$)</b>	<b>2,689.05</b>	<b>695.50</b>	<b>1,993.55</b>	<b>74.14</b>

## INSPECTION

Date of Assignment: 02/04/2018  
 Date Inspected: 05/04/2018 Inspected At: Mova Automotive Pte Ltd (HQ)  
 Block 1008 Bukit Merah Lane 3 #01-04/06/08/94  
 Singapore 159722  
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2018)
<b>Parts:</b>	143	VOLKSWAGEN JETTA 1.4 TSI 1623Q5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFA240Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	540.85 FL	*- FL
2	1		*FRONT BUMPER	Repair	1,140.60 FL	*- FL
3	1		*FRONT BUMPER SIDE BRACKET LH	Serviceable	44.25 FL	*- FL
4	1		*HEAD LAMP LH (NPA)	Serviceable	0.00 FL	*- FL
5	1		*FRONT FENDER INNER BRACKET (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,725.70</b>	<b>0.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>172.57</b>	<b>0.00</b>
<b>Total Parts (\$\$)</b>	<b>1,553.13</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR FRONT INNER PANEL, TO REMOVE AND REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREA	New	380.00	250.00
2	TO SPRAY AFFECTED AREA	New	500.00	400.00
3	TO CHECK WHEEL ALIGNMENT	New	80.00	0.00
Gross Labour Cost (\$\$)			960.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >