

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





NTU	JC INCOME INSURANCE CO-OPERATIVE LTD			Ref: NS/INC18006020/K1vbn2		
72 DI		D				
	RAS BASAH ROA )1 NTUC TRADE	UNION HOUSESINGAPORE	Date:	13-04-2018		
1895					11 11 11 11 11 11 11 11 11 11 11 11 11	
			Code:	INC4		
1.		Policy Particulars	:- THIRI	D PARTY CLAIM		
	Insured Veh.	SJL 270E	Veh. Ir	nspected	SHA 9768J	
	Policy No.	5088229793	Cover	age (\$)	0.00	
	Claim No.	MT/0988775-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	02/04/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	of Reg.	2015	
	Chassis No.	KMHLB41UMFU064633	Colou	r	YELLOW	
	Odometer	360680	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3.		Conditi	ons of	Tyres		
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	TRIAN	GLE	7 mm	
	L/H Front Tyre	205/60 R16	TRIAN	GLE	7 mm	
	R/H Rear Tyre	205/60 R16	TRIAN	GLE	7 mm	
	L/H Rear Tyre	205/60 R16	TRIANG	GLE	7 mm	
	_,	1			7 1111111	
4.		Description			7 11111	
4.		<u> </u>	on of Da	amages		
4.		Description STAINED DAMAGES AT THE N/S	on of Da	amages		
<b>4</b> . <b>5</b> .	THE VEHICLE SU	Description STAINED DAMAGES AT THE N/S	on of Da	PORTION.		
	THE VEHICLE SU	Description STAINED DAMAGES AT THE N/S ETAILS.	on of Da FRONT	PORTION.	02/04/2018	
	THE VEHICLE SU	Description STAINED DAMAGES AT THE N/S ETAILS. General	on of Da FRONT I Inform	amages PORTION.  Pation Ction Date		
	THE VEHICLE SUDAMAGES SEE D	Description STAINED DAMAGES AT THE N/S ETAILS. General 30/03/2018	on of Da FRONT I Inform	amages PORTION.  Pation Ction Date		
	THE VEHICLE SUDAMAGES SEE D	Description STAINED DAMAGES AT THE N/S ETAILS.  General 30/03/2018  COMFORTDELGRO ENGINEER 59 LOYANG DRIVE SINGAPORE 508969	on of Da FRONT I Inform	amages PORTION.  Pation Ction Date		
5.	THE VEHICLE SUDAMAGES SEE D  Accident Date Survey held at	Description STAINED DAMAGES AT THE N/S ETAILS.  General 30/03/2018  COMFORTDELGRO ENGINEER 59 LOYANG DRIVE SINGAPORE 508969	I Inform Inspec	amages PORTION.  Pation Ction Date E LTD  PREJUDICE" BASIS.	02/04/2018	
5.	THE VEHICLE SUDAMAGES SEE D  Accident Date Survey held at	Description STAINED DAMAGES AT THE N/S ETAILS.  General 30/03/2018  COMFORTDELGRO ENGINEER 59 LOYANG DRIVE SINGAPORE 508969  Re ON WAS CONDUCTED ON A"WIT	I Inform Inspec	reamages  PORTION.  Pation  Ction Date  E LTD  PREJUDICE" BASIS.  NOT AUTHORISED	02/04/2018	