

INS. CASE OWNER:

Chee Heng

CC 6, ALB 1800 6021, U ja39

LKK:
IDAC:

Surveyor:

C/S

DOI:

ASSIGNMENT

27/4/18

Date / Time:

21/4/18

Registered in Merimen:

21/4/18

Pre-assign / CCU / FTE

Sku 8196A



Insured Vehicle No.:

CHN NGA 764

Claim No.:

404923933156

Name of Insured:

Policy No.:

2100416742

Insured Tel No.:

HP:

97603816

Make / Model:

Excess Sec II :SS

D.O.A.:

26/3/18

Place of Accident:

LA-PAYRA SPORTS HALL OPEN C/P

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SPL 7715R

INSRS:
WSP:
Tel:
Liability:
RMKS:

Jm Auto

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

4/4
Joy

SPL 7715R - X; Sku 8196A - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

204 12-4-18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

SS

1,498.xx

VIDEO

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

166 (380 x 2 days)

Loss of Income (LOI):

SS

— (\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1,658

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1,658

Name 1:

JIN AUTO SERVICES PTY LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
4/4/18

ASS. REC. BY: Marius

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFL 7715Rat Workshop m/s T. A. M.

of _____

Insured: SKU 81964

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 15k

IDAC / Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 18/11/2018 9/16/13

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFL 7715R Tr Regn: 11 08Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Mercedes C.C. 1799Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 2244/4 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRN684085205149

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/3/18 D.O.I. 23/4/18

Survey held at _____

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/4/18	confirmed LTA 10975 2/5 & 1400 with Jarius.

R(\$886.28/389.)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S - RS \$ _____

Photos _____

Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

JIN AUTO SERVICES PTE LTD

Blk 14 #01-412 Defu Lane 10
Singapore 539195
Tel:62898126 Fax :62870590

Your ref :

Our Ref :

Date:

2/4/2018

DEAR SIR/MADAM

ESTIMATED REPAIR COST FOR SFL7715R HONDA STREAM

1	1 PC	GRILLE	SCR	\$	235.90	✓
2	1 PC	Front bumper	no/R	\$	635.60	✓
3	1 PC	Front bumper clip (1 set)	all	\$	30.00	✓
4	1 PC	Front bumper reinforcement	R	\$	222.40	X
5	2 PCS	Front Bumper Beam	n1	\$	89.80	X
6	2 PCS	Front bumper side retainer	n1	\$	38.40	X
7	1 PC	FRONT LH HEADLAMP	SCR	\$	774.50	✓
				\$	2,026.60	
				less 20%	\$	(405.32)
				\$	1,621.28	
8		SPRAY PAINTING FRONT PORTIONS		\$	280.00	200
10		LABOUR CHARGE TO REMOVE AND RENEW FRONT PARTS		\$	350.00	200
9		CHECK WIRING		\$	35.00	20
				\$	2,286.28	

not Allowed
2/4/18
2/5/18 1400/c
2 day.

P-1676
1340.60
1760.8
1408.

23/4/18
Thank to Aftercare

UKK Auto Consultants hence notify the Repairs of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No extra modification is allowed
- Supplementary costs must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Business
Owner ID:	9165B

Vehicle Details

Vehicle No.:	SFL7715R
Vehicle to be Exported:	No
Intended De-registration Date:	23 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	R18A12805163
Chassis No.:	JHMRN68408S205149
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$21,003.00
Original Registration Date:	19 Nov 2008
First Registration Date:	19 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$21,003.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Nov 2018
PARF Rebate Amount:	\$10,501.00

Intended COE Rebate Details

COE Expiry Date:	18 Nov 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$8,301.00
COE Rebate Amount:	\$474.00
Total Rebate Amount:	\$10,975.00

The information contained herein is correct as at 23 Apr 2018

OK

*Sharing
&
Serving***COME VOLUNTEER WITH US!**

If you are 40 years old and above and are able to spend half a day every month to contribute your talents and skills in many meaningful ways, we want you

Honda Stream

Price Range ▼

Depreciation ▼

2008 ▼

Vehicle Type ▼

Home » Used Cars » Dickson Automobile » Honda Stream 1.8A RSZ Sunroof

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Honda Stream 1.8A RSZ Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map



Listen | Advise | Serve

DICKSON AUTOMOBILE PTE LTD

A member of DICKSON AUTO GROUP

Established since 1988

P8 818133
ISO 9001:2008

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price	\$20,800	?
Depreciation	\$15,270 /yr View models with similar depreciation	?
Reg Date	08-Nov-2008 (6mths 15days COE left)	?
Manufactured	2008	?
Mileage	-	?
Transmission	Auto	?
Engine Cap	1,799 cc	?
Road Tax	\$978 /yr	?
Power	103.0 kW (138 bhp) View specs of the Honda Stream (2007-2014)	?
Curb Weight	1,385 kg	?
Features	1.8L I-VTEC Engine, 5 Speed Automatic Transmission, SRS Airbags, Paddle Shifters, Sunroof, Auto Climatic Air-con Control, Knockdown Rear Seats.	?
Accessories	Sport Rims, Pioneer Touchscreen Audio System, Reverse Camera, Roof Mount Monitor, Rear Spoiler, Electric Retractable Side Mirrors, Leather Seats.	?
Description	Ideal For Short Term Usage Or Even Renewal Of COE! Just 2 Owner! Extended Warranty Available! High Trade-in! Well Taken Care Stylish MPV In Tip Top	?



Location Ma

Seller Infor

Company

Car Tyres

**MICHELIN
PILOT SPORT 4**
AS RESPONSIVE
AS YOU ARE.



Compare

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Business Registration No:200704370C

30/04/2018

C/O LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Park
(S) 408933

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SFL7715R AND SKU 8196A ON 26/03/2018

. we are now seeking the total amount of claim as follow:

Repair cost	S\$1498.00(with gst)
Loss of Use 3DAYS	240.00

TOTAL S\$ 1738.00

We shall appreciate if you could kindly consider our claim at your earliest convenience and kindly let us have your acknowledgement of receipt of this letter within 14days of your receipt of this letter.

Yours faithfully



Jouis Seow (Email: jouis@jinauto.com.sg)

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Thursday, 12 April 2018 11:38 AM
To: 'ntchia8@gmail.com'
Cc: Admin A; Vivian Lau (LKKAuto)
Subject: ACCIDENT INVOLVING SKU 8196A AND SFL 7715R ON 26/03/2018 ALONG TOA PAYOH SPORTS HALL OPEN CAR PARK

Our ref: CC4/AIG18006021/ja3

CHIA NGA TEH

Policy Holder

Dear Sir,

ACCIDENT INVOLVING SKU 8196A AND SFL 7715R ON 26/03/2018 ALONG TOA PAYOH SPORTS HALL OPEN CAR PARK

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

LETTER OF AUTHORISATION

To: Jin Auto Services Pte Ltd

Dear Sir

ACCIDENT INVOLVING SFL7715 R-88K48196A ON 26/3/18

I/We, the owner of Vehicle Registration Number SFL7715 R hereby authorise you to repair my/our vehicle repair, submit, correspond, negotiate and settle my/our claim for cost of repair and/or uninsured losses arising from the above accident.

I/We further authorise you M/S Jin Auto Services Pte Ltd, to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me/us in respect of my/our claim above.

I/We hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my/our behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me/us in person.

I/We further confirm that the acceptance by M/s Jin Auto Services Pte Ltd of the settlement amount in respect of such claim shall constitute the full discharge of my/our claim in respect of such loss and damage.

Signed by:



Name: Eugene Wee Boon Hae

NRIC NO: S7205045B

Date: 28/3/18

RELEASE VOUCHER

"We/I, **JIN AUTO SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **SS1,498.00** (Repair Cost), **SS160.00** (Loss of Use)- (Disbursement) for vehicle no. **SFL 7715R** that was damaged pursuant to the accident which occurred on **26/03/2018** (date) along **TOA PAYOH SPORTS HALL CAR PARK** (location) involving vehicle no/s **SKU 8196A**. This is pursuant to the inspection conducted on **23/04/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **CHAMPION ENTERPRISE** ("the third party claimant") of vehicle no. **SFL 7715R** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SFL 7715R** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 09 (day) of MAY (month) 20 18 (year)

Signed by appointed surveyor

Signed by "the workshop" (with chop)

JIN AUTO SERVICES PTE LTD

JinAuto **JIN AUTO SERVICES PTE LTD**
Blk 14 #01-410/412 Defu Lane 10 Singapore 539195
Tel: 6289 8126 (24 hrs) Fax: 6287 0500

Blk 14 #01- 410/412 Defu Lane 10 Singapore 539195
Tel: 6280 8126 (24h) Fax: 6280 8127

Tel: 6289 8126 (24 hrs) Fax: 6287 0590

Email: jin@jinauto.com.sg

Company Reg. No. 200704370C GST Reg. No. 200704370C

TAX INVOICE

M/s Alh Insurance

Invoice No: 15814

Vehicle No: SFL7715R

Date: 30/4/18

[illegible]

N.B No responsibility will be accepted for any loss or damage to any Vehicles or parts left in this workshop for any reason whatsoever.

E. & O. E.

ADD GST

TOTAL



...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2018 Edit Reg		23 Apr 2018 00:00 Edit Adj Rpt	S\$1,400.00 Edit Estimates	S\$1,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	Chia Nga Teh, ID: S0464320H								
Main Claimant:	CHAMPION ENTERPRISE, Co. Reg. No.: 52919165B								
Vehicle Reg. No.:	SFL7715R	Date of Loss:	26/03/2018 17:00 - :59 [112 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4049239331SG	Policy/Cover Note No.:	2100416742-02000 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKU8196A	Policy No. (Claimant):	5091412702						
		Excess:							
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/04/2018]								
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail						
<ul style="list-style-type: none"> AIG_SG (03/04/2018): NO OI GIA REPORT 									
ALL ASSOCIATED TASKS		View All	Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFL7715R (4049239331SG)
[SKU8196A]
TP
CHAMPION ENTERPRISE
Mar 26 2018 5:30PM
[Chia Nga Teh]
Jin Auto Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	14/05/18 11:48	TP witness video							Load MP4		
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	10/04/18 16:18	Accident Statement <small>From: SC - Reg. No: SKU8196A, Claimant: CHIA NGA TEH</small>							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	23/04/18 18:16	General View							Load JPG		
2	23/04/18 18:16	General View							Load JPG		
3	23/04/18 18:16	General View							Load JPG		
4	23/04/18 18:16	General View							Load JPG		
5	23/04/18 18:16	General View							Load JPG		
6	23/04/18 18:16	General View							Load JPG		
7	23/04/18 18:16	General View							Load JPG		
8	23/04/18 18:16	General View							Load JPG		
9	23/04/18 18:16	General View							Load JPG		
10	23/04/18 18:16	General View							Load JPG		
11	23/04/18 18:16	General View							Load JPG		
12	23/04/18 18:16	General View							Load JPG		
13	23/04/18 18:16	General View							Load JPG		
14	23/04/18 18:16	General View							Load JPG		
15	23/04/18 18:16	General View							Load JPG		
16	23/04/18 18:16	General View							Load JPG		
17	23/04/18 18:16	General View							Load JPG		
18	23/04/18 18:16	General View							Load JPG		
19	23/04/18 18:16	General View							Load JPG		
20	23/04/18 18:16	General View							Load JPG		
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	02/04/18 19:55	TP GIA REPORT							Load PDF		
2	04/04/18 08:39	Non reporting letter							Load PDF		
3	02/05/18 20:42	TP ESTIMATE - MARKED							Load PDF		
4	17/05/18 15:41	WORKSHOP INVOICE							Load PDF		
5	17/05/18 15:41	AUTHORISATION TO ACT FORM							Load PDF		
6	17/05/18 15:41	Release Voucher							Load PDF		
7	17/05/18 15:41	LETTER TO OI							Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKU8196A (Insd veh)	Model:	HONDA STREAM 1.8 L (A)
	SFL7715R (TP veh)		
Date of Accident:	26/03/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	2,446.32	
Final Repair Cost	:	\$	1,498.00	
Loss of Use	:	\$	160.00	2.00 days at \$80.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	0.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	1,658.00	

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____ 100 ____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown			
1)	Jin Auto Services Pte Ltd	:	\$ 1,658.00
2)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 May
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18006021/UJA3Q2

Date: 17/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100416742-02000

Claimant Vehicle No: SFL7715R

Insured Vehicle No: SKU8196A

Date of Loss: 26/03/2018

Nature of Claim: TP

Claim No: 4049239331SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFL7715R

Make & Model: HONDA STREAM, 1.8 L (A)

Reg. Date: 19/11/2008 (Man. Year: 2008)

Colour: Blue

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: R18A12805163

Chassis No: JHMRN68408S205149

Odometer: 224414 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size: 215/50 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,621.28	1,340.80	280.48	17.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	665.00	420.00	245.00	36.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,286.28	1,760.80	525.48	22.98
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	2,286.28	1,400.00	886.28	38.77
+ GST 7.00/7.00% (S\$)	160.04	98.00	62.04	38.77
Nett Amount (S\$)	2,446.32	1,498.00	948.32	38.77
+ Loss of Use (2.0 x S\$80.00/day) (S\$)		160.00		
Nett Liability (S\$)		1,658.00		

INSPECTION

Date of Assignment: 23/04/2018

Date Inspected: 23/04/2018 Inspected At:

Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GRILLE	Scratched	235.90 FL	*235.90 FL
2	1		*FRONT BUMPER	Dented / Deformed	635.60 FL	*635.60 FL
3	1		*SET FRONT BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	222.40 FL	*- FL
5	2		*FRONT BUMPER BEAM	Not Necessary	89.80 FL	*- FL
6	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	38.40 FL	*- FL
7	1		*FRONT LH HEADLAMP	Scratched	774.50 FL	*774.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,026.60	1,676.00
- List Item Discount on L Items 20.00/20.00% (S\$)	405.32	335.20
Total Parts (S\$)	1,621.28	1,340.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING FRONT PORTIONS	New	280.00	200.00
2	LABOUR CHARGE TO REMOVE AND RENEW FRONT PARTS	New	350.00	200.00
3	CHECK WIRING	New	35.00	20.00
Gross Labour Cost (S\$)			665.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >