

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







יייון	IC INCOME INSURANCE CO-OPERATIVE LTD			Ref: NS/INC18006025/K1rbn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE				11-04-2018		
1895		ONION HOUSESINGAP ONE	Date:	11 04 2010		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJG 4840K	Veh. Ir	nspected	SH 6484E	
	Policy No.	5098029929	Cover	age (\$)	0.00	
	Claim No.	MT/0988889-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	02/04/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	of Reg.	2015	
	Chassis No.	KMHLB41UMGU078321	Colou	r	BLUE	
	Odometer	314383	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	HANKC	ООК	7 mm	
	L/H Front Tyre	205/60 R16	HANKC	ООК	7 mm	
		00E/00 D40	HANKO	OOK	7 mm	
	R/H Rear Tyre	205/60 R16	HAINK			
	R/H Rear Tyre L/H Rear Tyre	205/60 R16 205/60 R16	HANKO		7 mm	
4.			HANKO	OOK	7 mm	
4.	L/H Rear Tyre	205/60 R16	HANKO	OOK amages	7 mm	
4.	L/H Rear Tyre	205/60 R16 Description STAINED DAMAGES AT THE REA	HANKO	OOK amages	7 mm	
4 . 5 .	THE VEHICLE SU	205/60 R16 Description STAINED DAMAGES AT THE REA	HANKO	amages TION.	7 mm	
	THE VEHICLE SU	205/60 R16 Description STAINED DAMAGES AT THE REALES.	HANKO On of Da AR POR	amages TION.	7 mm 02/04/2018	
	THE VEHICLE SUIDAMAGES SEE D	205/60 R16 Description STAINED DAMAGES AT THE REAL ETAILS. General	HANKO On of Da AR POR	amages TION. ation ction Date		
	THE VEHICLE SUDAMAGES SEE D	205/60 R16 Description STAINED DAMAGES AT THE REA ETAILS. General 31/03/2018	HANKO On of Da AR POR	amages TION. ation ction Date		
	THE VEHICLE SUDAMAGES SEE D	205/60 R16 Description STAINED DAMAGES AT THE REAL ETAILS. General 31/03/2018 COMFORTDELGRO ENGINEER 59 LOYANG DRIVE SINGAPORE 508969	HANKO On of Da AR POR	amages TION. ation ction Date		
5.	L/H Rear Tyre THE VEHICLE SUDDAMAGES SEE D Accident Date Survey held at	205/60 R16 Description STAINED DAMAGES AT THE REAL ETAILS. General 31/03/2018 COMFORTDELGRO ENGINEER 59 LOYANG DRIVE SINGAPORE 508969	HANKO On of Da AR POR' Inform Inspec RING PTI emarks	amages TION. ation ction Date E LTD REJUDICE" BASIS.	02/04/2018	
5.	L/H Rear Tyre THE VEHICLE SUDDAMAGES SEE D Accident Date Survey held at	205/60 R16 Description STAINED DAMAGES AT THE REAL ETAILS. General 31/03/2018 COMFORTDELGRO ENGINEER 59 LOYANG DRIVE SINGAPORE 508969 ROON WAS CONDUCTED ON A"WIT	HANKO On of Da AR POR I Inform Inspect RING PTI EMARKS HOUT P	amages TION. ation ction Date E LTD REJUDICE" BASIS. NOT AUTHORISED	02/04/2018	