

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 52983356E GST Reg. No. 20-0405911-H





NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006027/K1vbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE			Date: 11-04-2018	
1895	00		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PC 4534U	Veh. Inspected	SH 8949T
	Policy No.	5077310363-02	Coverage (\$)	0.00
	Claim No.	MT/0989145-001	Excess (\$)	0.00
	Assign From		Assign Date	02/04/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDKB3FU003557293	Colour	BLUE
	Odometer	132279	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	30/03/2018	Inspection Date	02/04/2018
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD	
		59 LOYANG DRIVE SINGAPORE 508969		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	2 Working Days	