

AGS REC BY

REP CS/MSG18006039/R/qd3ez

Special Inspection

Surveyor
Menimen

Rasul

ASSIGNMENT (Office)

From (Person)

Elaine Ngu

of

MSIG

Date/Time

03/04/18 @ 11:38am

Estimated Cost

Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

S1B 6916R

Insured

GW 5250H

at Workshop no

Mova Automotive

Tel

6272 3892

of

No. 22 Jalan Kilang #07-01

Policy No

28790952 MKC

Claim No

554184

Sum Insured

Excess

Make of Vch

(Client's Record)

D.O.A 31/03/2018

CA / REV / REP. / REV 24 HRS

lwp

Insp: 15 Fan Yong Rd

H.O.D. Endorsement

Date/Time

11:50am 3/4/18

Person Contacted

Nitha

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	S1B 6916R - x
	GW 5250H - CS/AVIOR02204/Dnf
05/04/18 @ 17:16 pm	revised to Elaine Ngu Bau Mei via menimen.
01/10/18 @ 9:14am	Rasul Analised with Alan CS @ 12000, 8 days.
	(Red @ 18307.15, 56%)

D.O.A: 31/7/2008

Signature: *[Signature]*

REF:

37742


EXP. DATE: 2019/MAY

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLB 6916R
 at Workshop m/s: Mova
 of: 15, Frangipani
 Insured: MSK / TP
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 57K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLB 6916R Yr Regn: 2009 / MAY
 Type: M.C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: B.M.W X5 XL cc 2996
 Colour: Black A/C: Insured / Std / NI / NA
 Sp Reading: 112172 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBAFE42060LK97612
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 255/55 R18
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or CONTINENTAL

Front: 6 mm Rear: 6 mm
 R/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 31/07/18 D.O.I: 03/04/18

Survey held at: Mova (FY)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 04 OCT 2018

[Signature]
 31/10/2018

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

MEK-TI
1200

200

10

210

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18006039/R1qd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 03-04-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 5250H	Veh. Inspected	SLB 6916R
Policy No.	28790952MKC	Coverage (\$)	0.00
Claim No.	554184	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/03/2018	Inspection Date	03/04/2018
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2018		03 Apr 2018 11:38 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	DRYCLEAN EXPRESS SERVICES, Co. Reg. No.: 53003586C		
Main Claimant:	TAN KIAN CHAI, ID: S7773774Z		
Vehicle Reg. No.:	SLB6916R	Date of Loss:	31/03/2018 16:00 - :59 [106 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 554184	Policy/Cover Note No.:	28790952MKC (TP, Fire & Theft) Coverage: 30/07/2017 - 29/07/2018
Vehicle Reg. No. (Insured):	GW5250H	Policy No. (Claimant):	
		Excess:	
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/04/2018]		
Driver/Custodian (Insured):	THAM WAI CHUEN (), NRIC: S1483134G, Tel: +6584845325		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Rasul (LKKAuto)
Sent: Monday, 1 October 2018 9:14 AM
To: Alan Chng
Cc: SUR
Subject: RE: finalization for veh no:SLB6916R

Hi Alan,

Finalised amount of 12K / 8 days lump sum confirmed

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Alan Chng [mailto:tuckmeng@mova.com.sg]
Sent: Thursday, 5 April, 2018 10:16 AM
To: Rasul (LKKAuto)
Cc: Admin A
Subject: RE: finalization for veh no:SLB6916R

Dear Rasul,

Can close @ \$12K lump sum limits?
Thank you!

Best Regards
Alan Chng
Claims Estimator
Mova Automotive Pte Ltd
H/P 9686 9276
Office No:6262 3377
Fax No:6264 3151

-----Original Message-----

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Thursday, 5 April 2018 9:01 AM
To: Alan Chng
Cc: Admin A
Subject: RE: finalization for veh no:SLB6916R

Hi Alan,

The NETT amount for this case is 10K only

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Alan Chng [mailto:tuckmeng@movva.com.sg]

Sent: Wednesday, 4 April, 2018 11:42 AM

To: Rasul (LKKAuto)

Cc: Admin A

Subject: finalization for veh no:SLB6916R

Dear Rasul,

Please refer the attach estimate to confirm the COR & working days.

Repair cost lump sum \$16,000 & 8 working days, please confirm and reply by email ASAP.

I will send you the after paint photos once the car ready.

Thank you!

Best Regards

Alan Chng

Claims Estimator

Mova Automotive Pte Ltd

H/P 9686 9276

Office No:6262 3377

Fax No:6264 3151

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 05 Apr 2018

Preliminary Advice

Insured Vehicle No	: GW5250H	Accident Date	: 31/03/2018
TP Vehicle No	: SLB6916R	Assignment Date	: 03/04/2018
Make	: BMW X5 XL	Est. Duration of Repair	: 8 days
Date of Inspection	: 03/04/2018		
Inspection At	: Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #07-01, Mova Building Singapore 159419		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,307.15
Revised Amount	:S\$	18,538.20
Check Items (Estimated)	:S\$	2,890.85
Total	:S\$	21,429.05

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

BMW X5 xDrive30i

Price	\$55,888
Reg date	13-May-2009
Manufactured	2008
Mileage	102,000 km
Transmission	Auto
Engine Capacity	2,996 cc
Road Tax	\$2,382 per year
Power	200.0 kW (268 bhp)
Curb Weight	1,840 kg
Features	Powerful 3.0L Inline 6 Cylinders Engine, 6 Speed Auto Transmission, i-Drive, Traction Control, DTC, Front And Rear Sensors, Quad-Zone Climate Control
Accessories	Sport Rims, Auto Tailgate, Multi Function Steering, Electric Memory Seat, Front & Rear Parking Sensors, BMW Built-in Entertainment System, Solar Film
Description	Luxury 7 Seater SUV, Low Mileage Done, Sporty Black With Brown Leather Seats, High OMV, Low Depreciation, Good For Short Term Drive Or COE Renewal, Don't Miss, Come And View It Now!
COE	\$8,501
OMV	\$78,604
ARF	\$78,604
Depreciation	\$14,950 / year
No. of owners	4
Type of Vehicle	SUV
Availability	Available

Seller Information

Company	TTS Eurocars * dealer's price list * 35 vehs sold 41 vehs available	
Address	383 Sin Ming Drive	
Office No	68422222	
Contact Person(s)	Alex Loh	94576408
	Samantha	91809596
	Noel	91011079
	Ivan Ong	96359315



Posted on : 16-Mar-2018

Last Updated : 01-Apr-2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3774Z

Vehicle Details

Vehicle No.: SLB6916R
Vehicle to be Exported: Yes
Intended De-registration Date: 02 Apr 2018
Vehicle Make: B.M.W.
Vehicle Model: X5 XL
Primary Colour: Black
Manufacturing Year: 2008
Engine No.: 04606917N52B30AF
Chassis No.: WBAFE42060LK97612
Maximum Power Output: 200.0 kW (268 bhp)
Open Market Value: \$80,563.00
Original Registration Date: 04 May 2009
First Registration Date: 04 May 2009
Transfer Count: 2
Actual ARF Paid: \$80,563.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 03 May 2019
PARF Rebate Amount: \$44,309.00

Intended COE Rebate Details

COE Expiry Date: 03 May 2019
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$7,490.00
COE Rebate Amount: \$813.00
Total Rebate Amount: \$45,122.00

The information contained herein is correct as at 02 Apr 2018

OK

58,000
45,122
12,878
(PK)

TPMS16

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/03/2018 17:23
Date Of Accident	31/03/2018 15:50
Exact Location Of Accident	JUNC OF HILL ST & COLEMAN ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB6916R
Insured/Policyholder	
Name Of Registered Owner	TAN KIAN CHAI
NRIC No	S7773774Z
Email Address	TABKIANCHAI@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97203056
Alternative Phone No	OTHERS-97203056

Vehicle Particulars

Manufacturer	BMW
Model	X5 XL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA106465/1
Cover Note Number	

Driver

Name of Driver	TAN KIAN CHAI
NRIC No	S7773774Z
Date Of Birth	20/08/1977
Occupation	INDOOR
Date Of Driving Pass	29/05/2001
Driving Experience	16 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97203056
Fax Number	
Contact Number	OTHERS-97203056
Email Address	TABKIANCHAI@HOTMAIL.COM

Address	30 DOVER RISE #0209
Postcode	138687
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : TAN ZEN ANN ALLYSA GENDER: : FEMALE
Passenger 2	NAME: : TJENDRA YULIANA GENDER: : FEMALE
Passenger 3	NAME: : TJENDRA YULIANA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW5250H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	THAM WAI CHUEN
NRIC/Passport Number	S1483134G
Contact Number	84845325/68615933



Address

ORCHID LAUNDRY

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SLB 6916R	ACCIDENT DATE & TIME: 31/03/2018 @ 1548 HRS
CONTACT NUMBER: 97203056	E-MAIL ADDRESS: tankianchoi@hotmail.com
LOCATION: Junction of Hill Street & Coleman Street traffic light.	
- while stopped at the RED light at the junction of/between Coleman Street & Hill Street; there is a sudden impact felt from behind of the car. - sore neck and stiff muscles felt after the impact. - there are a lady passenger and two children in the car during the incident.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
☐ Claim Own Policy ☒ Claim Third Party ☐ Claim OD/TP at other workshop ☐ Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature:
Name:
NRIC/TIN No.:

LIST ITEMS

<u>PAY</u>	<u>UNPAID</u>
1300.00	450.00
230.00	210.00
300.00	320.00
450.00	520.00
210.00	320.00
780.00	320.00
1480.00	380.00
2458.00	1160.00
130.00	160.00
680.00	438.00
360.00	60.00
580.00	230.00
40.00	45.00
1980.00	780.00
960.00	1578.00
180.00	685.00
458.00	485.00
1680.00	
310.00	
240.00	
360.00	
390.00	
1300.00	

NETT ITEMS

<u>PAY</u>	<u>UNPAID</u>
40.00	15.00
35.00	40.00
80.00	

LABOUR

<u>PAY</u>	<u>UNPAID</u>
40.00	20.00
120.00	20.00
80.00	50.00
60.00	20.00
150.00	100.00
60.00	300.00
200.00	20.00
700.00	50.00
60.00	400.00
100.00	
800.00	

155.00**55.00****16856.00****8141.00****2370.00****980.00**

24997.00

210.00

3350.00

16856.00

155.00

2370.00

8141.00

55.00

980.00

16856.00

842.80 (5% DISC)

16013.20 LIST ITEM AFTER DISC (PAY)

155.00 NETT ITEM (PAY)

2370.00 LABOUR (PAY)

18538.20

780.00
1578.00
685.00



CHECK ITEM

3043.00

152.15 (5% DISC)

2890.85 LIST ITEM AFTER DISC (CHECK ITEM)

0.00 LABOUR (CHECK ITEM)

2890.85

TOTAL = 21429.05 (PAY ITEM + CHECK ITEM)



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

02/04/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Page # :- 1

Veh # :- SLB6916R

Veh Model :- BMW X5

Estimate# :- CK417303

Claim # :-

ACC. Date :- 31/03/18

Terms :- C.O.D Days

Remarks :-

Alan 96869276

Attention :- XA013

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1. REAR BUMPER
2. REAR BUMPER CTR BRACKET
3. REAR BUMPER L/R BRACKET
4. REAR BUMPER SIDE COVER L/R
5. REAR BUMPER SIDE BRACKET
6. REAR BUMPER REINFORCEMENT
7. TAILGATE LOWER
8. TAILGATE LOWER HINGE
9. TAILGATE LOWER L/R LOCK
10. TAILGATE LOWER DRIVE FLAP
11. TAILGATE LOWER LEVEL LOCK
12. TAILGATE LOWER GAS STRUT
13. TAILGATE UPPER
14. TAILGATE LOGO
15. TAILGATE REFLECTOR LAMP
16. TAILGATE INNER TRIM
17. TAILGATE LOCK
18. TAILGATE LOCK CABLE
19. TAILGATE INNER CTR TRIM
20. TAILGATE CENTRE COVER
21. TAILGATE WIPER ARM
22. TAILGATE WIPER MOTOR
23. TAILGATE WIPER BLADE
24. TAILGATE INJECTION NOZZLE
25. REAR WINDSCREEN GLASS
26. TAILGATE RH
27. REAR PARKING SENSOR
28. REAR PARKING SENSOR HOLDER
29. REAR PARKING SENSOR WIRE HARNESS
30. REAR EXHAUST ASSY
31. REAR EXHAUST HEAT SHIELD
32. REAR EXHAUST MOUNTING
33. END PANEL GARNISH
34. TAILGATE RUBBER
35. END PANEL OUTER
36. END PANEL INNER
37. BATTERY BOX COVER
38. FRONT SEAT HEAD REST AIRBAG REPAIR KIT

LIST TOTAL S\$

5% DISCOUNT S\$

SPECIAL NET ITEMS :

1. REAR WINDSCREEN SEALANT
2. REAR NUMBER PLATE
3. ACCIDENT TOWING TO FAN YOONG

1	PC	1,300.00	1,300.00
1	PC	230.00	230.00
2	PC	150.00	300.00
2	PC	450.00	900.00
2	PC	210.00	420.00
1	PC	780.00	780.00
1	PC	1,480.00	1,480.00
2	PC	160.00	320.00
2	PC	260.00	520.00
2	PC	160.00	320.00
2	PC	160.00	320.00
2	PC	190.00	380.00
1	PC	2,458.00	2,458.00
1	PC	130.00	130.00
2	PC	580.00	1,160.00
1	PC	680.00	680.00
1	PC	360.00	360.00
1	PC	160.00	160.00
1	PC	438.00	438.00
1	PC	60.00	60.00
1	PC	230.00	230.00
1	PC	580.00	580.00
1	PC	40.00	40.00
1	PC	45.00	45.00
1	PC	1,980.00	1,980.00
1	PC	780.00	780.00
3	PC	320.00	960.00
3	PC	60.00	180.00
1	PC	458.00	458.00
1	PC	1,680.00	1,680.00
1	PC	310.00	310.00
4	PC	60.00	240.00
1	PC	360.00	360.00
1	PC	390.00	390.00
2	PC	789.00	1,578.00
1	PC	685.00	685.00
1	PC	485.00	485.00
2	PC	650.00	1,300.00
			24,997.00
			-1,249.85
			23,747.15

1	PC	40.00	40.00
1	PC	50.00	50.00
1	PC	120.00	120.00

80



Automotive Pte Ltd

Main Office
Mova Building
No. 22, Jalan Kilang
Singapore 159411
Tel: (65) 6476 3331
Fax: (65) 6271 589
www.mova.com.sg

Workshop Dept
Block 100B
Bukit Merah Lane 3
#01-04/05/06/07
Singapore 159721

Tel: (65) 6272 3891
Fax: (65) 6270 8311

Co. Reg. 198904033C
GST Reg. M2-0088864-2

Estimate

02/04/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1 131203

Veh # :- SLB6916R

Veh Model :- BMW X5

Estimate# :- CK417303

Claim # :-

ACC. Date :- 31/03/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	SPECIAL NET TOTAL S\$			210.00
	LABOUR :			
	TO INSPECT RR LIGHTING WATER & LEAKAGE TEST			40.00
	TO REMOVE & INSTALL REAR WINDSCREEN			120.00
	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE			100.00
	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE LOWER			60.00
	TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES, CARPET & ETC IN ORDER TO CUT OFF END PANEL			200.00
	TO REMOVE & INSTALL REAR EXHAUST			80.00
	TO REMOVE & RENEW FRONT SEAT REST AIRBAG REPAIR KIT IN ORDER TO REPROGRAMMING AIRBAG CONTROL SYSTEM			300.00
	TO CUT OFF END PANEL OUTER & INNER PANEL, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGES PARTS			1,000.00
	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS			80.00
	TO APPLY RUST PROOF ON AFFECTED AREAS			150.00
	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS			1,200.00
	LABOUR TOTAL S\$			3,350.00

RASUL
Hp 90010068
8 days
4/5
03/04/18 @ 1650
Rear after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

27,307.15

GST @ 7 %

1,911.50

AMOUNT DUE S\$

29,218.65

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

\$16,000
Edwards

Estimate

02/04/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Page # :- 1

Veh # :- SLB6916R

Veh Model :- BMW X5

Estimate# :- CK417303

Claim # :-

ACC. Date :- 31/03/18

Terms :- C.O.D Days

Remarks :-

Alan 96859276

Attention :- XA013

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :				
1.	REAR BUMPER	1	PC	1,300.00
2.	REAR BUMPER CTR BRACKET	1	PC	230.00
3.	REAR BUMPER L/R BRACKET	2	PC	150.00
4.	REAR BUMPER SIDE COVER L/R	2	PC	450.00
5.	REAR BUMPER SIDE BRACKET	2	PC	210.00
6.	REAR BUMPER REINFORCEMENT	1	PC	780.00
7.	TAILGATE LOWER	1	PC	1,480.00
8.	TAILGATE LOWER HINGE	2	PC	160.00
9.	TAILGATE LOWER L/R LOCK	2	PC	260.00
10.	TAILGATE LOWER DRIVE FLAP	2	PC	160.00
11.	TAILGATE LOWER LEVEL LOCK	2	PC	190.00
12.	TAILGATE LOWER GAS STRUT	1	PC	2,458.00
13.	TAILGATE UPPER	1	PC	130.00
14.	TAILGATE LOGO	2	PC	580.00
15.	TAILGATE REFLECTOR LAMP	1	PC	680.00
16.	TAILGATE INNER TRIM	1	PC	360.00
17.	TAILGATE LOCK	1	PC	180.00
18.	TAILGATE LOCK CABLE	1	PC	438.00
19.	TAILGATE INNER CTR TRIM	1	PC	60.00
20.	TAILGATE CENTRE COVER	1	PC	230.00
21.	TAILGATE WIPER ARM	1	PC	580.00
22.	TAILGATE WIPER MOTOR	1	PC	40.00
23.	TAILGATE WIPER BLADE	1	PC	45.00
24.	TAILGATE INJECTION NOZZLE	1	PC	1,980.00
25.	REAR WINDSCREEN GLASS	1	PC	780.00
26.	TAILGATE WIPER - Crude / Grazed.	3	PC	320.00
27.	REAR PARKING SENSOR	3	PC	60.00
28.	REAR PARKING SENSOR HOLDER	1	PC	458.00
29.	REAR PARKING SENSOR WIRE HARNESS	1	PC	1,680.00
30.	REAR EXHAUST ASSY	1	PC	310.00
31.	REAR EXHAUST HEAT SHIELD	4	PC	60.00
32.	REAR EXHAUST MOUNTING	1	PC	360.00
33.	END PANEL GARNISH	1	PC	390.00
34.	TAILGATE RUBBER	12	PC	789.00
35.	END PANEL OUTER	1	PC	685.00
36.	END PANEL INNER	1	PC	485.00
37.	BATTERY BOX COVER	2	PC	650.00
38.	FRONT SEAT HEAD REST AIRBAG REPAIR KIT			

LIST TOTAL S\$

5% DISCOUNT S\$

- SPECIAL NET ITEMS :
- REAR WINDSCREEN SEALANT
 - REAR NUMBER PLATE
 - ACCIDENT TOWING TO FAN YOUNG

P-19,265
-58
18,301.75

1 PC 40.00 40.00
1 PC 50.00 50.00
1 PC 120.00 120.00

24,997.00
-1,249.85
23,747.15

80

SIN-155



Automotive Pte Ltd

Main Office
Mova Building
No. 22, Jalan Kilang
Singapore 159411
Tel: (65) 6476 333;
Fax: (65) 6271 589;
www.mova.com.sg

Workshop Dept
Block 1008
Bukit Merah Lane 3
#01-04/06/08/9
Singapore 159722

Tel: (65) 6272 389;
Fax: (65) 6270 831;

Co. Reg. 198904033C
GST Reg. M2-0088864-4

Estimate

02/04/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1 131203

Veh # :- SLB6916R

Veh Model :- BMW X5

Estimate# :- CK417303

Claim # :-

ACC. Date :- 31/03/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

SPECIAL NET TOTAL S\$

LABOUR :

TO INSPECT RR LIGHTING WATER & LEAKAGE TEST

TO REMOVE & INSTALL REAR WINDSCREEN

TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE

TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE LOWER

TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES, CARPET & ETC IN ORDER TO CUT OFF END PANEL

TO REMOVE & INSTALL REAR EXHAUST

TO REMOVE & RENEW FRONT SEAT REST AIRBAG REPAIR KIT IN ORDER TO REPROGRAMMING AIRBAG CONTROL SYSTEM

TO CUT OFF END PANEL OUTER & INNER PANEL, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGES PARTS

TO APPLY BODY JOINT SEALANT ON CUTTING AREAS

TO APPLY RUST PROOF ON AFFECTED AREAS

TO SPRAY PAINT ON REPLACED, REPAIRED AREAS

LABOUR TOTAL S\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

210.00

40.00

120.00

100.00

80.00

200.00

80.00

300.00

1,000.00

80.00

150.00

1,200.00

3,350.00

Customer's Signature/Co. Stamp

MOVA AUTOMOTIVE PTE LTD

NON-TAX AMOUNT S

AMOUNT S\$

27,307.15

GST @ 7 %

1,911.50

AMOUNT DUE S\$

29,218.65

P-181301-75
QIN-155
LC-2370

E & O E

20826.75
20845

LC-2370

161661.40

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2018		03 Apr 2018 11:38 Edit Adj Rpt	S\$12,000.00 Edit Estimates	S\$12,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: DRYCLEAN EXPRESS SERVICES , Co. Reg. No.: 53003586C									
Main Claimant: TAN KIAN CHAI , ID: S77737742									
Vehicle Reg. No.: SLB6916R		Date of Loss: 31/03/2018 16:00 - :59 [106 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 554184		Policy/Cover Note No.: 28790952MCC (TP, Fire & Theft) Coverage: 30/07/2017 - 29/07/2018							
Vehicle Reg. No. (Insured): GW5250H		Policy No. (Claimant):							
		Excess:							
Repairer: Mova Automotive Pte Ltd (Bukit Merah) Blk 100B, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 03/05/2018]									
Driver/Custodian (Insured): THAM WAI CHUEN (J) , NRIC: S1483134G, Tel: +6584845325									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB6916R (554184)
[GW5250H]
TP
TAN KIAN CHAI
Mar 31 2018 4:00PM
[DRYCLEAN EXPRESS SERVICES]
Mova Automotive Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View

Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/04/18 10:57	Accident Statement From: SC - Reg. No: GW5250H, Claimant: DRYCLEAN EXPRESS SERVICES	 Load HTM	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/18 17:16	Adjuster Immediate Advice	 Load HTM	Print

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/10/18 14:22	Odometer Reading	 Load JPG ☒	<input checked="" type="button" value="Print"/>
2	03/10/18 14:22	Chassis Number	 Load JPG ☒	<input checked="" type="button" value="Print"/>
3	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
4	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
5	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
6	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
7	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
8	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
9	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
10	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
11	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
12	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
13	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
14	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
15	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
16	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
17	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
18	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
19	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
20	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
21	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
22	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
23	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
24	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
25	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
26	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
27	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
28	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
29	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
30	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
31	03/10/18 14:22	General View	 Load JPG ☒	<input checked="" type="button" value="Print"/>
32	03/10/18 14:22	General View	Load JPG ☒	<input checked="" type="button" value="Print"/>

Assessment Reports			1 per page	☒	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
			1		☒
33	03/10/18 14:22	General View	1	Load JPG	☒
34	03/10/18 14:22	General View	1	Load JPG	☒
35	03/10/18 14:22	General View	1	Load JPG	☒
36	03/10/18 14:22	General View	1	Load JPG	☒
37	03/10/18 14:22	General View	1	Load JPG	☒
38	03/10/18 14:22	General View	1	Load JPG	☒
39	03/10/18 14:22	General View	1	Load JPG	☒
40	03/10/18 14:22	General View	1	Load JPG	☒
41	03/10/18 14:22	General View	1	Load JPG	☒
42	03/10/18 14:22	General View	1	Load JPG	☒
43	03/10/18 14:22	General View	1	Load JPG	☒
44	03/10/18 14:22	General View	1	Load JPG	☒
45	03/10/18 14:22	General View	1	Load JPG	☒
46	03/10/18 14:22	General View	1	Load JPG	☒
47	03/10/18 14:22	General View	1	Load JPG	☒
48	03/10/18 14:22	General View	1	Load JPG	☒
49	03/10/18 14:22	General View	1	Load JPG	☒
50	03/10/18 14:22	General View	1	Load JPG	☒
51	03/10/18 14:22	General View	1	Load JPG	☒
52	03/10/18 14:22	General View	1	Load JPG	☒
53	03/10/18 14:22	General View	1	Load JPG	☒
54	03/10/18 14:22	General View	1	Load JPG	☒
55	03/10/18 14:22	General View	1	Load JPG	☒
56	03/10/18 14:22	General View	1	Load JPG	☒
57	03/10/18 14:22	General View	1	Load JPG	☒
58	03/10/18 14:22	General View	1	Load JPG	☒
59	03/10/18 14:22	General View	1	Load JPG	☒
60	03/10/18 14:22	General View	1	Load JPG	☒
61	03/10/18 14:22	General View	1	Load JPG	☒
62	03/10/18 14:22	General View	1	Load JPG	☒
63	03/10/18 14:22	General View	1	Load JPG	☒
64	03/10/18 14:22	General View	1	Load JPG	☒
65	03/10/18 14:22	General View	1	Load JPG	☒
66	03/10/18 14:22	General View	1	Load JPG	☒
67	03/10/18 14:22	General View	1	Load JPG	☒
68	03/10/18 14:22	General View	1	Load JPG	☒
69	03/10/18 14:22	General View	1	Load JPG	☒
70	03/10/18 14:22	General View	1	Load JPG	☒
71	03/10/18 14:22	General View	1	Load JPG	☒
72	03/10/18 14:22	General View	1	Load JPG	☒
73	03/10/18 14:22	General View	1	Load JPG	☒
74	03/10/18 14:22	General View	1	Load JPG	☒
75	03/10/18 14:22	General View	1	Load JPG	☒
76	03/10/18 14:22	Reinspection Photo	1	Load JPG	☒
77	03/10/18 14:22	Reinspection Photo	1	Load JPG	☒
78	03/10/18 14:22	Reinspection Photo	1	Load JPG	☒
79	03/10/18 14:22	Reinspection Photo	1	Load JPG	☒
80	03/10/18 14:22	Reinspection Photo	1	Load JPG	☒
81	03/10/18 14:22	Reinspection Photo	1	Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
82	03/10/18 14:22	Reinspection Photo		Load JPG	☒
83	03/10/18 14:22	Reinspection Photo		Load JPG	☒
84	03/10/18 14:22	Reinspection Photo		Load JPG	☒
85	03/10/18 14:22	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	03/04/18 10:56	TPD SLB6916R GIA REPORT		Load PDF	
2	03/04/18 10:57	TPD SLB6916R EST		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006039/R1QD3E2

Date: 05/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28790952MKC

Claimant Vehicle No: SLB6916R

Insured Vehicle No: GW5250H

Date of Loss: 31/03/2018

Nature of Claim: TP

Claim No: 554184

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB6916R

Make & Model: BMW X5 XL, 3.0 (A)

Engine No: 04606917N52B30AF

Reg. Date: 04/05/2009 (Man. Year: 2008)

Chassis No: WBAFE42060LK97612

Colour: Black

Odometer: 112172 km

Engine Capacity: 2996 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R18

Rear Tyre Size: 255/55 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,837.15	17,578.75	6,258.40	26.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	2,450.00	1,020.00	29.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,307.15	20,028.75	7,278.40	26.65
Approved Total (Overridden) (S\$)		12,000.00		
(S\$)	27,307.15	12,000.00	15,307.15	56.06
+ GST 7.00/7.00% (S\$)	1,911.50	840.00	1,071.50	56.06
Nett Amount (S\$)	29,218.65	12,840.00	16,378.65	56.06

INSPECTION

Date of Assignment: 03/04/2018

Date Inspected: 03/04/2018 Inspected At:

Mova Automotive Pte Ltd (Bukit Merah)
15 FAN YONG ROAD
SINGAPORE 629792

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2018)
Parts:	M1-SUV	BMW X5 XL 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB6916R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,300.00 FL	*1,300.00 FL
2	1		*REAR BUMPER CTR BRACKET	Cracked	230.00 FL	*230.00 FL
3	2		*REAR BUMPER L/R BRACKET	Necessary	300.00 FL	*300.00 FL
4	1		*REAR BUMPER SIDE COVER L/R	O/S Cut / N/S Serviceable	900.00 FL	*450.00 FL
5	1		*REAR BUMPER SIDE BRACKET	O/S Necessary / N/SServiceable	420.00 FL	*210.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	780.00 FL	*780.00 FL
7	1		*TAILGATE LOWER	Buckled	1,480.00 FL	*1,480.00 FL
8	2		*TAILGATE LOWER HINGE	Serviceable	320.00 FL	*- FL
9	2		*TAILGATE LOWER L/R LOCK	Serviceable	520.00 FL	*- FL
10	2		*TAILGATE LOWER DRIVE FLAP	Serviceable	320.00 FL	*- FL
11	2		*TAILGATE LOWER LEVEL LOCK	Serviceable	320.00 FL	*- FL
12	2		*TAILGATE LOCK GAS STRUT	Serviceable	380.00 FL	*- FL
13	1		*TAILGATE UPPER	Bent	2,458.00 FL	*2,458.00 FL
14	1		*TAILGATE LOGO	Necessary	130.00 FL	*130.00 FL
15	2		*TAILGATE REFLECTOR LAMP	Serviceable	1,160.00 FL	*- FL
16	1		*TAILGATE INNER TRIM	Deformed	680.00 FL	*680.00 FL
17	1		*TAILGATE LOCK	Bent	360.00 FL	*360.00 FL
18	1		*TAILGATE LOCK CABLE	Serviceable	160.00 FL	*- FL
19	1		*TAILGATE INNER CTR TRIM	Serviceable	438.00 FL	*- FL
20	1		*TAILGATE CENTRE COVER	Serviceable	60.00 FL	*- FL
21	1		*TAILGATE WIPER ARM	Serviceable	230.00 FL	*- FL
22	1		*TAILGATE WIPER MOTOR	Deformed	580.00 FL	*580.00 FL
23	1		*TAILGATE WIPER BLADE	Cut	40.00 FL	*40.00 FL
24	1		*TAILGATE INJECTION NOZZLE	Serviceable	45.00 FL	*- FL
25	1		*REAR WINDSCREEN GLASS	Broken	1,980.00 FL	*1,980.00 FL
26	1		*TAILGATE RH	Cracked	780.00 FL	*780.00 FL
27	3		*REAR PARKING SENSOR	Not Working	960.00 FL	*960.00 FL
28	3		*REAR PARKING SENSOR HOLDER	Necessary	180.00 FL	*180.00 FL
29	1		*REAR PARKING SENSOR WIRE HARNESS	Cut	458.00 FL	*458.00 FL
30	1		*REAR EXHAUST ASSY	Dented	1,680.00 FL	*1,680.00 FL
31	1		*REAR EXHAUST HEAT SHIELD	Distorted	310.00 FL	*310.00 FL
32	4		*REAR EXHAUST MOUNTING	Necessary	240.00 FL	*240.00 FL
33	1		*END PANEL GARNISH	Deformed	360.00 FL	*360.00 FL
34	1		*TAILGATE RUBBER	Cut	390.00 FL	*390.00 FL
35	1		*END PANEL OUTER (2PCS)	Bent-1PC ONLY	1,578.00 FL	*789.00 FL
36	1		*END PANEL INNER	Serviceable	685.00 FL	*- FL
37	1		*BATTERY BOX COVER	Serviceable	485.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	2		*FRONT SEAT HEAD REST AIRBAG REPAIR KIT	Activated	1,300.00 FL	*1,300.00 FL
39	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
40	1		*REAR NUMBER PLATE	Scratched	50.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	25,087.00	18,500.00
- List Item Discount on L Items 5.00/5.00% (S\$)	1,249.85	921.25

Total Parts (S\$)	23,837.15	17,578.75
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ACCIDENT TOWING TO FAN YOONG	New	120.00	80.00
2	TO INSPECT RR LIGHTING WATER & LEAKAGE TEST	New	40.00	40.00
3	TO REMOVE & INSTALL REAR WINDSCREEN	New	120.00	120.00
4	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE	New	100.00	80.00
5	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE LOWER	New	80.00	60.00
6	TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES, CARPET & ETC IN ORDER TO CUT OFF END PANEL	New	200.00	150.00
7	TO REMOVE & INSTALL REAR EXHAUST	New	80.00	60.00
8	TO REMOVE & RENEW FRONT SEAT REST AIRBAG REPAIR KIT IN ORDER TO REPROGRAMMING AIRBAG CONTROL SYSTEM	New	300.00	200.00
9	TO CUT OFF END PANEL OUTER & INNER PANEL, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGES PARTS	New	1,000.00	700.00
10	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	80.00	60.00
11	TO APPLY RUST PROOF ON AFFECTED AREAS	New	150.00	100.00
12	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,200.00	800.00
Gross Labour Cost (S\$)			3,470.00	2,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >