

INS. CASE OWNER:

CC<sup>3</sup> /AIG1800 6048, S w639

LKK:  
IDAC:

Surveyor:

WKF

DOI:

ASSIGNMENT

10/4/18

Date / Time:

3/4/18

Registered in Merimen:

3/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLC 8437H

Name of Insured:

LIAMH MUN SUIM

Insured Tel No.:

HP:

9637 962

Excess Sec II :SS

D.O.A.:

24/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

9906081754

Policy No.:

70046770-01000

Make / Model:

NISSAN

Place of Accident:

12 BION RO LIKUN OF ST  
BERMABETTE UP

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJE 16164



INSRS:

WSP:

Tel:

Liability:

RMKS:

Performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

5/4/18  
WKF

SJE 16164-4

SLC 8437H-4

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

5/4/18  
UWION.

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: NRIC

called OE, confirm accident details.  
inform TP claim. agree to settle  
letter and out.

Email workshop liability claim.

RECEIVED 16 OCT 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

9/10/18

Confirm with:

Caroline

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

SS

3685.35

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

180.00

(

days)

Loss of Income (LOI):

SS

(

days)

LOR only ☐ LOU only ☐

LOR + LOU

☐

LOR + LOI

☐

(Tick only one)

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

3867.35

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3687.35

Name 1:

Performance Motors Ltd.

Payee 2: (Strike if N.A.)

SS

180.00

Name 2:

Angelvin Baby Lourdes Chee Porma

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

REF: AIG

W

## ASSIGNMENT

From:

Date:

10/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJE1616Y

at Workshop m/s

Performance Motor

of

303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Before 12pm

Make of Veh:

Inthiran

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAC Accident Report:

Consistent? : Yes or No

GIA / FR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res: Yes or No

Lump Sum:

282%

3 Val: Yes or No

CA / REV / REP. / 24 HRS / wp

Date

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJE1616Y

Yr Regn:

30/5/2017

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 218

CC 1499

Colour:

White

A/C Insured / Std / NI / NA

Sp. Reading

110 / 2

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W 0112 F-12 0000886024

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N/A / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgestone

Front

Rear

R/Bal.

7

mm

R/Bal.

3

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A

27/3/18

D.O.I

10/4/18

Survey held at

Performance motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/6/18 Confirm 2B. &gt; \$3444.25 with 3 working days

(Bal = \$2828-73  
45.1)

Date/Time: File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ - RE - \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18006048/wb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 03-04-2018	
		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLC 8537H	Veh. Inspected	SJE 1616Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/04/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	29/03/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

180, Kampong Arang Road  
East Coast Centre  
Singapore 439180  
Tel. 63190888 (AfterSales)  
Fax. 63449772

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190328 (AfterSales)  
63190333/330 (Motorrad)  
Fax. 64786601 (AfterSales)  
64786624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

03 APR 2018

Estimate No. : b1 46469

Page No. : 1 of 2

Date Estimated : 03/04/2018

Prepared By : Inthiran A/L Thurasamy

## - ESTIMATE REPAIR FOR -

Angelvin Baby Lourdes Chee Parma  
31 Tampines Street 34  
#09-30

Singapore 529237

## - ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJE1616Y	V886024	30/05/2017	218iA/2	0

## DESCRIPTION

To replace front bumper and attachments.

VALUE
850 1,275.00

Painting front bumper.

734 1,038.00
--------------

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00
------------

To replace tyre and wheel rim including balancing. (1x).

80 94.00
----------

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

451 531.00
------------

Sundries.

7 80.00
---------

Total Labour 1: 3,195.00

## DESCRIPTION

Disc wheel 1

QTY	PRIC	VALUE
1	1,049.65	1,049.65

CLOSED GRID RH (SPORT)

1	126.25	126.25
---	--------	--------

RH AIR INLET FINISHER BASIS

1	91.85	91.85
---	-------	-------

FRT BUMPER PANEL PRIMED SRA (SPORT)

1	927.45	927.45
---	--------	--------

SET MOUNTING PDC/PMA SENSOR FRT

1	30.35	30.35
---	-------	-------

DECOUPLING RING PDC TORQUE CONVERTE

4	5.05	20.20
---	------	-------

RR PDC SENSOR ALPINWEISS (300)

1	368.80	368.80
---	--------	--------

(DG/SL) ADHESIVE SET K6

1	53.05	53.05
---	-------	-------

Total Parts : 2,667.60

# Performance Motors Limited

A member of the Straits Times Group  
Co. Reg. No. 19740155W. GST Reg. No. M3-0020081-K



## FINAL REPORT

Estimate No. : b1 46469  
Date Estimated : 03/04/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Angelvin Baby Lourdes Chee Parma  
31 Tampines Street 34  
#09-30

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 529237

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE	
SJE1616Y	V886024	30/05/2017	218iA/2	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
To make good the front bumper include removing attachments to facilitate repairs and knocking out dents caused by the accident	850.00		850.00		
To spray paint front bumper	934.00		934.00		
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00		
To replace wheel rim include balancing (1x)	80.00		80.00		
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00		
Sundries:	80.00		80.00		
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
ALLOY RIM 7.5JX17 STAR SPOKE 379	899.25	1.00		899.25	

### # SUPPLEMENTARY ITEMS

Total Labour :	2,545.00
Total Parts :	899.25
Total Labour & Parts :	3,444.25
Deduction for Excess :	
Total Repair Costs less Excess:	3,444.25
GST @7%:	241.10
Grand Total :	3,685.35



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190200 (Sales & Admin)  
63190222 (AfterSales)  
Fax. 64747770

305, Kampong Arang Road  
East Coast Centre  
Singapore 434180  
Tel. 63190886 (AfterSales)  
Fax. 63449773

312, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190532/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796626 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 46469  
Date Estimated : 03/04/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJE1616Y	V886024	30/05/2017	218iA/2	0

4 days  
Sebastian  
10/4/18.  
- Part by part repair.  
- Question Mark Item  
Photo  
- Photo Before Paint.  
90036121  
sebastianyang@lkkauto.com

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	3,195.00
Parts	:	2,667.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	410.38
Grand Total	:	6,272.98

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008  
(PAYMENT BREAKDOWN)**

Vehicle No:	SJE 1616Y	Model:	
Date of Accident:	29.3.18		

Global Sum Settlement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	\$	6,272.98	
Final Repair Cost	\$	3,685.35	
Loss of Use	\$	180.00	3 days at \$60 per day
Rental (if any)	\$	—	days
LTA / GIA Search Fee	\$	2.00	
Others:	\$	/	
	\$		
Final Settlement Sum	\$	3,867.35	

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	\$ 3,685.35
2)	Performance Motors Ltd	\$ 2.00
3)	Angelvin Baby Laundry Chee Poon	\$ 180.00

Signed by appointed surveyor \_\_\_\_\_

Date \_\_\_\_\_

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;  
Survey Report; Medical Report/ Bill (if any))



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564313

Our Ref: CC3/AIG18006047/wb3

05 April 2018

**CHANG MUN SUM**

10 Stirling Rd

#13-06

Singapore 148954

Dear Sir/Madam,

**ACCIDENT INVOLVING SLC 8537H AND SJE 1616J ON 29/03/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau

Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)



**AUTHORISATION TO ACT**  
**(AIG Express Third Party Claim)**

I, Angelvin Baby Lourdes Chea Parwa (the third party claimant) of 71 Tampines  
Street 74 #09-70 (S) 524767 (address), owner of SJE1616Y (vehicle no.)  
hereby authorize Performance Motors Ltd ("the workshop") to act for me  
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle  
no. SJE1616Y that was damaged pursuant to the accident which occurred on 24.3.18  
(date) along St Bernadette's Church (River Valley) (location) involving vehicle no/s  
SLC8537H ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit  
and the workshop is further authorized to receive payment further to settlement of my claim with  
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without  
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 10 (day) of 4 (month) 20 18 (year)



Signed by "the third party claimant"  
(with chop if applicable)



**PERFORMANCE MOTORS LIMITED**  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
TEL: 63190100 (Sales)  
63190111 (After sales)

Signed by "the workshop"  
(with chop)

**RELEASE VOUCHER**  
**(AIG Express Third Party Claim)**

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,655.35 (Repair Cost), S\$180.00 (Loss of rental/use), S\$2.00 (Disbursement), for vehicle no. SJE16164 that was damaged pursuant to the accident which occurred on 29-2-18 (date) along St Bernadette's Church (River Valley) (location) involving vehicle no/s SLC8517H. This is pursuant to the inspection conducted on 10-4-18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Angelyn Baby Lourdes Chop Arman ("the third party claimant") of vehicle no. SJE16164 make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJE16164 (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 9 (day) of 10 (month) 2018 (year)

  
yml LKK

Signed by appointed surveyor

  
**PERFORMANCE MOTORS LIMITED**  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
TEL: 63190100 (Main)  
63190111 (AfterSales)  
Signed by "the workshop" (with chop)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64767770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

319, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796401 (AfterSales)  
64796524 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1257928</b>	Page No. : <b>1 of 2</b>
Date IN : <b>10/04/2018</b>	Invoice Number : <b>1982176 / WSB</b>
Cust. Svc. Advisor: <b>Inthiran A/L Thurasamy</b>	Invoice Date : <b>02/07/2018</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Toh Jing Xuan</b>

**- CUSTOMER INFORMATION -**

**Ms Angelvin Baby Lourdes Chee Parma**  
**31 Tampines Street 34**  
**#09-30**

**Singapore 529237**

**- INVOICE TO - 121**

**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO. <b>SJE1616Y /</b>	CHASSIS NO. <b>V886024</b>	REGN. DATE <b>30/05/2017</b>	MODEL <b>218IA/2</b>	MILEAGE <b>11012</b>
--------------------------------	-------------------------------	---------------------------------	-------------------------	-------------------------

**- - - - LABOUR 1 - - - -**

To make good the front bumper including remove attachments  
to facilitate repairs and knock out dented area caused  
by the accident.

To respray front bumper.

To check electrical wiring systems and lightings at the  
rear section for proper function.

To replace front right wheel rim including balancing.

To check steering geometry and conduct wheel alignment in  
accordance with BMW specifications.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 29.03.2018. 3RD PARTY CAR : SLC8537H.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR SEBASTIAN FROM LKK AUTO  
ON 10.04.2018. AUTHORISED REPAIR BY MS VIVIAN LAU FROM  
LKK AUTO ON 05.04.2018 VIA EMAIL.

PROPOSE LOSS OF USE = \$60x3. THE AMOUNT IS SUBJECTED  
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

Total Labour 1: **2,545.00**

**- - - - PARTS - - - -**

**ALLOY RIM 7.5JX17 STAR SPOKE 379**

Qty	Retail Price	NETT
1	899.25	899.25
Total Parts :		<b>899.25</b>

**- - - - LABOUR 2 - - - -**

-

Total Labour 2: **0.00**

**Performance Motors Limited**

A member of the Sime Darby Group  
Co. Reg. No. 197401155M GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 436180  
Tel. 63190000 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190000 (AfterSales)  
63190033/330 (Motocrad)  
Fax. 64796401 (AfterSales)  
64796424 (Motocrad)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1257928</b>	Page No. : <b>2 of 2</b>
Date IN : <b>10/04/2018</b>	Invoice Number : <b>1982176 / WSB</b>
Cust. Svc. Advisor: <b>Inthiran A/L Thurasamy</b>	Invoice Date : <b>02/07/2018</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Toh Jing Xuan</b>

Labour Charges : <b>2,465.00</b>	Total Labour & Parts Charges : <b>S\$ 3,444.25</b>
Parts Charges : <b>899.25</b>	Less Insurance Excess : <b>S\$ 0.00</b>
Lubricant/Misc : <b>80.00</b>	Invoice Total Amount Exclude GST : <b>S\$ 3,444.25</b>
	GST @ 7% : <b>S\$ 241.10</b>
	Invoice Total Amount Include GST : <b>S\$ 3,685.35</b>

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 3,685.35**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-048372  
Date of Request: 02/04/2018

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 02/04/2018  
Enquiry By Vivi  
TP Vehicle No. SLC8537H  
Accident Date 29/03/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLC8537H	AIG Asia Pacific Insurance Pte. Ltd.	27/05/2017-26/05/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-048372  
Date of Request: 02/04/2018

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 02/04/2018  
Enquiry By: Vivi  
TP Vehicle No: SLC8537H  
Accident Date: 29/03/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
* Class 2 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	11 Jul 1991

HP 428A



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2018 <a href="#">Edit Reg</a>		10 Apr 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,444.25</b> <a href="#">Edit Estimates</a>	<b>S\$3,444.25</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> [Created by adjuster]									
Insured:	<b>CHANG MUN SUM</b> , ID: S0094109C								
Main Claimant:	<b>ANGELVIN BABY LOURDES CHEE PARMA</b> , ID: S7206773H								
Vehicle Reg. No.:	<b>SJE1616Y</b>	Date of Loss:	29/03/2018 19:00 - :59 [9 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4990608113SG</b>	Policy/Cover Note No.:	2100467740 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLC8537H</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	<b>Liberty Insurance Pte Ltd (HQ)</b> - Tel: 6221 8611								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Sebastian Yeang Wai Keen</b> ] ... [Final Rpt due 12/04/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SJE1616Y (4990608113SG)  
[SLC8537H]  
TP  
ANGELVIN BABY LOURDES CHEE PARMA  
Mar 29 2018 7:00PM  
[CHANG MUN SUM]  
Performance Motors Limited

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>	
<b>Letters/Correspondences</b>			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit
<b>Assessment Reports</b>			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	04/04/18 17:13	Accident Statement <small>From: SC - Reg. No: SLC8537H, Claimant: CHANG MUN SUM</small>	1	Load HTM
<b>Photos/Images</b>			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
2	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
3	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
4	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
5	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
6	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
7	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
8	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
9	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
10	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
11	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
12	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
13	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
14	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
15	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
16	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
17	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
18	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
19	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
20	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
21	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
22	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
23	09/10/18 11:14	General View	1	Load JPG <input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	03/04/18 12:46	TP GIA REPORT	1	Load PDF
2	03/04/18 12:46	TP ESTIMATE	1	Load TIF
3	12/04/18 16:58	TP ESTIMATE- MARKED	1	Load PDF
4	17/10/18 09:13	WORKSHOP INVOICE	1	Load PDF
5	17/10/18 09:13	AUTHORISATION TO ACT FORM	1	Load PDF

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
6	17/10/18 09:13	Release Voucher		Load PDF
7	17/10/18 09:13	GIA SEARCH		Load PDF
8	17/10/18 09:13	NRIC		Load PDF
9	17/10/18 09:13	LETTER TO OI		Load PDF

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLC8537H (Insd veh)	Model:	BMW 218D 2.0 D (A)
	SJE1616Y (TP veh)		
Date of Accident:	29/03/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	6,272.98
Final Repair Cost	:	\$	3,685.35
Loss of Use	:	\$	180.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,867.35

3.00 days at \$60.00 per day  
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ 100 \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 3,687.35
2)	Angelvin Baby Lourdes Chee Parma	:	\$ 180.00
3)		:	\$

JOANNE LEE KHANG MIN

17 Oct  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18006048/SWB3Q2

Date: 17/10/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100467740

Claimant Vehicle  
No: SJE1616Y

Insured Vehicle No: SLC8537H

Date of Loss: 29/03/2018

Nature of Claim:

TP

Claim No: 4990608113SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJE1616Y

Make &amp; Model: BMW 218D, 2.0 D (A)

Reg. Date: 30/05/2017 (Man. Year: 2017)

Colour: White

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: F6961722B38B15A

Chassis No: WBA2F12000V886024

Odometer: 11012 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Bridgestone 7 mm

Rear Left Side:

Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side:

Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,747.60	979.25	1,768.35	64.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,115.00	2,465.00	650.00	20.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,862.60</b>	<b>3,444.25</b>	<b>2,418.35</b>	<b>41.25</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>410.38</b>	<b>241.10</b>	<b>169.28</b>	<b>41.25</b>
<b>Nett Amount (S\$)</b>	<b>6,272.98</b>	<b>3,685.35</b>	<b>2,587.63</b>	<b>41.25</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		<b>180.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>3,867.35</b>		

### INSPECTION

Date of Assignment: 10/04/2018

Date Inspected: 10/04/2018 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

---

**Adjuster:** Sebastian Yeang Wai Keen**Manager:** VIVIAN LAU PEI FENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*DISC WHEEL L	Scratched	1,049.65 FS	*899.25 FS
3	1		*CLOSED GRID RH (SPORT)	Not Necessary	126.25 FS	*- FS
4	1		*RH AIR INLET FINISHER BASIS	Not Necessary	91.85 FS	*- FS
5	1		*FRT BUMPER PANEL PRIMED SRA (SPORT)	Not Necessary	927.45 FS	*- FS
6	1		*SET MOUNTING PDC/PMA SENSOR FRT	Not Necessary	30.35 FS	*- FS
7	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
8	1		*RR PDC SENSOR ALPINWEISS (300)	Not Necessary	368.80 FS	*- FS
9	1		*(DG/SL) ADHESIVE SET K6	Not Necessary	53.05 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)      2,747.60      979.25**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER AND ATTACHMENTS	New	1,275.00	850.00
2	PAINTING FRONT BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
Gross Labour Cost (S\$)			3,115.00	2,465.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >