

A26

COMFORTDELGRO ENGINEERING PTE LTD

Date: 02.04.2018

Time: 16:17:30

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305137258
 REGN NO : SHC8055D
 MILEAGE : 0000000000
 MAKE : MERCEDES BENZ
 MODEL : E220CDI(E6)
 DATE OF REGN : 28.05.2015
 DATE/TIME IN : 02.04.2018 10:10
 ACCIDENT DATE : 01.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0202-2292-G 212VB FRONT BUMPER ASSY 1 1,890.50 20.00 1,512.40 ~~1,890.50~~

SUB-TOTAL : 1,512.40

JOB NATURE

0000 L PANEL BEATING- FRT.
 0001 23-502 SPRAYPAINT ON AFFECTED AREA
 0002 17-01 CHECK ALL LIGHTING

~~300.00~~ 100
~~250.00~~ 200
~~50.00~~ 4

SUB-TOTAL : 600.00

TOTAL : 2,112.40

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

Kalish / LKK
 2/4/18 1610h
 2 Pys
 PIP
 After Repair plls

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: