

INS. CASE OWNER:

Lynthia

CC 4 ASM
AXA1800

6097, A W67/L

LKK:

IDAC

Surveyor:

ADRIAN

DOI:

ASSIGNMENT

03/04/18

Date / Time:

3/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJR 25613

Name of Insured:

FOO PIT 4UEN

Insured Tel No.:

HP:

97887750

Excess Sec II :SS

D.O.A.:

1/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) (YES / NO)

Claim No.:

S8M00LOS / 37891

Policy No.:

P089779

Make / Model:

HONDA

Place of Accident:

LEE TWS UEN

OI GIA REPORT (YES / NO) : TP GIA REPORT (YES / NO)

Insured Liability:

Final ? Yes / No

SJR 17450

SJR 25613

SJR 469m



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

my solution
TP

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

4/4/18
vivan

SJR 469m - x

SJR 25613 - x

confirm accident details inform TP claim.
agree to settle - aware NCD will be on hold. later find out.

File pass to typist type report

seek advice via SMART

- ASK APPROVED WALKER
- SEND 1st OFFER TO TP
- TP ACCEPTED OFFER.
- IN POSE IN OFFER.
- TO CLOSE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: NO IN

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA/GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: DO FORM

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: LG

SS 4,300.00 (6 days) Reduction: 57 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with: GU WONG

Email ☐ Call ☐

Final Liability:

SS 100 (Agreed / Assessed) BOLA S/N No.: 28

If NO or B 28, Ass. Lia: 0 %

Repair Cost: 400/450

SS 4,601.00

02 involved in 36C

Loss of Rental (LOR):

SS - (- days)

02 is the 2nd veh

Loss of Use (LOU):

SS 40.00 x 9 days

(NON-OUT) 14/07/19

Loss of Income (LOI):

SS - (\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS 7.45

Medical:

SS -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS -

(e.g. Tow/Independent)

2) Report Format:

Legal Cost

SS -

3) Survey fee: 4350.00

Total:

SS 5,148.45

Global Sum SS: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 5,148.45

Name 1:

MG SOLUTION PTE LTD

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

w

(Red. 15149.44
51%)

NOTES



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18006097/wb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 03-04-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJV 2861J	Veh. Inspected	SLX 469M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/04/2018	Inspection Date		
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 03/04/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLX469M		
MODEL	: HONDA JAZZ 1.4A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 1-Apr-18
		TIME	: 11:30HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

QUOTATION SUMMARY

CLAIM DETAIL : PARTS (REAR)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Painted</i>	1	\$ 1,122.00	\$ 1,122.00
2	TAIL GATE LOGO <i>new</i>	1	\$ 45.00	\$ 45.00
3	TAIL GATE EMBLEM 'JAZZ' <i>new</i>	1	\$ 45.00	\$ 45.00
4	TAIL GATE DETECTOR <i>Painted</i>	1	\$ 155.30	\$ 155.30
5	TAIL GATE SENSOR LOCK <i>Painted</i>	1	\$ 180.00	\$ 180.00
6	TAIL GATE INNER LOCK <i>Painted</i>	1	\$ 225.80	\$ 225.80
7	TAIL GATE CATCH <i>new</i>	1	\$ 72.00	\$ 72.00
8	TAIL GATE WEATHER STRIP <i>new</i>	1	\$ 128.00	\$ 128.00
9	TAIL GATE INNER TRIM <i>Painted</i>	1	\$ 118.20	\$ 118.20
10	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 190.00	\$ 190.00
11	REAR BUMPER <i>Painted</i>	1	\$ 730.00	\$ 730.00
12	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 42.00	\$ 84.00
13	TAIL LAMP <i>RA Painted</i>	2	\$ 330.00	\$ 660.00
14	TAIL LAMP LOWER BRACKET <i>new</i>	2	\$ 62.00	\$ 124.00
15	TAIL LAMP PANEL <i>new</i>	2	\$ 230.00	\$ 460.00
16	REAR END PANEL <i>Painted</i>	1	\$ 520.00	\$ 520.00
17	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 190.00	\$ 190.00

2850.70

2780.50

TOTAL PRICE	\$	5,049.30
LESS 20%	\$	1,009.86
SUB TOTAL PRICE	\$	4,039.44

SPECIAL NETT ITEMS (REAR)

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00 ✓
2	TAIL GATE SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 ✗
3	TAIL GATE INNER TRIM CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00 ✓
4	TAIL GATE WINDSCREEN SEALANT <i>2 new</i>	1	\$ 80.00	\$ 80.00 30
5	TAIL GATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00 30
6	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00 ✓
7	REAR BUMPER LOWER LID <i>2 new d.</i>	1	\$ 1,100.00	\$ 1,100.00 700
8	REAR BUMPER LOWER LID STICKER <i>new</i>	1	\$ 90.00	\$ 90.00 30
9	TAIL LAMP CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00 10
10	TAIL LAMP PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 ✗
11	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1	\$ 20.00	\$ 20.00 10
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00 60
13	REVERSE SENSOR <i>2 new d</i>	1	\$ 220.00	\$ 220.00 200

1160

TOTAL \$ 1,960.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,600.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$1,400.00	900	
3	TUFF COAT	\$250.00	40	
4	WIRING CHECK	\$80.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$180.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	50	
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$120.00	100	
8	TRANSFER TAILGATE MECHANISM	\$80.00	✓	
9	CONDUCT WATER LEAKAGE TEST	\$80.00	✗	
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$180.00	✗	

1960

TOTAL

\$4,050.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,999.44
TOTAL LABOUR COST : \$ 4,050.00
TOTAL REPAIR COST : \$ 10,049.44

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

total: \$4005.6
L/S: 4.3K
060m/s

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No.: 201427944N

MOTOR CLAIM DISCHARGE

INSURED: LIM ENG CHUN
CAR/LORRY/CYCLE: REG NO: SLX 469M POLICY NO:
ACCIDENT CLAIM NO:

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle
Registered No. SLX 469M from the repairers,
Messrs MG SOLUTION PTE LTD

And that all repairs necessary as a result of an accident in which the said vehicle was involved on or
about the 01 day of 04 2018 have been completed to my / our satisfaction, and that
I / we have no further claim on the above company in Respect thereof.

Date: Signature:

Co's Stamp: NRIC No:

02/04/2018 PF1
02/04/2018 - Sunday

Vehicle In - 02/04/2018
Vehicle Out - 11/04/2018
Lev - 9 days + \$80
+ \$720



Re:RE: S8M00COS- mandate approval

Type

🔔 Question

Message

APPROVED

Reply



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 201427944N)

Date : 17/08/2018

Your Ref : SJV2861J

To : AXA INSURANCE SINGAPORE PTE LTD

Attn : Motor Claims Department

Dear Sir/Mdm,

**RE: ACCIDENT INVOLVING VEHICLE SLX469M & SJV2861J ON 01/04/2018 AT
ALONG CTE TOWARDS ATE BEFORE BALESTIER ROAD EXIT.**

We refer to the above matter.

Attached copies of the following for your kind perusal:

- 1) Proforma Bill No.188251 @ S\$4,601.00 (Inclusive Of 7% GST)
- 2) Loss of Use @ S\$720.00 (9 Days x S\$80)
- 3) LTA Search @ S\$7.45
- 4) Authorisation to Act
- 5) GIA Report

Hope the above is in order and kindly let us have your confirmation soon.

Tax invoice will be issue upon amount finalized.

Thank You.

Yours faithfully,



Sharon Chia

HP: 9188 6931

E-mail: mg3solution@gmail.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

05 April 2018

Foo Pit Yuen

Blk 101 Clementi Street 14
08-147
Singapore 120101

Dear Sir/ Mdm

OUR REF : CC4/ASM18006097/wb3
YOUR REF : SJV 2861J

**ACCIDENT INVOLVING SJV 2861J & SLX 469M ALONG CTE TWDS CITY ON
01/04/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from MG Solution Pte Ltd acting on behalf of the owner of SLX 469M against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com within 7 days if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AXA Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORITY

Name : LIM ENG CHUN
Address : BLK 310A ANCHORVALE ROAD
#15-27 SINGAPORE 541310
Contact No : _____

TO: AXA INSURANCE PTE LTD

Dear Sirs,

ACCIDENT INVOLVING SLX 469M AND SJV 2861J ON 01/04/2018
AT/ALONG CTE TOWARDS AYE BEFORE RALESTIER ROAD EXIT

I/We, LIM ENG CHUN, am/are the registered owner of
motor car no. SLX 469M

Please note that I have assigned all compensations monies due to me/us in the above said accident
to M/S MG SOLUTION PTE LTD.

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned
accident to M/S MG SOLUTION PTE LTD and forward your settlement cheque to M/S MG SOLUTION
PTE LTD whom I had authorized to collect the said compensation monies.

Thank you



Signature of Claimant



Witness By

Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.

AUTHORIZATION TO ACT

I, LIM ENG CHUN ("the third party claimant")
of BLK 310A ANCHURVALE ROAD #15-27 S(541310) (address),
owner of SLX469M (vehicle no.) hereby authorize
MG SOLUTION PTE LTD
("The workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
Vehicle No. SLX469M that was damaged pursuant to the
accident which occurred on 01/04/2018 (date) along CTE TOWARDS
AYE BEFORE BALESTIER ROAD EXIT (location)
involving Vehicle No/s SJV 2861J
("The accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this _____ day of _____ (month) 20 ____ (year)

L

Signed by "the third party claimant"



Signed by "the workshop"



redefining / insurance

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SJV 2861J (Insd veh)	Model:	HONDA JAZZ 1.5 CVT
	SLX 469M (TP veh)		
Date of Accident/ Time:	01/04/2018 - 11:30		

Repair Estimate:	: S	10,752.90	
Final Repair Cost (w/gst)	: S	4,601.00	
Loss of Use:	: S	540.00	9 days at \$ 60 per day
Rental (if any):	: S	-	days at \$ per day
LTA / GIA Search Fee:	: S	7.45	
Others:	: S	-	
Final Settlement Sum	: S	5,148.45	
Payee Name: MG SOLUTION PTE LTD			

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A)	For Non GIA Registered Workshop:	Agreed Liability <u>100</u> (%)		
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No:		
	BOLA Liability: _____ (%)	Assessed Liability (%): <u>0</u> (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks:				

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVE THEIR RIGHTS OF RECOVERY IN THE EVENT OF FRAUD / MIS REPRESENTATION / MISTAKE / MATERIAL NON DISCLOSURE. AXA ALSO RESERVES THEIR RIGHTS TO WITHDRAW THEIR ACCEPTANCE IN THE EVENT OF ANY INCONSISTENCIES/FRAUD/SUSPECTED FRAUD/MIS REPRESENTATION AND/OR MATERIAL NON DISCLOSURE OF FACTS/MISTAKE(S).

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and/or our client/insureds/agent(s) (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident. We confirmed that we have the authority of our client to act for and on their behalf in this agreement.

Signature of workshop representative / Workshop stamp
Name of Representative: WONG SU HUI
Date: LKK

Signature of Witness / Workshop stamp (if applicable)
Name of Witness: Eric Tan
Date:

Signature of AXA's surveyor/representative:
Name of AXA's surveyor/Representative:
Date:

AXA Pte. Ltd. The Lion Company, Reg. No. 1999087121
8 Shenton Way, #24-01 AXA Tower, Singapore 068611
Customer Centre #B3-01
Tel: +65 6580 4668 Fax: +65 6338 2522 Website: www.axa.com.sg



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

TAX INVOICE

Bill To:

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

INVOICE No : TI 199076

PB No : 188251

Date : 01-April-2019

ATTN : MOTOR CLAIMS DEPARTMENT

Vehicle Number : SLX 469M

QTY	DESCRIPTION	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 4,300.00
BEFORE GST		4,300.00
7% GST		301.00
TOTAL		\$ 4,601.00

Cheque should be made payable to MG Solution Pte Ltd



Co's stamp & Authorised Signature



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0005529-2

Print Date/Time : 02 Apr 2018 / 12:51:45

Receipt Date/Time : 02 Apr 2018 / 12:51:45

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180402-001037

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SJV2861J

As at 01 Apr 2018/11:30:00

Insurance Co: AXA INSURANCE PTE LTD

1 Insurance Enquiry - SJV2861J

Enquiry Fee

20180402125031060179

7.00 0.49 7.49

Sub-Total 7.00 0.49 7.49

Total Before Rounding 7.00 0.49 7.49

Rounding Difference 0.04

Total Amount Payable 7.45

Paid By

20180402125037572 Direct Debit: eNETS Debit
(Internet Banking) 7.45

Total 7.45

Cash Change 0.00

Tendered Amount 7.45

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SJV2861J	01 Apr 2018 / 11:30:00	AXA INSURANCE PTE LTD

[Print](#)[OK](#)[Save as PDF](#)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJV 2861J (Insd veh)	Model:	HONDA JAZZ
	SLX 469M (TP veh)		
Date of Accident:	01/04/2018		

Global Sum Settlement	: [] Yes	[X] No
Repair Estimate	: \$	10,752.90
Final Repair Cost	: \$	4,601.00
Loss of Use	: \$	540.00
Rental (if any)	: \$	9days at \$60.00 per day
LTA / GIA Search Fee	: \$	7.45

Others:	: \$	0.00
---------	------	------

	: \$	
Final Settlement Sum	: \$	5,148.45

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ___100___(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____(%)	Assessed Liability (*): ___0___(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	MG SOLUTION PTE LTD	: \$ 5,148.45

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

14/06/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18006097/Ahb3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA LOH		Date : 14-06-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJV 2861J	Veh. Inspected	SLX 469M	
Policy No.	P0892379	Coverage (\$)	0.00	
Claim No.	S8M00COS	Excess (\$)	0.00	
Assign From		Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JHMGK5850JX203973	Colour	BLUE	
Odometer	673	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	DUNLOP	6 mm	
L/H Front Tyre	185/55 R16	DUNLOP	6 mm	
R/H Rear Tyre	185/55 R16	DUNLOP	6 mm	
L/H Rear Tyre	185/55 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/04/2018	Inspection Date	03/04/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 469M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE (CONSISTENT)	DENTED	1,122.00	749.90
1	TAIL GATE LOGO (CONSISTENT)	NOT NECESSARY	45.00	-
1	TAIL GATE EMBLEM 'JAZZ' (CONSISTENT)	NECESSARY	45.00	45.00
1	TAIL GATE DETECTOR (CONSISTENT)	CRACKED	155.30	44.50
1	TAIL GATE SENSOR LOCK (CONSISTENT)	CRACKED	180.00	180.00
1	TAIL GATE INNER LOCK (CONSISTENT)	DAMAGED	225.80	198.70
1	TAIL GATE CATCH (CONSISTENT)	NOT NECESSARY	72.00	-
1	TAIL GATE WEATHERSTRIP (CONSISTENT)	CUT	128.00	128.00
1	TAIL GATE INNER TRIM (CONSISTENT)	CRACKED	118.20	118.20
1	TAIL GATE WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	190.00	125.00
1	REAR BUMPER (CONSISTENT)	DEFORMED	730.00	492.60
2	REAR BUMPER SIDE RETAINER @\$42.00 (CONSISTENT)	NECESSARY	84.00	84.00
2	TAIL LAMP @\$330.00 (CONSISTENT)	O/S CRACKED	660.00	330.00
2	TAIL LAMP LOWER BRACKET @\$62.00 (CONSISTENT)	NOT NECESSARY	124.00	-
2	TAIL LAMP PANEL @\$230.00 (CONSISTENT)	NOT NECESSARY	460.00	-
1	REAR END PANEL (CONSISTENT)	DENTED	520.00	354.80
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	190.00	-
	LESS 20% DISCOUNT		-1,009.86	-570.14
			4,039.44	2,280.56
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	TAIL GATE SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	SET TAIL GATE INNER TRIM CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	TAIL GATE WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	30.00
1	TAIL GATE WINDSCREEN INNER SEAL (SN) (CONSISTENT)	NECESSARY	60.00	30.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	REAR BUMPER LOWER LID (SN) (CONSISTENT)	DEFORMED	1,100.00	700.00
1	REAR BUMPER LOWER LID STICKER (SN) (CONSISTENT)	NECESSARY	90.00	30.00
1	SET TAIL LAMP CLIP (SN) (CONSISTENT)	NECESSARY	20.00	10.00
1	TAIL LAMP PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-

Report Ref No. CC4/ASM18006097/Ahb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	10.00
1	REAR END PANEL INSULATION SEAL (SN) (CONSISTENT)	NECESSARY	120.00	60.00
1	REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	220.00	200.00
			1,960.00	1,160.00
	LABOUR			
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.		1,600.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	800.00
	TUFF COAT.		250.00	40.00
	WIRING CHECK.		80.00	30.00
	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.		180.00	60.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	REMOVE AND REFIX TAILGATE WINDSCREEN.		120.00	100.00
	TRANSFER TAILGATE MECHANISM.		80.00	80.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	80.00	-
	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			4,050.00	1,960.00
GRAND TOTAL			10,049.44	5,400.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CC4/ASM18006097/Ahb3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SSM000005
Reference	CCA/ASM18060977/ANb3p2
Loss Date	1 April 2018
Report Date	2 Apr 2018 12:00:00 AM
Request Date	17 July 2018
Due Date	

Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Auto Insurance

Vehicle Information	
Incident Vehicle Registration #	SLK469M
Make	TPVD HONDA
Model	JAZZ 1.5 CVT
Service Address	
...	

Primary Contact/Insured
FOO PRT YUEN
BLK 101 CLEMENTI STREET 14, #08-147, Singapore 97882790

Claim Handler
LOH Cynthia
656804843
cynthia.loh@aaa.com.sg

Additional Instructions

Document Type Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKK Invoice 1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
LIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
LKK Inspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
LKK Adjustment 1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
LOD.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2018
MARKED ESTIMATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2018
LKK Inspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2018
LKK Reinspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2018
Immediate Advice-SLX 469M.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2018
S/V286 LJ INSD GIA REPORT.PDF	Other	Other	DHWAR Namrata	3 April 2018
SLG1345U GIA REPORT.PDF	Reports & Statement	GIA Report	DHWAR Namrata	3 April 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 EMAIL RECEIVED FROM WORKSHOP TP-GIA REPORT.msx	Legal	Others	CHIRWAR Namrata	3 April 2018