

INS. CASE / OWNER: stacy | CC # AXA1800 6099, K 9 as LKK: IDAC: 3/4/18

Surveyor: Kenneth DOI: 3/4/18 Date / Time: 3/4/18 Registered in Merimen: 3/4/18

Pre-assign / CCU / FTE: SJS 24375 TEAM MOVE DRIVER DAVEN 68442475

Insured Vehicle No.: 58m0098V / 37883 Claim No.: 61A7074011

Name of Insured: SHAHID RAN S/O RANA HANDEHAN Policy No.: 61A7074011

Insured Tel No.: 93224437 Make / Model: VOLKSWAGEN

Excess Sec II :SS 12/12/18 D.O.A: 12/12/18 Place of Accident: SEARMIDON RD INOS PIE & MARLIPERSON

Is driver the owner? (YES / NO) (YES) Nature of Accident: MARLIPERSON

If NO, Driver Name / Age: 93224437 OI GIA REPORT: (YES) / NO: TP GIA REPORT: (YES) / NO

Driver Tel No.: 93224437 (VL: (YES) / NO) Insured Liability: % Final ? Yes / No

SJS 20605 → → → → →

INSRS: WSP: Wen Guan INSRS: WSP: INSRS: WSP: INSRS: WSP:

Tel: Tel: Tel: Tel: Tel: Tel:

Liability: Liability: Liability: Liability: Liability: Liability:

RMKS: RMKS: RMKS: RMKS: RMKS: RMKS:

Date/ Time		STAGE	DATE / PIC
<u>4/4/18</u>	<u>SJS 20605</u>	Non-Reporting ltr (1st):	
<u>4/4/18</u>	<u>SJS 24375</u>	Non-Reporting ltr (2nd):	
<u>4/4/18</u>	<u>SJS 24375</u>	Non-Reporting ltr (Final):	
<u>4/4/18</u>	<u>SJS 24375</u>	Notification ltr (if non-pickup):	
<u>4/4/18</u>	<u>SJS 24375</u>	Call OI:	<u>4/4/18</u>
<u>4/4/18</u>	<u>SJS 24375</u>	After call ltr to OI:	<u>4/4/18</u>
<u>4/4/18</u>	<u>SJS 24375</u>	Documentation Check List:	
<u>4/4/18</u>	<u>SJS 24375</u>	Notification ltr (if non-pickup):	☒
<u>4/4/18</u>	<u>SJS 24375</u>	After call ltr to OI:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	Authorisation To Act:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	Release Voucher:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	Final Repair Bill:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	Car Rental Invoice:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	Towing Invoice:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	LTA / GIA:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	Medical Bill:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	PIR:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	Mandate/Reject Instruction:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	LOD:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	Payment Breakdown Form:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	Post-Repair Photos:	☒
<u>4/4/18</u>	<u>SJS 24375</u>	Others:	☒

PRELIMINARY ADVICE Date/Time: 4/4/18 Sent By: KSC

FINALIZATION Date/Time: 4/4/18 Confirm with: KSC Confirm by: KSC

Repair Cost: 115 SS 1900.00 (4 days) Reduction: 45205.76 % 73

FINAL SETTLEMENT Date/Time: 4/4/18 Confirm with: KSC Email: ☐ Call: ☐

Final Liability: 53 (Agreed / Assessed) BOLA S/N No.: 115

Repair Cost: 42033 SS 1016.50 (u/est)

Loss of Rental (LOR): 482 SS 240.00 x 60 days

Loss of Use (LOU): 482 SS 240.00 x 60 days

Loss of Income (LOI): 482 SS 240.00 x 60 days

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: 31.00

Medical: 31.00

Disbursement: 31.00 (e.g. Tow/ Independent)

Legal Cost: 31.00

Total: 1289.50 Global Sum SS: 1289.50

FINAL PAYMENT Date/Time: 4/4/18 Confirm with: KSC Email: ☐ Call: ☐

Payee 1: 1289.50 Name 1: Wen Guan motor

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:

COPY SENT
5/13/2020

REFERENCE NUMBER	ACTIONS / REMARKS
DATE / TIME	
2/11	50/50 email send to file DAO etc to handle case. ✓
5/2	Pending mandate approval (50/1.)
7/2	off 41287-50 (pending acceptance)
11/2	Call @ 41287-50, DV send pending DV.
2/13	DV in, File pass Admin to close.

ASS. REG. BY:

REF:

AXA/

M

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Vsh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

4/4

File pass to Catherine

4/4 \$1900. (confirm w KLC) ✓
(Red: \$5205.70 / 737)

4 4 repair days + 2 pbs + 1 Sunday + 1 cat = 8 days.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS \$

Photos

Others

TOTAL

Veh No:

SKK 7060 Yr Regn: 08, 13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Cruze cc 1598

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

39212

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KL1JA69E90K 151291

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

205/80R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

9

mm

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

17/2/18

D.O.I.

3/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Work OPC

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

AXA Insurance (S) Pte Ltd

To: _____

Accident Date : 17.02.2018

Not Authorized

61 Smg 8?

Recovery After Paint

4 days

Third Party

Policy No: _____

Date: 02.04.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 額 \$ cts.
Estimate Cost of Repair to "Chevrolet Cruze" Reg. No. SKK7060S Claiming Against Your Insured Veh. No. SJS2437S			
1pc	Rear Taillamp RH		585.00 X
1pc	Rear Bumper		1,152.00
12pcs	Rear Bumper Clips	3.00	36.00
1pc	Rear Bumper Side Holder RH		20.70
1pc	Rear Bumper Side Retainer		20.70
1pc	Rear Wheel Rim RH		756.00
1pc	Rear Shock Absorber RH		247.00 X
1pc	Rear Wheel Bearing		505.00 X
1pc	Rear Wheel Axle		2,784.00 X
			6,106.40
	Less 10%		610.64
			5,495.76
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair		280.00 R
	To Conduct Computerize Wheel Alignment Test		80.00 600
	Labour Charge - Panel Beating, Repairing Of Rear O/S Door, Rear Fender and Parts Replacement		550.00 400
	To Respray Affected Areas		700.00 600
	Total :		7,105.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6820C
Vehicle Details	
Vehicle No.:	SKK7060S
Vehicle to be Exported:	No
Intended De-registration Date:	19 Feb 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Primary Colour:	Grey
Manufacturing Year:	2013
Engine No.:	F16D4463645KA
Chassis No.:	KL1JA69E9DK151291
Maximum Power Output:	91.0 kW (122 bhp)
Open Market Value:	\$13,287.00
Original Registration Date:	22 Aug 2013
First Registration Date:	22 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$13,287.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18006099/mb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 03-04-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJS 2437S	Veh. Inspected	SKK 7060S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/02/2018	Inspection Date		
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

THIRD PARTY'S DISCHARGE AGREEMENT

Claim ref. : _____

To M/s : AXA INSURANCE PTE LTD

In consideration of your paying at my request to M/S CHEW GOON MOTOR of Blk 10
Ang Mo Kio Ind. Park 2A, #01-15, 16 & 17, Ave 5, Singapore 568047 the sum of Dollars
: TWO THOUSAND SEVEN HUNDRED AND FOUR ONLY

(\$ 2704.00) being cost of repair carried out to my/our motor vehicle no :
SKK7060S. All actions, claims and damages arising out of and, in
consequence of an accident occurring on 17.02.2018
at JUNCTION OF SERANGOON RD / MACPHERSON RD / PIE
between SKK7060S & SJS2437S

I/We furthermore agree that the foregoing sum is voluntarily accepted as full and final
compromise and settlement of all claims, that the payment of the said amount shall never
be construed as an admission of liability by the parties hereby reached.

Signature : 



Witness : _____



Name : WEE DAISY

Name : _____

NRIC No. : S1156820C

Date : _____

Address : BLK 931 TAMPINES ST 91 #03-481

S 520931

Date : 09.04.2018

WITHOUT PREJUDICE to:

- (a) Insurers' Subrogated Claim and/or
- (b) Any Personal Injury Claims

[Note: This Notice supersedes any inconsistencies
found in this Discharge Voucher]

C/O BLK 10 ANG MO KIO IND. PARK 2A
AVE 5, #01-15, 16 & 17 AMK AUTOPOINT
SINGAPORE 568047

DATE : 25.02.2019

THE MOTOR CLAIMS DEPARTMENT

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 058811

DEAR SIRs,

ACCIDENT ON : 17.02.2018
ALONG/AT : JUNCTION OF SERANGOON RD / MACPHERSON RD / PIE
INVOLVING : SKK7060S & SJS2437S

I/ We /am /are the registered owner of vehicle no. SKK7060S which was involved
in the above mentioned accident with your insured vehicle no. SJS2437S.

As the accident was caused due to the gross negligence on the part of your insured driver of
vehicle no. SJS2437S . I/we have no alternative but to look to you for
compensation for the losses sustained as a result of the above accident.

Presently, my/ our vehicle is lying at M/S CHEW GOON MOTOR of Blk 10, Ang Mo Kio
Industrial Park 2A, Ave 5, #01-15, 16 & 17 AMK Autopoint, Singapore 568047. Telephone
6484 1626. Kindly arrange to have it surveyed by your assessor, failing which I / we shall
authorised my/ our repairer to proceed on with the repairs and the final bills will be
forwarded to you for settlement.

Thank you.

Yours faithfully



Service Request Details

Claim
S8M0098V

Reference
None

Loss Date
February 17, 2018

Request Date
April 3, 2018

Due Date
April 10, 2018

LKK AUTO CONSULTANTS PTE LTD (TP)

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

03042018 @ 11.16pm
Enrol veh in.
Kenneth.

Actions

Next Step
Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #
SKK7060S

Make
TPVD CHEVROLET

Service Address

...

Primary Contact/Insured

SHACHIDRAN S/O RAMA CHANDERAN
48 BEDOK SOUTH AVENUE 3, #09-234, 460048, Singapore
93222439

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Re:RE: FILE REVIEW- PLS UPDATE CLAIM STATUS

Type

 Question

Message

PLS PROCEED AT 50/50.

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 05/02/2020

Survey Details:

Date of loss	17-Feb-18
Date of appointment	3-Apr-18
Date of survey	3-Apr-18
Location of survey	CHEW GOON MOTOR

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKK 7060S
Make and Model	CHEVROLET CRUZE
Date of registration	22/8/2013
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 7,105.76
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,786.86
Check items (estimate)	\$ -
Labour	\$ 1,060.00
Total	\$ 2,846.86
Lump Sum(if applicable)	\$ 1,900.00

Number of days for repair	4
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

04 RECOMMENDED REPAIR DAYS + 2PRS + 1SUNDAY + 1SATURDAY =
8DAYS

Mandate:

Liability(TP)	50%	
Proposed repair cost (W/GST)	\$	1,016.50
Loss of use	\$	240.00 8days x \$60
Loss of rental	\$	-
Loss of income	\$	-
LTA search fees	\$	31.00
Others	\$	-
Proposed Total	\$	1,287.50



<MANDATE IA> - S8M0098V {ACCIDENT INVOLVING
SJS 2437S (OI) & SKK 7060S (TP) ON 17/02/2018}

Type

Question

Message

LIABILITY: 50% BOLA: NIL (CONFLICTING VERSION) - INFORMED OI ABOUT TP CLAIM AND NCD
ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$1287.50 (CLAIMING LOU).
MANDATE IA HAS BEEN UPLOADED. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS
- CCL 05/02/2020

Reply

TAX INVOICE NO. 23870

Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint

Singapore 568047 Email: chewgoon@singnet.com.sg

Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

TEL: 6484 1626 (24Hrs) FAX: 6484 0465

◀ 修理各种汽车烧焊打吗咭喷漆等 ▶

ACCIDENT DATE : 17.02.2018

Date 25.02.2019

趙源摩哆
CHEW GOON MOTOR

Ch



**Re:<MANDATE IA> - S8M0098V {ACCIDENT INVOLVING
SJS 2437S (OI) & SKK 7060S (TP) ON 17/02/2018}**

Type

 Question

Message

PLS PROCEED

Reply

趙 源 摩 哆
Chew Goon Motor

新加坡宏茂桥第 2A 工业园第五道大牌十号门牌十五,十六,十七(一楼)及门牌五(三楼)

Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint

Singapore 568047

Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

TEL: 6484 1626 (24Hrs) FAX: 6484 0465

Date : 25.02.2019

◀ 修理各种汽车敲焊打吗咭喷漆等 ▶

Your Reference : SJS2437S

THE MOTOR CLAIM DEPARTMENT
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Dear Sir,

ACCIDENT ON : 17.02.2018

ALONG / AT : Junction Of Serangoon RD / Macpherson RD / PIE

INVOLVING : SKK7060S & SJS2437S

We wish to have a "Direct Settle" to the above matter.

We enclose herewith the following documents for your perusal and attention.

1. Final repair bill for \$2033.00 (Include GST)
2. Letter of Authority
3. Third Party Discharge Voucher
4. Motor Accident Report made by SKK7060S
5. Certificate of Insurance
6. Vehicle of Registration Log Card
7. Third Party Insure Enquiry Charges @\$2.00 (SJS2437S)
8. GIA Search Result Charges @\$29.00 (SJS2437S)
9. Loss of Use (8days X \$80/-) @\$640.00 (Surveyor Recommend 4D Working + Loss Of Use for 1D Pre-repair Inspec + 2D Weekend)
(In 02.04.2018 Out 09.04.2018)

Thank you.

Yours faithfully

.....

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18006099/Kga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 30-03-2020		
ATTN: STACEY NG		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJS 2437S	Veh. Inspected	SKK 7060S	
Policy No.	GA270740/1	Coverage (\$)	0.00	
Claim No.	S8M0098V	Excess (\$)	0.00	
Assign From		Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET CRUZE (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KL1JA69E9DK151291	Colour	METALLIC GREY	
Odometer	39212	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	9 mm	
L/H Front Tyre	205/60 R16	HANKOOK	9 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	8 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/02/2018	Inspection Date	03/04/2018	
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 7060S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILLAMP RH (CONSISTENT)	SERVICEABLE ✓	585.00 ✓	-
1	REAR BUMPER (CONSISTENT)	DENTED / MTG CRACKED ✓	1,152.00 ✓	1,152.00 ✓
12	REAR BUMPER CLIPS @\$3.00 (CONSISTENT)	NECESSARY ✓	36.00 ✓	36.00 ✓
1	REAR BUMPER SIDE HOLDER RH (CONSISTENT)	NECESSARY ✓	20.70 ✓	20.70 ✓
1	REAR BUMPER SIDE RETAINER (CONSISTENT)	NECESSARY ✓	20.70 ✓	20.70 ✓
1	REAR WHEEL RIM RH (CONSISTENT)	DENTED ✓	756.00 ✓	756.00 ✓
1	REAR SHOCK ABSORBER RH (CONSISTENT)	SERVICEABLE ✓	247.00 ✓	-
1	REAR WHEEL BEARING (CONSISTENT)	NOT NECESSARY ✓	505.00 ✓	-
1	REAR WHEEL AXLE (CONSISTENT)	SERVICEABLE ✓	2,784.00 ✓	-
	LESS 10% DISCOUNT		-610.64 ✓	-198.54 ✓
			5,495.76 ✓	1,786.86 ✓
LABOUR				
	TO DISMANTLE /REPLACE REAR UNDER CARRIAGE TO FACILITATE REPAIR.	NOT NECESSARY	280.00 ✓	-
	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST.		80.00 ✓	60.00 ✓
	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF REAR O/S DOOR ,REAR FENDER AND PARTS REPLACEMENT.		550.00 ✓	400.00 ✓
	TO RESPRAY AFFECTED AREAS.		700.00 ✓	600.00 ✓
			1,610.00 ✓	1,060.00 ✓
GRAND TOTAL			7,105.76 ✓	2,846.86 ✓
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00 ✓

Report Ref No. CC4/ASM18006099/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	50M0098V
Reference	CC4/ASM18006099/Kga3u2
Loss Date	17 February 2018
Report Date	3 Apr 2018 8:38:00 AM
Request Date	3 April 2018
Due Date	

Actions

Next Step: Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SKK70605
Make	TPVO CHEVROLET
Model	CRUZE-1.6 2WD (A)
Service Address	
...	

Vendor Name	LUK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Primary Contact/Insured	SHACHIDRAN S/O RAMA CHANDERAN 48 BEDOK SOUTH AVENUE 3, #09-23A, 460048, Singapore 93222439
-------------------------	--

Claim Handler	NG Stacey 6568804351 stacey.ng@axa.com.sg
---------------	---

Additional Instructions

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UNLOADED
Accident Statement	Reports & Statement		Merimen	

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKKInspection.pdf	Firms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKKAdjustment1a (1).pdf	Firms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 GIA SEARCH.pdf	Firms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Firms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 AUTHORIZATION TO ACT FORM.pdf	Firms / Claim Documents	PCA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 February 2020
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 February 2020
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 February 2020
 MANDATE (A DO 05022020).pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 February 2020
 PAIRF CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 February 2020
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 February 2020
 OI COUNTER CLAIM DV.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 October 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LXX AUTO CONSULTANTS PTE LTD (TP)	4 April 2018
 Preliminary Advice.pdf	Reports & Statement	Estimate / Quotation	LXX AUTO CONSULTANTS PTE LTD (TP)	4 April 2018
 EMAIL FROM WORKSHOP PRL.mig	Legal	Warrant to act	VISHNU BATHAM Shekhar	3 April 2018
 GJA SAK70605 TP.PDF	Reports & Statement	GJA Report	VISHNU BATHAM Shekhar	3 April 2018