

21000000

ASS. REC. BY:

REF: CS/MSG18006108 / Uqd3

Special Instructions:

Surveyor  
Meimen

Marcus

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk Pui

of

MSG

Date/Time:

3/4/18 @ 1:35pm

Estimated Cost:

Bill to:

OD ☒ IP WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIN 9986 E

Insured:

SGR 11754

at Workshop no/s

Pegasus Engineering

Tel:

6858 1846

of

51 Defu Lane 10

Policy No:

80427090QMX

Claim No:

554210

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/04/2018

CA / REV / REP. / REV 24 HRS

lwp

04/04/2018

03

H.O.D. Endorsement:

Date/Time:

2:20pm @ 3/4/18

Person Contacted:

Caymen

Vehicle

☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SIN 9986 E - X</u>
	<u>SGR 11754 - CS/MSG18006108 / lwb</u>
<u>06/4/18 @ 3:27PM</u>	<u>revised to Chhia Nyuk Pui via meimen.</u>

REF: MSIG

## ASSIGNMENT

From: Date: 5/4/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 9986E

at Workshop m/s: Pegasus Engineering  
of: 51 Defu Lane 10

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS'up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLN 9986E Yr Regn: 5-17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 41

Make: Toyota v.105 C.C. 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 2730 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MHYB29 3202011521

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-1 son 16  
R:BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal: 7 mm R/Bal: 7 mm

L/Bal: 7 mm L/Bal: 7 mm

D.O.A. 2/4/18 D.O.I. 5/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/4/18 Confirmed fuel by 3618.80 with San.  
(Ref # 1300.53, 2710)  
Lm 174

RECEIVED 13 APR 2018

Date/Time: File Pass to? ☐ : Preli. Report11/3/18 train ☐ : Final Report

Date/Time: File Return to?

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1 S + R1 S1

: Photos

: Other

TOTAL

Report Format: MER-70

Lump Sum / I.B.I.: 3618.00

Add Fee: ☐ Site Insp. \$☐ Interview \$☐ Tech Insp. \$☐ Neck-and \$

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2018		03 Apr 2018 13:35 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	WONG CHIN WEN, ID: S8822864B		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLN9986E	Date of Loss:	02/04/2018 11:00 - :59 [10 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 554210	Policy/Cover Note No.:	80427090QMX (Comprehensive) Coverage: 01/03/2017 - 30/07/2018
Vehicle Reg. No. (Insured):	SGR1175U	Policy No. (Claimant):	
		Excess:	
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/04/2018]		
Driver/Custodian (Insured):	WONG CHIN WEN (), NRIC: S8822864B		
Adj Asg. Remarks:	Vehicle is in, please survey today. Thank You.		

#### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18006108/Uqd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 03-04-2018		
		Code : MSG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGR 1175U	Veh. Inspected	SLN 9986E	
Policy No.	80427090QMX	Coverage (\$)	0.00	
Claim No.	554210	Excess (\$)	0.00	
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	03/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	02/04/2018	Inspection Date		
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chhia Nyuk Pul

Date: 06 Apr 2018

**Preliminary Advice**

Insured Vehicle No	: SGR1175U	Accident Date	: 02/04/2018
TP Vehicle No	: SLN9986E	Assignment Date	: 03/04/2018
Make	: TOYOTA VIOS	Est. Duration of Repair	: 6.00
Date of Inspection	: 05/04/2018		
Inspection At	: PEGASUS ENGINEERING & TRADING PTE LTD (HQ) 51 DEFU LANE 10 SINGAPORE 539216		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,918.88
Revised Amount	:S\$	3,906.78
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,906.78

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	7200G
<b>Vehicle Details</b>	
Vehicle No.:	SLN9986E
Vehicle to be Exported:	Yes
Intended De-registration Date:	02 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2NRX156585
Chassis No.:	MHFB29F3202011521
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,855.00
Original Registration Date:	24 May 2017
First Registration Date:	24 May 2017
Transfer Count:	0
Actual ARF Paid:	\$7,855.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 May 2027
PARF Rebate Amount:	\$5,891.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$41,600.00
<b>Total Rebate Amount:</b>	<b>\$47,491.00</b>

The information contained herein is correct as at 02 Apr 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/04/2018 18:25
Date Of Accident	02/04/2018 12:10
Exact Location Of Accident	AYE TOWARDS CITY NEAR EXIT 7B
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN9986E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68014188

### Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

### Driver

Name of Driver	LU JIE
NRIC No	S8923127B
Date Of Birth	10/07/1989
Occupation	OUTDOOR
Date Of Driving Pass	07/07/2009
Driving Experience	8 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98765432
Fax Number	
Contact Number	
EMail Address	LUJIE@HOTMAIL.COM

Address	80 ELIAS ROAD #05-06
Postcode	519945
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : FIANCEE GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PAYA LEBAR NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 114 HOUGANG AVENUE 1 #01-1270 , POSTCODE: 530114 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2899999 - FAX NO: 62815961
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer to Police report T/20180402/2122

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGR1175U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	EDDIE
NRIC/Passport Number	
Contact Number	87223438
Address	



Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number FB4447J  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category MOTORCYCLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? FB4447J  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? YES  
Address  
Postcode



### SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report  
7/20180402/2122

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 02.04.2018 @ 14:08 hrs

Reporting Centre Personnel's Signature  
Name: Law KPI Shun  
NRUC/FIN No.: G6864052R

**SINGAPORE  
POLICE FORCE**


T/20180402/2122

1 of 3

Police Station Of Origin:

Paya Lebar NPP

114 Hougang Avenue 1 #01-1270

SINGAPORE 530114

Tel No: 1800-2899999

Report No. T/20180402/2122

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/04/2018 16:54	Vide Report No.:	Station Diary No.: 38
--	------------------	--------------------------

## Informant's Particulars

Name of Informant: LU JIE	Address: 80 ELIAS ROAD #05-06 SINGAPORE 519945		
ID Type / ID No.: NRIC NO / S8923127B	Contact No.: Home/Office: Mobile: 98328385		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 28	Date of Birth: 10/07/1989	Type of Informant: Driver
Race: Chinese	Language:		Institution / School Name:
Occupation: Student	Driving Licence Information: Class: 3 Date of Expiry:		

## General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 02/04/2018 12:05	Type of Location:
Location: Along Road 1 CENTRAL EXPRESSWAY  Along AYE towards CTE				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SGR1175U	Car				Slightly Damaged	0
SLN9986E	Car				Slightly Damaged	1



**SINGAPORE  
POLICE FORCE**



T/20180402/2122

Police Station Of Origin:  
Paya Lebar NPP  
114 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2899999

2 of 3

Report No. T/20180402/2122

**CONTINUATION OF REPORT**

**Brief Details.**

On 02/04/2018 at about 1205hrs, I was driving along AYE towards CTE in my vehicle (SLN 9986E). I wish to state that everything was in order.

As I was following through the traffic, the vehicle in front of me stopped suddenly without notice, I was able to brake and stop in time. The vehicle at my rear (SGR 1175U) collided onto me which caused the whole accident. I wish to state that another motorcyclist was also involved in the accident however, I did not managed to take a clear photo of the registration plate number.

I wish to state that both driver's came down and exchanged particulars, currently there were no visible injuries inflicted on myself and my passenger. This report is for record and insurance purposes. I wish to state that the motorcyclist was injured, I had a passenger with me and that my vehicle suffered damages which was located the left rear headlight, the bumper was damaged.



**SINGAPORE  
POLICE FORCE**



T/20180402/2122

Police Station Of Origin:  
Paya Lebar NPP  
114 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2899999

3 of 3

Report No. T/20180402/2122

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F/ Sgt 1 ONG YU HAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/04/2018 16:54
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No: 65476430	Classification Of Case:
Authentication Stamp NP158 Signature: Singapore Police Force	

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

Not Authored

**From :**  
PEGASUS ENGINEERING & TRADING PTE LTD  
C/O 51 DEFU LANE 10  
539216  
Officer in Charge : ALVIN LOW WAI LUN  
Tel :  
Email :

**Customer :**  
GRAB RENTALS PTE LTD  
18 SIN MING LANE  
#01-08 MIDVIEW CITY  
SINGAPORE 573960  
Attn :  
Tel :  
Fax :  
6/4/18 2/2 3618.80

Quotation No : QO18/04-1011	Quotation Date : 02/04/2018	Terms : 30 DAYS
Vehicle No : SLN9986E	Chassis No : MHFB29F3202011521	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: MSIG, INSURED'S VEHICLE NO: SGR1175U, DATE OF ACCIDENT: 02.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID	3 set / 3 set	270.0000	✓ 270.00
2	BOOTLID VIOS BADGE	1 set	25.0000	20 25.00 ✓
3	BOOTLID CENTRE EMBLEM BADGE	1 set	25.0000	30 25.00 ✓
4	BOOTLID E BADGE	1 set	18.0000	15 18.00 ✓
5	BOOTLID LOCK	1 set	40.0000	- 40.00 ✓
6	BOOTLID LOCK STRIKER	1 set	10.0000	10.00 X
7	BOOTLID WEATHERSTRIP	1 set	70.0000	- 70.00 ✓
8	BOOTLID HINGE	2 set	30.0000	60.00 X
9	REAR END PANEL	1 set	250.0000	- 250.00 ✓
10	REAR END PANEL INNER TRIM	1 set	100.0000	105 100.00 ✓
11	REAR BUMPER	1 set	200.0000	✓ 200.00 ✓
12	REAR BUMPER REINFORCEMENT	1 set	135.0000	✓ 135.00 ✓
13	REAR BUMPER SIDE RETAINER	1 set	55.0000	45 110.00 100
14	REAR BUMPER SIDE RETAINER HOLDER	1 set	25.0000	10 50.00 100
15	N/S REAR BUMPER REFLECTOR	1 set	261.5000	60 261.50 ✓
16	REAR BUMPER CLIPS	6 set	1.5000	9.00 X
17	N/S REAR BUMPER END SPLASHIELD COVER	1 set	30.0000	30.00 X
18	N/S REAR LAMP	1 set	105.0000	- 105.00 ✓
19	REAR LAMP CLIP HOLDER	2 set	2.0000	4.00 X
20	N/S REAR LAMP	1 set	70.0000	70.00 X
21	MARK UP 15% ITEM (1-20)	1	276.3800	276.38
22	REAR BUMPER PARKING SENSOR	2 set	250.0000	132 500.00
23	TO RUST-PROOFING OF THE AFFECTED AREAS	1	150.0000	60 150.00

rear air vent n/s one ✓ 25

C/F 0.00

Page 1 of 2

p-1512  
plus 15%  
1772.00

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b>  <b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> C/O 51 DEFU LANE 10 539216  Officer in Charge : ALVIN LOW WAI LUN Tel : Email :
---

<b>Customer :</b>  <b>GRAB RENTALS PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960  Attn : Tel : Fax :
---

Quotation No : QO18/04-1011	Quotation Date : 02/04/2018	Terms : 30 DAYS
Vehicle No : SLN9986E	Chassis No : MHFB29F3202011521	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: MSIG, INSURED'S VEHICLE NO: SGR1175U, DATE OF ACCIDENT: 02.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	20 60.00
25	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	50 120.00
26	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	1	120.0000	50 120.00
27	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	950.0000	850 950.00
28	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	900.0000	850 900.00

1880

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Sub Total	4,918.88
GST(7.00%)	344.32
<b>Total (SGD)</b>	<b>5,263.20</b>

Please conduct the survey at  
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

4129.13





# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b>  <b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> C/O 51 DEFU LANE 10 539216  Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	<b>Customer :</b>  <b>GRAB RENTALS PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960  Attn : Tel : Fax :
---	---

Quotation No : QO18/04-1123	Quotation Date : 10/04/2018	Terms : 30 DAYS
Vehicle No : SLN9986E	Chassis No : MHFB29F3202011521	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : SUPPLEMENTRY , TP INSURER: MSIG, INSURED'S VEHICLE NO: SGR1175U, DATE OF ACCIDENT: 02.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	AIR VENT NET	1	25.0000	25.00
2	MARK UP 15%(ITEM 1)	1	3.7500	3.75

<b>Sub Total</b>	28.75
<b>GST(7.00%)</b>	2.01
<b>Total (SGD)</b>	30.76

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



**MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403**

TEL: 6291 2827 FAX: 6296 4390

**A/C: 6291 1886 FAX: 6291 7717**

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

## TAX INVOICE

M/S: PEGASUS ENGINEERING & TRADING PTE LTD ✓

51, DEFU LANE 10  
SINGAPORE 539216

NSP151 (SLN 9986E)  
ATT:AH HWA

NO: DLI9201632

PAGE: 1

DATE: 05/04/2018

A/C CODE: LDPE001

TERMS: CR

P/O NO: SLN 9986E

5/4/18  
SM 201804017












### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2018		03 Apr 2018 13:35 <a href="#">Edit Adj Rpt</a>	<b>S\$3,618.80</b> <a href="#">Edit Estimates</a>	<b>S\$3,618.80</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>


















































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>WONG CHIN WEN</b> , ID: S8822864B								
Main Claimant:	<b>GRAB RENTALS PTE LTD</b> , Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	<b>SLN9986E</b>	Date of Loss:	02/04/2018 11:00 - :59 [10 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 554210</b>	Policy/Cover Note No.:	80427090QMX (Comprehensive) Coverage: 01/03/2017 - 30/07/2018						
Vehicle Reg. No. (Insured):	<b>SGR1175U</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Pegasus Engineering &amp; Trading Pte Ltd (HQ)</b> 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 03/05/2018]								
Driver/Custodian (Insured):	WONG CHIN WEN (), NRIC: S8822864B								
Adj Asg. Remarks:	Vehicle is in. please survey today. Thank You.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLN9986E (554210)  
[SGR1175U]  
TP  
GRAB RENTALS PTE LTD  
Apr 2 2018 11:00AM  
[WONG CHIN WEN]  
Pegasus Engineering & Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	06/04/18 15:07	Adjuster Immediate Advice									Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
2	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
3	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
4	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
5	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
6	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
7	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
8	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
9	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
10	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
11	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
12	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
13	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
14	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
15	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
16	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
17	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
18	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
19	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
20	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
21	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
22	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
23	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
24	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
25	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
26	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
27	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
28	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
29	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
30	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
31	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
32	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
33	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	
34	05/04/18 15:09	General View									Load JPG <input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
38	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
39	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
40	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
41	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
42	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
43	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
44	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
45	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
46	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
47	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
48	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
49	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
50	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
51	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
52	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
53	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
54	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
55	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
56	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
57	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
58	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
59	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
60	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
61	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
62	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
63	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
64	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
65	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
66	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
67	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
68	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
69	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
70	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
71	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
72	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
73	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
74	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
75	05/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
76	07/04/18 12:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	07/04/18 12:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	07/04/18 12:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	07/04/18 12:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	07/04/18 12:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	07/04/18 12:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	07/04/18 12:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	07/04/18 12:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	07/04/18 12:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	07/04/18 12:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	07/04/18 12:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	07/04/18 12:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	07/04/18 12:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	07/04/18 12:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/04/18 12:38	SLN9986E E-FILE REPORT	 Load PDF	
2	03/04/18 12:38	TP ESTIMATE	 Load PDF	
3	03/04/18 12:39	TP PRI Request	 Load PDF	
4	03/04/18 12:40	OI SGR1175U E-FILE REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG18006108/UQD3Q2  
**Date:** 17/04/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 80427090QMX
Claimant Vehicle No: SLN9986E	Insured Vehicle No: SGR1175U
Date of Loss: 02/04/2018	Nature of Claim: TP Claim No: 554210

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SLN9986E</b>	Engine No: 2NRX156585
Make & Model: TOYOTA VIOS, 1.5 E (A)	Chassis No: MHFB29F3202011521
Reg. Date: 24/05/2017 (Man. Year: 2017)	Odometer: 52730 km
Colour: Silver	
Engine Capacity: 1496 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): <b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size: 195/50 R16	Rear Tyre Size: 195/50 R16
Front Left Side: Bridgestone 7 mm	Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm	Rear Right Side: Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,734.13	1,738.80	995.33	36.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,880.00	420.00	18.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,034.13</b>	<b>3,618.80</b>	<b>1,415.33</b>	<b>28.11</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>352.39</b>	<b>253.32</b>	<b>99.07</b>	<b>28.11</b>
<b>Nett Amount (S\$)</b>	<b>5,386.52</b>	<b>3,872.12</b>	<b>1,514.40</b>	<b>28.11</b>

### INSPECTION

Date of Assignment:	03/04/2018	
Date Inspected:	05/04/2018 Inspected At:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10 Singapore 539216
Estimated Period of Repair:	6.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2018)
<b>Parts:</b>	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLN9986E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	270.00 F	*270.00 F
2	1		*BOOTLID VIOS BADGE	Necessary	25.00 F	*20.00 F
3	1		*BOOTLID CENTRE EMBLEM BADGE	Necessary	30.00 F	*30.00 F
4	1		*BOOTLID BADGE	Necessary	18.00 F	*15.00 F
5	1		*BOOTLID LOCK	Twisted	40.00 F	*40.00 F
6	1		*BOOTLID LOCK STRIKER	Not Necessary	10.00 F	*- F
7	1		*BOOTLID WEATHERSTRIP	Twisted	70.00 F	*70.00 F
8	2		*BOOTLID HINGE	Repair	60.00 F	*- F
9	1		*REAR END PANEL	Badly Dented	250.00 F	*250.00 F
10	1		*REAR END PANEL INNER TRIM	Twisted	105.00 F	*105.00 F
11	1		*REAR BUMPER	Distorted	200.00 F	*200.00 F
12	1		*REAR BUMPER REINFORCEMENT	Bent	135.00 F	*135.00 F
13	1		*REAR BUMPER SIDE RETAINER	N/S Cracked	110.00 F	*45.00 F
14	1		*REAR BUMPER SIDE RETAINER HOLDER	N/S Cracked	50.00 F	*10.00 F
15	1		*N/S REAR BUMPER REFLECTOR	Cracked	261.50 F	*60.00 F
16	6		*REAR BUMPER CLIPS	Not Necessary	9.00 F	*- F
17	1		*N/S REAR BUMPER END SPLASHIELD COVER	Not Necessary	30.00 F	*- F
18	1		*N/S REAR LAMP	Cracked	105.00 F	*105.00 F
19	2		*REAR LAMP CLIP HOLDER	Not Necessary	4.00 F	*- F
20	1		*N/S REAR LAMP	Repeated	70.00 F	*- F
21	2		*REAR BUMPER PARKING SENSOR	Shorted	500.00 F	*132.00 F
22	1		*REAR AIR VENT N/S	Cracked	25.00 F	*25.00 F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>2,377.50</b>	<b>1,512.00</b>
<b>+ Margin on L,N Items 15.00/15.00% (\$\$)</b>	<b>356.63</b>	<b>226.80</b>
<b>Total Parts (\$\$)</b>	<b>2,734.13</b>	<b>1,738.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	60.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
4	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	120.00	50.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	950.00	850.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	900.00	850.00
<b>Gross Labour Cost (S\$)</b>			<b>2,300.00</b>	<b>1,880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >