

106/11/13

Surveyor: Kalvin

REF: CC3 / TML18006122 / K1602

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspected Vehicle No: _____
at Workshop m/s _____
of _____
Insured: SLH 5866G
Policy No: M1001519
Claims No: M1801935
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 33465 Yr Regn: 24 / 26
Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~o~~ / Prime Mover /
Truck / Trailer or _____
Make: Hyundai C.C. 1685
Colour: Blue A/C: Ins~~ured~~ / Std / NI / NA
Sp. Reading: 178052 T/Radio: Ins~~ured~~ / Std / NI / NA
Eng/No: _____
C/No: KMHCB414M64092187
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD / Rim or
Tyre Size: F: 205 / 60 R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hyundai
Front _____ Rear _____
R/Bal. 7 mm R/Bal. 7 mm
L/Bal. 7 mm L/Bal. 7 mm
D.O.A. 2/4/8 D.O.I. 3/4/8
Survey held at Cole (67mm)
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
o/s B.o.f.
The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time	Action / Instruction
	<u>SHD 33465 - CC3 / LCR18001358 / K1603</u>
	<u>SLH 5866G - x</u>
<u>9/4/8</u>	<u>Conduct P/P \$313.620 / 3 Pp. (Used \$2040.48, 39%)</u>

RECEIVED 09 APR 201

Date/Time, File Pass to? ☐ : Preli. Report
1) 07/4/2008 ☐ : Final Report

Date/Time, File Return to?
2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
Photos _____
Others _____

Report Format: 78
Lump Sum / L.B. (\$ 3136.20)

250
10
260

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD

Ref : CC3/TMI18006122/K1qb

20 MCCALLUM STREET #09-01

TOKIO MARINE CENTRESINGAPORE 069046

Date : 03-04-2018



Code : TMI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 5866G	Veh. Inspected	SHD 3346S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/04/2018	Inspection Date	03/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/04/2018 10:25
Date Of Accident	02/04/2018 22:20
Exact Location Of Accident	PUGGOL CENTRAL X PUNGGOL EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3346S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	ONG PANG MING
NRIC No	S7219678C
Date Of Birth	03/06/1972
Occupation	OUTDOOR
Date Of Driving Pass	13/05/1999
Driving Experience	18 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	STEVENO72@YAHOO.COM.SG

Address	BLK 604C PUNGGOL ROAD #13-736
Postcode	823604
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG5866G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG YIN WEN
NRIC/Passport Number	S9009685J
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	WHOLE LEFT SIDE

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO REG NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/4/18 at about 2220hr while I Veh A was making a right turn onto Punggol East within my lane, Veh B from the lane on my right ^{side} lane intercepted into my lane abruptly causing a collision that damaged the right front portion of my vehicle. The ^{damage} stretched towards the whole right front side ^{door} of my vehicle.

DECLARATION




I/We declare the foregoing particulars are true in every respect.
COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NPIC/FIN No.:

SR Moorthy
SO
3/4/18





am: ARC Repair TP(CLSO)1 **JOB CARD** Sales Order: 3815003 JC NO305138036

COMER IS COMFORT TRANSPORTATION PTE LTD OMER NO. 7010045 RESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) OUNT CARD NO.	REGN NO.: SHD3346S	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 02.04.2018 22:20
	YR OF MANU. 21.07.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMGU092187	COMPLETION DATE/TIME:

JOB DESCRIPTION


ccident Date: 02.04.2018
ATURE: 3P 02.04.18

/NO	LABOR CODE	DESCRIPTION
00010	23-01	TOWING FEE

CKED & PASSED OUT BY: _____

_____ SERVICE ADVISOR	_____ CUSTOMER'S SIGNATURE
--------------------------	-------------------------------

Acknowledgement Slip		Exit Pass	
No.: SHD3346S	FZ TOKIO LKK	Vehicle No.: SHD3346S	
_____ if Service Advisor	_____ Signature/Date	_____ Name of Service Advisor	_____ Date
Returned to Service Reception upon collection		To be kept by Security Guard	



REPAIR ESTIMATE*

VEHICLE NO : SHD 3346S

DATE 3/4/2018 11:42

MAKE :

Han Kook

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover — <i>Detail</i>			\$ 562.30	
	Front Bumper Bracket Top (RH) <i>Xone</i>			\$ 22.40	
	Front Bumper Side Bracket <i>Xone</i>			\$ 14.30	
	Front Door (RH) <i>X 149.00</i>			\$ 1,403.00	
	Rear Door (RH) — <i>Detail</i>			\$ 1,351.00	
	Front Wheel Hub Cap (RH) — <i>492.70</i>			\$ 150.70	
	SUB TOTAL			\$ 3,503.70	
	LESS 20%			\$ 700.74	
	DISCOUNTED TOTAL			\$ 2,802.96	
	Front Door Comfort Logo (RH) — <i>all</i>			\$ 75.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) — <i>all</i>			\$ 80.00	Nett
				\$ 155.00	
	Labour Charge				
	Panel Beating-Repair Fender			\$ 750.00 <i>400</i>	
	Spray Painting Charge-Doorx2,Mirror/Fender/Bumper			\$ 1,100.00 <i>800</i>	
	Wiring Charge			\$ 50.00 <i>X 1.1</i>	
	Tuff Kote			\$ 50.00 <i>20</i>	
	Towing Fees			\$ 50.00	
	Transfer of Door			\$ 120.00 <i>50</i>	
	Frt Wheel Alignment			\$ 80.00 <i>X 1.1</i>	
	<i>Murim Fee \$10</i>				
	TOTAL LABOUR			\$ 2,200.00	
	ESTIMATE TOTAL			\$ 5,157.96	

Kalvin (LKK)
 3/4/18 1515 hrs.
 3 Days
 P/P
 Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/04/2018
Vehicle Reg. No.:	SHD3346S	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	21/07/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDGU660005	Chassis No:	KMHLB41UMGU092187
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,966.68
Miscellaneous Items	10.00
Labour	2,200.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,176.68
+ GST 7.00% (S\$)	362.37
Nett Amount (S\$)	5,539.05

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2018)
 Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: **ComfortDelGro Engineering Pte Ltd/SHD3346S/03/04/2018 15:00**
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY	20.00	0.00	*562.30 FL <i>pe</i>
2	1		*FRT BUMPER BRACKET TOP RH	20.00	0.00	*22.40 FL <i>gvc</i>
3	1		*FRT BUMPER SIDE BRACKET RH	20.00	0.00	*24.60 FL <i>gvc</i>
4	1		*FRT DOOR RH	20.00	0.00	*1,403.00 FL <i>xR</i>
5	1		*REAR DOOR RH	20.00	0.00	*1,351.60 FL <i>bd</i>
6	1		*FRT WHEEL HUB CAP RH	20.00	0.00	*150.70 FL <i>GPA</i>
7	1		*FRT DOOR COMFORT LOGO RH	0.00	0.00	*75.00 F <i>ncl</i>
8	1		*REAR DOOR COMFORTDELGRO & APPS STICKER RH	0.00	0.00	*80.00 F <i>ncl</i>
Sub Total (S\$)						3,669.60
- List Item Discount on L Items (S\$)						702.92
Total Parts (S\$)						2,966.68

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHD3346S/03/04/2018 15:00. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

10.00

Sub Total (S\$)

10.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

40

750.00

2 SPRAYPAINT

New

800

1,100.00

3 WIRING

New

50.00 x 70

4 TUFF KOTE

New

70

50.00

5 TRANSFER DOOR PARTS

New

80

120.00

6 FRT WHEEL ALIGNMENT

New

80.00 x 70

50.00

TOWING

Gross Labour Cost (S\$)

2,200.00

ComfortDelGro Engineering Pte Ltd/SHD3346S/03/04/2018 15:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Accident



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE


Job Requisition

1. Date: 2/4/18 Time Received: 2240		3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)		4. Type of Towing: <input checked="" type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up	
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer: ONG Contact No.: SH3346S Vehicle No.: 8609 8693 Make / Model / Colour: J-40 Email:		5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery		6. Parts Replaced/Remarks:	
7. Location: 50 punggol East Main Road		8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input checked="" type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi			
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others:					

10. Odometer Reading :
 Fuel Level : F 1/4 1/2 3/4 E

11. Radio / CD Player

☐ OK
☐ Faulty
☐ Not tested



: Cracked X : Dented
 / : Scratched O : Missing

Signature of Customer

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☒ QA ☐ GAO ☐ TZ ☐ YISHUN ☐ OTHERS
 Name of Driver : SAM
 Vehicle No. : JN39760
 Time Dispatch : 2240
 Time of Arrival : 2310
 Time Completed : 2335

Cash Invoice Details (if applicable)

13. Cash Invoice No. :

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
 b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
 c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

2/4/18

Date

2310

Time

Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

CUSTOMER'S COPY

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 06.04.2018

Time: 18:10:44

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305138036
REGN NO : SHD3346S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 21.07.2016
DATE/TIME IN : 02.04.2018 22:20
ACCIDENT DATE : 02.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,330.00

TOTAL : 3,136.20

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305138036
Date : 06.03.2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No : SHD3346S

Fax :

Date of Accident : 02.04.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: TOKIO MARINE --- SLG5866G
2. The finalized amount shall be:
- | | |
|-------------------------------------------|-------------------|
| (a) Spare Parts after List discount | \$1,806.20 |
| (b) Labour Charges | \$1,330.00 |
| Total for Part-By-Part Repair Cost | \$3,136.20 |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | 20% \$0.00 |
| Final Lumpsum Repair cost | \$0.00 |


3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : FAUZY BIN MOKHTAR
Tel : 62148319
Fax : 65468156

Signature : 
Name : K. L. N.
Date : 9/4/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 06.04.2018
Time: 18:10:44
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305138036
REGN NO : SHD3346S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 21.07.2016
DATE/TIME IN : 02.04.2018 22:20
ACCIDENT DATE : 02.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	562.30	20.00	449.84
0002 04-01-0103-0595-G	I40VC PANEL ASSY-RR DR RH	1	1,351.00	20.00	1,080.80
0003 04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	150.70	20.00	120.56
0004 28-01-0103-0003-A	(I40)FRT DOOR LOGO SONATA	1	75.00	2.00-	75.00
0005 28-01-0103-2013-A	I40V3 APP LOGO REAR DOOR	1	80.00	0.20	80.00

SUB-TOTAL : 1,806.20

JOB NATURE

0000 23-01	TOWING FEE	50.00
0001 L	PANEL BEATING	400.00
0002 L	SPRAY PAINTING CHARGE	800.00
0003 L	TUFF KOTE	20.00
0004 L	TRANSFER OF DOOR	50.00
0005 L	MERIMEN FEE	10.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18006122/K1QBN2

Date: 10/04/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI001519
Claimant Vehicle No :	SHD3346S	Insured Vehicle No :	SLG5866G
Date of Loss:	02/04/2018	Nature of Claim:	TP
		Claim No:	M1801735

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3346S	Engine No:	D4FDGU660005
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU092187
Reg. Date:	21/07/2016 (Man. Year: 2016)	Odometer:	178052 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,966.68	1,806.20	1,160.48	39.12
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	2,200.00	1,320.00	880.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,176.68	3,136.20	2,040.48	39.42
+ GST 7.00/7.00% (S\$)	362.37	219.53	142.84	39.42
Nett Amount (S\$)	5,539.05	3,355.73	2,183.32	39.42

INSPECTION

Date of Assignment:	03/04/2018	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	03/04/2018	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2018)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3346S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT BUMPER ASSY	Deformed	562.30 FL	*562.30 FL
2	1	*FRT BUMPER BRACKET TOP RH	Serviceable	22.40 FL	*- FL
3	1	*FRT BUMPER SIDE BRACKET RH	Serviceable	24.60 FL	*- FL
4	1	*FRT DOOR RH	Repair	1,403.00 FL	*- FL
5	1	*REAR DOOR RH	Dented	1,351.60 FL	*1,351.00 FL
6	1	*FRT WHEEL HUB CAP RH	Cracked	150.70 FL	*150.70 FL
7	1	*FRT DOOR COMFORT LOGO RH	Necessary	75.00 F	*75.00 FS
8	1	*REAR DOOR COMFORTDELGRO & APPS STICKER RH	Necessary	80.00 F	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,669.60	2,219.00
- List Item Discount on L Items 20.00/20.00% (S\$)	702.92	412.80
Total Parts (S\$)	2,966.68	1,806.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	400.00
2	SPRAYPAINT	New	1,100.00	800.00
3	WIRING	New	50.00	-
4	TUFF KOTE	New	50.00	20.00
5	TRANSFER DOOR PARTS	New	120.00	50.00
6	FRT WHEEL ALIGNMENT	New	80.00	-
7	TOWING	New	50.00	50.00
Gross Labour Cost (S\$)			2,200.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >