



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD

Ref : CC3/TMI18006125/K1rb

20 MCCALLUM STREET #09-01

TOKIO MARINE CENTRESINGAPORE 069046

Date : 03-04-2018



Code : TMI

1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SLV 4855R	Veh. Inspected	SHC 2917G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	29/03/2018	Inspection Date	03/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

COMFORT
PTE LTD

COMFORT

Date/Time: 03.04.2018 10:10 Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305137859

OMER
S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

REGN NO: SHC2917G	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL SONATA	DATE/TIME IN 03.04.2018 09:30
YR OF MANU. 27.01.2011	TARGET DATE
CHASSIS CODE KMHE141VMAA803654	COMPLETION DATE/TIME:

UNT CARD NO.

JOB DESCRIPTION

cident Date: 29.03.2018
TURE: 3P 29.03.18

NO LABOR CODE DESCRIPTION

WETUAKE

KED & PASSED OUT BY: _____

SERVICE ADVISOR CUSTOMER'S SIGNATURE

edgement Slip	Exit Pass
No.: SHC2917G JU TOKIO LKK	Vehicle No.: SHC2917G
Service Advisor	Name of Service Advisor
Signature/Date	Date
turned to Service Reception upon collection	To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/03/2018 09:18
Date Of Accident	29/03/2018 22:00
Exact Location Of Accident	CLEMENTI ROAD.(SIM BUS STOP)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC2917G
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	TOH CHIN HOCK (ZHUO QINGFU)
NRIC No	S7111448A
Date Of Birth	16/04/1971
Occupation	OUTDOOR
Date Of Driving Pass	18/08/2003
Driving Experience	14 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	AMOSTCH@GMAIL.COM

Address	BLK 178 BUKIT BATOK WEST AVENUE 8 #04-227
Postcode	650178
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV4855R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	LEFT FRT
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303824R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

31/3/18
Jackson Hong
CSO

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/3/2018 at about 2200hrs, I vehicle A was driving along Claude road (31m bus stop). While I was on the left lane of three lane. Vehicle B suddenly dash out from the bus stop.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time:

GIARMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)




Date & Time:


31/3/18
Jackson Heng
CSO

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:





ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)  **Jumani**
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	NO	Date of Loss:	29/03/2018
Vehicle Reg. No.:	SHC2917G	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI SONATA, 2.0 CRDI (A)	Vehicle Reg. Date:	27/01/2011
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4EAA929640	Chassis No:	KMHET41VMAA803654
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	2,114.56
Miscellaneous Items	10.00
Labour	900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,024.56
+ GST 7.00% (S\$)	211.72
Nett Amount (S\$)	3,236.28

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2018)**Parts:** 143 HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC2917G/03/04/2018 12:26**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY — <i>Pchd</i>	20.00	0.00	*538.80 FL
2	1		*FRT BUMPER PROTECTOR LH <i>X ngn</i>	20.00	0.00	*29.20 FL
3	1		*FRT BUMPER BRACKET LH <i>Run</i>	20.00	0.00	*20.10 FL
4	1		*FRT BUMPER SIDE BRACKET LH <i>Run</i>	20.00	0.00	*14.30 FL
5	1		*HEADLAMP ASSY LH — <i>hngsd</i>	20.00	0.00	*797.90 FL
6	1		*FRT FENDER LH — <i>Pchd</i>	20.00	0.00	*593.00 FL
7	1		*FRT FENDER SHIELD LH <i>Run</i>	20.00	0.00	*86.00 FL
8	1		*FRT FENDER RETAINER LH <i>Run</i>	20.00	0.00	*9.20 FL
9	1		*FRT WHEEL RIM <i>Run</i> — <i>Pchd</i>	20.00	0.00	*284.70 FL
10	1		*FRT WHEEL HUB CAP LH — <i>hngsd</i>	20.00	0.00	*145.00 FL
11	1		*FRT FENDER ADVERTISEMENT LOGO — <i>me</i>	0.00	0.00	*100.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) **2,618.20**- List Item Discount on L Items (S\$) **503.64**Total Parts (S\$) **2,114.56**

ComfortDelGro Engineering Pte Ltd/SHC2917G/03/04/2018 12:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

19 85-88

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	300 400.00
2	SPRAYPAINT	New	360 400.00
3	WIRING	New	20 50.00
4	TUFF KOTE	New	20 50.00
Gross Labour Cost (S\$)			900.00

ComfortDelGro Engineering Pte Ltd/SHC2917G/03/04/2018 12:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

K. G. 10/10/18
3/4/18 1425
300
400
After Repair ph

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary damage must be resurveyed and is subject to final approval from insurer's company

Acknowledged by Repairer
Signature:
Date:

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199508048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

(SUPPLEMENTARY)

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MG000530	Date of Loss:	29/03/2018
Vehicle Reg. No.:	SHC2917G	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI SONATA, 2.0 CRDI (A)	Vehicle Reg. Date:	27/01/2011
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4EAA929640	Chassis No:	KMHET41VMAA803654
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	542.12
Miscellaneous Items	0.00
Labour	270.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	812.12
+ GST 7.00% (S\$)	56.85
Nett Amount (S\$)	868.97
+ Previous Estimates (S\$)	3,236.28
Claim Total (S\$)	4,105.25

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2018)
Parts:	143	HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHC2917G/06/04/2018 11:18	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

N.o.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT LOWER ARM LH <i>- Det</i>	20.00	0.00	*250.45 FL
2	1		*FRT BALL JOINT LH <i>- Det</i>	20.00	0.00	*87.70 FL
3	1		*STREERING TIE ROD LH <i>- Det</i>	20.00	0.00	*69.50 FL
4	1		*TYRE FRT LH <i>- 50%</i>	0.00	0.00	*216.00 F <i>108</i>

F=Franchise part. L=List Item Disc.

Sub Total (\$\$)	623.65
- List Item Discount on L Items (\$\$)	81.53
Total Parts (\$\$)	542.12

ComfortDelGro Engineering Pte Ltd/SHC2917G/06/04/2018 11:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REMOVE/RENEW FRT SUSPENSION DAMAGED PARTS	New	150.00 150
2	ADJUST FRT WHEEL ALIGNMENT	New	120.00 60
Gross Labour Cost (S\$)			270.00

ComfortDelGro Engineering Pte Ltd/SHC2917G/06/04/2018-11:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305137859

Date : 06/04/18

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHC2917G

Date of Accident : 29.03.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- SLV4855R
###

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges ###

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$2,550.00

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : Kalvin

Date : 9/4/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

...CLAIM SUBFOLDER...(Pending for Survey Report)



































Pre-Repair Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Apr 2018 12:19 Sendback Est	03 Apr 2018 12:26 \$3,024.56 Edit Adj Rpt	03 Apr 2018 16:41 Edit Estimates	\$2,550.00 View Rpt	\$2,550.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	06 Apr 2018 11:02	06 Apr 2018 11:18 \$812.12	06 Apr 2018 11:18			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	CTPL, Co. Reg. No.: 199303821R								
Main Claimant:	CTPL								
Vehicle Reg. No.:	SHC2917G	Date of Loss:	29/03/2018 21:00 - :59 [86 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1801669	Policy/Cover Note No.:	MG000530 (Comprehensive) Coverage: 10/06/2017 - 09/06/2018						
Vehicle Reg. No. (Insured):	SLV4855R	Policy No. (Claimant):							
		Excess:	\$1,800.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 12/04/2018]								
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHC2917G (M1801669)
[SLV4855R]
TP
CTPL
Mar 29 2018 9:00PM
[CTPL]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View In Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	03/04/18 12:26	Repairer Estimates	 Load HTM	
2	06/04/18 11:18	Repairer Estimates Suppl. #1	 Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	03/04/18 16:41	Accident Statement From: SC - Reg. No: SLV4855R, Claimant: COMFORT LIMOUSINE SERVICES PTE LTD	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
2	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
3	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
4	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
5	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
6	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
7	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
8	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
9	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
10	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
11	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
12	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
13	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
14	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
15	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
16	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
17	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
18	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
19	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
20	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
21	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
22	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
23	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
24	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
25	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
26	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
27	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
28	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
29	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
30	04/04/18 08:25	General View	 Load JPG	<input checked="" type="checkbox"/>
31	04/04/18 08:25	General View	 Load JPG	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
					<input checked="" type="checkbox"/>
32	04/04/18 08:25	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	04/04/18 08:25	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	05/04/18 17:40	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	05/04/18 17:40	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	05/04/18 17:40	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	05/04/18 17:40	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	05/04/18 17:40	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	05/04/18 17:41	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	05/04/18 17:41	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	05/04/18 17:41	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	03/04/18 12:27	E-filed GIA report	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/04/18 13:54	Supplementary	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI18006125/K1RBE2**Date:** 16/04/2018REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MG000530

Claimant Vehicle No : SHC2917G**Insured Vehicle No :** SLV4855R**Date of Loss:** 29/03/2018**Nature of Claim:** TP**Claim No:** M1801669DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No:** SHC2917G**Make & Model:** HYUNDAI SONATA, 2.0 CRDI (A)**Engine No:** D4EAB934139**Reg. Date:** 27/01/2011 (Man. Year: 2010)**Chassis No:** KMHET41VMAA803654**Colour:** Blue**Odometer:** 509360 km**Engine Capacity:** 1991 cc**Market Value/New Car Price:** N/A**Sum Insured (\$\$):** Market Value/New Car PriceCONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition:** Good **Steering (Serviceable):** Yes**Footbrake (Serviceable):** Yes**Handbrake (Serviceable):** Yes **Engine Modification:** No**Pre-accident Condition:** AverageCONDITION OF TYRES**Front Tyre Size:** 215/60 R16**Rear Tyre Size:** 215/60 R16**Front Left Side:** West Lake 7 mm**Rear Left Side:** West Lake 7 mm**Front Right Side:** West Lake 7 mm**Rear Right Side:** West Lake 7 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,656.68	2,421.64	235.04	8.85
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,170.00	860.00	310.00	26.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,836.68	3,291.64	545.04	14.21
Approved Total (Overridden) (\$\$)		2,550.00		
(\$\$)	3,836.68	2,550.00	1,286.68	33.54
+ GST 7.00/7.00% (\$\$)	268.57	178.50	90.07	33.54
Nett Amount (\$\$)	4,105.25	2,728.50	1,376.75	33.54

INSPECTION**Date of Assignment:** 03/04/2018 **Present Location:**ComfortDelGro Engineering Pte Ltd
(Loyang)**Date Inspected:** 03/04/2018 **Inspected At:**59 Loyang Drive
Singapore 508969**Estimated Period of Repair:** 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Apr 2018)
Parts: 143 HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC2917G)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Deformed	538.80 FL	*538.80 FL
2	1		*FRT BUMPER PROTECTOR LH	Repair	29.20 FL	*- FL
3	1		*FRT BUMPER BRACKET LH	Serviceable	20.10 FL	*- FL
4	1		*FRT BUMPER SIDE BRACKET LH	Serviceable	14.30 FL	*- FL
5	1		*HEADLAMP ASSY LH	Grazed	797.90 FL	*797.90 FL
6	1		*FRT FENDER LH	Dented	593.00 FL	*593.00 FL
7	1		*FRT FENDER SHIELD LH	Serviceable	86.00 FL	*- FL
8	1		*FRT FENDER RETAINER LH	Serviceable	9.20 FL	*- FL
9	1		*FRT WHEEL RIM	Bent	284.70 FL	*284.70 FL
10	1		*FRT WHEEL HUB CAP LH	Grazed	145.00 FL	*145.00 FL
11	1		*FRT FENDER ADVERTISEMENT LOGO	Necessary	100.00 F	*100.00 F
Supplementary #1						
12	1		*FRT LOWER ARM LH	Bent	250.45 FL	*250.45 FL
13	1		*FRT BALL JOINT LH	Bent	87.70 FL	*87.70 FL
14	1		*STREERING TIE ROD LH	Bent	69.50 FL	*69.50 FL
15	1		*TYRE FRT LH	Cut	216.00 F	*108.00 F
Sub Total (\$\$)					3,241.85	2,975.05
- List Item Discount on L Items 20.00/20.00% (\$\$)					585.17	553.41
Total Parts (\$\$)					2,656.68	2,421.64

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	300.00
2	SPRAYPAINT	New	400.00	360.00
3	WIRING	New	50.00	20.00
4	TUFF KOTE	New	50.00	20.00
Supplementary #1				
Labour Items				
5	REMOVE/RENEW FRT SUSPENSION DAMAGED PARTS	New	150.00	100.00
6	ADJUST FRT WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (S\$)			1,170.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >