



Your Ref: 394982

Date: 27th April 2018

Our Ref: CS1/MSG18006144/Utbs2

M/s MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay
#24-01 Hong Leong Bldg
Singapore 048581
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SGQ 2830K
INSURED VEHICLE: SGH 6286C
ACCIDENT DATE: 28/10/2014

We thank you for your instruction on 02/04/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGQ 2830K from M/s Sincere Appraisal Services.
- b) Singapore Accident Statement of Vehicles SGQ 2830K and SGH 6286C.
- c) Colour damaged vehicle photographs of SGQ 2830K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGQ 2830K
Make & Model	: Toyota Mark X 2.5A
Year of Registration	: 2007
Chassis Number	: GRX1200080111
Engine Capacity	: 2499 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.