

longpac *E17A*

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1052M
 Ref. No : TAX/03/18/2150
 Reg. Date : 15/11/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : NOOR RAMLI BIN MD NOR
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 31/03/2018 09:50:00 PM
 Accident Reported Date / Time : 02/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095329
 Special Instruction to ARC,if any :
 SJV6809K
 Prepared Date : 02/04/2018 05:16:48 PM



Sebastian.
3/4/18.
 - Lump Sum Repair.
 - Question Mark Item
 Photo
 - Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U50-5706535

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	845.00	0.00
Total Spray Painting Charges :	936.00	0.00
Total Material Charges :	2,017.42	2,017.42
Other Charges :	600.00	0.00
TOTAL :	4,398.42	0.00
Lum Sum Total :	4,400.00	0.00
No. of Repair Days :	5.00	0.00
Prepared / Adjusted By :		2 days
Arc / Surveyor Sing Off Date :	02/04/2018 06:22:26 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/04/2018 06:20:27 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 4/2/2018 6:22:54 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	845.00	0.00 300
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 X
TO RESPRAY RIM	180.00	0.00 X
Total Spray Painting & Panel Beating	936.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
Total Other Costs	600.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
2159-17905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace R	No
6087-17020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace ✓ SCR	No
2591-17021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace ?	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓ NEC	No
1604-17090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace X	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace X	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace X	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace X	No
2611-17140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace X	No
2575-17020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace ?	No
TOTAL MATERIALS								2,521.79	2,521.78	
TOTAL MATERIALS(Discounted)							2,017.42	2,017.42		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									