

ASS. REC. BY:

REF: CS/SPF18006205 / Utbnd Special Instruction:

Survivor

ASSIGNMENT (Office)From (Person): Abdul Rahman of SPF Date/Time: 03/04/2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: G8G 8761Z Insured: QX 233Sat Workshop m/s Hock Wah Motor Tel: \_\_\_\_\_of Blk 3011 Bedok Ind Park E #01-2018Policy No: \_\_\_\_\_ Claim No: REM0/105/009/2018/030

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 28032018  
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 04/04/2018 7:41am Person Contacted: Anysia Vehicle IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	<u>G8G 8761Z - x</u>
	<u>QX 233S - x</u>

Do Not Finalize

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GGG87612

at Workshop m/s: Kockuch 162

of \_\_\_\_\_

Insured: QX 2335

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

CIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

2/5 @ 1750 Summit.  
(red: 1065.59! 34%)

RECEIVED 18 MAY 2015

Veh No: GGG87612 Yr Regn: 11 / 17

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or ☒ M /

Make: Toyota hiace c.c. 2982

Colour: s.hur A/C: Insured / Std / NI / NA

Sp. Reading: 4553 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTFHT02P400233245

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ N / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 195-R15

BSY DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A. 28/3/18 D.O.I. 6/4/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rep.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report

1) 12/5 Tupist

☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S ~ RS: \$

Photos

Others

TOTAL

280

Report Format: TP

Lump Sum / I.B.I. (\$) 1750/-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18006205/Utb		
ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 04-04-2018		
		Code : SPF		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	QX 233S	Veh. Inspected	GBG 8761Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2018/030	Excess (\$)	0.00	
Assign From	ABDUL RAHMAN	Assign Date	03/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	28/03/2018	Inspection Date		
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



# SINGAPORE POLICE FORCE

SPF Accidents Claims Section  
Automotive Engg & Mgmt Div  
Police Logistics Department  
No. 1 Mount Pleasant Road  
Block 8 Old Police Academy  
#02-12 Singapore 298333

Your Ref: GBG8761Z

Our Ref: AEMD/105/009/2018/030

Date: 3 April 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd  
Paya Ubi Industrial Park  
51 Ubi Avenue 1 #01/02-25  
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

## ACCIDENT INVOLVING GOVT VEHICLE QX233S AND OTHER VEHICLE GBG8761Z ON 28 MARCH 2018

We refer to the above matter.

2. Please arrange for a **Pre-Repair Inspection** of vehicle no. GBG8761Z at M/s Hock Wah Motor Workshop Pte Ltd of Blk 3011 Bedok Ind'l Pk E Bedok North Ave 4 #01-2008/10/12, Singapore 489977.
3. Estimates were provided by the workshop.
4. For appointment kindly contact **Anysia Foo** at Tel: **64415655**.
5. Thank you.

04042018 @ 941am  
Anysia veh outlin

Yours faithfully,

Abdul Rahman  
for Assistant Director

A FORCE FOR THE NATION

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	4526N
<b>Vehicle Details</b>	
Vehicle No.:	GBG8761Z
Vehicle to be Exported:	No
Intended De-registration Date:	06 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2750267
Chassis No.:	JTFHT02P400233245
Maximum Power Output:	-
Open Market Value:	\$28,138.00
Original Registration Date:	28 Nov 2017
First Registration Date:	28 Nov 2017
Transfer Count:	1
Actual ARF Paid:	\$1,407.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	27 Nov 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$35,878.00
COE Rebate Amount:	\$34,592.00
<b>Total Rebate Amount:</b>	<b>\$34,592.00</b>

The information contained herein is correct as at 06 Apr 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 29/03/2018 12:09  
Date Of Accident 28/03/2018 16:30  
Exact Location Of Accident CHANGI ROAD BESIDE ESSO PETROL STATION  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBG8761Z  
**Insured/Policyholder**  
Name Of Registered Owner D & G MARKETING PTE LTD  
Co Reg No 200204526N  
Email Address NOEMAIL  
Mobile Phone No  
Alternative Phone No OFFICE-62420333

### Vehicle Particulars

Manufacturer TOYOTA  
Model HIACE-3.0 D TURBO 5 DR (M)  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number 5097722252  
Cover Note Number 01/02/2018 - 27/11/2018

### Driver

Name of Driver LIM BAN HIN  
NRIC No S0031336Z  
Date Of Birth 13/10/1954  
Occupation OUTDOOR  
Date Of Driving Pass 16/07/1977  
Driving Experience 40 YEARS AND 8 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-93653977  
Fax Number  
Contact Number  
Email Address NOEMAIL

Address BLK303B ANCHORVALE LINK  
 #06-90  
 Postcode 42303  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name TRAFFIC POLICE DIVISION HQ  
 Police Station Address ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 65470000 - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

28/03/2018 @ 1630HRS (CHANGI ROAD BESIDE ESSO PETROL STATION) I WAS DRIVING ALONG CHANGI ROAD SENDING ORDER, I WAS DRIVING ON THE MOST EXTREME RIGHT LANE, WHEN I JUST PAST THE PETROL STATION, SUDDENLY THE POLICE VEHICLE (QX233S) FROM THE SECOND LANE CUT INTO MY LANE AND WANTED TO TURN INTO THE MINOR LANE. BUT WE MADE CONTACT, WE STOP AND EXITED OUR VEHICLE. HE SAID :SORRY: TO ME, LATER ON I WAITED WHILE HE MADE A FEW CALLS AND A FEW MORE OFFICER CAME TO THE SCENE. THEN HE WROTE ON THE PAPER AND ASK ME TO LODGE A REPORT AT THE TRAFFIC POLICE HQ. THAT'S ALL.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: OVERWRITE  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number QX233S  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category GOVERNMENT  
 Name of Driver  
 NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) in complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report. 7/20180328/2115

**DECLARATION**  
I/We declare the following particulars are true in every respect.

**D & G**  
Marketing Pte. Ltd.  
Singapore  
Tel: 6792 0333  
www.dgsglobal.com.sg

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's  
Name:  
NRIC/FIN No.:



## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180328/2175

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20180328/2175

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/03/2018 18:02	Vide Report No.: G/20180328/0165	Station Diary No.: /
--	-------------------------------------	----------------------

## Informant's Particulars

Name of Informant: LIM BAN HIN			Address: APT BLK 303B ANCHORVALE LINK #06-90 HDB-KANGKAR SINGAPORE 542303	
ID Type / ID No.: NRIC NO / S0031336Z			Contact No.: Home/Office: Mobile: 93653977	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 63	Date of Birth: 13/10/1954	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: D&G DELIVERY			Driving Licence Information: Class: 2B,2A,2,3,4 Date of Expiry:	

## General Information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 28/03/2018 16:30	Type of Location: Straight Road
Location: Along Road 1 CHANGI ROAD				
CHANGI ROAD BESIDE ESSO PATROL STATION				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled		Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBG8761Z	Van				Slightly Damaged	0
QX233S	Car				Slightly Damaged	0

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20180328/2175

2 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180328/2175

## CONTINUATION OF REPORT

Driver		ID No.		S0031336Z	
Name	LIM BAN HIN			Contact No.	93653977
Related Vehicle	NIL			Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Hospital/Clinic	NIL				
Date Treatment	NIL	Date Discharge	NIL		
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL		

**Brief Details.**

28/03/2018 @1630HRS (CHANGI ROAD BESIDE ESSO PATROL STATION)  
I WAS DRIVING ALONG CHANGI ROAD SENDING ORDER, I WAS DRIVING ON THE MOST  
EXTREME RIGHT LANE. WHEN I JUST PAST THE PATROL STATION, SUDDENLY THE POLICE  
VEHICLE FROM THE 2 LANE CUT INTO MY LANE AND WANTED TO TURN INTO THE MINOR LANE.  
BUT WE MADE CONTACT, WE STOP AND EXITED OUR VEHICLE. HE SAID "SORRY" TO ME,  
LATER ON I WAITED WHILE HE MADE A FEW CALLES AND A FEW MORE OFFICER CAME TO THE  
SCENE. THEN HE WROTE ON THE PAPER AND ASK ME TO LODGE A REPORT AT THE TRAFFIC  
POLICE HQ.  
THAT'S ALL



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20180328/2175

3 of 3

Report No. T/20180328/2175

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
TP /  
KEE CHUAN JIA MARCUS

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIA /  
Staff Sgt TANG SIEW PING  
Contact No.: 65476430

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
28/03/2018 18:02

Classification Of Case:



SINGAPORE  
POLICE FORCE

Signature:

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 200204526N  
D & G MARKETING PTE LTD  
NO 3013 BEDOK NORTH AVE 4  
03-2134 BEDOK INDUSTRIAL PARK E  
SINGAPORE 489979  
TEL : +65 6242 0333 FAX : +65 6242 9500  
PH : +65 9848 0622  
ATTN :

## ESTIMATE BILL

Number : EB00004786  
Date : 29/03/2018  
Case No : AD00009639  
Vehicle No : GBG8761Z  
Chassis : JTFHT02P400233245  
Year of Mfr : 2017  
Policy No : 5097722252  
Model : TOYOTA HIACE

### Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BUMPER <i>Deep Cut</i>	1.0	597.97	25	448.48
2	FRONT BUMPER RETAINER LH <i>3rd</i>	1.0	148.60	25	111.45
3	FRONT BUMPER FOGLAMP COVER LH <i>17</i>	1.0	92.14	25	69.11
4	HEADLAMP LH <i>Scu</i>	1.0	675.40	25	506.55
List Price - Parts Sub Total					1,135.59
5	FRONT DOOR LH - REPAIR <i>2x</i>	1.0	1421.97		
6	FRONT STEP PANEL GARNISH LH - REPAIR <i>2</i>	1.0	1066.48		
7	FRONT DOOR COMPANY STICKER LH <i>rec</i>	1.0	20.00	0	20.00
8	FRONT DOOR STICKER - APP STORE <i>rec</i>	1.0	80.00	0	80.00
9	FRONT DOOR STICKER - "SOLDIERTALK" <i>rec</i>	1.0	80.00	0	80.00
10	FRONT DOOR STICKER - COMPANY LOGO <i>rec</i>	1.0	80.00	0	80.00
11	FRONT DOOR STICKER - GOOGLE PLAY <i>rec</i>	1.0	80.00	0	80.00
Special Nett Price - Parts Sub Total					340.00
Parts Total					1,475.59
12	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	450.00	0	450.00
13	SPRAY PAINT ON THE AFFECTED AREAS	1.0	700.00	0	700.00
14	ANTI-RUST COATING	1.0	150.00	0	150.00
15	WIRING	1.0	40.00	0	40.00
Labour 1 Sub Total					1,340.00
TOTAL					2,815.59
SINGAPORE DOLLARS: THREE THOUSAND TWELVE AND CENTS SIXTY-EIGHT ONLY					0.00
Less Excess					0.00
SUBTOTAL					2,815.59
GST 7.00%					197.09
TOTAL					3,012.68

Date of accident : 28/03/2018 04:30 PM Place : CHANGI ROAD BESIDE ESSO PETROL STATION

E. & O. E.

Signature:

Date:

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING &amp; MGT DIVISION

Ref : CS/SPF18006205/Utbn2

ACCIDENT CLAIM SECTION  
(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

ATTN: ABDUL RAHMAN

Date : 23-05-2018



Code : SPF

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	QX 233S	Veh. Inspected	GBG 8761Z
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/030	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	03/04/2018

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTFHT02P400233245	Colour	SILVER
Odometer	4553	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

Accident Date	28/03/2018	Inspection Date	06/04/2018
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 8761Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEEP CUT	597.97	597.97
1	FRONT BUMPER RETAINER LH	BENT	148.60	148.60
1	FRONT BUMPER FOGLAMP COVER LH	NOT NECESSARY	92.14	-
1	HEADLAMP LH	SCRATCHED	675.40	675.40
	LESS 25% DISCOUNT		-378.52	-355.49
			1,135.59	1,066.48
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT DOOR LH (NPA)(SN)	TO REPAIR SEE LABOUR	-	-
1	FRONT STEP PANEL GARNISH LH (NPA)(SN)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR COMPANY STICKER LH (SN)	NECESSARY	20.00	20.00
1	FRONT DOOR STICKER-APP STORE (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR STICKER-SOLDIERTALK (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR STICKER-COMPANY LOGO (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR STICKER-GOOGLE PLAY (SN)	NECESSARY	80.00	80.00
			340.00	340.00
<b><u>LABOUR</u></b>				
	LABOUR TO REMOVE & REFIT NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND FRONT STEP PANEL GARNISH LH.		450.00	300.00
	SPRAY PAINT ON THE AFFECTED AREAS.		700.00	480.00
	ANTI-RUST COATING.	NOT NECESSARY	150.00	-
	WIRING.		40.00	20.00
			1,340.00	800.00
<b>GRAND TOTAL</b>			<b>2,815.59</b>	<b>2,206.48</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,750.00</b>

Report Ref No. CS/SPF18006205/Utnb2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.