

ASS. REC. BY:

REF: CG/EG118006207/Kn bez Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Yee Pui Li of EGI Date/Time: 03042018 452pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH 2677A Insured: SJL 8567Y

at Workshop m/s Motor Image Tel: 9090 2323

of 17 Lorong 8 Toa Payoh

Policy No: Claim No: SJL 8567Y / SL/pi

Sum Insured: Excess:

Make of Veh: D.O.A. 31032018  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: 04042018 10:11am Person Contacted: Kuan Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLH 2677A - X
	SJL 8567Y - X.
24/4/18	Insurance inform insurer no longer with ERGO.
26/4/18	submit poli report

REF: EGI

## ASSIGNMENT

From:

Date:

09/04/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLH 2677A

at Workshop m/s

Motor Image

of

19 lorong &amp; toa payoh

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

1pm @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rport:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.3.1%

3 Val: Yes or No

CA / REV / REP. / 24 HRS <sup>hup</sup>

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLH 2677A Yr Regn: 10 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru <sup>A</sup> Forester c.c. 1995

Colour:

M. D. Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

29088

T/Radio: Insured / Std / NI / NA

Eng/No:

JF/ST5KC5GG078281

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

3.13.18

D.O.I.

9/4/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/4 PM pass to Catherine.

RECEIVED 26 APR 2018

Date/Time: File Pass to?



Preli. Report



Final Report

1) typist

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp. (\$)



Interview (\$)



Tech Invs (\$)



Weekend (\$)

Survey Fee:

Transportation

Y \$ + RS \$

Photos

Others

TOTAL

250

250

Report Format :

Lump Sum / I.B.I. (\$)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18006207/Krb

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 04-04-2018



Code : EGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 8567Y	Veh. Inspected	SLH 2677A
Policy No.		Coverage (\$)	0.00
Claim No.	SJL8567Y/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	03/04/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	31/03/2018	Inspection Date	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**Catherine Chong (LKK Auto)**

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Tuesday, 3 April, 2018 4:52 PM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : SJL8567Y / TP : SLH2677A/LKK / DOA : 31/03/2018  
**Attachments:** SLH2677A - SAS.pdf; SLH2677A - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **MOTOR IMAGE ENTERPRISES PTE LTD.**

04/04/2018 @ 1011am

Mr Kuan veh not in

05/04/2018 @ after lunch

**ADDRESS** : 19 LORONG 8 TOA PAYOH  
SINGAPORE 319255

**PERSON TO CONTACT** : KUAN WEI LOONG @ 9090 3323

**ERGO OFFICER-IN-CHARGE** : STEVE LIM

**Note:** To survey on without prejudice basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

**Janice Lee (LKKAUTO)**

---

**From:** ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>  
**Sent:** Tuesday, April 24, 2018 3:04 PM  
**To:** 'Kuan Wei Loong'; Admin-D (LKKAUTO)  
**Cc:** Sayedinah Ali; Daniel Lim; Daniel Jude  
**Subject:** RE: SLH2677A-3RD PARTY CLAIMS-AIG-TP(SJL8567Y)ERGO-LIABILITY STATUS (DSMPC1800682)  
**Attachments:** SJL8567Y - VEH SALES RECEIPT.pdf  
**Importance:** High

WITHOUT PREJUDICE

Dear Sir,

With regards to above, SJL 8567Y is no longer insured with ERGO wef 28/03/2018 – 11am. Enclosed vehicle sales agreement.

Hence kindly direct your claims to the new insurer of SJL 8567Y.

**Aside to LKK, kindly close your file and submit your final bill to ERGO.**

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

---

**From:** Kuan Wei Loong [mailto:weiloong@motorimage.net]  
**Sent:** Monday, 16 April, 2018 9:36 AM  
**To:** ERGO Insurance Pte. Ltd. (Claims Department)  
**Cc:** Sayedinah Ali; Daniel Lim; Daniel Jude  
**Subject:** RE: SLH2677A-3RD PARTY CLAIMS-AIG-TP(SJL8567Y)ERGO-LIABILITY STATUS  
**Importance:** High

Hi Claims Team,

Car surveyed. Any update on liability status?

Best Regards  
Kuan Wei Loong  
Claims Advisor  
Motor Image Enterprises Pte Ltd  
19 Lorong 8 Toa Payoh Singapore 319255

HP:90903323

Email:weiloong@motorimage.net

Website:www.tanchong.com :: [www.motorimage.net](http://www.motorimage.net)

**From:** Kuan Wei Loong

**Sent:** Monday, April 2, 2018 8:58 PM

**To:** claims@ergo.com.sg

**Cc:** Sayedinah Bin Ali <sayedinah@motorimage.net>; Daniel Lim <daniellim@motorimage.net>

**Subject:** SLH2677A-3RD PARTY CLAIMS-AIG-TP(SJL8567Y)ERGO-LIABILITY STATUS

**Importance:** High

Hi Claims Team,

Kindly advise liability status of the above mentioned vehicle.

Regards

Kuan Wei Loong

Claims Advisor


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP:90903323

Email:weiloong@motorimage.net

Website:www.tanchong.com :: [www.motorimage.net](http://www.motorimage.net)



LESS SLIP.  
MORE GRIP.  
SYMMETRICAL AWD

SUBARU  
TECHNOLOGY

LEARN MORE

SUBARU

f i y

Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

# HUI HUA CREDIT PTE LTD

NO. 1 BUKIT BATOK CRESCENT, #02-22 WCEGA PLAZA, SINGAPORE 658064  
Tel: 6469 6611 Fax: 6469 8358  
ROC No. 199301638D GST Reg. No.: M2-0113522-2

Attended By

SPARE KEY ☐

PURCHASE AGREEMENT

INV. NO. P201803-001691

AGREEMENT NO.: PAAG201803-000071

DATE 27/03/2018

## SELLER DETAILS

SELLER NAME : LOH HIAK LEE

NRIC / ROC NO. :

ADDRESS :

CONTACT PERSON :

CONTACT NO. :

(H)

(H/P)

(O)

## VEHICLE DETAILS

REGISTRATION NO. : SJL8867Y

REGISTRATION DATE : 01/09/2008

MAKE & MODEL : MERCEDES BENZ A170

ENGINE NO. :

26694030532143

CHASSIS NO. :

WDD1690322J636405

YEAR OF MANUFACTURE : 2008

OMV

\$ 25,154.00

## PURCHASE DETAILS

AGREED PRICE : \$ 13,500.00

DEPOSIT PAID : \$ 0.00

FINANCE BALANCE : \$ 0.00

OTHER FEE : \$ 0.00

BALANCE PAYMENT : \$ 13,500.00

CASH / CHEQUE : DATE :

FINANCE CO. :

CHEQUE NO. : DATE :

CASH / CHEQUE :

REMARK CONTRA SALE INV:000091=>SLT4836G

A/C OF BRYANT KEAGAN LUO ZHONG YUAN

EXPECTED DATE OF DELIVERY :

## TERMS AND CONDITIONS

1. The said vehicle is the absolute property of the seller and is free from all encumbrances except for the amount owing to the finance company disclosed above (if any).
2. The agreed price quoted above is subject to the said vehicle being accident-free.
3. The Company reserves the right to re-negotiate the agreed price if the said vehicle is delivered after the expected delivery date stated above.
4. The Company reserves the right to claim 10% of the agreed price from the seller in the event of any cancellation of this Purchase Agreement, regardless of the cause.
5. The seller shall be fully responsible for any illegal acts and/or expenses relating to unlawful driving or parking offences arising from the use of the said vehicle at any time prior to the date of delivery on 28/3/2018 at 11am to the Company.

Signed on behalf of

HUI HUA CREDIT PTE LTD

199301638D

Authorised Signature

We certify that the above are to my knowledge and true in every detail

Signature of Seller

(Company Stamp if Applicable)



# ERGO

Date: 03.04.2018  
Our Reference: SJL 8567Y/SL/pl  
Your Reference: SLH 2677A

Sent via Fax

or

Email

weiloong@motorimage.net

To: MOTOR IMAGE ENTERPRISES PTE LTD

## Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLH 2677A  
Insured's Vehicle: SJL 8567Y  
Date Of Accident: 31.03.2018


We acknowledge receipt of your request for PRS on: 02.04.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.  
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.  
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.  
☒ Our Insured's driver has not reported the accident to us to date.  
☒ Others: OFFICER-IN-CHARGE STEVE LIM

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:

### Workshop use only:

#### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

*Note: Our inspection is on a without admission to liability basis.*



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/04/2018 19:47
Date Of Accident	31/03/2018 09:30
Exact Location Of Accident	CAUSEWAY (MALAYSIA)
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH2677A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHONG YON LAI
NRIC No	S7379837Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91889279
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 AWD (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	2100487136
Cover Note Number	

### Driver

Name of Driver	CHONG YON LAI
NRIC No	S7379837Z
Date Of Birth	08/04/1973
Occupation	INDOOR
Date Of Driving Pass	07/05/2005
Driving Experience	12 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91889279
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	NOEMAIL

Address	1
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : 1 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident


KINDLY REFER TO DOCUMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### Accident Sketch Plan

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Heavy traffic to Malaysia at causeway  
While stopping, the car behind hit my car  
back side.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

x Air

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

## Accident Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : TOA PAYOH  
CONTACT NO : 64730333  
REFERENCE : INS/IC/CHI/0716/2018  
DATE : 04-APR-2018

ERGO INSURANCE PTE LTD  
5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
S(038985)  
TEL : 6829 9199/200  
FAX : 6829 9248/49  
MOTOR CLAIM DEPT

OWNER'S NAME : CHONG YON LAI  
ADDRESS : APT BLK 538 JELAPANG ROAD  
#06-28  
S(670538)  
TELEPHONE NO : 9188 9279

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100487136  
VEHICLE NO : SLH2677A  
MODEL CODE : SJ5DK7C  
MODEL/YEAR : FORESTER 2.0I-L AWD CVT  
ENGINE NO : FB20Y426723  
CHASSIS NO : JF18J5KC5GG078281  
MILEAGE : 1 KM  
DATE IN : 04/04/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : KUAN WEI LOONG\*\*  
ACCIDENT DATE : 04/04/2018

Print Date : 04/04/2018  
Print Time : 22:21:10

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLH2677A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	22/001	CONDUCT TP CLAIM ERGO LOCATION: CAUSEWAY (MALAYSIA) DATE: 31/03/2018 TIME: 0930HRS		
3	22/002	REPAIR/REPLACE REAR BUMPER AND REAR PANEL	1680.00	2801
4	22/003	RESPRAY REAR BUMPER AND REAR PANEL	840.00	4201
5	22/004	TO CONDUCT REAR LIGHTING TEST	50.00	251
6	22/005	TO CONDUCT REAR PROTECTANT COATING	500.00	2801
7	22/006	SUNDRIES	100.00	X
TOTAL LABOUR CHARGES			3170.00	

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLH2677A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
			NETT	LIST	S/NETT		
1	FLOOR PAN R R CP	52129SG0019P	R 432.00	X			
2	SKIRT COMPL R	USE SG0009P (SUPP)	52401SG0109P	R 288.00	X		
3	BUMPER FACE R	(1PC-DTM USE)	57704SG012	B 540.00	✓		
4	BRKT CORNER R RH	57707SG060	R 18.00	X			
5	BRKT CORNER R LH	57707SG070	Sm 18.00	X			
6	BRKT SD R RH	57707SG080	43.20	?			
7	BRKT SD R LH	57707SG090				R 14.40	X
8	BEAM COMPL R EU	57711SG0219P	288.00	?			
9	COVER HOOK R	57731SG010NN	Sm 12.60	X			
10	COVER BMPR R (SUPP)	57731SG060	Sm 14.40	X			
11	REFLEC AY RH	(SUPP) 84281SC000	Sm 20.40	X			
12	REFLEX AY LH	84281SC010	Sm 20.40	X			
SUB TOTAL			1695.00	0.00	0.00	14.40	
LESS DISCOUNT ( NETT-20 % S/LIST-30 % )			339.00	0.00	0.00	4.32	
GRAND TOTAL			1356.00	0.00	0.00	10.08	
OVERALL TOTAL			1366.08				

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED



MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLH2677A

TOTAL LABOUR CHARGES	3170.00
TOTAL SPARE PARTS CHARGES	1366.08
GRAND TOTAL	4536.08 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

*Not Withheld  
Resurvey 1-B1  
B4 paint  
2 days*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EG118006207/Krbe2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 30-04-2018	
		Code : EGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJL 8567Y	Veh. Inspected	SLH 2677A
Policy No.		Coverage (\$)	0.00
Claim No.	SJL8567Y/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	03/04/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	SUBARU FORESTER (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JF1SJ5KC5GG078281	Colour	METALLIC DARK GREY
Odometer	29088	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/60 R17	YOKOHAMA	8 mm
L/H Front Tyre	225/60 R17	YOKOHAMA	8 mm
R/H Rear Tyre	225/60 R17	YOKOHAMA	8 mm
L/H Rear Tyre	225/60 R17	YOKOHAMA	8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	31/03/2018	Inspection Date	09/04/2018
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2677A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BRKT SD R LH	TO REPAIR SEE LABOUR	14.40	-
	LESS 30% DISCOUNT		-4.32	-
			10.08	-
	<b><u>NETT ITEMS</u></b>			
1	FLOOR PAN R R CP (N)	TO REPAIR SEE LABOUR	432.00	-
1	SKIRT COMPL R (N)	TO REPAIR SEE LABOUR	288.00	-
1	BUMPER FACE R (N)	BENT	540.00	540.00
1	BRKT CORNER R RH (N)	SERVICEABLE	18.00	-
1	BRKT CORNER R LH (N)	SERVICEABLE	18.00	-
1	BRKT SD R RH (N)	* CHECK	43.20	-
1	BEAM COMPL R EU (N)	* CHECK	288.00	-
1	COVER HOOK R (N)	SERVICEABLE	12.60	-
1	COVER BMPR R (N)	SERVICEABLE	14.40	-
1	REFLEC AY RH (N)	SERVICEABLE	20.40	-
1	REFLEC AY LH (N)	SERVICEABLE	20.40	-
	LESS 20% DISCOUNT		-339.00	-108.00
			1,356.00	432.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
			100.00	-
	<b><u>LABOUR</u></b>			
	REPAIR/REPLACE REAR BUMPER AND REAR PANEL.INCLUSIVE OF THE REPAIR OF FLOOR PAN R R CP,SKIRT COMPL R AND BRKT SD R LH.		1,680.00	280.00
	RESPRAY REAR BUMPER AND REAR PANEL.		840.00	420.00
	TO CONDUCT REAR LIGHTING TEST.		50.00	25.00
	TO CONDUCT REAR PROTECTANT COATING.		500.00	280.00
			3,070.00	1,005.00

Report Ref No. CS/EGI18006207/Krbe2



GRAND TOTAL		Page No.:2 of 2	
		4,536.08	1,437.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$264.96 NETT)			1,437.00

Report Ref No. CS/EGI18006207/Krbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.