

5/21/03/2007

A/S REC BY:

REF: CS3/CT118006244/Gd3b

range & delay

Surveyor

GQ

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CT1

Date/Time: 4/4/18 @ 3:14pm

Estimated Cost:

OD / TP / WS / TT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJP 9544K

Insured:

SJP 2258J

at Workshop m/s

Alpha Car Services

Tel:

9807 3304

of

Blk C, Kaki Bkt Ave 6 # 01-59

Policy No:

DMPCSN 3072171700

Claim No:

SNM18D01741C02

Sum Insured:

Excess:

D.O.A. 29/03/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time:

9:12am @ 5/4/18

Person Contacted:

Ah Yap

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SJP 9544K - X
	SJP 2258J - X
	Demantle: 6/4/2018
	After repair: 13/4/2018

REF: CTI

ASSIGNMENT

(-2027)

From:

Date: 5/1/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

SJP 9544K

at Workshop m/s

Alpha Car Services

of

BIKC, Kaki Bkt Ave 6 #01-59

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Mr. Ah Yap @ 9807 3304

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / up

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

* Repair Estimate : S\$ 10,500 - \$12,500

* 8 days

RECEIVED 21 MAY 2018

Date/Time: File Pass to?

☐

Preli. Report

1)

Date/Time: File Return to?

☐

Final Report

2)

Report Format :

PRG

Lump Sum / I.B.I. (\$) 1

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Survey Fee:

Transportation

) S + RS SI

) Photos

) Others

TOTAL

190

190

Veh No: SJP 9544K Yr Regn: 19 Apr 2007

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Golf. 1984

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

86033

T/Radio: Insured / Std / NI / NA

Eng/No:

www 222 1KZ 74026 895

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/40ZR18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

05-04-18

Survey held at

w/s

12:10pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018		04 Apr 2018 15:14 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PHUA MENG SONG (PAN MINGSONG), ID: S7831771Z		
Main Claimant:	ANG LAY HUA, ID: S6926457C		
Vehicle Reg. No.:	SJP9544K	Date of Loss:	29/03/2018 20:00 - :59
Claim Type:	TP / SNM18D01741C02	Policy/Cover Note No.:	DMPCSN3072171700 (Comprehensive)
Vehicle Reg. No. (Insured):	SLP2258J	Policy No. (Claimant):	GA186756/1
		Excess:	S\$0.00
Repairer:	Alpha Car Services Pte Ltd (HQ) BLK C KAKI BUKIT AVE 6 #01-59 AUTOBAY@KB, 417883 Kaki Bukit - Tel: 82265945		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/04/2018]		
Driver/Custodian (Insured):	PHUA MENG SONG (PAN MINGSONG) (39 / Male), NRIC: S7831771Z		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your Insured's vehicle; ref: SLP 2258J ; SNM18D01741C02
Our client's vehicle ; ref: SJP 9544K; AP /sy
Date : 4 April 2018

China Taiping Insurance (Singapore) Pte Ltd

By Email Only

Dear Sirs,

DATE OF ACCIDENT: 29 MARCH 2018
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

<u>Name</u>	<u>Company</u>
1. Dave Chang	Sincere Appraisal Services
2. Sebastian Lim	Constant Appraiser Services
3. Alan Cheong	CL Appraiser Pte Ltd
4. Yap Teck Chye	MC-Coy Appraiser Pte Ltd
5. Andrew How	Prominent Appraiser Services
6. Marc Ananda	United Appraisal and Management Pte Ltd
7. Dennis Yap	PAL'S Appraiser Pte Ltd
8. Yap Teck Lee	LCW Appraiser Pte Ltd
9. Dixon Yeo	Treasure Appraiser Pte Ltd
10. T.T. Rajan	ST Appraisal Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which we will commence repairs thereafter without any further notice or reference to you. Please also let us know if you required a Post-Repair Survey/Inspection for our client's consideration. Please be informed that the said vehicle can be surveyed / inspected at:

Workshop Address: Alpha Car Services Pte Ltd
Block C Kaki Bukit Ave 6
#01-59 Kaki Bukit Autobay
Singapore 417883
Contact person/Hp: Mr. Ah Hwa (Hp: 8226 5945); Mr. Ah Yap (Hp: 9807 3304)

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,



Your Insured's vehicle; ref: SLP 2258J ; SNM18D01741C02
Our client's vehicle ; ref: SJP 9544K; AP /sy
Date : 4 April 2018

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as
follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (after dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (party by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6457C
Vehicle Details	
Vehicle No.:	SJP9544K
Vehicle to be Exported:	No
Intended De-registration Date:	05 Apr 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF GTI
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	BWA115251
Chassis No.:	WVWZZZ1KZ7U026895
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$31,944.00
Original Registration Date:	19 Apr 2007
First Registration Date:	19 Apr 2007
Transfer Count:	2
Actual ARF Paid:	\$35,139.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Apr 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$52,008.00
COE Rebate Amount:	\$46,995.00
Total Rebate Amount:	\$46,995.00

The information contained herein is correct as at 05 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/04/2018 17:04
Date Of Accident	29/03/2018 20:45
Exact Location Of Accident	YISHUN SAFRA MC DONALDS DRIVE THRU
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP9544K
Insured/Policyholder	
Name Of Registered Owner	ANG LAY HUA
NRIC No	S6926457C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96360035
Alternative Phone No	OTHERS-96360035

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	GOLF GTI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA186756/1
Cover Note Number	

Driver

Name of Driver	LEON TOH YI HAO
NRIC No	S9345565G
Date Of Birth	19/11/1993
Occupation	INDOOR
Date Of Driving Pass	17/04/2012
Driving Experience	5 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96360035
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

BLK 413 SERANGOON CENTRAL #06-351

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured CHILDREN

Vehicle Registration Number of Driver's Own Vehicle -

-

-

Insurance Company of Driver's Own Vehicle -

-

-

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLP2258J

Vehicle Make/Model/Colour B.M.W. 325I COUPE AT HID ABS D/AB 2WD 2DR SR

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number EH118T

Vehicle Make/Model/Colour B.M.W. 730LI AT ABS D/AB 2WD 4DR NAV HID SR

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all Insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

02 APR 2018


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Suhaimi
NUC/F.N No: S8040377A

Yishun Safra MacDonald's Drive-Thru

SKETCH PLAN



Veh A: SJP 9544 K

Veh B: SLP 2258 J

Veh C: EH 11 8 T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time I vehicle A was stationary on the stated venue Suddenly vehicle B came from behind and hit into my vehicle's rear portion. I got off the car and went over to vehicle B to check on him, at this point he accelerated and hit my vehicle rear portion a second time causing my vehicle to propel forward to hit the rear portion of vehicle C.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Suhaimi
NIC/FIN No: S8040377A

02 APR 2018

Accident Photo



Accident Photo



Accident Photo



Accident Photo








Accident Photo





VOLKSWAGEN AG

WVWZZZ1KZ7U026895

1920 kg

3320 kg

1 - 1060 kg

2 - 0910 kg

Typ 1K

**BWA 1706
0916594**




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

EFFECTIVE DATE

Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg 17 Apr 2011

NP 428A





redefining / insurance

AXA Insurance Pte Ltd
 ☎ 1800 880 8888 (Within Singapore)
 ☎ (65) 6860 8888 (International)
 ☎ (65) 6860 4746
 ✉ customer.care@axa.com.sg
 🌐 www.axa.com.sg

Account number
 04139

Certificate of Insurance

Motor Vehicle (Third Party) Reinsurance Policy (Chapter 122) - Motor Vehicle (Third Party) Reinsurance (Compensation) Rules, 1997 (Road Transport Act, 1997) (Malaysia)
 Motor Vehicle (Third Party) Rules (1997) (Malaysia)

Policy details

Policyholder name	AYO LAT SIA	Certificate number	QA186756 / 1
Cover	Comprehensive	Class number	WVA221A2 / 0000000
Plan name	For Her	Engine number	0WN113251
NCD applicable	30%		
Vehicle registration number	SIP9544K		
Period of Insurance	From 12/04/2017 to 18/04/2018 (claim before expiry)		
Finance lease company	SPELCO CAPITAL PTE LTD		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws, or regulations to drive the Motor Vehicle, or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation or that in full from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover: use for hire or reward, racing, speed-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade, or when the Motor Car, whether stationary, is used or otherwise, as in or on a racing track, circuit, road, course or any other road by whatever name called that are typically used for racing, speed-making or such similar purposes.

* Exclusions without regard to by Section 6 of the Motor Vehicle (Third Party) Rules and Compensation Act, Chapter 122 and Section 25 of the Road Transport Act, 1997 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 500.00
	Windscreen Excess	SGD 100.00

- An Additional Excess is applicable as follows:
1. S\$500 for unlicensed Authorized Driver
 2. S\$500 for Licensed Young and Inexperienced Driver
 3. S\$5,000 for unlicensed young and inexperienced drivers. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

Under hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicle (Third Party) Rules and Compensation Rules, (Chapter 122) and Part IV of the Road Transport Act, 1997 (Malaysia).

AXA Insurance Pte Ltd

Authorized signatory

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to this effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third Party) Rules and Compensation Act (Cap. 122).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period following which there would be no liability under the policy, renewal certificate, endorsement etc.

AXA Insurance Pte Ltd | 09900101238
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068911
 Customer Centre, #01-01

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018		04 Apr 2018 15:14 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: PHUA MENG SONG (PAN MINGSONG) , ID: S7831771Z									
Main Claimant: ANG LAY HUA , ID: S6926457C									
Vehicle Reg. No.: SJP9544K		Date of Loss: 29/03/2018 20:00 - :59 [131 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D01741C02		Policy/Cover Note No.: DMPCSN3072171700 (Comprehensive)							
Vehicle Reg. No. (Insured): SLP2258J		Policy No. (Claimant): GA186756/1							
		Excess: S\$0.00							
Repairer: Alpha Car Services Pte Ltd (HQ) BLK C KAKI BUKIT AVE 6 #01-59 AUTOBAY@KB, 417883 Kaki Bukit - Tel: 82265945									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/04/2018]									
Driver/Custodian (Insured): PHUA MENG SONG (PAN MINGSONG) (39 / Female), NRIC: S7831771Z									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJP9544K (SNM18D01741C02)
[SLP2258J]
TP
ANG LAY HUA
Mar 29 2018 8:00PM
[PHUA MENG SONG (PAN MINGSONG)]
Alpha Car Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	02/04/18 17:15	Alpine Motors Pte Ltd (HQ) Accident Statement		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	02/04/18 17:14	Alpine Motors Pte Ltd (HQ) Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	02/04/18 17:14	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	02/04/18 17:14	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	02/04/18 17:14	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	02/04/18 17:14	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	02/04/18 17:14	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	02/04/18 17:14	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	02/04/18 17:14	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	02/04/18 17:15	Driving License [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	02/04/18 17:15	Driving License [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
11	02/04/18 17:15	Insurance policy [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>

No	Relabel/Reorder			Thumbnail	Print
1	21/05/18 12:54	LKK Auto Consultants Pte Ltd (HQ) General View		Load PDF	
2	21/05/18 12:54	Photographs of Damaged Parts		Load PDF	
3	21/05/18 12:54	Photo After Spray		Load PDF	














Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	04/04/18 15:13	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) PRS		Load PDF	
2	04/04/18 15:13	OI GIA REPORT		Load PDF	

No	Finalized On			Thumbnail	Print
1	02/04/18 17:15	Alpine Motors Pte Ltd (HQ) Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	02/04/18 17:15	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	02/04/18 17:15	Alpine Motors Pte Ltd (HQ) Accident Statement		Load HTM	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	02/04/18 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	02/04/18 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	02/04/18 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	02/04/18 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	02/04/18 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	02/04/18 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	02/04/18 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	02/04/18 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	02/04/18 17:15	Driving License	 Load JPG	<input checked="" type="checkbox"/>
10	02/04/18 17:15	Driving License	 Load JPG	<input checked="" type="checkbox"/>
11	02/04/18 17:15	Insurance policy	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	02/04/18 17:15	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	02/04/18 17:15	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18006244/GD3E2

Date: 22/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3072171700

Claimant Vehicle
No: SJP9544KInsured Vehicle
No: SLP2258J

Date of Loss: 29/03/2018

Nature of Claim: TP

Claim
No: SNM18D01741C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJP9544K

Make & Model: VOLKSWAGEN GOLF, 1.4 GTI (A)

Engine No: BWA115251

Reg. Date: 19/04/2007 (Man. Year: 2007)

Chassis No: WWWZZZ1KZ7U026895

Colour: Black

Odometer: 86033 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size: 225/40Z R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/04/2018

Date Inspected: 05/04/2018 Inspected At:

Alpha Car Services Pte Ltd (HQ)
BLK C KAKI BUKIT AVE 6 #01-59
AUTOBAY@KB
Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,500.00 - \$12,500.00

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2018)
Parts: 144	VOLKSWAGEN GOLF 1.4 GTI (A) (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJP9544K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >