

ASS. REC. BY:

REF:

TP / CS / TP 18006257 / Kthbs

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1/2

1. Pay 85000 (Red: 3718 : 4270)

STN 3351A - 13/CTI 17012792 / Kthbs22

REP: 280617

RECEIVED 03 APR 2018

Date/Time, File Pass to?



Prel. Report



Final Report

1) 614 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 5000/-

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

TOTAL

160
50
20
80
310

Veh No:

STN 3351A Yr Regn: 02, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Sportage c.c 1915

Colour

In Silver A/C: Insured / Std / NI / NA

Sp. Reading

98426 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAJE 55 23876 24607

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: 215 / 65 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Viking

Front

Rear

R/Bal.

9 mm

R/Bal.

9 mm

L/Bal.

9 mm

L/Bal.

9 mm

D.O.A.

12/2/18

D.O.I.

12/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

KANG AUTO ENGINEERING PTE LTD

Ref : CS/TP18006257/Ktb

160 SIN MING DRIVE #02-16
SIN MING AUTOCITY
SINGAPORE 575722

Date : 05-04-2018



Code : TP291

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SJN 3351A
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	12/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/02/2018	Inspection Date	12/02/2018
Survey held at	KANG AUTO ENGINEERING PTE LTD 160 SIN MING DRIVE #02-16 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/02/2018 16:13
Date Of Accident	12/02/2018 06:35
Exact Location Of Accident	SLE TOWARDS BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN3351A
Insured/Policyholder	
Name Of Registered Owner	SOO YI
NRIC No	S1771162H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96163470
Alternative Phone No	OFFICE-96163470

Vehicle Particulars

Manufacturer	KIA
Model	SPORTAGE-2.0 ABS (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3023731700
Cover Note Number	

Driver

Name of Driver	SOO YI
NRIC No	S1771162H
Date Of Birth	24/12/1966
Occupation	INDOOR
Date Of Driving Pass	24/03/1986
Driving Experience	31 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96163470
Fax Number	
Contact Number	OFFICE-96163470
EEmail Address	NOEMAIL

Address	BLK 818 WOODLANDS STREET 82 #04-413
Postcode	730818
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS EAST N.P.C
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC6605H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	GREAT AMERICAN INSURANCE COMPANY
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SOO YI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJN3351A

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode




SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 _____ Policyholder's Signature Date & Time:	 _____ Driver's Signature (If driver is not the policyholder) Date & Time:	 _____ Reporting Centre Personnel's Signature Name: NRIC/FIN No.:
--	---	---

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER POLICE REPORT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Police Report Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180212/2084

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

1 of 3

Report No. T/20180212/2084

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/02/2018 13:05		Vide Report No.:		Station Diary No.: 106	
Name of Informant: SOO YI		Address: APT BLK 818 WOODLANDS STREET 82 #04-413 SINGAPORE 730818			
ID Type / ID No.: NRIC NO / S1771162H		Contact No.: Home/Office: Mobile: 96163470			
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 51	Date of Birth: 24/12/1966	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: IT SPECIALIST		Driving Licence Information: Class: 3		Date of Expiry:	

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 12/02/2018 06:30	Type of Location: Expressway
Location: Along Road 1 WOODLANDS AVENUE 2 From Woodlands Ave 2, On SLE towards BKE.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

GBA660R	Lorry				No Damage	0
SJN3351A	Car	KIA	SPORTAGE 2.0 AT ABS D/AIRBAG 2WD 5DR	Silver	Seriously Damaged	0
SLC8605H	Car				Seriously Damaged	0

**SINGAPORE
POLICE FORCE**

T/20180212/2084

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

2 of 3

Report No. T/20180212/2084

CONTINUATION OF REPORT

SJN3351A	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN30237317 00	16/03/2017	15/03/2018
----------	--	----------------------	------------	------------

Brief Details.

On the 12/02/2018 at about 0630hrs, I was travelling in my vehicle (SJN3315A) on Woodlands Ave 2 and subsequently entered SLE towards BKE. On SLE, I was travelling on the center lane when I observed a vehicle (GBA660R) in front of mine jammed the brakes, upon seeing that I was nearing the front vehicle I manage brake in time and avoid the collision, however I was hit from the rear by another vehicle (SLC6605H). My right rear bumper was damaged. No one was injured at that point of time. No police or ambulance was at scene. I am lodging this report for my insurance claim purposes.

I also wish to inform, while waiting at the side of the road for the tow truck, another accident happened at the same location.



**SINGAPORE
POLICE FORCE**



T/20180212/2084

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

3 of 3

Report No. T/20180212/2084

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ Sgt 2 JONATHAN LOW JIN HUA Sgt Mohd. Haigni
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65476430

Signature Of Informant:
Date/Time: 12/02/2018 13:05
Classification Of Case:



KANG

AUTO ENGINEERING PTE LTD



Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015

Email: kangauto@singnet.com.sg

M/S Soo Yi

Blk 818 Woodlands Street.81

#04-413

Singapore 730818

POLICY NO : THIRD PARTY CLAIMS

OUR REF : TP18/02/1093

VEHICLE NO : SJN3351A

MAKE/MODEL : Kia Sportage 2.0A

DATE OF ACCIDENT : 12.02.2018

1 PC TAILGATE GLASS INNER SEAL	S\$	165.00	✓
1 PC TAILGATE	RM	992.00	✓
1 PC TAILGATE EMBLEM	RM	45.00	✓
1 PC TAILGATE 'CVVT 2.0' BADGE	RM	38.00	✓
1 PC TAILLAMP ASSY (RIGHT)	CM	465.00	✓
1 PC REAR BUMPER	RM	876.00	✓
1 PC REAR BUMPER REINFORCEMENT	RM	325.00	✓
1 PC REAR BUMPER BRACKET (RIGHT)	RM	156.00	✓
1 PC REAR BUMPER CLIPS	RM	32.00	✓
1 PC REAR BUMPER SIDE RETAINERS (RIGHT)	DIS	35.00	✓
1 PC REAR BUMPER SPONGE	RM	135.00	X
1 PC REAR BUMPER TOP PAD	RM	182.00	✓
1 PC REAR END PANEL	RM	535.00	✓
1 PC REAR FENDER PROTECTOR (RIGHT)	RM	223.00	X
1 PC EXHAUST SILENCER (RIGHT)	RM	965.00	✓
1 PC REAR SHOCK ABSORBER (RIGHT)	RM	528.00	X
	S\$	5532.00	5697
	LESS 10%	553.20	
	S\$	4978.80	5127.30

1 SET REAR REVERSE SENSOR

1 PC WINDSCREEN GUM

1 PC TOWING BRACKET

shot 400.00 S'NETT
RM 80.00 4050
R 125.00 X

*Not Authorised
61 Sep. @ 5000
Repair After Pain*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City



160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

M/S Soo Yi
Blk 818 Woodlands Street.81
#04-413
Singapore 730818

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP18/02/1093
VEHICLE NO : SJN3351A
MAKE/MODEL : Kia Sportage 2.0A
DATE OF ACCIDENT : 12.02.2018

TOWING CHARGES	S\$	64.20	501
TO CHECK WIRING		50.00	201
TO RE-SET WHEEL ALIGNMENT	nn	80.00	x
TO REMOVE & REFIX EXHAUST SILENCER		120.00	601
TO REMOVE & REFIX TAILGATE GLASS		160.00	1201
TO APPLY RUST PROOFING ON REPLACED/REPAIED PANEL		160.00	601
TO PUTTY AND SPRAY PAINT CHARGES		1,200.00	8001
LABOUR CHARGES		1,300.00	8001
	S\$	8,718.00	
			8866.50

SGD EIGHT THOUSAND SEVEN HUNDRED AND EIGHTEEN ONLY

YOURS FAITHFULLY,

KANG AUTO ENGINEERING PTE LTD

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

KANG AUTO ENGINEERING PTE LTD

Ref : CS/TP18006257/Ktbs2

160 SIN MING DRIVE #02-16

SIN MING AUTOCITY

SINGAPORE 575722

ON BEHALF OF SOO YI

Date : 10-04-2018



Code : TP291

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SJN 3351A
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	12/02/2018

2. Vehicle Particulars & Condition

Make & Model	KIA SPORTAGE (A)	c.c	1975
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KNAJE552397624607	Colour	METALLIC SILVER
Odometer	96426	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/65R16	VIKING	9 mm
L/H Front Tyre	215/65R16	VIKING	9 mm
R/H Rear Tyre	215/65R16	VIKING	9 mm
L/H Rear Tyre	215/65R16	VIKING	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/02/2018	Inspection Date	12/02/2018
Survey held at	KANG AUTO ENGINEERING PTE LTD 160 SIN MING DRIVE #02-16 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 3351A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE GLASS INNER SEAL	NECESSARY	165.00	165.00
1	TAILGATE	BENT	992.00	992.00
1	TAILGATE EMBLEM	NECESSARY	45.00	45.00
1	TAILGATE 'CVVT 2.0' BADGE	NECESSARY	38.00	38.00
1	TAILLAMP ASSY (RIGHT)	CRACKED	465.00	465.00
1	REAR BUMPER	BUCKLED	876.00	876.00
1	REAR BUMPER REINFORCEMENT	BENT	325.00	325.00
1	REAR BUMPER BRACKET (RIGHT)	BENT	156.00	156.00
1	REAR BUMPER CLIPS	NECESSARY	32.00	32.00
1	REAR BUMPER SIDE RETAINERS (RIGHT)	DISTORTED	35.00	35.00
1	REAR BUMPER SPONGE	SERVICEABLE	135.00	-
1	REAR BUMPER TOP PAD	NECESSARY	182.00	182.00
1	REAR END PANEL	BENT	535.00	535.00
1	REAR FENDER PROTECTOR (RIGHT)	SERVICEABLE	223.00	-
1	EXHAUST SILENCER (RIGHT)	BENT	965.00	965.00
1	REAR SHOCK ABSORBER (RIGHT)	SERVICEABLE	528.00	-
	LESS 10% DISCOUNT		-569.70	-481.10
			5,127.30	4,329.90
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR REVERSE SENSOR (SN)	SHORTED	400.00	200.00
1	WINDSCREEN GUM (SN)	NECESSARY	80.00	40.00
1	TOWING BRACKET (SN)	TO REPAIR SEE LABOUR	125.00	-
			605.00	240.00
<u>LABOUR</u>				
	TOWING CHARGES.		64.20	50.00
	TO CHECK WIRING.		50.00	20.00
	TO RE-SET WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO REMOVE & REFIX EXHAUST SILENCER.		120.00	60.00
	TO REMOVE & REFIX TAILGATE GLASS.		160.00	120.00
	TO APPLY RUST PROOFING ON REPLACED / REPAIRED PANEL.		160.00	60.00
	TO PUTTY AND SPRAY PAINT CHARGES.		1,200.00	800.00

Report Ref No. CS/TP18006257/Ktbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF TOWING BRACKET.		1,300.00	800.00
			3,134.20	1,910.00
	GRAND TOTAL		8,866.50	6,479.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00

Report Ref No. CS/TP18006257/Ktbs2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.