

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/7P 18006258/Unb02

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 618X

at Workshop m/s Bul

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 506.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLT 618X Yr Regn: 28/6/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 4

Make: BMW 523i c.c. 2497

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 232597 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W13AF32070C544043

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or other

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/35 ZR 20

R: 285/30 ZR 20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 3/4/18 D.O.I. 5/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R/L - O/S L/R 2

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Muc App. LTA33641 Dep 13 net 16359
30/4/18	L/S 814500 (Red 9073.31, 352)
RECEIVED 30 APR 2018	

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 30/4 - typist

Report Format: TP

Lump Sum / I.B.I: (\$ 14,500)

Days Of Repair: 12

Resurvey No. of Trip: 3

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Other

TOTAL

13x15=195

170+195

50

50+50+50

176

80

(821)

Ref. No : <u>CS/TP18006258/urban2</u>	Res. Date: <u>10/4/18</u>	Date Received:
Veh. No : <u>STP 6184</u>	SP:	WKSP: <u>Bul</u>
C/No :		
Action/Instruction:		
1.File	2.Submit Photo? YES / NO	
3.Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to	a) No authorisation b) Days of repair	
others:		
Final Re-inspection or Progress Photos		Inspected By:

Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house?

Sell it on Marketplace. Posting an advertisement is FREE!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan. Trade In Are
Welcome. 100% Deposit Refund
For Unapproved Loan.
Classic Credit Start!

HIN LUNG AUTO
Ho Bee Group
30 years of car sale
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

Browse by Category

• Back (1 2) Next •

Sort by Date Posted

20 results/page

33 vehicles

bmw 523

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 523		Any	Any	2010	Any	Any	Any	Available
	BMW 5 Series	523i	\$51,000	\$14,870 /yr	30-Apr-2010	2,497 cc	108,901 km	Luxury	Available
Just Arrived. Nice SLW Plate! Brand New Glossy Black Paintwork Done! New Door Inner Handle X4! High OMV \$40475. Min PARF \$20238. Genuine Low Mileage Done 108901 Km. Well Maintained By Owner. 100% Acc...									
Posted: 04-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
	BMW 5 Series	523i	\$56,200	\$13,700 /yr	29-Nov-2010	2,497 cc	125,000 km	Luxury	Available
Performance Unit, Road Tax Inspection Done, Flawless Deep Blue Paintwork In Showroom Condition, Neat And Clean Interior Like New Car, One Of The Best Maintained And Reliable 6 Cylinder Naturally Aspir...									
Wheeler Dealers 2018 Pte Ltd									
Posted: 04-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
	BMW 5 Series	523i	\$50,800	\$13,930 /yr	29-Jun-2010	2,497 cc	-	Luxury	Available
\$0 Down Payment Available! Balloon Scheme Available! We Are SGCARMART Premium Dealer 2015-2017! Buy With Confidence! No Hidden Cost! 100% Accident Free! In House Loan Or Bank Loan Available! No Need G...									
88 Motor Trading									
Posted: 03-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
	BMW 5 Series	523i	\$54,300	\$13,520 /yr	27-Oct-2010	2,497 cc	140,000 km	Luxury	Available
Lowest 1 Owner In The Market! PML Unit. 100% Accident Free. Drives Like New. Sta And Vicom Evaluation Welcome. Highest Trade In With High Loan, Balloon Loan. In House Loan. Max Loan Up To 90%. Test Dr...									
Posted: 03-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
Car Buying Car Aftermarket Car Selling On The Move Car Ownership Lifestyle Buy Tyres Online! Latest Special Offers from Tyrepack!									
	BMW 5 Series	523i	\$59,800	\$15,020 /yr	01-Dec-2010	2,497 cc	123,000 km	Luxury	Available
Buy With A Peace Of Mind, Pml Unit. 100% Quality Buy! Sta And Vicom Evaluation Welcome. Vehicle In Showroom Condition By Professional Groomer. Elegant Silver With Cream Leather Interior. Lowest Intere...									
Shuang Hup Credit									
Posted: 03-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
	BMW 5 Series	523i	\$51,800	\$15,290 /yr	02-Jun-2010	2,497 cc	129,000 km	Luxury	Available
Extremely Popular Luxury Executive Sedan That Blends Perfectly For Business And Leisure. Executive Sedan Owned. Immaculate Condition. Cheapest In Town, Peace Of Mind! Highest Trade In And High In Hous...									
Posted: 02-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
	BMW 5 Series	523i	\$59,555	\$13,760 /yr	30-Dec-2010	2,497 cc	87,458 km	Luxury	Available
Guaranteed Lowest Price! One Owner Only! Well Maintained, Free Car Spa, Free Servicing, Highest Trade In With Lowest In House Interest Easy Loan, \$3k Deposit, Low Down Payment. Call Now To View!									
Cars Inn Credit Pte Ltd									
Posted: 02-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
	BMW 5 Series	523i	\$49,800	\$14,290 /yr	30-Apr-2010	2,497 cc	-	Luxury	Available
Well Taken Care, Excellent Condition, View To Believe! Hurry! Trade In Welcome, Car Available In Showroom For Viewing Now, Contact For More Details.									
Posted: 02-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4676C
Vehicle Details	
Vehicle No.:	SLT618X
Vehicle to be Exported:	No
Intended De-registration Date:	05 Apr 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	03757397N52B25AF
Chassis No.:	WBAFP32070C544043
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$41,218.00
Original Registration Date:	28 Jun 2010
First Registration Date:	28 Jun 2010
Transfer Count:	1
Actual ARF Paid:	\$41,218.00 20609
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2020
PARF Rebate Amount:	\$24,730.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$41,000.00
COE Rebate Amount:	\$8,911.00
Total Rebate Amount:	\$33,641.00

The information contained herein is correct as at 05 Apr 2018

OK

MSME10045154 / 5016 Andor Pte Ltd - Kaka Bhat
ENTRY DATE & TIME: 04/04/2018 17:44
SUBMITTED BY: Farida Wen Ya Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurers to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 04/04/2018 17:44
Date Of Accident 03/04/2018 17:25
Exact Location Of Accident JUNCTION OF BUKIT BATOK EAST AVE 6 & BUKIT BATOK A
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLT618X
Insured/Policyholder
Name Of Registered Owner R GUNASEGARAN
NRIC No S7244676C
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-93243333
Alternative Phone No OFFICE-93243333

Vehicle Particulars

Manufacturer BMW
Model 523i
Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number GA191132/1
Cover Note Number

Driver

Name of Driver LAL S/O SUBIDOR SINGH
NRIC No S7303209A
Date Of Birth 27/01/1973
Occupation INDOOR
Date Of Driving Pass 30/04/1997
Driving Experience 20 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91487223
Fax Number
Contact Number
Email Address NOEMAIL

Address 61 UPPER SERANGOON VIEW #06-18
Postcode 534015
Was driver an employee of the Insured's Company? NO
If No, Relationship of the Driver with the Insured FRIEND
Vehicle Registration Number of Driver's Own Vehicle
Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in this Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1

NAME: DANNY KHONG
GENDER: MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name PUNGGOL N.P.C
Police Station Address ROAD: 21A TEBING LANE, POSTCODE: 828837, COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE POLICE REPORT NO. T/20180404/2064.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJY8617Z
Vehicle Make/Model/Colour
Details Of Properties VEHICLE B
Vehicle Category PRIVATE CAR
Name of Driver POH LAI HENG
NRIC/Passport Number S1335399I
Contact Number
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

DETAILS OF INJURED PERSON 1

Name

LAL SIO SUBIDOR SINGS

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLT618X

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

DANNY KHONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLT618X

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or Agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 4/4/18


Driver's Signature
(If driver is not the policyholder)
Date & Time: 4/4/18

Reporting Centre Personnel's Signature
Name:
NMIC/PIN No.:

QIA/ACC Form/001/2018 rev. 0.1

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 4/4/18

Driver's Signature
(If driver is not the policyholder)
Date & Time: 4/4/18

Reporting Centre Personnel's Signature
Name:
NARC/FIN No.:

GI/ACC Sketch Plan Form_V3

2



SINGAPORE POLICE FORCE



T/20180404/2064

1 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20180404/2064

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/04/2018 13:15		Vide Report No.:		Station Diary No.: 45
Informant's Particulars				
Name of Informant: LAL S/O SUBIDOR SINGH		Address: 61 UPPER SERANGOON VIEW #06-18 SINGAPORE 534015		
ID Type / ID No.: NRIC NO / S7303209A		Contact No.: Home/Office:	Mobile: 91487223	
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 45	Date of Birth: 27/01/1973	Type of Informant: Driver	
Race: Malayalee		Language: English	Institution / School Name:	
Occupation: SALES CONSULTANT		Driving Licence Information: Class: 3,4		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 03/04/2018 17:25	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 BUKIT BATOK AVENUE 1 BUKIT BATOK EAST AVENUE 6 Cross Junction of Bukit Batok Avenue 1 and Bukit Batok East Avenue 6 (Travelling along Bukit Batok Avenue 1 towards Jurong East)				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SJE8617Z	Car	SUBARU		Silver	Seriously Damaged	1
SLT618X	Car	BMW	532i	Black	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLT618X	AXA INSURANCE SINGAPORE PTE LTD	GA191132/1	28/06/2017	27/06/2018



**SINGAPORE
POLICE FORCE**



T/20180404/2064

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 4

Report No. T/20180404/2064

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	DANNY KHONG @ DANNY WIJAYAKUSUMA	ID No.	S2195822J
Related Vehicle	SLT618X (Car)	Contact No.	98213388
Hospital/Clinic	INTEMEDICAL 24 HR CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	03/04/2018	Date Discharge	03/04/2018
No. of Days granted Medical Leave	05	Degree of Injury	Serious
Driver			
Name	LAL S/O SUBIDOR SINGH	ID No.	S7303209A
Related Vehicle	SLT618X (Car)	Contact No.	91487223
Hospital/Clinic	INTEMEDICAL 24 HR CLINIC	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	03/04/2018	Date Discharge	03/04/2018
No. of Days granted Medical Leave	05	Degree of Injury	Serious
Driver			
Name	POH LAI HENG	ID No.	S1335399I
Related Vehicle	NIL	Contact No.	98269438
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 03/04/2018 at about 1725hrs, I was driving my car one black BMW bearing plate no. SLT618X along Bukit Batok Avenue 1 towards Jurong East. I was in the center lane of the 3 lane road and approaching the cross junction of Bukit Batok Avenue 1 and Bukit Batok East Avenue 6. The traffic light indicated "green" and was in my favour as such I continued driving, however out of a sudden a silver colour Subaru car bearing plate no. SJE8617Z from the opposite direction suddenly came out to do a right turning. I immediately honk and did an emergency braking however could not avoid the silver car. The front of the silver car collided to the right side of my car.



**SINGAPORE
POLICE FORCE**



T/20180404/2064

3 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20180404/2064

CONTINUATION OF REPORT

After the collision, I went out of my car to make a check and called for ambulance. Subsequently, the ambulance and traffic police arrived at scene. My passenger and I felt unwell as such the ambulance made a check on us. We were not conveyed to the hospital as at that point there were valuables in my car and I had to settle my car first. There was no police report number given to us as no one was conveyed to the hospital from scene and we were advised by the traffic police to lodge a police report if we were given more than 3 days MC.

There is no in-vehicle camera installed in my car, however there is a witness Kenneth Seah, H/P: 96945525 who approached us and he has a in-vehicle camera which had captured the accident. It was shown in the footage that the silver car was coming from the opposite direction along Bukit Batok Avenue 1 in the middle lane. The middle lane was a straight only road however the silver car was seen turning right and overtaking a car which was already in the right turning pocket. In the footage, the silver car was seen moving forward to turn right without stopping which caused the collision between my vehicle and his.

After the accident, my passenger and I still felt unwell as such we went to see a doctor and was given 5 days MC each.

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999



T/20180404/2064

4 of 4

Report No. T/20180404/2064

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt ANG PEI YING, AGNES

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MOHAMMAD ZULKARNIAN BIN
SAMSUDIN

Contact No : 65475429

Authentication Stamp

NP188

Signature Of Informant:

Date/Time:

04/04/2018 13:15

Classification Of Case:



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-51/53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

not allowed
 nkr
 1/5 414500/-
 12dy.

527618X

	Front fender o/s	body	881.11	/
	Front fender inner shield o/s	Trn	212.50	/
1set	Front fender inner shield clips o/s	per	48.00	/
	Front fender signal lamp o/s	one	96.65	/
	Front washer tank o/s	de	266.39	/
	Front door o/s	body/ent	1866.32	/
	Front door inner rubber o/s	per	248.20	/
	Front door inner lock o/s	tw/shld	466.30	/
2pr	Front door hinges @ 100.21	tw	200.42	/
	Front door frame chrome moulding o/s	per	148.60	/
	Front door glass outer moulding o/s	nn	89.50	X
	Front door glass regulator & motor o/s	ent/ent	362.30	/
	Front door glass lifter o/s	ent	246.11	/
	Front door inner trim board o/s	ent/en	995.00	/
	Front shock absorber o/s	svc	545.12	X
	Front lower arm o/s	ent/ent	266.02	/
	Front knuckle arm o/s	ent	822.31	/
	Front knuckle arm bearing o/s	per	305.00	/
	Front top arm o/s	tw	288.15	/
	Front door outer pillar o/s	body	745.22	/
	Rear door o/s	body/ent	1820.15	/
	Rear door inner rubber o/s	per	202.30	/
	Rear door inner lock o/s	tw/shld	466.30	/
2pr	Rear door hinges @ 100.21	tw	200.42	/
	Rear door frame chrome moulding o/s	per	138.00	/
	Rear door glass outer moulding o/s	nn	88.50	X
	Rear door glass lifter o/s	ent	246.11	/
	Rear door glass channel o/s	nn	315.30	X
	Rear door inner trim board o/s	svc	920.00	X
	Rocker panel garnish o/s	dis	688.00	/



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-51/53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

SLT 618X

Rocker panel o/s	n	845.11	X
Rocker panel outer bracket o/s	one	122.60	✓
Centre pillar outer o/s	Subs	692.30	✓
	(5h)	15823.31	13019.78
S. Net			
Front sport rim o/s '20 inch'	2/each	1500.00	1000
Rear sport rim o/s '20 inch'	2/each	1500.00	1000
To check wiring		80.00	20
To spray rust proofing		180.00	120
To transfer both o/s door mechanism		180.00	180
To dismantle & refix seat cushion upholstery		150.00	100
To dismantle & refix front dashboard		380.00	300
To conduct wheel alignment		150.00	120
To Dismantle & replacing front undercarriage		180.00	150
To reset & clear fault code		150.00	80
labour for panel beating, cut, weld,		1800.00	1400
straighten & replacing parts		1500.00	1300
To putty & spray painting			
		TOTAL \$ 23573.31	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1803878



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref : CS/TP18006258/Uvbn2	
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883		Date : 08-05-2018	
ON BEHALF OF R GUNASEGARAN		Code : TP149	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected	SLT 618X	
Policy No.	Coverage (\$)	0.00	
Claim No.	Excess (\$)	0.00	
Assign From	Assign Date	05/04/2018	
2. Vehicle Particulars & Condition			
Make & Model	B.M.W 523I (A)	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WBAFP32070C544043	Colour	BLACK
Odometer	232597	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/35 ZR20	YOKOHAMA	6 mm
L/H Front Tyre	255/35 ZR20	YOKOHAMA	6 mm
R/H Rear Tyre	285/30 ZR20	YOKOHAMA	6 mm
L/H Rear Tyre	285/30 ZR20	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/04/2018	Inspection Date	05/04/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 618X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER O/S	BADLY DENTED	861.11	861.11
1	FRONT FENDER INNER SHIELD O/S	TORN	212.50	212.50
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NECESSARY	48.00	48.00
1	FRONT FENDER SIGNAL LAMP O/S	CRACKED	96.65	96.65
1	FRONT WASHER TANK O/S	DEFORMED	266.39	266.39
1	FRONT DOOR O/S	BADLY DENTED / BENT	1,865.32	1,865.32
1	FRONT DOOR INNER RUBBER O/S	NECESSARY	248.20	248.20
1	FRONT DOOR INNER LOCK O/S	TWISTED / SHORTED	466.30	466.30
2	FRONT DOOR HINGES @\$100.21	TWISTED	200.42	200.42
1	FRONT DOOR FRAME CHROME MOULDING O/S	NECESSARY	148.60	148.60
1	FRONT DOOR GLASS OUTER MOULDING O/S	NOT NECESSARY	89.50	-
1	FRONT DOOR GLASS REGULATOR & MOTOR O/S	BENT / SHORTED	362.30	362.30
1	FRONT DOOR GLASS LIFTER O/S	BENT	246.11	246.11
1	FRONT DOOR INNER TRIM BOARD O/S	DEFORMED / CRACKED	995.00	995.00
1	FRONT SHOCK ABSORBER O/S	SERVICEABLE	545.12	-
1	FRONT LOWER ARM O/S	BENT / TWISTED	266.02	266.02
1	FRONT KNUCKLE ARM O/S	BENT	822.31	822.31
1	FRONT KNUCKLE ARM BEARING O/S	NECESSARY	305.00	305.00
1	FRONT TOP ARM O/S	TWISTED	288.15	288.15
1	FRONT DOOR OUTER PILLAR O/S	BADLY DENTED	745.22	745.22
1	REAR DOOR O/S	BADLY DENTED / BENT	1,820.15	1,820.15
1	REAR DOOR INNER RUBBER O/S	NECESSARY	202.30	202.30
1	REAR DOOR INNER LOCK O/S	TWISTED / SHORTED	466.30	466.30
2	REAR DOOR HINGES @\$100.21	TWISTED	200.42	200.42
1	REAR DOOR FRAME CHROME MOULDING O/S	NECESSARY	138.00	138.00
1	REAR DOOR GLASS OUTER MOULDING O/S	NOT NECESSARY	88.50	-
1	REAR DOOR GLASS LIFTER O/S	BENT	246.11	246.11
1	REAR DOOR GLASS CHANNEL O/S	NOT NECESSARY	315.30	-
1	REAR DOOR INNER TRIM BOARD O/S	SERVICEABLE	920.00	-
1	ROCKER PANEL GARNISH O/S	DISTORTED	688.00	688.00

Report Ref No. CS/TP18006258/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ROCKER PANEL O/S	TO REPAIR SEE LABOUR	845.11	-
1	ROCKER PANEL OUTER BRACKET O/S	CRACKED	122.60	122.60
1	CENTRE PILLAR OUTER O/S	BADLY DENTED	692.30	692.30
	LESS 5% DISCOUNT		-	-650.99
			15,823.31	12,368.79
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT SPORT RIM O/S "20 INCH" (SN)	DENTED / BENT	1,500.00	1,000.00
1	REAR SPORT RIM O/S "20 INCH" (SN)	DENTED / BENT	1,500.00	1,000.00
			3,000.00	2,000.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	20.00
	TO SPRAY RUST PROOFING.		180.00	120.00
	TO TRANSFER BOTH O/S DOOR MECHANISM.		180.00	180.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	100.00
	TO DISMANTLE & REFIX FRONT DASHBOARD.		380.00	300.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	120.00
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE.		180.00	150.00
	TO RESET & CLEAR FAULT CODE.		150.00	80.00
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF ROCKER PANEL O/S.		1,800.00	1,400.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,300.00
			4,750.00	3,770.00
	GRAND TOTAL		23,573.31	18,138.79
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			14,500.00

Report Ref No. CS/TP18006258/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.