

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CD TP 18006259/440n2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKUF388H

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

12/4/18 2/5 @ 2800 (Red 3489-38, 55M) (NO RES)

RECEIVED 13 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 12/4 - typist

Report Format : TP

Lump Sum / I.B.I.: (\$ 2800)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS. \$

Photos

Others

TOTAL

145

50

25

80

300

Veh No: SKUF388H Yr Regn: 2 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A /

Make: BMW 2161GT c.c. 1499

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 2542 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA2D920005E91641

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S / Rim / STD A/Rim or

Tyre Size: F: 205 / 55 R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 3/4/18

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 5/4/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref : CS/TP18006259/Uvb	
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883			Date : 05-04-2018	
Code : TP149				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		SKV 8388H
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		05/04/2018
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 03/04/2018		Inspection Date 05/04/2018		
Survey held at		BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0367H
Vehicle Details	
Vehicle No.:	SKV8388H
Vehicle to be Exported:	No
Intended De-registration Date:	05 Apr 2018
Vehicle Make:	B.M.W.
Vehicle Model:	216I GT LED NAV
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	35125114B38A15A
Chassis No.:	WBA2D920005E91641
Maximum Power Output:	75.0 kW (100 bhp)
Open Market Value:	\$30,858.00
Original Registration Date:	12 Feb 2018
First Registration Date:	12 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$35,202.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Feb 2028
PARF Rebate Amount:	\$26,401.00
Intended COE Rebate Details	
COE Expiry Date:	11 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,000.00
COE Rebate Amount:	\$39,402.00
Total Rebate Amount:	\$65,803.00

The information contained herein is correct as at 05 Apr 2018

OK

MSRA18045086 / BME User Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 04/04/2018 16:14
 SUBMITTED BY: FANCY WEN YE HING

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 04/04/2018 16:14
 Date Of Accident 03/04/2018 17:40
 Exact Location Of Accident SERANGOON ROAD,
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKV8388H
 Insured/Policyholder
 Name Of Registered Owner TAI WEI SHIH, FABIAN
 NRIC No S8210367H
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-97657655
 Alternative Phone No OFFICE-97657655

Vehicle Particulars

Manufacturer BMW
 Model 216

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number QA324498/1
 Cover Note Number

Driver

Name of Driver TAI WEI NA
 NRIC No S8603883H
 Date Of Birth 04/02/1988
 Occupation INDOOR
 Date Of Driving Pass 23/04/2009
 Driving Experience 6 YEARS AND 11 MONTHS
 Gender FEMALE
 Mobile Number (LOCAL) +65-97657655
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 172A EDGEDALE PLAINS #12-402
 Postcode 821172
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SIBLING
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 5

Passenger 1
 NAME: CHEN YIXI EVENE
 GENDER: FEMALE

Passenger 2
 NAME: TAI KIN SENG
 GENDER: MALE

Passenger 3
 NAME: TAI ZHEN HYUNG TAYLOR
 GENDER: MALE

Passenger 4
 NAME: LEE FANG YU RANDALL
 GENDER: MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, Against whom?

Circumstances of Accident

I WAS DRIVING ALONG SERANGOON ROAD ON THE 2ND LANE WHEN SUDDENLY I FELT AN IMPACT AT THE REAR OF MY VEHICLE. CAR B HIT MY CAR WHILE TRYING TO CHANGE LANE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number G8D6100K
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE

Name of Driver CHINNAIYAN MURUGANATHAM
NRIC/Passport Number 034112924
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false information may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and so copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 4/4/18

Driver's Signature

(If driver is not the policyholder)

Date & Time: 4/4/18

Reporting Centre Personnel's Signature


Name:

NR/C/PIN No.:

GIA/MS/SPR/2018/0001_V.1

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Serangson Road on the 3rd lane when suddenly I felt an impact at the rear of my car. Car B hit my car while trying to change lane.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 4/4/18

CIAMAC Sketch Plan Form V3

Driver's Signature
(If driver is not the policyholder)
Date & Time: 4/4/18

Reporting Centre Personnel's Signature
Name:
NISC/FFN No.:

2

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18006259/Uvbn2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 17-04-2018



ON BEHALF OF TAI WEI SHIH,FABIAN

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SKV 8388H
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	05/04/2018

2. Vehicle Particulars & Condition

Make & Model	BMW 216I GT (A)	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBA2D920005E91641	Colour	BLUE
Odometer	2542	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R17	BRIDGESTONE	6 mm
L/H Front Tyre	205/55 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55 R17	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/04/2018	Inspection Date	05/04/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 8388H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEEP CUT	1,219.22	1,219.22
1	REAR BUMPER SIDE HOLDER O/S	NECESSARY	66.80	66.80
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER PDC SENSOR	NOT NECESSARY	185.00	-
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	1,688.36	-
1	REAR SPORT RIM O/S	CUT	1,150.00	1,150.00
	LESS 5% DISCOUNT		-	-124.30
			4,359.38	2,361.72
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REFIX REAR PDC SENSOR.		80.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	120.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER O/S.		680.00	380.00
	TO PUTTY & SPRAY PAINTING.		800.00	500.00
			1,930.00	1,150.00
	GRAND TOTAL		6,289.38	3,511.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00

Report Ref No. CS/TP18006259/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.