

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

A/C 1 6265/UPA3 - 1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 723M

at Workshop m/s Jan. 4pm

of _____

Insured: SLP 4959,

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

G/A / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLH 723M Yr Regn: 10 / 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 c.c. 1395

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 21458 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WA42228V8G1109860

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-216

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 29/3/18 D.O.I. 9/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rep.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS + SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0861I
Vehicle Details	
Vehicle No.:	SLH723M
Vehicle to be Exported:	No
Intended De-registration Date:	10 Apr 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI (ATTRACTION)
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	CZC572493
Chassis No.:	WAUZZZ8V8G1109860
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$25,069.00
Original Registration Date:	21 Oct 2016
First Registration Date:	21 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$17,097.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Oct 2026
PARF Rebate Amount:	\$12,822.00
Intended COE Rebate Details	
COE Expiry Date:	20 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,507.00
COE Rebate Amount:	\$43,919.00
Total Rebate Amount:	\$56,741.00

The information contained herein is correct as at 10 Apr 2018

OK