


INSURER: Lonchee Ins. | CC3 / AIG 180 06276, Kima39 | LKK: AWK | IDAC:

INS. CASE OWNER: AWK | **ASSIGNMENT** | Date / Time: 4-4-18 | Registered in Merimen: 3-4-18

Pre-assign / CCU / FTE: SKX 3739B
 Insured Vehicle No.: SKX 3739B | Claim No.: 671095260156
 Name of Insured: Leong Albert | Policy No.: 210442233
 Insured Tel No.: HP: 91887934 | Make / Model: GAZTRON
 Excess Sec II :SS: D.O.A: 03-04-18 | Place of Accident: YCK ROAD
 Is driver the owner? (YES / NO) (YES) | Nature of Accident: _____
 IF NO: Driver Name / Age: _____ | OI GIA REPORT: YES / NO: YES | TP GIA REPORT: YES / NO: YES
 Driver Tel No.: _____ | (VE: YES / NO) _____ | Insured Liability: _____ % | Final? Yes / No: _____



Date / Time	STAGE	DATE / PIC
10/4/18 Revan	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	
11/4/18	Documentation Check List: Handler Typist Notification ltr (if non-pickup): After call ltr to OI: Authorization To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Storage Invoice: OI / GIA: Medical Bill: PPH: Candidate/Reject Instruction: LDU: Payment Breakdown Form: Post-Repair Photos: Others:	
RECEIVED 16 MAY 2018		

PRELIMINARY ADVICE Date/Time: _____ Sent by: _____

FINALIZATION Date/Time: _____ Confirm with: _____

Repair Cost: \$S _____ (_____ days) Reduction: _____ %

FINAL SETTLEMENT Date/Time: 11/5/18 Confirm with: CCCELIA

Final Liability: % 100 (Agreed / Assessed) BU A S/N No.: NL

Repair Cost: \$S 599.20

Loss of Rental (LOR): \$S 163.43 (1 1/2 days) 108-93

Loss of Use (LOU): \$S _____ (5 x 1 1/2 days)

Loss of Income (LOI): \$S 75 (50 x 1 1/2 days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIALTA Search: \$S 747

Medical: \$S _____

Disbursement: \$S _____ (1 row / Independent)

Legal Cost: \$S _____

Total: \$S 845.12 Global Fee: \$S 840.00 /

FINAL PAYMENT Date/Time: _____ Confirm with: _____

Payee 1: \$S 840.00 Name 1: komfortdelgro Engineering Pte Ltd

Payee 2: (Strike if N.A.) \$S _____ Name 2: _____

Payee 3: (Strike if N.A.) \$S _____ Name 3: _____

COPY SENT 17/05/18

Call 7799910

Team: IN ARC Repair TP(CLSO)1 **JOB CARD** Sales Order: JC NO305138424

CUSTOMER NAME: COMFORT TRANSPORTATION PTE LTD CUSTOMER NO: 7010045 ADDRESS: 383 SIN MING DRIVE Singapore SINGAPORE 575717 TEL (R): 65508755 (O) (P) DISCOUNT CARD NO.	REGN NO: SHB6324X	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: SONATA	DATE/TIME IN 04.04.2018 09:45
	YR OF MANU: 25.06.2013	TARGET DATE
	CHASSIS CODE: KMHET41VMDA835118	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 03.04.2018
 NATURE: 3P 03.04.2018

S / NO	LABOR CODE	DESCRIPTION
		AIG - taxi left front damage LKK / Kohni -

CHECKED & PASSED OUT BY: _____

 SERVICE ADVISOR CUSTOMER'S SIGNATURE

Acknowledgement Slip
 Name: _____
 Job No.: **SHB6324X** **LARRY**
 Signature: *Larry Ng*
 Name of Service Advisor: _____
 Signature/Date: _____
 To be returned to Service Reception upon collection.

Exit Pass
 Vehicle No.: **SHB6324X**
 Name of Service Advisor: _____
 Date: _____
 To be kept by Security Guard

ACG

DOA: 03.04.18

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB6324X

MAKE : HYUNDAI

MODEL : SONATA

Date : 04.04.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Front Bumper <i>X Repair</i>			\$ 538.80
1	Front Bumper Top Bracket - LH <i>X 500</i>			\$ 22.40
1	Front Bumper Side Bracket - LH <i>X 500</i>			\$ 14.30
1	Front Bumper Protector - LH <i>X 1400</i>			\$ 29.20
10	Front Bumper clips <i>X 20</i>		\$2.20	\$ 22.00
1	Front Fender - LH <i>X Repair</i>			\$ 593.00
1	Front Fender Retainer - LH <i>X 500</i>			\$ 9.20
SUB TOTAL				\$ 1,228.90
LESS 20%				245.78
DISCOUNTED TOTAL				\$ 983.12
				\$ 0.00
Labour Charge				
Panel Beating				\$ 400.00 ²⁰⁰
Spray Painting Charge				\$ 400.00 ³⁶⁰
Tuff Kote				\$ 100.00 ^{X 20}
TOTAL LABOUR				\$ 900.00
ESTIMATE TOTAL				\$ 1,883.12

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Kahin 10/1/18
4/4/18 1305hrs
2 Prys
45
After Repair p kote

LKK Auto
the Repi
• To repair the
• Third party survey is on a "Without Prejudice" basis
• No illegal motor laborer is allowed
• Supplier entry form must be surveyed and is subject to the terms and conditions of the insurance Company

Acknow:
Sign:
Date:

ACG

DOA: 03.04.18

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB6324X

MAKE : HYUNDAI

MODEL : SONATA

Date : 04.04.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Front Bumper <i>X Myair</i>			\$ 538.80
1	Front Bumper Top Bracket - LH <i>?</i>			\$ 22.40
1	Front Bumper Side Bracket - LH <i>?</i>			\$ 14.30
1	Front Bumper Protector - LH <i>X Myair</i>			\$ 29.20
10	Front Bumper clips <i>X</i>		\$2.20	\$ 22.00
1	Front Fender - LH <i>X Myair</i>			\$ 593.00
1	Front Fender Retainer - LH <i>X</i>			\$ 9.20
SUB TOTAL				\$ 1,228.90
LESS 20%				245.78
DISCOUNTED TOTAL				\$ 983.12
				\$ 0.00
Labour Charge				
Panel Beating				\$ 400.00 ²⁰⁰
Spray Painting Charge				\$ 400.00 ³⁶⁰
Tuff Kote				\$ 100.00 ^X
TOTAL LABOUR				\$ 900.00
ESTIMATE TOTAL				\$ 1,883.12

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Kahin 16/4/18
4/4/18 1305hrs
2 Prys
45
After Repair photo

LKK Auto Consultants - Once notified the Repairer will be responsible for resurveying and displaying damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Checked by Repairer
Signature:
Date:

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305138424
Date : 6. Apr. 2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHB6324X

Date of Accident: 03/04/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SKX3739B

2. The finalized amount shall be:

(a) Spare Parts after List discount 1

(b) Labour Charges \$560.00

Total for Part-By-Part Repair Cost \$560.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: _____

Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Calvin

Date : 6/4/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 06.04.2018

REPAIR ESTIMATE

Time: 08:43:26

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305138424
REGN NO : SHB6324X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 25.06.2013
DATE/TIME IN : 04.04.2018 09:45
ACCIDENT DATE : 03.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 L PANEL BEATING 200.00

0001 23-502 SPRAYPAINT ON AFFECTED AREA 360.00

SUB-TOTAL : 560.00

TOTAL : 560.00

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

M

COMFORTDELGRO ENGINEERING

Our Ref : T 0418 / SHB6324X /CL(st)
 Your Ref: _____
 Date : 11-Apr-18

ComfortDelGro Engineering Pte Ltd
 205 Braddell Road Singapore 579701

CDGE Taxi Claims Dept
 59 Loyang Drive 4th Floor
 Singapore 508969

Mainline +65 6383 6280
 Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 198606489R

Workshops

Braddell
 205 Braddell Road
 Singapore 579701

Loyang
 59 Loyang Drive
 Singapore 508969

Sin Ming
 383 Sin Ming Drive
 Singapore 575717

Pandan
 45 Pandan Road
 Singapore 609286

Ubi
 320 Ubi Road 3
 Singapore 408549

Senoko
 24 Senoko Loop
 Singapore 758158

Sungei Kadut
 7 Sungei Kadut Way
 Singapore 728791

Yishun
 501 Yishun Industrial Park A
 Singapore 768732

AIG ASIA PACIFIC INSURANCE PTE LTD

CHARTIS Buliding

78 Shenton Way

#07-16

Singapore 079120

Attn : **Motor Claims Department** WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHB6324X YOUR INSURED SKX3739B
 AND OTHER _____ ON 03.04.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : **SHB6324X** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SKX3739B** we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$	599.20
2	<u>2</u> days Loss of Rental @ \$ 108.95 per day	\$	217.90
3	Survey Report Fees (<i>Surveyed by M/s LKK</i>)	\$	-
4	GIA / LTA Search Fees	\$	7.49
5	GIA / Police Report Fees	\$	-
6	Towing / Medical / Transportation	\$	-
Sub Total :		\$	824.59

HIRER'S CLAIM

7	<u>2</u> days Loss of Income @ \$ 80.00 per days	\$	160.00
Total Claims :		\$	984.59

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 8 pcs.
 b) LTA search slip/s of : SKX3739B
 c) GIA / Police report/s of : SHB6324X
 d) Letter of authority from owner / hirer / operator
 (X) Photograph/s of Accident Scene () Certificate of Insurance
 () Witness statement/s (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Cecilia Lee

Executive

CDGE Claims Department

Tel : 6214 8354 Fax: 6214 1843 Email : cecillalee@sparkcarcare.com

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG18006276/K1ma3

13 APRIL 2018

LEONG ALBERT
2 SELETAR CRESCENT
SINGAPORE 807154

Dear Sir/Madam,

ACCIDENT INVOLVING SKX 3739B AND SHB 6324X ON 03/04/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: bevanlim@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****SONATA SHB6324X , SKX3739B****ON 03-Apr-18 21:35****T JUNCTION OF JALAN REDOP AND YIO CHU KANG RD**

I / We

KASIM BIN CHHOTE RAI

(Hirer) NRIC No.:

S0281637G

and/or

(Relief) NRIC No.:

Taxi Number

SHB6324X

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

04-Apr-2018

Name of Hirer

KASIM BIN CHHOTE RAI

Hirer NRIC

S0281637G

Signature :



Address

**537 PASIR RIS STREET 51 #06-56
510537**

Contact No.

91497052

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **COMFORTDELGRO ENGINEERING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **SS 840.00** (Global Sum) for vehicle no. **SHB 6324X** that was damaged pursuant to the accident which occurred on **03/04/2018** (date) along **T-JUNCTION OF JALAN REDOP AND YIO CHU KANG RD** (location) involving vehicle no/s **SKX3739B**.

This is pursuant to the inspection conducted on **04/04/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **COMFORT TRANSPORTATION PTE LTD** ("the third party claimant") of vehicle no. **SHB 6324X** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SHB 6324X** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 16th (day) of May (month) 2018 (year)

AWK 

Signed by appointed surveyor

CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD
205 BRADDELL ROAD
SINGAPORE 578701

Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

Please forward your cheque made payable to
COMFORTDELGRO ENGINEERING PTE LTD

TAX INVOICE

8010004
AIG ASIA PACIFIC INSURANCE PTE LTD
#08-16 78 SHENTON WAY, CHARTIS BUILD
SINGAPORE SG 079120
CONTACT NO: 64193000 3225094

VEHICLE NO SHB6324X INV. NO/DATE 91366917 10.04.2018

MAKE HYUNDAI JOB NO. 305138424

MODEL SONATA ODOMETER READING

DATE OF REG 25.06.2013 DATE/TIME IN 04.04.2018 09:45

CHASSIS CODE KMHET41VMDA835118

Issued by : CHEWBEELING 10.04.2018 10:47:00
Repair type : CL30/57/57
Payment Type/Term: /Credit 30 days

1. WHILST TAKING ALL REASONABLE PRECAUTIONS TO PREVENT FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR GEAR OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
2. CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
3. INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
4. PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THE INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91366917	599.20	

Our Ref: CT18040074

Date: 09 April 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 03/04/2018 @ 21:35 hrs
ALONG T JUNCTION OF JALAN REDOP AND YIO CHU KANG
RD
INVOLVING SKX3739B

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHB6324X** (the "Taxi"). The Taxi was hired to **KASIM BIN CHHOTE RAI IC NO S0281637G** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$108.95** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SKX3739B	03 Apr 2018 / 21:35:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous

OK

SHB6324X

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Apr 2018 Edit Reg		04 Apr 2018 00:00 Edit Adj Rpt	\$560.00 Edit Estimates	\$560.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	LEONG ALBERT, ID: S1062656J								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHB6324X	Date of Loss:	03/04/2018 21:00 - :59 [57 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6710952601SG	Policy/Cover Note No.:	2100442233 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKX3739B	Policy No. (Claimant):	MCOM0015						
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 16/04/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
• AIG_SG (06/04/2018): NO TP GIA REPORT									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB6324X (6710952601SG)
[SKX3739B]
TP
COMFORT TRANSPORTATION PTE LTD
Apr 3 2018 9:00PM
[LEONG ALBERT]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Letters/Correspondences														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit			
Assessment Reports														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print			
1	06/04/18 14:25	Accident Statement <small>From: SC - Reg. No: SKX3739B, Claimant: LEONG ALBERT</small>											Load HTM			
Photos/Images														3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
2	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
3	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
4	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
5	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
6	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
7	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
8	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
9	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
10	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
11	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
12	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
13	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
14	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
15	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
16	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
17	05/04/18 17:13	General View											Load JPG <input checked="" type="checkbox"/>			
18	06/04/18 08:38	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>			
19	06/04/18 08:38	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>			
20	06/04/18 08:38	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>			
21	06/04/18 08:38	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>			
Documentation														1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	06/04/18 17:56	TP ESTIMATE - MARKED											Load PDF			
2	06/04/18 17:56	TP GIA REPORT											Load PDF			
3	23/05/18 09:52	WORKSHOP INVOICE											Load PDF			
4	23/05/18 09:52	AUTHORISATION TO ACT FORM											Load PDF			
5	23/05/18 09:52	Release Voucher											Load PDF			
6	23/05/18 09:52	RENTAL RECEIPT											Load PDF			
7	23/05/18 09:52	LTA SEARCH											Load PDF			
8	23/05/18 09:52	LETTER TO OI											Load PDF			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKX3739B (Insd veh)	Model:	HYUNDAI SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO (A)
	SHB6324X (TP veh)		
Date of Accident:	03/04/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:\$	2,014.94	
Final Repair Cost	:\$	840.00	
Loss of Use	:\$	1.50 days at \$50.00 per day	
Rental (if any)	:\$	1.50 days	
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (Global Sum)	:\$	840.00	
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes / No BOLA Scenario No:	
		NIL	
BOLA Liability: _____100____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	:\$	840.00
2)		:\$	
3)		:\$	
4)		:\$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

23 May
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18006276/K1MA3Q2
Date: 23/05/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100442233
Claimant Vehicle No :	SHB6324X	Insured Vehicle No :	SKX3739B
Date of Loss:	03/04/2018	Nature of Claim:	TP
		Claim No:	6710952601SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6324X		
Make & Model:	HYUNDAI SONATA NF, 2.0 CRDI AT ABS 2WD 4DR TURBO (A)	Engine No:	D4EAD322158
Reg. Date:	25/06/2013 (Man. Year: 2013)	Chassis No:	KMHET41VMDA835118
Colour:	Blue	Odometer:	659517 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R16	Rear Tyre Size:	215/65R16
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 7 mm
Front Right Side:	Maxxis 7 mm	Rear Right Side:	Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	983.12	0.00	983.12	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	560.00	340.00	37.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,883.12	560.00	1,323.12	70.26
+ GST 7.00/7.00% (S\$)	131.82	39.20	92.62	70.26
Nett Amount (S\$)	2,014.94	599.20	1,415.74	70.26
+ Loss of Use (1.5 x S\$50.00/day) (S\$)		75.00		
+ Car Rental (1.5 x S\$108.95/day) (S\$)		163.43		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		845.12		
Global Sum Settlement (S\$)		840.00		

INSPECTION

Date of Assignment:	04/04/2018	
Date Inspected:	04/04/2018 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Lim Chin Siong Bevan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	538.80 FL	*- FL
2	1		*FRONT BUMPER TOP BRACKET -LH	Serviceable	22.40 FL	*- FL
3	1		*FRONT BUMPER SIDE BRACKET -LH	Serviceable	14.30 FL	*- FL
4	1		*FRONT BUMPER PROTECTOR-LH	Repair	29.20 FL	*- FL
5	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
6	1		*FRONT FENDER-LH	Repair	593.00 FL	*- FL
7	1		*FRONT FENDER RETAINER-LH	Serviceable	9.20 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,228.90	0.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	245.78	0.00
Total Parts (\$\$)	983.12	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING CHARGE	New	400.00	360.00
3	TUFF KOTE	New	100.00	0.00
Gross Labour Cost (S\$)			900.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >