

22/03/2002

ASS. REC. BY:

REF:

063 / III 800 6294 / Gber

Special Instruction:

SURVAYOR

Molmen

GG

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time:

04042018 258pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 23467

Insured:

SHC 1992U

at Workshop m/s

Lush Automotive

Tel:

9796 6779

of

No. 8 Kaki Bukit Ave 4 #03-47

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04042018

CA / REV / REP. / REV 24 HRS Wp

05-04-2018 @ after 3pm

H.O.D. Endorsement:

Date/Time:

04042018 5.10pm

Person Contacted:

Max

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SJH 23467
	SHC 1992U 063 / III 800 6294 / 15th 6592
	Disassemble: 6/4/2018
	After repair: 9/4/2018

PRS
H&R


REF: III

ASSIGNMENT

From: Date: 5/4/18
 Estimated Cost:
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To inspect Vehicle No: SJG 2346J
 at Workshop m/s Lush Automotive
 of No. 8 Kaki Bkt Ave 4 #03-17
 Insured:
 Policy No.
 Claims No.
 Sum Insured: Excess:
 (Client's Record) after 3pm
 Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:
 IDAC Accident Report: - Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS wpi

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJG2346J Yr Regn: 08
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Daihatsu Terios cc 1795
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: B7214 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: MHKG2CK208K000092
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/65R16
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. D.O.I. 05-04-18
 Survey held at W/S 5:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 11 MAY 2018

Date/Time File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time File Return to?

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

Transportation

1) S + PS SI

2) Photos

3) Others

TOTAL

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech. Invs \$
☐ Weekend \$

Report Format :

PRC

Lump Sum / I.B.I. (\$) :

80
80480

10

250

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 4 April, 2018 2:58 PM
To: Yvonne; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sherini Pillai
Subject: RE: [NOA] III Insured SHC1992U - EAL: 2018.5571.MK.ya - SJG2346J
Attachments: 180404 GIA SJG2346J (ins).pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SJG2346J
III INSURED VEHICLE NO. : SHC1992U
DATE OF LOSS : 04.04.18

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sherini**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Yvonne [mailto:yvonne@ealc.com.sg]

Sent: 04 April, 2018 2:38 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: [NOA] III Insured SHC1992U - EAL: 2018.5571.MK.ya - SJG2346J

Our ref : 2018.5571.MK.ya - **SJG2346J**

Your ref : **SHC1992U**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

India International Insurance Pte Ltd
64 Cecil Street,

For your information only
Owner of **SHC1992U**

#04/#05 IOB Building,
Singapore 049711
Attn: Motor Claims Department
NOTICE OF ACCIDENT

Comfort Transportation Pte Ltd
383 Sin Ming Drive
Singapore 575717

Dear Sir/Madam,

CLAIMANT: LIMO 88 PTE. LTD.

ACCIDENT INVOLVING SJG2346J & SHC1992U ON 04-Apr-18 ALONG PIE FILTER LANE TOWARDS LOR 2 TOA PAYOH AT ABOUT 0710 HOURS

We are instructed by **LIMO 88 PTE. LTD.** to notify you (the insurer of **SHC1992U**) of a road traffic accident on **04-Apr-18 ALONG PIE FILTER LANE TOWARDS LOR 2 TOA PAYOH AT ABOUT 0710 HOURS** involving our client's vehicle registration number **SJG2346J** and vehicle registration number **SHC1992U** driven by your insured at the material time.

A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle **SJG2346J** has been damaged. Before our client proceed to repair the damaged vehicle:

1. Please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle; and
2. Please forward a copy of your insured's report.

Our client proposes to use one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

3. Kelvin Automotive Appraising Services

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Enquire Transfer Fee

Vehicle Details

Vehicle No.: SJG2346J
 Vehicle Type: Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover
 Vehicle Attachment 1: No Attachment
 Vehicle Scheme: Normal
 Vehicle Make: DAIHATSU
 Vehicle Model: F700RG-GQDF TERIOS SX 1.5 AT
 Chassis No.: MHKG2CK208K000092
 Propellant: Petrol
 Engine No.: DAG8202
 Engine Capacity: 1495 cc
 Maximum Power Output: 77.0 kW (103 bhp)

Maximum Laden Weight: 1800 kg

Unladen Weight: 1210 kg

Year Of Manufacture: 2008

Original Registration Date: 25 Jun 2008

Lifespan Expiry Date: -

COE Category: A - Car (1600cc & below)

Quota Premium: \$14,101.00

COE Expiry Date: 24 Jun 2018

Road Tax Expiry Date: 24 Jun 2018

PARF Eligibility Expiry Date: 24 Jun 2018

Date:

Inspection Due Date: 24 Jun 2019

Intended Transfer Date: 11 May 2018

CO2 Emission: -

CO Emission: -

HC Emission: -

NOx Emission: -

PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 4954C

Vehicle Details

Vehicle No.: SJG2346J
Vehicle to be Exported: Yes
Intended De-registration Date: 11 May 2018
Vehicle Make: DAIHATSU
Vehicle Model: F700RG-GQDF TERIOS SX 1.5 AT
Primary Colour: Blue
Manufacturing Year: 2008
Engine No.: DAG8202
Chassis No.: MHKG2CK208K000092
Maximum Power Output: 77.0 kW (103 bhp)
Open Market Value: \$17,764.00
Original Registration Date: 25 Jun 2008
First Registration Date: 25 Jun 2008
Transfer Count: 3
Actual ARF Paid: \$17,764.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Jun 2018
PARF Rebate Amount: \$8,882.00

Intended COE Rebate Details

COE Expiry Date: 24 Jun 2018
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$14,101.00
COE Rebate Amount: \$168.00
Total Rebate Amount: \$9,050.00

The information contained herein is correct as at 11 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/04/2018 13:19
Date Of Accident	04/04/2018 07:40
Exact Location Of Accident	PIE FILTER LANE TOWARDS LOR 2 TOA PAYOH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG2346J
Insured/Policyholder	
Name Of Registered Owner	LIMO 88 PTE. LTD.
Co Reg No	201524954C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96885380
Vehicle Particulars	
Manufacturer	DAIHATSU
Model	F700RG-GQDF TERIOS SX 1.5 AT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5072245905-02 CLASSIC
Cover Note Number	

Driver

Name of Driver	GOH KAH WEI (WU JIAHUI)
NRIC No	S8219238G
Date Of Birth	18/06/1982
Occupation	INDOOR
Date Of Driving Pass	29/03/2006
Driving Experience	12 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96885380
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 678 CHOA CHU KANG CRESCENT #11-624
Postcode	680678
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC1992U
Vehicle Make/Model/Colour	TOYOTA PRIUS HYBRID 1.8 CVT
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 04/04/18

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: enquiry@idacsb.com.sg
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary at the traffic light then suddenly behind vehicle hit me and there was an impact



DECLARATION

I/We declare that the above particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

- 4 APR 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 May 2018 Edit Reg		04 Apr 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	SJG2346J	Date of Loss:	04/04/2018 00:00 - :59 [117 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHC1992U	Policy No. (Claimant):	
		Excess:	
Repairer:	LUSH AUTOMOTIVE PTE LTD (HQ) No. 8 Kaki Bukit Avenue 4,, #03-47 Premier@Kaki Bukit,, 415875 Kaki Bukit - Tel: 86662345		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/05/2018]		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete





Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

*SJG2346J
[SHC1992U]
TP
-

Apr 4 2018 12:00AM
[-]
LUSH AUTOMOTIVE PTE LTD

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/05/18 10:15	General View	 Load PDF	
2	11/05/18 10:15	Photographs of Damaged Parts	 Load PDF	
3	11/05/18 10:16	Photo After Spray	 Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	11/05/18 09:14	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III18006294/GBE2

Date: 11/05/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SJG2346J

Insured Vehicle No : SHC1992U

Date of Loss: 04/04/2018

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJG2346J

Make & Model: DAIHATSU TERIOS, 1.5

Engine No: DAG8202

Reg. Date: 25/06/2008 (Man. Year: 2008)

Chassis No: MHKG2CK208K000092

Colour: Blue

Odometer: 137214 km

Engine Capacity: 1495 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16

Rear Tyre Size:

215/65 R16

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/04/2018

Date Inspected: 05/04/2018 Inspected At:

LUSH AUTOMOTIVE PTE LTD (HQ)
No. 8 Kaki Bukit Avenue 4,, #03-47
Premier@Kaki Bukit,
Singapore 415875

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 11 May 2018)
Parts: M1-SUV DAIHATSU TERIOS 1.5 (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJG2346J)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >