

21472001

ASS. REC. BY:

REF:

CS/CTI18006315/ T19d3

Field Instructions

Surveyor

Menimen

From (Person):

Taufik
Irene Tay

ASSIGNMENT (Office)

of CTI

Date/Time:

5/4/18 @ 3:37pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 483L

Insured:

YM 9688S

at Workshop n/o:

Weemmes Automotive

Tel:

6378 2680

of

28 Leng Kee Rd

Policy No:

DMCVSN3013331800

Claim No:

SNM18D01774C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/04/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

4:35pm @ 5/4/18

Person Contacted:

Mandy

Vehicle IN (OUT)

Date/Time

Action/Instruction

(✓)

Estimate

SLB 483L - X

YM 9688S - NS / INC 14007799 / CI

D.O.A: 25/4/18

13/4/18 @ 5:09pm Confirmed with Mandy final Ag \$10669.67, 4 days by email!

(Red & 2727.65, 25%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18006315/T1qd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 05-04-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 9688S	Veh. Inspected	SLB 483L
Policy No.	DMCVSN3013331800	Coverage (\$)	0.00
Claim No.	SNM18D01774C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	05/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/04/2018	Inspection Date
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2018		05 Apr 2018 15:37 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	OH LI FANG		
Vehicle Reg. No.:	SLB483L	Date of Loss:	02/04/2018 00:00 - :59
Claim Type:	TP / SNM18D01774C02	Policy/Cover Note No.:	DMCVSN3013331800
Vehicle Reg. No. (Insured):	YM96885	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/04/2018]		
Adj Asg. Remarks:	EST \$10,960.00 , CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 23 July 2018 5:09 PM
To: 'Mandy Neo'; SUR; Taufikh (LKKAUTO)
Subject: RE: SLB483L Finalization

Dear Mandy,

WITHOUT PREJUDICE

Confirm final fig \$10,669.67 before GST and 4 repair days.

Kindly send the relevant documents to insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mandy Neo <mandy.neo@wearnes.com>
Sent: Monday, 25 June 2018 9:55 AM
To: SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: SLB483L Finalization

Hi

Vehicle SLB483L
Attached copy for finalization

Best regards,

Mandy Neo
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
49 Alexandra Road 159935
F (65) 6264 7137 O (65) 97704368
www.wearnes.com mandy.neo@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: it.services@wearnes.com [<mailto:it.services@wearnes.com>]
Sent: Monday, 25 June, 2018 9:34 AM
To: Mandy Neo
Subject: Attached Image

53463

MOR118044257 / ETHQZ Protect Pte Ltd - Bukit Batok
 ENTRY DATE & TIME: 03/04/2018 11:36
 SUBMITTED BY: Toh Khair Idan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/04/2018 11:36
Date Of Accident	02/04/2018 17:30
Exact Location Of Accident	OPEN SPACE CAR PARK NEAR BLK625A CHOA CHU KANGST62
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB483L
Insured/Policyholder	
Name Of Registered Owner	OH LI FANG
NRIC No	S8426806B
Email Address	CELEST.OH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92743498
Alternative Phone No	OFFICE-92743498

Vehicle Particulars

Manufacturer	JAGUAR
Model	XE 2.0 I4D TSS-2.0 D (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01005339
Cover Note Number	

Driver

Name of Driver	ONG PENG CHYE (WANG BINGCAI)
NRIC No	S7441855D
Date Of Birth	26/10/1974
Occupation	INDOOR
Date Of Driving Pass	09/09/1999
Driving Experience	18 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90991855
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 445 CHOA CHU KANG AVE 4 #04-301 SINGAPORE 680445
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN AND POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Details of Witness 1

Name	JOE
Phone Number	81417518
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM9688S
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


3/4/18 1150am.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

run Khar Kian

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 3/4/18 open space car park.

Refer to Police Report No: T20180403/2013 dd 3/4/18.

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

- Reporting Only
- Claim OD
- Claim TP
- Claim OD/TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature
Date & Time


Driver's Signature
(if driver not the policyholder)
Date & Time

3/4/18 1150am

Reporting Centre Personnel's Signature
Name:
Nric/Fin No. Toh Khar Kian

Owner letter of consent

I (owner name) Sh lifang i/c S8426806B
owner of this car no SLB 483L authorize
the driver (name) Francis Ong Peng Chye ik no
S7441855D to file accident report which
happened on (Accident Date) 2/4/18 at
(Location) open carpark next to Yew Teo
market

Owner's name: Sh lifang
Signature: 

~~Owner~~

220-2

Sketch Plan Pg. 7





**SINGAPORE
POLICE FORCE**



T/20180403/2013

1 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20180403/2013

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/04/2018 10:49		Vide Report No.:		Station Diary No.: 43
Informant's Particulars				
Name of Informant: ONG PENG CHYE, FRANCIS		Address: APT BLK 445 CHOA CHU KANG AVENUE 4 #04-301 SINGAPORE 680445		
ID Type / ID No.: NRIC NO / S7441855D		Contact No.: Home/Office: Mobile: 90991855		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 43	Date of Birth: 26/10/1974	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: ENGINEER		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 02/04/2018 17:30	Type of Location: Car Park
Location: Along Road 1 CHOA CHU KANG STREET 62				
Open spaced car park near Blk 625A Choa Chu Kang St 62, along double yellow line.				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SLB483L	Car	JAGUAR	XE 2.0 I4D TSS	Black	Slightly Damaged	0
YM9688S	Lorry					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180403/2013

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

2 of 3

Report No. T/20180403/2013

CONTINUATION OF REPORT

Driver			
Name	ONG PENG CHYE, FRANCIS		ID No. S7441855D
Related Vehicle	SLB483L (Car)		Contact No. 90991855
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On 02/04/2018 at about 1715hrs, I parked my vehicle at an open spaced car park near Blk 625A Choa Chu Kang St 62 along the yellow line and went to buy dinner.

On the same day at about 1900hrs, I came back to my car and was approached by a witness namely Joe, HP: 81417518, that someone had collided with my vehicle when I was not around while reversing. He further informed that the driver of the lorry had alighted and looked at my vehicle after colliding with it. He then left without leaving any notes. Joe also provided me the number plate of the vehicle, YM9688S, and willing to be the witness of this accident.

My vehicle suffered a cracked front grille, a scratched front bumper and a dented bonnet.

After I went home, I retrieved my in-car camera footage and saw that at about 1730hrs, a lorry, YM9688S, who was parked in front of me, reversing and collided with the front of my vehicle.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilogram 09 Sep 1999

NP 428A



Licence No: S7441855D

3 6 7 3 3 4 6



NRIC No: S7441855D



Date of issue

08-02-2005

APT BLK 445 CHOA CHU KANG AVENUE 4 #04-301
SINGAPORE 680445

NRIC No: S7441855D

Date: 04/03/2011

No: 6670661

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of a man with glasses.

Licence Number: **S7441855D**
Name: **ONG PENG CHYE (WANG BINGCAI)**

Birth Date: **26 Oct 1974**
Issue Date: **15 Aug 2003**

Barcode: **000748230J**

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7441855D**

Portrait of a man with glasses.

Name: **ONG PENG CHYE, FRANCIS**
王炳财

Race: **CHINESE**

Date of birth: **26-10-1974** Sex: **M**

Country of birth: **SINGAPORE**

Small crest logo on the right.



SINGAPORE POLICE FORCE



T/20180403/2013

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

1 of 3

Report No. T/20180403/2013

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/04/2018 10:49	Vide Report No.:	Station Diary No.: 43
--	------------------	--------------------------

Informant's Particulars

Name of Informant: ONG PENG CHYE, FRANCIS			Address: APT BLK 445 CHOA CHU KANG AVENUE 4 #04-301 SINGAPORE 680445		
ID Type / ID No.: NRIC NO / S7441855D			Contact No.: Home/Office: Mobile: 90991855		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 43	Date of Birth: 26/10/1974	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: ENGINEER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 02/04/2018 17:30	Type of Location: Car Park
Location: Along Road 1 CHOA CHU KANG STREET 62				
Open spaced car park near Blk 625A Choa Chu Kang St 62, along double yellow line.				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume:
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLB483L	Car	JAGUAR	XE 2.0 I4D TSS	Black	Slightly Damaged	0
YM9688S	Lorry					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

CONTINUATION OF REPORT

Driver			
Name	ONG PENG CHYE, FRANCIS		ID No. S7441855D
Related Vehicle	SLB483L (Car)		Contact No. 90991855
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 02/04/2018 at about 1715hrs, I parked my vehicle at an open spaced car park near Blk 625A Choa Chu Kang St 62 along the yellow line and went to buy dinner.

On the same day at about 1900hrs, I came back to my car and was approached by a witness namely Joe, HP: 81417518, that someone had collided with my vehicle when I was not around while reversing. He further informed that the driver of the lorry had alighted and looked at my vehicle after colliding with it. He then left without leaving any notes. Joe also provided me the number plate of the vehicle, YM9688S, and willing to be the witness of this accident.

My vehicle suffered a cracked front grille, a scratched front bumper and a dented bonnet.

After I went home, I retrieved my in-car camera footage and saw that at about 1730hrs, a lorry, YM9688S, who was parked in front of me, reversing and collided with the front of my vehicle.



**SINGAPORE
POLICE FORCE**



T/20180403/2013

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 3

Report No. T/20180403/2013

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
J /
Sgt 2 NG TYAN SOON

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / HRT /
Sr Staff Sgt ESTHER CHONG
Contact No.: 65476368

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
03/04/2018 10:49

Classification Of Case:



**SINGAPORE
POLICE FORCE**



T/20180403/2013

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 3

Report No. T/20180403/2013

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ Sgt 2 NG TYAN SOON	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 03/04/2018 10:49
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHONG Contact No.: 65476368	Classification Of Case:
Authentication Stamp NP168	

CLK

SERVICE ESTIMATE

84732 - C00001 SL: SERVICE SALES - PC

Ms Oh Li Fang
445 Choa Chu Kang Ave 4
04-301

Singapore 680445

Closed by : Mandy Neo
Svc Consultant :
Remarks : Ms Oh Li Fang

GST Reg.No: M28920628X
Inv.No. : B&P 0 Page 1
Inv.date : 03/04/2018
WIP No. : 53493
Veh.In/Out:
*Tel.No. : Mobile: 90991855FRANC
Reg.No. : SLB483L
Reg.date : 24/03/2016
Mileage : 0
Chassis No: SAJAB4AN1GA925926

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
302	TO REPLACE FRONT BONNET, 900	0	2700.00	0		2,700.00	S
	FRT BUMPER, FRT BRACKET, FRT GRILL, ETC					1800 ✓	
800	TO PUTTY SPRAY PAINT ON FRT BONNET, FRT BUMPER, ETC	0	2400.00	0		2,400.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		✓ 486.00	S
	BONNET PANEL XE	1138.68 1.0 EA	1265.20		bt ✓	1,265.20	S
	COVER-BUMPER	1540.99 1.0 EA	1712.20		de ✓	1,712.20	S
	BRACKET-FEND	1.0 EA	34.10		X nn ✓	34.10	S
	BRACKET-FEND	1.0 EA	34.10		7 ✓	34.10	S
	PANEL-FENDER	1.0 EA	667.30		✓	667.30	S
	ADHESIVE SEALER FL2	1.0 EA	425.40	382.86	NE ✓	425.40	S
	GRILLE-RADIA	1.0 EA	435.70	392.13	CHO ✓	435.70	S
	BUMPER BRACKET PLAST	10.0 EA	4.80	43.20	NE ✓	48.00	S
	NUT	10.0 EA	3.50	31.50	NE ✓	35.00	S

Radum grille

Labour Total 5,586.00
Parts Total 4,657.00
Package Total 0.00

Gross Total. 10,243.00
Net..... 10,243.00
GST @ 7.0% 717.01
Total..... 10,960.00
Paid..... 0.00
Please Pay.. 10,960.00

GST: S=StdRated; O=OutOfScope

Wearnes Auto Consultants must notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary detail(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Tough: 97445749
21/4/18 1430
4 days
* Resurvey before paint
surve | kkanato.com
1279232

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date : 22/06/2018
 SINGAPORE 079909 WIP No. : 53493
 Veh.In/Out: 21/05/2018 18/06/2018
 *Tel.No. : 63896111
 Reg.No. : SLB483L
 Reg.date : 24/03/2016
 Mileage : 0
 Chassis No: SAJAB4AN1GA925926
 Closed by : Mandy Neo
 Svc Consultant :
 Remarks : Ms Oh Li Fang

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BONNET, FRT BUMPER,FRT BRACKET,FRT GRILL,ETC	0	1800.00	0	1,800.00	\$	✓
800	TO PUTTY SPRAY PAINT ON FRT BONNET,FRT BUMPER,ETC	0	1700.00	0	1,700.00	\$	✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0	486.00	\$	✓
	BONNET PANEL XE 1	1.0 EA	1265.20	10	1,138.68	\$	
	COVER-BUMPER 2	1.0 EA	1712.20	10	1,540.98	\$	
	ADHESIVE SEALER FL2 6	1.0 EA	425.40	10	382.86	\$	
	GRILLE-RADIA 7	1.0 EA	435.70	10	392.13	\$	
	BUMPER BRACKET PLAST 8	10.0 EA	4.80	10	43.20	\$	
	NUT 9	10.0 EA	3.50	10	31.50	\$	
	PANEL-NOSE <i>supp</i>	1.0 EA	89.50	10	80.55	\$	H ✓
	DUCT-AIR <i>supp</i>	1.0 EA	109.70	10	98.73	\$	am ✓
	JT4A1410/HEADLAMPS <i>supp</i>	1.0 EA	3305.60	10	2,975.04	\$	Geny ✓
	Gross Total.				10,669.67		
Labour Total	3,986.00	Net.....			10,669.67		
Parts Total	6,683.67	GST @ 7.0%			746.88		
Package Total	0.00	Total.....			11,416.55		
		Paid.....			0.00		
		Please Pay..			11,416.55		

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. . : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date. : 25/06/2018
 SINGAPORE 079909 WIP No. . : 53493
 Veh.In/Out: 21/05/2018 18/06/2018
 *Tel.No. . : 63896111
 Reg.No. . : SLB483L
 Closed by : Mandy Neo Reg.date .: 24/03/2016
 Svc Consultant : Mileage .. : 0
 Remarks : Ms Oh Li Fang Chassis No: SAJAB4AN1GA925926

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

NOTES	SUPP ITEMS	0	0.00	0		S	
	PANEL-NOSE	1.0 EA	89.50	10	80.55	S	4 hr
	DUCT-AIR	1.0 EA	109.70	10	98.73	S	1 hr
	JT4A1410/HEADLAMP	1.0 EA	3305.60	10	2,975.04	S	1 hr

		Gross Total.	3,154.32
Labour Total	0.00	Net.....	3,154.32
Parts Total	3,154.32	GST @ 7.0%	220.80
Package Total	0.00	Total.....	3,375.12
		Paid.....	0.00
		Please Pay..	3,375.12

GST: S=StdRated; O=OutOfScope; Z=ZeroRated






































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Apr 2018		05 Apr 2018 15:37 Edit Adj Rpt	S\$10,669.67 Edit Estimates	S\$10,669.67 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, ID: -									
Main Claimant: OH LI FANG									
Vehicle Reg. No.: SLB483L		Date of Loss: 02/04/2018 00:00 - :59 [24 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D01774C02		Policy/Cover Note No.: DMCVSN3013331800							
Vehicle Reg. No. (Insured): YM9688S		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/04/2018]									
Adj Asg. Remarks: EST \$10,960.00 , CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB483L (SNM18D01774C02)
[YM9688S]
TP
OH LI FANG
Apr 2 2018 12:00AM
[-]
Wearnes Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/07/18 16:36	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/07/18 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
30	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/07/18 16:37	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
38	23/07/18 16:37	General View		Load JPG <input checked="" type="checkbox"/>
39	23/07/18 16:37	General View		Load JPG <input checked="" type="checkbox"/>
40	23/07/18 16:37	General View		Load JPG <input checked="" type="checkbox"/>
41	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
42	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
43	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
44	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
45	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
46	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
47	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
48	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
49	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
50	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	23/07/18 16:40	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	05/04/18 15:36	REPAIR EST		Load PDF <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	26/07/18 08:48	SUPPLEMENTARY PART		Load PDF <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118006315/T1QD3Q2

Date: 26/07/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3013331800

Claimant Vehicle
No: SLB483LInsured Vehicle
No: YM9688S

Date of Loss: 02/04/2018

Nature of Claim: TP

Claim
No: SNM18D01774C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB483L

Make & Model: JAGUAR XE 2.0 I4D TSS, 2.0 D (A)

Engine No: 150930W0144204DTD

Reg. Date: 24/03/2016 (Man. Year: 2015)

Chassis No: SAJAB4AN1GA925926

Colour: Black

Odometer: 49591 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 R19

Rear Tyre Size: 235/35 R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,811.32	6,683.67	1,127.65	14.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,586.00	3,986.00	1,600.00	28.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,397.32	10,669.67	2,727.65	20.36
+ GST 7.00/7.00% (S\$)	937.81	746.88	190.93	20.36
Nett Amount (S\$)	14,335.13	11,416.55	2,918.58	20.36

INSPECTION

Date of Assignment: 05/04/2018

Date Inspected: 21/05/2018 Inspected At:

Wearnes Automotive Pte Ltd (Leng Kee)
28 Leng Kee Road
Singapore 159105

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jul 2018)	
Parts:	N/A	JAGUAR XE 2.0 I4D TSS 2.0 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB483L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET PANEL XE	Bent	1,265.20 FS	*1,138.68 FS
2	1		*COVER-BUMPER	Deformed	1,712.20 FS	*1,540.98 FS
3	1		*BRACKET -FEND	Not Necessary	34.10 FS	*- FS
4	1		*BRACKET -FEND	Not Necessary	34.10 FS	*- FS
5	1		*PANEL -FENDER	Not Necessary	667.30 FS	*- FS
6	1		*ADHESIVE SEALER FL2	Necessary	425.40 FS	*382.86 FS
7	1		*GRILLE -RADIA	Cracked	435.70 FS	*392.13 FS
8	10		*BUMPER BRACKET PLAST	Necessary	48.00 FS	*43.20 FS
9	10		*NUT	Necessary	35.00 FS	*31.50 FS
10	1		*PANEL -NOSE	Bent	80.55 FS	*80.55 FS
11	1		*DUCT- AIR	Cracked	98.73 FS	*98.73 FS
12	1		*JT4A1410/HEADLAMP	Cracked	2,975.04 FS	*2,975.04 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **7,811.32** **6,683.67**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BONNET FRT BUMPER ,FRT BRACKET ,FRT GRILLE ETC	New	2,700.00	1,800.00
2	TO PUTTY SPRAY PAINT PAINT ON FRT BONNET ,FRT BUMPER ,ETC	New	2,400.00	1,700.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	486.00	486.00
Gross Labour Cost (S\$)			5,586.00	3,986.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >