

REF: CS / LAW 1800648 / Uvbn2

Special Instruction:

US: ~~\$~~ 6700.00

### ASSIGNMENT (Office)

From (Person): Karen Leung of Lawrence Chua Date/Time: 28/03/2018  
Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

*Third Parties:*

Claimant:

Surveyor: MC-Coy Appraisers

Workshop: Blümel Automotive

OD(TP Re-inspection) / Evaluation

To Inspect Vehicle No: SJJ 3789S Insured: SHA 3942L

at Workshop m/s **Bluiwet Automotive** Tel: **6745 2088**

of Bik 1 Kaki Bukit Ave 6 #01-55

Policy No: MN.TG.B1.1711959 Claim No: RY/R5-981-18/K

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 06-10-2017

(Client's Record)

D.O.A. 06.10.2017

06/04/2018 (Friday) @ Ham

275

H.O.D. Embarsement/Date

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: \_\_\_\_\_ Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_\_ days (Red \$ \_\_\_\_\_ / \_\_\_\_\_ %; Original 9 days)

Date/Time: 13/4/18 Submit Final Fig 4922 8 days (Red \$ 1800 / 27 %; Original days)

Date/Time	Action/Instruction
	<p>SJJ 3789S - X</p> <p>SHA 3942L - 004/III 1800394/TK03</p> <p>NO. 8 Tampines Industrial Drive [5-2 8544]</p> <p>83992362</p>
	<p>RECEIVED 13 APR 2018</p>

---

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

**Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)**

\$ 1000.00

**Para(3) : Nett Value**

Market Value :

Salvage Value :

Nett Value :

Inspected/  
Evaluated by:

*Fee Charged:*

Date: \_\_\_\_\_

Basic & Add	
Transport	
Photos	
Others	
Total	

1000

1) Date/Time 13/4-4:15 File Pass to

2) Date/Time

File Return to

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

#### 4) Date/Time

File Return to

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time

File Return to



## Catherine Chong (LKK Auto)

---

**From:** Karen Leong <karen@lcp.com.sg>  
**Sent:** Tuesday, 3 April, 2018 3:27 PM  
**To:** 'Catherine Chong (LKK Auto)'  
**Subject:** FW: Appointing your firm as Single Joint Expert  
**Attachments:** R5-981 Survey Report by Mc-coy.pdf; R5-981 Re-inspection report by Vicom.pdf; R5-981 Plf's GIA report.pdf; R5-981 Def's GIA report.pdf

Hi Catherine,

Thank you for your e-mail dated 29/3/2018.

As requested, we attach the following documents :-

1. Survey Report dated 20/10/2017 by Mc-Coy Appraiser Pte Ltd;
2. Re-inspection Report dated 10/11/2017 by Vicom Ltd;
3. Plaintiff's GIA report;
4. Defendant's GIA report.

Please contact Plaintiff's lawyers directly to make the arrangements for a physical survey.

M/s M Nedumaran & Co  
No. 11 Sin Ming Road  
#B2-09 (Unit 2) Thomson V Two  
Singapore 417883  
Tel : 65098480 / 65098481  
Fax : 65098482  
E-mail : [igene.lim@mneduco.com.sg](mailto:igene.lim@mneduco.com.sg)  
Ref : MN.IG.B1.1711959

---

**From:** Catherine Chong (LKK Auto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Thursday, 29 March 2018 10:22 AM  
**To:** 'Karen Leong' <karen@lcp.com.sg>  
**Cc:** 'assignments' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: Appointing your firm as Single Joint Expert

Dear Karen,

Thank you for the email.

We are pleased to submit our Professional Fee Charges (Single Joint Expert) as follows:

Paper Survey - \$700.00

Physical Re-inspection - \$1,000.00

Court Attendance Expert Witness Fee :

- (a) State Courts
- i) Half day \$400.00
  - ii) Full day \$800.00

All above charges are subject to GST 7%.

Kindly provide us both party survey report, colour photograph and GIA report.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Karen Leong [<mailto:karen@lcp.com.sg>]

**Sent:** Thursday, 29 March, 2018 8:19 AM

**To:** 'Catherine Chong (LKK Auto)' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Subject:** RE: Appointing your firm as Single Joint Expert

Hi Catherine,

Repair is done by Bluwel Automotive Service Pte Ltd.

Regards,

Karen

Secretary to Roger Yek

Lawrence Chua Practice LLC

33 Kreta Ayer Road

Singapore 088999

Tel : 6671 8340 Fax : 6221 1084

Ref : LC/R5-981-18/kl

---

**From:** Catherine Chong (LKK Auto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Sent:** Wednesday, 28 March 2018 7:02 PM

**To:** 'Karen Leong' <[karen@lcp.com.sg](mailto:karen@lcp.com.sg)>

**Cc:** 'assignments' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Subject:** RE: Appointing your firm as Single Joint Expert

**McAfee Web Control Warning**

This e-mail message contains potentially unsafe links to these sites:



<mailto:assignments@lkkauto.com>

Dear Karen,

Kindly provide us the workshop detail.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Karen Leong [<mailto:karen@lcp.com.sg>]

**Sent:** Wednesday, 28 March, 2018 6:03 PM

**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Subject:** RE : Appointing your firm as Single Joint Expert

Hi Catherine,

We refer to the above matter.

We act for India International Insurance in a property damage claim.

Plaintiff has agreed to appoint your firm as single joint expert.

Plaintiff has survey report by Mc-coy and we have paper re-inspection report by Vicom.

Please let us have your quotation on the fees for preparing single joint expert report.

Please also let us have your quotation on the fees for Court attendances.

What are the documents you need from us to prepare the single joint expert report?

Please let us have your reply as soon as possible.

Regards,

Karen

Secretary to Roger Yek

Lawrence Chua Practice LLC

33 Kreta Ayer Road

Singapore 088999

Tel : 6671 8340 Fax : 6221 1084

Ref : LC/R5/R5-981-18/kl

**Catherine Chong (LKK Auto)**

---

**From:** Igene Lim <igene.lim@mneduco.com.sg>  
**Sent:** Wednesday, 4 April, 2018 12:27 PM  
**To:** Catherine Chong (LKK Auto)  
**Cc:** hislaw@lcp.com.sg  
**Subject:** RE : SJE | RE-INSPECTION ON SJJ 3789S | LCP'S REF : RY/R5-981-18/kl | MC SUIT NO. 1883/2018

WITHOUT PREJUDICE

Our Ref : MN.IG.B1.1711959

Hi Catherine,

As requested, we have made an arrangement for our client's vehicle **SJJ 3789S** to be re-inspected by your surveyor appointed by both parties as a Single Joint Expert in this matter as follows:

<b>Date</b>	}	<b>6 April 2018 (Friday)</b>
<b>Time</b>	}	<b>11.00 a.m.</b>
<b>Venue</b>	}	<b>Bluwel Automotive Service Pte Ltd 1 Kaki Bukit Avenue 6, #01-55, Autobay, Singapore 417883</b>
<b>Contact</b>	}	<b>Ms Sally @ 6745-2088</b>

Kindly ensure that your surveyor attends to the above without fail.

With thanks & regards,

**Igene Lim**

*(For and on behalf of Mr Nedumaran Muthukrishnan)*

**M NEDUMARAN & CO**

**Advocates & Solicitors**

**Commissioner for Oaths**

Branch Office :

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel : 6509-8480 / 6509-8481

Fax : 6509-8482

Email : [igene.lim@mneduco.com.sg](mailto:igene.lim@mneduco.com.sg)

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509-8480 if you have received this message in error. Thank you.

---

**From:** Catherine Chong (LKK Auto) [mailto:[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)]

**Sent:** Tuesday, April 3, 2018 7:47 PM

To: Igene Lim <igene.lim@mneduco.com.sg>

Subject: SJE

Dear Igene,

Kindly arrange appointment Re-Inspection for this SJE case.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	8385D
<b>Vehicle Details</b>	
Vehicle No.:	SJJ3789S
Vehicle to be Exported:	No
Intended De-registration Date:	19 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS J AUTO
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1NZX777215
Chassis No.:	MR053HY9305073869
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,434.00
Original Registration Date:	11 Sep 2008
First Registration Date:	11 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$11,434.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Sep 2018
PARF Rebate Amount:	\$5,717.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	10 Sep 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,685.00
COE Rebate Amount:	\$577.00
<b>Total Rebate Amount:</b>	<b>\$6,294.00</b>

The information contained herein is correct as at 13 Apr 2018

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as fruthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/10/2017 14:29
Date Of Accident	06/10/2017 17:20
Exact Location Of Accident	ALONG CTE AFTER UPPER SERANGOON EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ3789S
Insured/Policyholder	
Name Of Registered Owner	WEIDA LOGISTICS AND SUPPLY
Co Reg No	53338385D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83992362
Alternative Phone No	OFFICE-83992362
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS J AUTO
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092987128
Cover Note Number	
Driver	
Name of Driver	LYE EDREI
NRIC No	S7822321I
Date Of Birth	12/08/1978
Occupation	OUTDOOR
Date Of Driving Pass	02/09/2005
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83992362
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address APT BLK 715 YISHUN STREET 71 #08-288  
Postcode 760715  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - HIRER  
Vehicle Registration Number of Driver's Own Vehicle  
Insurance Company of Driver's Own Vehicle

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
Weather Conditions DRIZZLING  
Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Was any body injured in the Accident? NO  
Was any other material or property damaged? YES  
( have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

( Vehicle Registration Number SHA3942L  
Vehicle Make/Model/Colour  
Details Of Properties  
Name of Driver WILLIE KOH CHOON HEE (WILLIE XU CHUNXI)  
NRIC/Passport Number S7349462A  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**Details of Witness**

Name  
Phone Number  
Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SLN2193Y  
Vehicle Make/Model/Colour

▼ Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquires by me;  
(iv) administering my claims (including the filing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the claims as well as on the external cover of any enclosed mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes";  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their law firms/law firms, which may be based outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Exit to road via Singapore / PIE



### Sketch Plan #2

## Describe Circumstances of the Accident

While driving along ILE right after Upper Scrangoon / PLE Exit (Toward City)  
Holds Vehicle INVAZ 93 Y 26... at me they I ~~was~~ bumper and stopped right behind  
him A few second later, I felt and no impact at the back of my car and  
cause my car to leave the back of the front vehicle. I came out of the car and  
found over a Taxi (no number) SHA 2442L was the one that bumped me and cause  
me to bang the front cap.

Weather = very wet (dec. 22/10)

Time = April 1720hr

Date: 6/10/17

### Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/10/2017 08:59
Date Of Accident	06/10/2017 17:25
Exact Location Of Accident	CTE(CITY) AFT BRADDELL EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3942L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0016
Cover Note Number	
<b>Driver</b>	
Name of Driver	WILLIE KOH CHOON HEE
NRIC No	S7349462A
Date Of Birth	23/10/1973
Occupation	OUTDOOR
Date Of Driving Pass	19/04/2007
Driving Experience	10 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 512B YISHUN ST 51
	#07-487
Postcode	762512
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ3789S
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT AND REAR
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLN2193Y
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

**Details of Witness**

Name

Phone Number

Email Address



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes"
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303021R

Policyholder's Signature / Date & Time

Driver's Signature (driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

BTE (City) Apt Braddell Exit

A B C

A) SH A 3942 L  
B) SEI 3781 S  
C) SLN 2193 Y

Sketch Plan Pg. 2

Describe Circumstances of the Accident

On 6/10/17 at about 1735hrs while I Veh A was travelling along the Lane 1, collided on the rear of Veh B when it stopped suddenly. When I came out to check, it was realized that Veh C was also involved in the chain collision.

Declaration

We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 129303821R

Policyholder's Signature / Date &  
Time

Driver's Signature (if driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel

*SR Moorthy*  
7/10/17  
SR Moorthy  
CSO

Report Reference : **TP / 17009-10/MY / 2017**  
 Date of Report : **20 Oct 2017**

Weida Logistics And Supply  
 c/o No.1 Kaki Bukit Ave 6  
 #01-53/55 AutoBay@ Kaki Bukit  
 Singapore 417883

**THIRD PARTY SURVEY**  
**ACCIDENT HAPPENED ON 6 Oct 2017**

Workshop Address : Bluwel Automotive Service Pte Ltd  
 No.1 Kaki Bukit Ave 6  
 #01-53/55 AutoBay@ Kaki Bukit  
 Singapore 417883

As per your instruction dated **9 Oct 2017** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SJJ 3789 S**. We enclosed herewith our report and findings as follows:

**1. VEHICLE PARTICULARS**

Registration No	: SJJ 3789 S	Engine No	: 1NZX777215
Model	: Toyota Vios	Mileage	: 120576
Year / Capacity	: 2008/1497	Colour	: White
Chassis No	: MR053HY9305073869		

**2. TYRES CONDITION**

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 185/60 R15	Yokohama	2.00	mm	Sport
REAR O/S	: 185/60 R15	Yokohama	4.00	mm	Sport
FRONT N/S	: 185/60 R15	Bridgestone	4.00	mm	Sport
REAR N/S	: 185/60 R15	Yokohama	4.00	mm	Sport

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear and front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 9 working days to complete.
5. Enclosed number of photograph : 173 copies.
6. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SJJ 3789 S  
Report No: TP/ 17009-10/MY / 2017

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
2	Front headlamps	Damage	\$ 850.00	\$ NH 850.00 X
1	Front grille	Damage	\$ 240.00	\$ 240.00 /
1	Front grille chrome moulding	Necessary	\$ 105.00	\$ 105.00 /
1	Front bumper	Damage	\$ 430.00	\$ 430.00 /
2	Front bumper fog lamp covers	Damage	\$ 250.00	\$ NH 250.00 X
1	Front bumper lower grille	Damage	\$ 80.00	\$ 80.00 /
1	Front bumper reinforcement	Damage	\$ 380.00	\$ 380.00 /
2	Front bumper side retainers	Necessary	\$ 124.24	\$ 124.24 /
1	Front bumper logo	Necessary	\$ 38.00	\$ 38.00 /
1	Front bumper inner garnish	Damage	\$ 48.00	\$ 48.00 /
1	Boot lid	Damage	\$ 573.85	\$ 573.85 X
1	Boot lid inner lock	Damage	\$ 145.60	\$ 145.60 /
1	Boot lid logo	Necessary	\$ 48.50	\$ 48.50 /
1	Boot lid 'VIOS' emblem	Necessary	\$ 42.90	\$ 42.90 /
2	Rear taillamps	Damage	\$ 571.60	\$ 571.60 /
1	Rear end panel	Damage	\$ 769.86	\$ 769.86 /
1	Rear end panel inner garnish	Damage	\$ 129.70	\$ 129.70 /
1	Rear bumper	Damage	\$ 452.25	\$ 452.25 /
1	Rear bumper reflector	Damage	\$ 92.90	\$ 92.90 /
2	Rear bumper side retainers	Necessary	\$ 65.80	\$ 65.80 /
1	Rear spare tyre panel	Repair	\$ 732.90	\$ 732.90 X
1	Rear spare tyre board	Damage	\$ 127.53	\$ 127.53 /
2	Rear spare tyre sponge trays	Damage	\$ 219.40	\$ 219.40 /
1	Rear exhaust silencer	Damage	\$ 562.09	\$ 562.09 X
2	Rear exhaust silencer mountings	Necessary	\$ 97.00	\$ 97.00 X
2	Rear fenders	Repair	\$ 1609.90	\$ 1609.90 X
2	Rear fender inner trims	Damage	\$ 448.24	\$ 448.24 /
			\$ 9235.26	\$ 6892.46
	Discount 25.0%		\$ 2308.82	\$ 1723.12
			\$ 6926.44	\$ 5169.34
<u>Special Nett Items</u>				
1	Front number plate	Damage	\$ 45.00	\$ 45.00 ψ0
			\$ 45.00	\$ 45.00

Spare Parts Total \$ 6971.44 \$ 5214.34

Vehicle No: SJJ 3789 S  
Report No: TP/ 17009-10/MY / 2017

**LABOUR COST**

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 6971.44	\$ 5214.34
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00 20
2	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00 20
3	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 200.00	\$ 120.00 60
4	To remove and refit rear bumper sensor.	\$ 140.00	\$ 80.00 50
5	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 120.00	\$ 80.00 60
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1600.00	\$ 1100.00 1000
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1800.00	\$ 1540.00 1400
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 120.00	\$ 120.00 50
<b>Total</b>		<u>\$ 11051.44</u>	<u>\$ 8334.34</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 6700.00

SDLS: SIX THOUSAND SEVEN HUNDRED ONLY

  
Qualified Appraiser



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LAWRENCE CHUA PRACTICE LLC

Ref : CS/LAW18006318/Uvbn2

33 KRETA AYER ROAD  
SINGAPORE 088999

Date : 13-04-2018



Code : L149

### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SHA 3942L	Veh. Inspected	SJJ 3789S
Policy No.	MN.IG.B1.1711959	Coverage (\$)	0.00
Claim No.	RY/R5-981-18/kl	Excess (\$)	0.00
Assign From	KAREN LEONG	Assign Date	28/03/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305073869	Colour	WHITE
Odometer	153862	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	FALKEN	5 mm
L/H Front Tyre	195/55 R15	FALKEN	5 mm
R/H Rear Tyre	195/55 R15	FALKEN	5 mm
L/H Rear Tyre	195/55 R15	FALKEN	5 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

### 5. General Information

Accident Date	06/10/2017	Inspection Date	12/04/2018
Survey held at	NO 8 TAMPINES INDUSTRIAL DRIVE		
Repairer	BLUWEL AUTOMOTIVE SERVICE PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 3789S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
2	FRONT HEADLAMPS	NOT CHANGED	850.00	-
1	FRONT GRILLE	REPLACED	240.00	240.00
1	FRONT GRILLE CHROME MOULDING	REPLACED	105.00	105.00
1	FRONT BUMPER	REPLACED	430.00	430.00
2	FRONT BUMPER FOG LAMP COVERS	NOT NECESSARY	250.00	-
1	FRONT BUMPER LOWER GRILLE	REPLACED	80.00	80.00
1	FRONT BUMPER REINFORCEMENT	REPLACED	380.00	380.00
2	FRONT BUMPER SIDE RETAINERS	REPLACED	124.24	124.24
1	FRONT BUMPER LOGO	REPLACED	38.00	38.00
1	FRONT BUMPER INNER GARNISH	REPLACED	48.00	48.00
1	BOOT LID	REPAIRED SEE LABOUR	573.85	-
1	BOOT LID INNER LOCK	REPLACED	145.60	145.60
1	BOOT LID LOGO	REPLACED	48.50	48.50
1	BOOT LID "VIOS" EMBLEM	REPLACED	42.90	42.90
2	REAR TAILLAMPS	REPLACED	571.60	571.60
1	REAR END PANEL	REPLACED	769.86	769.86
1	REAR END PANEL INNER GARNISH	REPLACED	129.70	129.70
1	REAR BUMPER	REPLACED	452.25	452.25
1	REAR BUMPER REFLECTOR	REPLACED	92.90	92.90
2	REAR BUMPER SIDE RETAINERS	REPLACED	65.80	65.80
1	REAR SPARE TYRE PANEL	REPAIRED SEE LABOUR	732.90	-
1	REAR SPARE TYRE BOARD	REPLACED	127.53	127.53
2	REAR SPARE TYRE SPONGE TRAYS	REPLACED	219.40	219.40
1	REAR EXHAUST SILENCER	REPAIRED SEE LABOUR	562.09	-
2	REAR EXHAUST SILENCER MOUNTINGS	NOT NECESSARY	97.00	-
2	REAR FENDERS	REPAIRED SEE LABOUR	1,609.90	-
2	REAR FENDER INNER TRIMS	REPLACED	448.24	448.24

Report Ref No. CS/LAW18006318/Uvbn2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,308.82	-1,139.88
			6,926.44	3,419.64
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	REPLACED	45.00	40.00
			45.00	40.00
	<b><u>LABOUR</u></b>			
	TO REMOVE AND REFIT DAMAGE PARTS,TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		50.00	20.00
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING,REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		50.00	20.00
	TO REMOVE AND REFIT INNER TRIMS,INNER GARNISHES,TO FACILITATE THE REPAIRS.		200.00	60.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		140.00	50.00
	TO REMOVE AND REFIT,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS.		120.00	60.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF BOOT LID,REAR SPARE TYRE PANEL,REAR EXHAUST SILENCER AND REAR FENDERS.		1,600.00	1,000.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,800.00	1,400.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		120.00	50.00
	-		-	-
	-		-	-
	-		-	-
			4,080.00	2,660.00
<b>GRAND TOTAL</b>			<b>11,051.44</b>	<b>6,119.64</b>

Report Ref No. CS/LAW18006318/Uvbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,900.00
---	--	--	----------

Report Ref No. CS/LAW18006318/Uvbn2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.