

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



GST Reg No : MR-8500111-X

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

ESTIMATE

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info			
MS ETHEL HO GEK HOON	Cust No/Name	/MS ETHEL HO GEK HOON		
MS ETHEE HO GER HOOM	Reg No/Reg Date	SLM3503K / 28/03/201		
6 VAUGHAN RD	Date In/Mileage	/ 0		
SINGAPORE 358082	Chassis No	KNAPH81BMH5330465		
	Engine No	D4HBHH312219		
Contact No Mobile: 96330174	Make/Model	KIA/SORENTO2.2ASXSRGBV3		
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK		

Account No	Terms	Date/Time Pri	nted	CSE	Operator		WIP No			
CSM00081	Cash	12/03/2018/	16:30	Bod	442 / Cocol	Lu	24747			
		Description of	of Goods	s / Service	s	Qty	Unit Price	Disc%		nount
E PNT88000									3300	4400.00
		MPER, REAR BUM	IPER LOV	WER PANEL	, REAR FENDER	RH				
REAR DOO	R RH,								120	180.00
E PNT88000	E A THAT	ALL DEAD QUOTA	D CL AC	2 011					120	100.00
	F & INST	ALL REAR QUOTA	AR GLAS	5 KH					> 600	300 00
E PNT88000	E 0. TNCT	ALL REAR FENDE	D TDIM	S TO FACE	ITATE DEDATE				200	90.00
E PNT88000	E & INST	ALL KEAK FENDE	IN INTIN	3 TO TACE	LITAIL KLIAIK				120	300.00
	F & INST	ALL DOOR TRIMS	S AND GI	LASS					,	/
E PNT98000	2 4 11101	ALL DOOK THEFT							1260	1680.00
	PAINT F	OR REAR BUMPER	R. REAR	FENDER R	HREAR DOOR R	Н П				
B WHEELALIG			(24	III I TO TO	0510				120.00
To Condu	ct Compu	terize Full Wh	neel Al	ignment		GILL				
M SUNDRY		L	7	96	$\sqcup \sqcup \sqcup \sqcup$	CIGO	フ			30.00
	FER TYRE	TO NEW RIM								20 00
M SUNDRY	CEAL ANT	FOR ACCIDENT	٨٥٥٥٥٦١	CD						80.00
	SEALANT	FOR ACCIDENT	AFFECT	ED AREA						20.00
A 90000001	MIDING	& ELECTRICAL S	CVSTEM							/
A 90000001	WIKING	& ELECTRICAL S	JIJILII							200.00
	CT DIAGN	OSTIC CHECK FO	OR THE	CAR SYSTE	М					/
A 90000001									?	300.00
TO RENEW	REAR UN	DER CARRIAGE								-
M SUNDRY										20.00
Sundry						1 00	606.00	00 00	DE-	696.00
P COVER-RR						1.00	696.00 650.00			650.00
P COVER-RR			J			1.00		00.00		25.00
		BUMPER SIDE,RH R SIDE LWR,RH	1			1.00		00.00		18.00
		ER OUTER, RH				1.00	1545.00		_	1545.00
M PANEL AS						1.00	1250.00		14/	1250.00
M GARNISH						1.00		00.00		49.00
		DR SIDE, RH				1.00	202.00	00.00	SCA	202.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

ESTIMATE

Co Reg No : 199405410K	ESTIMATE	GST Reg No : MR-8500111-X		
Invoice Name & Address	Owner Name & Vehicle Info			
MS ETHEL HO GEK HOON	Cust No/Name	/MS ETHEL HO GEK HOON		
MS ETHEL HO GEN HOON	Reg No/Reg Date	SLM3503K / 28/03/201		
6 VAUGHAN RD	Date In/Mileage	/ 0		
	Chassis No	KNAPH81BMH5330465		
SINGAPORE 358082	Engine No	D4HBHH312219		
Contact No Mobile: 96330174	Make/Model	KIA/SORENTO2.2ASXSRGBV3		
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK		

					Colour/Irim	ARI PLATIN	or anarity	WK SA	TURN BLACK
Account No	Terms	Date/Time Pri	nted	CSE	Operator		WIP No		
CSM00081	Cash	12/03/2018/	16:30	Bod	442 / CocoLu		24747		
		Description (s / Services		Qty	Unit Price	Disc%	Amount
M GLASS &	MOULDING	ASSY-QUARTER				1.00	212.00		212.0
M GUARD-RE						1.00	167.00		167.0
		DR RR FRAME, RH	1			1.00	98.00		98.0
		DR FRAME, RH				1.00	51.00		51.0 FUR 1328.0
1 WHEEL AS						1.00	1328.00 687.00		7 687.0
M LAMP ASS M HUB ASSY		OMBINATION, RH				1.00	530.00		₹. 530.0
		land land		Sti	17 900100 11 clay 13/04/18	ate	7		
		Consultants hence			Hp 90010	368			
	 To resurvey To display 	er of the following before/after spray pa damaged part(s) during	inting g resurvey		lolay)			
	 Third party 	s are subject to confirm survey is on a "Withou nodification(s) is allow	at Prejudice	" basis	13/04/18	01530			
	e Sunnlemer	ntary item(s) must be roo final approval from I	esurveyed	and ompany	Pom 64	palat			
	Acknowledg	ed by Repairer			(63)				
	Signature:			1					

15,138.00 Nett 1059.66 15138.00 7% GST on

> Total Payable 16,197.66

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.