Ginzaue Rasu | REF: LPC 63431 Rlu -(10) | 8380m
COE EXPRY: 2030 / FG

ASSIGNMENT

From: Date: 5/4/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFZ7415H

at Workshop m/s Prime Auto

of 6 Benoi place

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 18K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: - % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No. SFZ 7415H Yr Regn: 2005 / OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA COROLLA ALTIS 1.6 c.c 1598

Colour GREY A/C: Insured / Std / NI / NA

Sp.Reading 273894 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR0532EC107100588

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: -.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or GOODRIDE

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	27/03/18	D.O.I.	05/04/18

Survey held at PRIME AUTO

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S & O/S FRG

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	refer to email

Date/Time. File Pass to? 1)

Date/Time. File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation ___S + RS___SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)