REF: FWD 6346 (Feat, ①

ASSIGNMENT

From: Date: 13/4/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKC 2721T

at Workshop m/s Motor Image

of 19 Lorong 8 Toa Payoh.

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No. SKC 2721T Yr Regn: 08 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Subaru Impreza (Car) c.c 1994

Colour M. Silver A/C: Insured / Std / NI / NA

Sp.Reading 136208 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JF1GE7KF39G005546

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	4/4/18	D.O.I.	13/4/18

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/4	File pass to Catherine

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: ☐ : Site Insp ($) S + RS SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

TOTAL