

ASS. REC. BY:

REF: CS/MSG18006358/Kvd3^{N2}

Special Instruction:

Surveyor:

Merimen

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSIG

Date/Time:

5/4/18 @ 5:27pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKC 7298R

Insured:

SKK 8178E

at Workshop m/s:

Cheng Hoe Motor

Tel:

6755 6142

of

81k 1019 # 01-374/382 Yishun Ind. Prk A

Policy No:

B29040710TMC

Claim No:

554537

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/04/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

8:52am 06/4/18

Person Contacted:

June

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKC 7298R - NBA/MSG18005921/Y

D.O.A.: 2/4/18

SKK 8178E - NBA/MSG18005921/Y

D.O.A.: 2/4/18

7/5/18

Send preli revised by merimen

10/5/18

@ 5:11pm Final fig \$ 340 Confirmed with Efeeda (Red 140, 29%)

COR run 24/05/18 (No LS)

ASS. REC. BY:

REF: MSG /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or No

Lum Sum: 1.41 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

7/5 AM per 15 to Catherine

RECEIVED 14 MAY 2018

Veh No: SKC 72P8R Yr Regn: 09, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Volkswagen A7 Pirococo 1390

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading 111706 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVV 722132CV 003271

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 235/40ZR18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 1/4/18 D.O.I. 4/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Fry

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 1

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2) 14/5 - typist

Add Fee: ☐ : Site Insp (\$

Transportation:

Report Format:

merimen

Lump Sum / I.B.I. (\$

340/2

☐ : Interview (\$

Photos

☐ : Tech Invs (\$

Others

☐ : Weekend (\$

TOTAL

150

10

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	02 Apr 2018		05 Apr 2018 17:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SIME DARBY SERVICES PTE LTD, Co. Reg. No.: 197501065W		
Main Claimant:	Donovan Tee Kim Leng, ID: S8858424D		
Vehicle Reg. No.:	SKC7298R	Date of Loss:	01/04/2018 14:00 - :59 [78 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 554537	Policy/Cover Note No.:	B29040710TMC (Third Party Only) Coverage: 01/10/2017 - 30/09/2018
Vehicle Reg. No. (Insured):	SKK8178E	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/04/2018]		
Driver/Custodian (Insured):	ZHANG LIANSHENG, JOSEPH (), NRIC: S88246511, Tel: +6581121487		
Adj. Asg. Remarks:	Please assign Mr Kenneth Kong to survey. Thank You.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 07 May 2018

Preliminary Advice

Insured Vehicle No	: SKK8178E	Accident Date	: 01/04/2018
TP Vehicle No	: SKC7298R	Assignment Date	: 05/04/2018
Make	: VOLKSWAGEN SCIROCCO	Est. Duration of Repair	: 1.00
Date of Inspection	: 04/05/2018		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	480.00
Revised Amount	:S\$	340.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	340.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8424D
Vehicle Details	
Vehicle No.:	SKC7298R
Vehicle to be Exported:	No
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SCIROCCO 1.4L AT TSI 1372Q5
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	CAV323825
Chassis No.:	WWZZZ13ZCV003271
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$25,277.00
Original Registration Date:	27 Sep 2011
First Registration Date:	27 Sep 2011
Transfer Count:	1
Actual ARF Paid:	\$25,277.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2021
PARF Rebate Amount:	\$16,430.00
Intended COE Rebate Details	
COE Expiry Date:	26 Sep 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$44,790.00
COE Rebate Amount:	\$15,253.00
Total Rebate Amount:	\$31,683.00

The information contained herein is correct as at 30 Apr 2018

OK

Enquire Vehicle & Owner Information (Vehicle No. SKK8178E As At 01 Apr 2018 / 13:10:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-SKC7298

Current Owner Details

Owner ID Type: Company

Owner ID: 197501065W

Owner Name: SIME DARBY SERVICES PRIVATE LIMITED

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.:305

Registered Street Name: ALEXANDRA ROAD

Registered Unit No.: # 02 - 01

Registered Building Name: VANTAGE AUTOMOTIVE CENTRE

Registered Postal Code: 159942

Current Vehicle Details

Vehicle No.: SKK8178E

Make Description/Model: PEUGEOT / 408 1.6 (A) TURBO

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Estimate No: ES1890489/WS

Date: 04 May 2018

Policy No:

Veh Reg No: SKC7298R

Make/Model: VOLKSWAGEN

VOLKSWAGEN

SCIROCCO 1.4L

Chassis No: WVVZZZ13ZCV003271

Engine No:

Reg. Date: 27/09/2011

WS Ref: TP MSIG

Claim Type: Third Party

Accident Date: 01/04/2018

TP Veh Reg No: SKK8178E

Estimate Repair Cost to Vehicle No :SKC7298R

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
1 REMOVE & REFIX FRT BUMPER, REPAIR AND RE-ALIGN TO SAME	200.00	1 LA	200.00	1200
2 PUTTY AND RESPRAY ON FRT BUMPER	280.00	1 LA	280.00	2200
			480.00	480.00
			Total	S\$ 480.00
			Add GST @ 7%	33.60
			Total Amount Payable	S\$ 513.60

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 11 May 2018 8:13 AM
To: 'Efeeda (Cheng Hoe -Yishun)'; SUR
Subject: RE: SKC7298R- DOA:1/4/18 TP/MSIG

Dear Efeeda,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Efeeda (Cheng Hoe -Yishun) [mailto:chmotor@singnet.com.sg]
Sent: Thursday, 10 May 2018 5:14 PM
To: SUR <sur@lkkauto.com>
Subject: SKC7298R- DOA:1/4/18 TP/MSIG

Hi Veron,

COR confirmed \$340.

Photos attached for your retention.

Thank you.

Rgds
Efeeda
Cheng Hoe Motor PL
Tel:67556142
Fax:67557719

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006358/KVD3N2

Date: 15/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29040710TMC
Claimant Vehicle No :	SKC7298R	Insured Vehicle No :	SKK8178E
Date of Loss:	01/04/2018	Nature of Claim:	TP
		Claim No:	554537

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC7298R	Engine No:	CAV323825
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)	Chassis No:	WWZZZ13ZCV003271
Reg. Date:	27/09/2011 (Man. Year: 2011)	Odometer:	111706 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40ZR18	Rear Tyre Size:	235/40ZR18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	480.00	340.00	140.00	29.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	480.00	340.00	140.00	29.17
+ GST 7.00/7.00% (S\$)	33.60	23.80	9.80	29.17
Nett Amount (S\$)	513.60	363.80	149.80	29.17

INSPECTION

Date of Assignment:	05/04/2018	
Date Inspected:	04/05/2018	Inspected At:
		Cheng Hoe Motor Pte Ltd (Yishun)
		Blk 1019 #01-374/382, Yishun Industrial
		Park A
		Singapore 768761
Estimated Period of Repair:	1.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2018)
Parts: 144	VOLKSWAGEN SCIROCCO 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC7298R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT BUMPER,REPAIR AND RE-ALIGN TO SAME	New	200.00	120.00
2	PUTTY AND RESPRAY ON FRT BUMPER	New	280.00	220.00
Gross Labour Cost (\$\$)			480.00	340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >