NATIONAL Assessment Centre S	services were dance		0	1
Date In 06/04/2018 09:57	leb description	Date &Time Completed	Done by	
Res No NA INC (8006362 K4	SAS e-filing			
Veh No SGD 3232Z	E-mail (within 8hrs, AIC 21			
DOA 05/04/2018 09:45	i-Motor Claim Form	mT/0989266-001	6/4/18	11502
	i-Motor W/O (Within: C	D 2hrs, TP 4hrs)		
OD TP / Reporting Only	i-Photo Uploaded			
	Assessment/Survey Rep	ort		,
TP Insurer:	Ass't Report by Fax / H	and to Owner/Wksp		
Preferred Wksp / INC Assign Wksp / QW: (Tel: Fax:)
	54923B . 11	NC()/Non-INC()		
Owner / Driver: (_ Tel:		
Policy No: () Period) Cover Type: (
Confirmed by : (Date:	Time:	9/1	
140 (140 May 100 May 1	All the ways with the second according	1: 0-20%; P: 21-79%. F: 80-100	70]	
Year of Registration: () Wa	rranty: YES ()/NO)()		
Excess: (\$) Loading: \$1,000	()/\$2,000()			
General Remarks:-	Service Services	posture restaurated described and the		
() Walk-In Customer: Customer's inform	ation strictly Confidentia	& Strictly NO rafer of repairer.		
() Total Loss Case : to e-mail Insurer				
Drive-In ()/ Towed-In (); Invoice:	CONTRACTOR SE CONTRACTOR) ; Towing Co. ()
	Secretary States	Date&Time Completed	Done b	у
Remarks:- (INC horline: 6788 6616)	urtesy Car ()	313792.3-4 5-38-38-28-2-3-3-3-3-3-3-3-3-3-3-3-3-3-3-		
-/PF-0 1	()			
2) QC Check / Post Repair Inspection	001 ()			
3) Upload Resurvey Photo [Repair Cost > \$300	001 (/			
Injury: ————				
Date/Time Actions			No Seattle	
		V		
		The second secon	A.ces	· Amt (1)
NAISO	7887 Invoi	ce Preparation Checklist	Amt (\$)	· Amt (5)
NA180	DAR:	Accident Reporting (\$30);	1st Bill	
TO CARE AND ADDRESS OF WHITE OF WHICH OF THE PARTY WATER	1) AR: 2) DA	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$80	lst Bill	
Claimant's Particulars :-	1) AR: 2) DA 3) TF:	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$80) Towing Fee \$40/ Follow-Through Survey \$	1st Bill) 545 120	
Claimant's Particulars :- Driver/Owner:	1) AR: 2) DA 3) TF: 4) FT:	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$80) Towing Fee \$40/ Follow-Through Survey \$ Follow-Through Survey (Resurvey) Claiming against INC Only (wef 10 Jan 2003)	1st Bill)) 545 120 530	
Claimant's Particulars :- Driver/Owner: Contact No:	1) AR: 2) DA: 3) TF: 4) FT: 5) i-T: Fore 6) TR:	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$80) Towing Fee \$400 Follow-Through Survey (Resurvey) Claiming against INC Only (wef 10 Jan 2003) Re-inspection	1st Bill) 545 120	
Claimant's Particulars :- Driver/Owner: Contact No:	1) AR: 2) DA 3) TF: 4) FT: 5) i-T: Fore 6) TR: 7) NI:	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$80) Towing Fee \$40/ Follow-Through Survey \$ Follow-Through Survey (Resurvey) Claiming against INC Only (wef 10 Jan 2003) Re-inspection	1st Bill)) 545 120 530	
Claimant's Particulars :- Driver/Owner: Contact No: Damaged Portion:	1) AR: 2) DA 3) TF: 4) FT: 5) i-T: Fore 6) TR: 7) NI: 8) NTI	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$80) Towing Fee \$40/. Follow-Through Survey (Resurvey) Claiming against INC Only (wef 10 Jan 2003) Re-inspection Idac DA + SMRT Survey \$ JC Additional Services:	1st Bill)) 545 120 530	
Claimant's Particulars :- Driver/Owner: Contact No: Damaged Portion:	1) AR: 2) DA 3) TF: 4) FT: 5) FT: For: 6) TR: 7) N1 2 8) NTU	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$30) Towing Fee \$40/ Follow-Through Survey (Resurvey) Claiming against INC Only (wef 10 Jan 2003) Re-inspection Idac DA + SMRT Survey \$ JC Additional Services: : Courtesy Car / Tpt Allowance : Repair Co-ordination	1st Bill	
Claimant's Particulars :- Driver/Owner: Contact No: Damaged Portion: QC Checked by (Engr-In-Charge):	1) AR: 2) DA 3) TF: 4) FT: 5) FT: Fore 6) TR: 7) NI: 8) NTI OD' *NS	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$30) Towing Fee \$40% Follow-Through Survey (Resurvey) Leiming against INC Only (wef 10 Jan 2003) Re-inspection Idac DA + SMRT Survey \$ JC Additional Services: Courtesy Car / Tpt Allowance Repair Co-ordination Post Repair Inspection	1st Bill	
Claimant's Particulars :- Driver/Owner: Contact No: Damaged Portion: QC Checked by (Engr-In-Charge): Auditors' Comments :-	1) AR: 2) DA 3) TF: 4) FT: 5) FT: 6) TR: 7) N1 2 8) NTU 0D' *N5 *N6 *N7 *N8	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$30) Towing Fee \$40/ Follow-Through Survey (Resurvey) Claiming against INC Only (wef 10 Jan 2003) Re-inspection Idae DA + SMRT Survey \$ JC Additional Services: Courtesy Car / Tpt Allowance Repair Co-ordination Post Repair Inspection DV / Collect Excess Coordination (N11): TP (Non INC) against INC	1st Bill 5 5445 1200 5300 575 1600 55 5100 525 535 520	
Claimant's Particulars :- Driver/Owner: Contact No: Damaged Portion: QC Checked by (Engr-In-Charge):	1) AR: 2) DA 3) TF: 4) FT: 5) iT: Fore 6) TR: 7) N1 8) NTI OD *N5 *N6 *N7 *N8 TP 9) N1	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$30) Towing Fee \$40/ Follow-Through Survey (Resurvey) Claiming against INC Only (wef 10 Jan 2003) Re-inspection Idae DA + SMRT Survey \$ JC Additional Services: : Courlesy Car / Tpt Allowance : Repair Co-ordination : Post Repair Inspection I; DV / Collect Excess Coordination	1st Bill	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

alcresaig,	
	ACCIDENT STATEMENT
Date Of Report	06/04/2018 09:57
Date Of Accident	05/04/2018 09:45
Exact Location Of Accident	GEYLANG ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SGD3232Z
Insured/Policyholder	
Name Of Registered Owner	SIAH HANG CHONG
NRIC No	S1186538J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97322177
Alternative Phone No	OTHERS-97322177
Vehicle Particulars	
Manufacturer	BMW
Model	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Ingurance Comment	

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5088919658

Cover Note Number

Driver

Name of Driver SIAH HANG CHONG

 NRIC No
 \$1186538J

 Date Of Birth
 03/12/1956

 Occupation
 OUTDOOR

 Date Of Driving Pass
 11/07/1975

Driving Experience 42 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97322177

Fax Number

Contact Number OTHERS-97322177

EMail Address NOEMAIL

94 BEDOK ROAD Address

469374 Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

NO Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO

NO

Was any other material or property damaged? YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

YES

GBB4923B

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera? NO NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

COMMERCIAL VEHICLE Vehicle Category

Name of Driver SEAH BOON TECK

NRIC/Passport Number S1384963C 90213357 Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

SKETCH PLAN		27	A- B-	SGD 3232 GBB 492	
B	JIAI	Gey 10	ang	ROI	
Vehicle A At the Vehicle A Vehicle	of the ACCIDENT was driv tractice light hit on the	ing along at Velicte he rear	Ge B Port	ylang Rd stop and	
DECLARATION I/We declare the foregoing particle Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyh	older) Nam		Personnel's Signature	20(



10 Sin Ming Drive Singapore 575701 Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

Our ref 1903180203N057014889

19 Mar 2018

SIAH HANG CHONG 94 BEDOK ROAD SINGAPORE 469374

002042

<u> Կրիսկիսիվորհիվ</u>

Dear Sir/Madam

NOTIFICATION ON SUCCESSFUL REPLACEMENT OF VEHICLE REGISTRATION NO. SKC2216K WITH VEHICLE REGISTRATION NO. SGD3232Z

You may be pleased to know that your application of 19 Mar 2018 for replacement of registration number is approved.

The details of the vehicle after the transaction are as follows: 2.

Vehicle Registration No. : SGD3232Z (Previously SKC2216K)

Vehicle Make

: B.M.W.

Vehicle Model

: 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV

Chassis No.

: WBAFP32040C866655

Engine No./ Motor No.

: 10187780N52B25AF/-

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	SGD32327		
Vehicle Type :			
Vehicle Type : Vehicle Attachment 1 :	P10 - Passenger Motor Car		
Vehicle Scheme :	No Attachment		
	Normal		
Vehicle Make :	B.M.W.		
Vehicle Model:	5231 2.5 AT ABS D/AB 2WD 4DR GAS/D NA	V	
Chassis No. :	WBAFP32040C866655		
Propellant:	Petrol		
Engine No. :	10187780N52B25AF		
Engine Capacity:	2497 cc		
Maximum Power Output :	150.0 kW (201 bhp)		
Maximum Laden Weight:	2260 kg		
Unladen Weight:	1650 kg		
Year Of Manufacture :	2011		
Original Registration Date:	29 Jul 2011		
Lifespan Expiry Date:			
COE Category :	E - Open Category		
Quota Premium:	\$68,811.00		
COE Expiry Date :	28 Jul 2021		
Road Tax Expiry Date :	28 Jul 2018		
PARF Eligibility Expiry Date:	28 Jul 2021		
Inspection Due Date :	28 Jul 2018		
Intended Transfer Date :	06 Apr 2018		
CO2 Emission :	(8)		
CO Emission :	(32)		
HC Emission:	883		
NOx Emission :			
PM Emission:	(%)		
Late renewal fee(s) will be impose	ed if road tax / lay up has expired. Please use Enqui	ire Road Tax Payable for feels have	able
Road tax, including Over Paymen Amount Payable	t (if any), of a vehicle will follow the vehicle to the	new registered owner when its own	nership is being transferred.
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(5\$)
Transfer Fee :	25.00		25.00

Total Amount Payable :
You may print this page for reference.

OK

Print

25.00 25.00

of changed	old Wehille Number Pepartedon,	5/4/2015
Plate to	old While Number Peportedon,	09 504411
Vehicle number	ACCIDENT STATEMENT	- ISCHILI
. ACC	CIDENT DATE: 4 / DOL 8) (DD/MM/YYYY), TIME: 09 : 45 (HH:MM	10000
Plate to Loca	EATION: Geylang Road	
SGD3232Z	DETAILS OF VEHICLE	
	a) VEHICLE NUMBER: SGD 3232 Z	*
	6) POLICY NUMBER:	
	d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE &THEFT)	
	e)MAKE & MODEL:	
	f)TYPE:(SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS) g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE) h)PURPOSE OF USING AT ACCIDENT TIME:	
	I) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES) NO))
2.	IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY) INSURED / POLICY HOLDER	<i>t</i> .
	A)NAME:(MALE / FEMALE) b)NRIC/FIN/PASSPORT:(CONTACT:	
	c)ADDRESS:CONTACT:CONTACT:	
nover	* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER	4.5
3.	. DRIVER	
(1)	a)NAME:(MALE / FEMALE) b)NRIC/FIN/PASSPORT:CONTACT: 97322	177
	c)ADDRESS:	
53 38	*d) DATE OF BIRTH: (/)(DD/MM/YYYY)	
	9)OCCUPATION: (INDOOR / OUTDOOR) f) YEARS OF DRIVING EXPRERIENCE:	
4.	WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)	OWNER
5.	IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED:	1
	b)ROAD SURFACE: (DRY / WET / OTHERS	
	a) REPORTED TO POLICE (YES /NO)	
8.	IF YES, PLEASE STATE WHICH POLICE STATION:	
	a) VEHICLE NUMBER: GBB4923B MODEL: b) DRIVER'S NAME: Segh Boon Teck	
	c) NRIC/FIN/PASSPORT: \$1384963 C CONTACT: 902/335	7
9.	THIRD PARTY VEHICLE	
	e) DRIVER'S NAME:	
	f) NRIC/FIN/PASSPORT:CONTACT:	W
* Ju		
Canala	y GIA report taken as Vehill	1
1 Pille	: 7 No: SQD 32327 an	107
Ju / 2	old Vehicle nutriber t	15kc7216k
on or Bu	al-les assert	acen as
will be	taken for NT certificate and	
De no John Ja	w. Certificate and	L 800
Jeho order or		

REPUBLIC OF SINGAPORE MENTITY CARD NO. S1186538J





SIAH HANG CHONG

CHINESE

03-12-1956

Country/Place of birth SINGAPORE



5756288



15-06-2017

94 BEDOK ROAD SINGAPORE 469374

DU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CO S1186538J S / No. 9000017360



Certificate of Insurance

MOTOR VEHICLES (THIRD	PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD	PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1	987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Cover : drivo CLASSIC Certificate Number: 5088919658

: SKC2216K 1. Index mark and Registration Number of Vehicle

: WBAFP32040C866655 Chassis Number : SIAH HANG CHONG

2. Name of Policyholder : 23 Mar 2017 3. Effective Date of Insurance : 28 Jul 2018

4. Expiry Date of Insurance Persons or Classes of Persons entitled to drive#

(a) The Policyholder. (b) Any other person who is driving on the Policyholder's order or with his/her permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any

enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

(a) Use for hire or reward.

(b) Use for racing, pace-making, reliability trial or speed-testing.

(c) Use for the carriage of goods (other than samples) in connection with any trade or business.

(d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

: \$\$600 EXCESS (SECTION 1) : N/A EXCESS (SECTION 2) : \$\$100 WINDSCREEN EXCESS : N/A ADDITIONAL EXCESS : PLEASE REFER OVERLEAF UNNAMED DRIVER EXCESS

REPAIR AT OWNER'S PREFERRED WORKSHOP : YES INSURE WITH COE : YES NCD PROTECTION : NO TRANSPORT ALLOWANCE

: NO EXCESS WAIVER : SIAH HANG CHONG PRIMARY DRIVER : EM AH GEOK NAMED DRIVER (1)

: N/A NAMED DRIVER (2)

: DBS BANK LTD HIRE PURCHASE COMPANY

: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS SUM INSURED

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

: PRO-LINK INSURANCE AGENCY (00000571869) Agency

: 23 Mar 2017 10:20 hrs Date of Issue

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

4/6/2018 Policy Search

eBao Tech			GeneralClai				eralClaim			
Hello, NAC_PAYA_UBI_80	0601						Change Lar	guage	Change Passwo	ord Log Ou
My Desktop	Polic	cy Query								
Notice of Loss	Policy N	io.				Date of Ac	cident	05/04	/2018 09:45	
	Vehicle	No.(For Motor)	SKC2216K							
						Search				
	Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
		5088919658	SIAH HANG CHONG	511865383	GPC	drivo CLASSIC	SKC2216K	SKC2216K	23/03/2017	28/07/2018
		5088919658		511865383	GPC	drivo CLASSIC	SKC2216K	SKC2216K	23/03/2017	28/07

Policy Information

Sequen	ce Date of Endorsement	Endorse	ement Type	Endorsement Status	Endorsement Content
	sements				
▶ Insure	d Object: SKC2216K				
Jnit No.		Related Policy Number	5088919658		
Address 4		Address Type	Singapore address	Post Code	469374
Address 1	94 BEDOK ROAD	Address 2	SINGAPORE 469374	Address 3	
	nolder Mailing Address				
Certificate Info					
Open Policy Info					
Co- nsurance Flag	No				
Agent	PRO-LINK INSURANCE AGENCY	Agent Tel.	65672149	GST Flag	Υ
Outside Singapore OD Excess	600	Outside Singapore TP Excess	0		
Additional Excess	0	OS Premium	0		
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Policy ssue Date	23/03/2017	Effective Date	23/03/2017 00:00	Expiry Date	28/07/2018 23:59
Product Name	PRIVATE CAR INSURANCE	Plan		Group Policy Flag	N
Address	94 BEDOK ROAD SINGAPORE 46	9374			
olicy No.	5088919658	Policyholder Name	SIAH HANG CHONG	Policyholder NRIC	S1186538J

4/6/2018 Claim Handling Accident MT/0989266

Accident MT/0989266					_
Policy No.	5088919658	Vehicle No.	SKC2216K	GST Registration No.	
Policyholder Name	SIAH HANG CHONG			Policyholder NRIC	511
Product Code	PRIVATE CAR INSURANCE	Cover Type	drivo CLASSIC	Loading	0
Contact No.(Mobile)	97322177	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No
KĖK	- No Yes	TCA	■ No : Yes	eCode Reason	
NCD Protection	Yes	NCD Entitlement(%)	50	Private Hire	No
Report Date	06/04/2018 11:02	Accident Report Within 24 hrs	Yes	Accident Type	Coll
Date of Accident	05/04/2018	Time of Accident hh:mm	09;45	Country of Accident	Sing
Reporting Centre		Orange Force		ICM No.	
Accident Location	GEYLANG ROAD				
▽ Benefits					
♥ Excess					
Own damage Excess	600.00	Additional Excess	0.00	Windscreen Excess	
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		
GST Registered Informa					
GST Registered	No		GST Registration Date		
GST Registration No.			GST Status Verified	Yes	
Modification History					
Policyholder Mailing Ad	dress				
Address 1	94 BEDOK ROAD	Address 2	SINGAPORE 469374	Address 3	
Address 4		Address Type	Singapore address	Post Code	469
Unit No.		Related Policy Number	5088919658		
▽ OI Driver Info					
Driver Name	SIAH HANG CHONG	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	\$11865383	Driver DOB	03/
Register Date of Driver License	01/04/1984	Driver Age	61	Driving Experience	34
Contact No.(Mobile)	97322177	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	94 BEDOK ROAD	Address 2		Address 3	
Address 4		Address Type	Singapore address	Post Code	469
Unit No.					
Does he own a Singapore Registered car?	Yes = No	Driver Vehicle No.		Driver Insurer Company	
Declaration					
Breathalyser or Blood Test Reading?	0 mg	Any injury?	○ Yes ⊯ No		
Modification History					
Claim 001 OD-MD Nev	<u>v</u>				
Claim Type *	OD-MD *	Insured Name	SIAH HANG CHONG	Insured NRIC	S11
Contact No.(Mobile)	97322177	Contact No.(Home)	67854255	Contact No.(Office)	
Email Address weichuan87@gmail.com		OI Vehicle Number	SKC2216K	TP Vehicle Number	GB
Claim Description	SKC2216K / GB84923B ON 5 Apr 2018			Name of Preferred Workshop	
Preferred Workshop Contact		Insured Liability *	Partially at Fault	W	
No.					12
Require Finalisation Yes		Preferered Repair Option	Preferred Workshop, Name unknown	GIA report	Re

GIA report Require Finalisation Preferered Repair Option Preferred Workshop, Name unknown Date Registered 06/04/2018 11:09 Claim Close Date Date Received 06/0 Workshop Repairer Total Loss but Repaired Report Taken By KRISHNASAMY Print AK letter

Save Submit

Attachment

Claim No. Accident No. MT/0989266 Last Doc. Received Yes No

Upload Date 06/04/2018 11:05

Path * Category * Confidential Urgency * Choose File No file chosen Clear Please Select * NO ▼ Normal Choose File No file chosen ▼ NO Clear Please Select * Normal Choose File No file chosen ▼ NO ▼ Normal Clear Please Select Choose File No file chosen Clear Please Select * NO * Normal Choose File No file chosen Y NO * Normal Clear Please Select Choose File No file chosen ▼ NO ▼ Normal Clear Please Select Message Read

(market	the second	hme	 1

	List					
Attachment		Uploaded By/Date	Category	8	Urgency	Descrip
/ 開	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:09		Normal	NRIC/ Driving Lio	
63	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:07	SAS		Normal	5A5 201
	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:07	Photos		Normal	Photos 20
1	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:07	Photos		Normal	Photos 20
	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:07	Photos		Normal	Photos 20
1. 6	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:07	Photos		Normal	Photos 20
3	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:07	Photos		Normal	Photos 20
6	NAC_PAYA_UB1_800601(YA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:07 Photos			Normal	Photos 20
	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:07	Photos		Normal	Photos 20
Tarrier .	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:07	Photos		Normal	Photos 20
The same	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:06	Photos		Normal	Photos 20
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:06	Photos		Normal	Photos 20
1	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:06	Photos		Normal	Photos 20
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:06	Photos		Normal	Photos 20
50	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:06	Photos		Normal	Photos 20
	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 06 Apr 2018 11:06	Photos		Normal	Photos 20
	Uploaded By/Date	Folder Date	File Name		9	Source

Display in New Window Scan and uploading

ASSIGNMENT (IDAC)

By CSO- Nature of Accident: (1) Vehicle hit Vehicles: (2) Vehicle hit ?? (3) Motorcar (4) (5) Micycle (7) (7) Animal (5) Bicycle (7) (8) Animal (6) Bicycle (7) (8) Animal (7) Vehicle hit Road Side Objects: (8) Govrn-Property (7) (8) Property (7) (9) Private Property (7) (10) Private Property (7) Private Property	
b) M/cycle () b) Animal () / Truck / Traller or c) Bicycle () 3) Vehicle hit Road Side Objects: a) Govrn.Property () b) Road Work Object () (Eg. signboard, barrier, tree sto) 4) Vehicle drop Into drain 5) Damage due to Act of God: a) Fallen Object () b) Flood c) Other, 6) Parked & Found Damaged: a) Vandalism () b) Hit by Moving Object () 7) Theft Case a) Stolen () b) Damage found when recovered. 8) Fire / Truck / Traller or Make & Model: BTW \(\) 5331 \(2.5 \) FT \(\) c.c \(2.5 \) Colour \(\) Slack \(\) Transmission Type: \(\) Arith / M Eng/No: Sp. Reading: \(\) 722 C/No: \(\) WBAFP3 \(2.5 \) FT \(\) Poor / Burnt \(\) or Sieering: \(\) In \(\) Ft \(\) / Jammed / Leaked / Burnt \(\) or Sieering: \(\) In \(\) Arith \(\) / SEID \(\) / STD \(\) A/Rim \(\) or Tyre Size: \(\) F: \(2.45 \) \(\) Arith \(\) R: TOYO / YOKO or Front Rear R/Bal. **Truck / Traller or Make & Model: BTW \(\) 5331 \(2.5 \) FT \(\) Colour Sp. Reading: \(\) \(\) 22. Colour \(\) Slock \(\) Transmission Type: \(\) Arith \(\) Arith \(\) Or Sp. Reading: \(\) \(\) 72. C/No: \(\) WBAFP3 \(\) 20 \(\) C \(\) Fill / M Sieering: \(\) In \(\) Arith \(\) / SEID \(\) / STD \(\) A/Rim \(\) or Tyre Size: \(\) F: \(\) 245 \(\) Arith \(\) R: TOYO / YOKO or Front Rear R/Bal. **Toyo / YOKO or **Toy	12011
Make & Model: RMW 5331 2.687 c.c 20 3) Vehicle hit Road Side Objects: a) Govrn.Property ()	ver/MPV
3) Vehicle hit Road Side Objects: a) Govrn.Property () b) Road Work Object () (Eg: signboard, barrier, free etc) c) Private Property () 4) Vehicle drop Into drain () Gen. Cond: GOD / Fair / Poor / Burnt or 5) Damage due to Act of God: a) Fallen Object () b) Flood () Brake: Inoteer / Jammed / Leaked / Burnt or 6) Parked & Found Damaged: a) Vandalism () b) Hit by Moving Object () 7) Theft Case a) Stolen () b) Damage found () when recovered. 8) Fire Colour Slack Transmission Type: All / Mic. / OHTSU / PIR / St. / Mic. / OHTSU / PIR / St. / Mic. / OHTSU / PIR / St. / Mic. / Mic. / OHTSU / PIR / St. / Mic. / Mic. / OHTSU / PIR / St. / Mic. / Mic. / OHTSU / PIR / St. / Mic. / OHTSU / PIR / Mic. / OHTSU / PIR / Mic. / OHTSU / Mic. / OHTSU / Mic. / OHTSU / Mic. / OHTSU / Mic. / Mic. / OHTSU / Mic. / OHTSU / Mic. / OHT	
a) Govrn.Property () b) Road Work Object () Eng/No: Sp.Reading: \22 \\ 4) Vehicle drop into drain () Gen. Cond: \(\text{Cond: WBPF32040} \) C \(\text{Folion} \) b) Flood () Steering: \(\text{Inoter } / \) Jammed / Leaked / Burnt or Steering: \(\text{Inoter } / \) Jammed / Leaked / Burnt or Steering: \(\text{Inoter } / \) Jammed / Leaked / Burnt or Steering: \(\text{Inoter } / \) Jammed / Leaked / Burnt or Steering: \(\text{Inoter } / \) Jammed / Leaked / Burnt or Steering: \(\text{Inoter } / \) Jammed / Leaked / Burnt or Steering: \(\text{Inoter } / \) Jammed / Leaked / Burnt or Steering: \(\text{Inoter } / \) Jammed / Steering: \(\text{Inoter } / \) Jammed / Leaked / Burnt or Steering: \(\text{Inoter } / \) Jammed / S	2497
(Eg. signboard, barrier, free sto) 4) Vehicle drop into drain 5) Damage due to Act of God: a) Fallen Object () b) Flood c) Other, 6) Parked & Found Damaged: a) Vandalism () b) Hit by Moving Object () T) Theft Case a) Stolen () b) Damage found () when recovered. c) Private Property () C/No: WBAFP32040 C \$666 Gen. Cond: God/ Fair / Poor / Burnt or Steering: In God / Fair / Poor / Burnt or Steering: In God / Jammed / Leaked / Burnt or Modi: Nil / Sclin / STD A/Rim or Tyre Size: F: 245 45 R18 R: TOYO / YOKO or God / Toyo / YOKO or Rear R/Bal. 8) Fire	Manual
4) Vehicle drop into drain () Gen. Cond: GCD / Fair / Poor / Burnt or 5) Damage due to Act of God: a) Fallen Object () b) Flood () Brake: Ino Ger / Jammed / Leaked / Burnt or c) Other. 6) Parked & Found Damaged: a) Vandalism () b) Hit by Moving Object () 7) Theft Case a) Stolen () b) Damage found () when recovered. 8) Fire C/No. WBY 7 S 20 C 8 60 Steering: In Ger / Jammed / Leaked / Burnt or Modi: Nil / SRim / STD A/Rim or Tyre Size: F: 245 45 R18 R: TOYO / YOKO or Casting State Front Rear R/Bal. mm R/Bal.	289
5) Damage due to Act of God: a) Fallen Object () b) Flood () Brake: Inoteer / Jammed / Leaked / Burnt or c) Other. 6) Parked & Found Damaged: a) Vandalism () b) Hit by Moving Object () 7) Theft Case a) Stolen () b) Damage found () when recovered. 8) Fire Steering: In Cer / Jammed / Leaked / Burnt or Modi: Nil / School / STD A/Rim or Tyre Size: F: 245 45 R18 R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / St	622
a) Fallen Object () b) Flood () Brake: Inofeer / Jammed / Leaked / Burnt or Modi: Nil / Skin / STD A/Rim or Tyre Size: F: 245 45 R18 R: Toyo / Yoko or When recovered. 8) Fire Brake: Inofeer / Jammed / Leaked / Burnt or Modi: Nil / Skin / STD A/Rim or Tyre Size: F: 245 45 R18 R: Toyo / Yoko or When recovered. Front Rear R/Bal. Mm R/Bal.	
c) Other, 6) Parked & Found Damaged: a) Vandalism () b) Hit by Moving Object () 7) Theft Case a) Stolen () b) Damage found () when recovered. 8) Fire Modi : Nil / SEin / STD A/Rim or Tyre Size: F: 245 / 45 R18 R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SI TOYO / YOKO or Rear R/Bal. Modi : Nil / SEin / STD A/Rim or Tyre Size: F: 245 / 45 R18 R: TOYO / YOKO or Rear R/Bal. Modi : Nil / SEin / STD A/Rim or Tyre Size: F: 245 / 45 R18 R: Toyo / YOKO or Rear R/Bal.	
6) Parked & Found Damaged: a) Vandalism () b) Hit by Moving Object () 7) Theft Case a) Stolen () b) Damage found () when recovered. 8) Fire Tyre Size: F: 245 45 R18 R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / Size: TOYO / YOKO or When recovered. Front Rear R/Bal. Tyre Size: F: 245 45 R18 R: R: R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / Size: Front Rear	
a) Vandalism () b) Hit by Moving Object () R: 7) Theft Case a) Stolen () b) Damage found () TOYO / YOKO or Shington Rear 8) Fire 8) Fire 8) Fire 8) R: 8 Fire 8 Find 8 Find	1-47.00
7) Theft Case a) Stolen b) Damage found when recovered. BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / Stolen TOYO / YOKO or when recovered. Front R/Bal. mm R/Bal.	
a) Stolen () b) Damage found () TOYO / YOKO or Continued () when recovered. 8) Fire R/Bal. Toyo / YOKO or Continued () Rear R/Bal.	
when recovered. Front Rear R/Bal. mm R/Bal.	SUMI /
8) Fire R/Bal. mm R/Bal.	1274
a) Whilst driving () b) Parked () L/Bal. 7 mm L/Bal. 7	mm
	mm
9) Accident date more than 24hrs () Parallel Import: Yes / No Towed-In: Yes	l No
Repair Type: (S) I.B.I Towing Required: (es)) I No
Remarks for internal information No of Repair Days: Vehicle in Idac: Yes	s No
D.O.I. 6/4/2018 Time: 10.150	an
By Assessor- 2) Comments	
Damages not due to recent accident.	
2) Damages do not seem hit onto:	
Remarks to appear in Works Order & Assessment report a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestri	strian ()
1) Potential Total Loss () e.Animal () f.Govrn Object () g.Road Work Object ())
2) SRS Light on () h.Private Property () i.Drain () j.Road Kerb/Grass Ven	erge ()
ABS Light on	
a.Fallen Object() b.Flood() c.Vandalism() d.Fire	ire()
e.Moving Object () f.Stolen () g.Stolen & Recovered (d()
Time Started: Time completed	
1) CSO	
2) ASS	

3) Entire Operation Completed Time:

ACTION (ACT)
(1)Replace(\sqrt{1}) (2)Rapple (C) (3)Check (C)
(4)Hat Corression (NC) SK C 2246 K

NAC	Portion INC Item		-	
0.16-1-4		CO	NA	CQ
1001		100	1	-
_		Dis		1
1003			-	1
1004		100	to	+
1.005		(SEC		t
006	991325 Frt Bumper Bracker	INC.	-	1
007	991462 Frt Bumper Side Retainer		1	-
1008	991433 Frt Bumper Reinforcement	-	1	
009	991318 Frt Bumper Beam	151	1	1
010	201462 P. Bumper Beam	Upon In		
	The state of the s	KRD	1	-
011	991427 Frt Bumper Protector		IK	-
012	991420 Frt Bumper Ped Emblem	100	-	-
013	991363 Fri Bumper Grille	D1	1	
014	991301 Frt Bumper Moulding		1	
015	1001402 F + D	17	255	
	991407 Fit Bumper Lower Spoiler			
016	991438 Frt Bumper Sensor		7	
017	995100 Frt LH Bumper Fog Lamp Cover		- 04	-
018	991333 Frt RH Bummer Foot Lamp Correct		-	-
019	995079 Frt LH Bumper Fog Lamp	-	-	-
020	995080 Frt RH Bumper Fog Lamp			
021		1 280		
022	001339 E-10-THE LA 4-KA	CRA	-	12
_	991328 Frt Grille Emblem			
023	991799 Fit Grille Chrome Moulding			
024	991222 Frt Apron Panel	1	-	-
025	992013 Frt Support Panel	BT	-	-
026	992025 Frt Support Panel Top Garnish Cover			-
027	992416 Horn	KRA	-	
028	991277 Frt Brace Panel			
029	DOSTOR FOR DIRECTION		12	
030	995153 Frt LH Headlamp Assy			
Marie Control	991821 Frt R& Headlamp Assy			
131	995088 Fr. LH Side Lamp		7	
)32	995089 Frt RH Side Lamp	CUT	-	-
033	990248 Bonnet	BAC	2	-
134	991328 Bonnet Emblem	B.M.C	2	
035	990287 Bonnet Lock		7	_
036	990285 Bonnet Insulator	1	w	1
037	990273 Bonnet Hinge	1000		
38	000261 In			
_	990261 Bonnet Damper			
139	990305 Bonnet Rubber			
140	990252 Bonnet Cable			
41	990311 Bonnet Stand Lack Colle	-	7	~
42	VIII - IVIII C-ON C-ONGENSET		1	1
13	990122 Air Con Fan Assy		2	2
44	990134 Air Con Sustan B	-		1
45	990134 Air Con Suction Pipe (Low Pressure) 990118 Air Con Suction Flose			
46	990133 A . C . B			
-	990133 Air Con Discharge Pipe (High Pressure)	4	- 20	1
	750114 All Con Discharge Hose			
16.1	990149 Air Con Liquid Pine			
19	993066 Air Con Receiver Drier	1	-	
20	990111 Air Con Compressor Assu			
	995294 Air Con Belt			
2	995074 Radiator			
	00272 0 p. 11		21	-
	992738 Radiator Cowling		2	
	992742 Radiotor Fan Assy	1	7	
12	992745 Radiator Fan Clutch		3	-
0	992758 Radiator Hose Ton	-	4	-
7	992757 Radiator Hose Bottom			
8	992741 Radiator Expansion Tank			
1	pool of Atlanta			
0.11	190151 Air Duct	1	7	
7 3	90070 Air Cleaner Assy		-	
0 0	90056 Air Cleaner Hose		-	_
0 9	90089 Air Cleaner Resonator			14
20 9	277772 AT LIGHTER RECORDIAN			- 1
50 9 51 9 52 9	9 717 Ert Belower Manual France La			_
20 9 21 9 2 9 3 9	91.712 Frt Exhaust Manifold			
50 9 51 9 52 9 63 9	91712 Frt Exhaust Manifold 91713 Frt Exhaust Manifold Cover		-	
50 5 51 5 52 5 53 5 4 5 5 9	91712 Frt Exhaust Manifold 91713 Frt Exhaust Manifold Cover 91054 Frt Exhaust Manifold Cover			
50 9 51 9 52 9 63 9 64 9 66 9	91712 Frt Exhaust Manifold 91713 Frt Exhaust Manifold Cover 91054 Frt Exhaust Manifold Sensor (Oxygen) 91714 Front Exhaust Pins			
0 9 1 3 2 9 3 9 5 9 5 9	91712 Frt Exhaust Menifold 91713 Frt Exhaust Manifold Cover 91054 Frt Exhaust Manifold Sensor (Owygen) 91714 Front Exhaust Pipe			
00 9 1 3 2 9 3 9 4 9 5 9 7 0	91712 Frt Exhaust Menifold 91713 Frt Exhaust Manifold Cover 91054 Frt Exhaust Manifold Sensor (Oxygen) 91714 Front Exhaust Pipe			
0 9 1 9 3 9 1 9 9 9	91712 Frt Exhaust Manifold 91713 Frt Exhaust Manifold Cover 91054 Frt Exhaust Manifold Sensor (Oxygen) 91714 Front Exhaust Pins			

1080 1081 1082 1083 1084 1085	99220 99401 99505	5 Fuse Box 1 Relay Box 2 Wiper Washer Tank 2 Wiper Washer Tank Motor 9 Alternator Assy 0 Alternator Belt 8 Power Steering Pump 9 Power Steering Belt 1 Power Steering Cooler Pipe	CO	N A	1C	5
1072 1073 1074 1075 1076 1077 1078 1079 1080 1081 1082 1083 1084 085	99401 99505 99505 99015 99016 99268 99266 99443 99269	1 Relay Box 2 Wiper Washer Tank 2 Wiper Washer Tank Motor 9 Alternator Assy 0 Alternator Belt 8 Power Steering Pump 9 Power Steering Belt 1 Power Steering Cooler Pipe				
1073 1074 1075 1076 1077 1078 1079 1080 1081 1082 1083 1084 1085	99505 99505 99015 99016 99268 99266 99443 99269	3 Wiper Washer Tank 2 Wiper Washer Tank Motor 9 Alternator Assy 0 Alternator Belt 8 Power Steering Pump 9 Power Steering Belt 1 Power Steering Cooler Pipe				
1074 1075 1076 1077 1078 1079 1080 1081 1082 1083 1084 1085	99505 99015 99016 99268 99266 99443 99269 99001	2 Wiper Washer Tank Motor 9 Alternator Assy 0 Alternator Belt 8 Power Steering Pump 9 Power Steering Belt 1 Power Steering Cooler Pipe				
1075 1076 1077 1078 1079 1080 1081 1082 1083 1084 1085	99015 99016 99268 99266 99443 99269 99001	9 Alternator Assy 0 Alternator Belt 8 Power Steering Pump 9 Power Steering Belt 1 Power Steering Cooler Pipe				
1076 1077 1078 1079 1080 1081 1082 1083 1084 1085	99016 99268 99266 99443 99269 99001	Alternator Belt Power Steering Pump Power Steering Belt Power Steering Cooler Pipe		-		
1077 1078 1079 1080 1081 1082 1083 1084 1085	99268 99266 99443 99269 99001	Power Steering Pump Power Steering Belt Power Steering Cooler Pipe				
1078 1079 1080 1081 1082 1083 1084 1085	99266 99443 99269 99001	Power Steering Belt Power Steering Cooler Pipe				
1079 1080 1081 1082 1083 1084 1085	99443 99269 99001	Power Steering Cooler Pipe				
1080 1081 1082 1083 1084 1085	99269 99001	and the second of the				
1081 1082 1083 1084 1085	99001					
1082 1083 1084 1085		2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1		
1083 1084 1085	90040	- Condo O O Idi				7
1084 1085						
1084 1085 1086	99040					Ī
	99100					
1086	99101			17		-
	990946	and the state of t		T	1	
1087	990949			T		
1088	990950					
1089	990952				f	
1090	990951			1	T	Т
1091	992234	The state of the s		T	1	-
1092	991520	Frt LH Chassis Member		1	1	
1093	991520	The state of the s				
094	990728	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4			1	
095	991863	The state of the s		1		-
096	995070	Frt LH Fender		1		
097	995072	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			1	
098	995147	Frt LH Fender Lamp				
099	995148	Frt LH Fender Protector		1	1	-
100	991740			10	1	
101	995179			1		
102	995170				1	_
103	994025					
104	995065				T	_
105	995071				T	_
106	991739	Frt RH Fender Inner Panel			1	
107	991744	Frt RH Fender Lamp			T	
108	991752	Frt RH Fender Protector	10			
109	991740	Frt R#4 Fender Inner Shield	150	2		
110	991884	Frt RH Mudflap				_
111	992087	Frt RH Wheel Rim			T	
112	994025	Frt RH Rim Cover			T	
113	995065	Frt RH Tyre				7
114	992093	Frt Windscreen Glass			T	_
115	992117	Frt Windscreen Rubber			T	
116	201276	Frt Windscreen Moulding			1	1
117	992098	Frt Windscreen Sealant				
118	991019	ERP Bracket			T	
19	991020	ERP Unit			T	1
20	992140	Frt Wiper Arm			1	
21	992142	Frt Wiper Blade			1	1
	995045	Wiper Panel Garnish	- 1		1	-
23	991126	Firewall Panel				-
24	990753	Dashboard Assy			-	
25	992282	Glove Box Cover			1	
26	992281	Glove Box Compartment			1	
	994483	Steering Wheel Airbag			-	
	994485	Steering Wheel Airbag Sensor			-	f
	990749	Dashbourd Airbag			1	-
30 3		Dashboard Airbag Sensor			-	
	-	Airbug Control Unit		-	-	
-	The state of the s	Fri Driver Seat		-	-	
	The second secon	Fit RH Seat Belt Assy		-	-	
	the same of the sa	Prt Passenger Scal				
		Fit LH Seat Belt Assy				
200	790247	Sticker -				
		Headlamp Wester Nople	1	3	2	-

Claim Handling Accident MT/0989	266						LOS SAL SI
Policy No.	5088919658	Vehicle No.	SKC2216K		GST Registration N	Vo.	
olicyholder Name	SIAH HANG CHONG				Policyholder NRIC	51186538J	
roduct Code	PRIVATE CAR INSURANCE	Cover Type	drivo CLASSIC		Loading	0	
ontact No.(Mobile)	97322177	Contact No.(Office)	0		Contact No.(Home	e) 0	
mail Address		Special Remark			eCode	No Y	
FK	= No Yes	TCA	« No Yes		eCode Reason		
CD Protection	Yes	NCD Entitlement(%			Private Hire	No	
Accident Details	1778		1,550				
	2004/2010 11:02	Accident Report Witi	hin Yes		Accident Type	Collision - Hea	d to Rear
eport Date	06/04/2018 11:02	24 hrs	tes				O TO KESI
rate of Accident	05/04/2018	Time of Accident hh	O DOLO DE ENGLES		Country of Accider	nt Singapore	
eporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No		ICM No.		
accident Location	GEYLANG ROAD						
♥ Benefits							
▽ Excess		U Ware-lands, extre Vivolent		*******	A CORPORATION CONTRACTOR OF		200
Own damage Excess	600.00	Additional Excess		0,00	Windscreen Exces	s	100.00
Innamed Driver Excess	0.00	Outside Singapore C Excess	OD .	600,00			
hird Party Excess	0.00	Outside Singapore T Excess	TP	0,00			
GST Registered In	formation	Excess					
ST Registered	No		GST Regis	tration Date			
SST Registration No.	340		GST Statu		Yes		
fodification History							
Policyholder Mailir		Address 3	THE ADDRESS OF THE	274	Address 3		
ddress 1	94 BEDOK ROAD	Address 2	SINGAPORE 469		Post Code	469374	
Address 4		Address Type	Singapore addre	55	Post Code	404374	
Unit No.		Related Policy Numb	ber 5088919658				
▽ OI Driver Info	erau usane europie	Don Time	Main Driver				
Oriver Name	SIAH HANG CHONG	Driver Type			Delves DOB	03/43/4056	
Jonamed driver Name Register Date of Driver		Driver NRIC	S11865383		Driver DOB	03/12/1956	
icense	01/04/1984	Driver Age	61		Driving Experience	e 34	
Contact No.(Mobile)	97322177	Contact No.(Office)	0		Contact No.(Home	2) 0	
Address 1	94 BEDOK ROAD	Address 2			Address 3		
Address 4		Address Type	Singapore addre	55	Post Code	469374	
Unit No.							
Does he own a Singapore Registered	Yes + No	Driver Vehicle No.			Driver Insurer Cor	mpany	
car?							
reathalyser or Blood est Reading?	0 mg	Any injury?	Yes No				
lodification History							
reservation chartery							
Claim 001 OD-MD							
	cer Tan Siew Choo						
Claim Type	OD-MD	Insured Nam	ne SIAH	HANG CHONG	Ins	ured NRIC	\$11865383
Contact No.(Mobile)	97322177	Contact No.((Home) 67854	255	Cor	ntact No.(Office)	
	weichuan87@gmail.com	OI Vehicle N	umber SKC22	216K	TP	Vehicle Number	GBB4923B
Email Address	SKC2216K / GBB4923B ON 5	Apr 2018				me of Preferred	
		1.50.000			Wo	rkshop	
Claim Description	SHOLLEN Y GUSTINESS GIV S	914150000 212000					
Claim Description	310222017 38073230 311 3	Insured Liab		ly at Fault			
Claim Description Preferred Workshop Contact No.	Yes	Preferered R	epair Option Prefer	ly at Fault red Workshop, Nan		A report	Received
Email Address Claim Description Preferred Workshop Contact No. Require Finalisation Date Registered			epair Option Prefer			A report te Received	Received 06/04/2018 13:1

Modification History

Approval

Reason

Remarks

WATER TO BE	22010		12000000000	140		Carles Const		2404
ehicle Make	BMW 29/07/2011 • Yes • No		Vehicle M	odel 523i		Engine Capcity		2494
ate of egistration			Classis No	0.	WBAFP32040C866655			
owing equired *			Vehicle in	IDAC -	○ Yes ® No	Parallel Import	•	🗦 Yes 🖲 No
pe of Tender	Own Damage	*	Assessor	Name *	SIMON	Survey Current	Status	
AC/Workshop ame	indscreen irts & Labour		IDAC/Wo	rkshop Location	51 UBI AVENUE 1 #01-25 PAYA			
findscreen arts & Labour			Total Loss		○ Yes ® No			
arket			Scrape Va	alue(\$)		Economical Repair Value(\$)		
alue(\$)					FRT GRILLE LH & RH REPLACE/1X FRT L			
Damage Lind a Part	isting		No.	Part No.	Description		Qty •	Repair Code
root			No.	Part No.	Description		Qty •	Repair Code
Not Appl	cable		1	32200101	NUMBER PLATE (F	RONT)	1	Replace
ABS			2	16005901	BUMPER SPONGE (FRONT)	1	Replace
ABSORE ACCELE			3	16005501	BUMPER SENSOR (FRONT)	1	Unconfirm
ACTUAT			4	41300901	SUPPORT PANEL TOP GARNIS	SH CLIP (FRONT)	1	Replace
ADVERT	ISEMENT STICKER	•	5	149037	BONNET LOCK C	ATCH	2	Unconfirm
			6	344001	RADIATOR		1	Unconfirm
			7	344005	RADIATOR COW	LING	1	Unconfirm
			8	32200201	NUMBER PLATE BASE	(FRONT)	1	Replace
			9	16000101	BUMPER (FROM	VT)	1	Replace
			10	16002401	BUMPER CLIPS (F	RONT)	6	Replace
			11	16005001	BUMPER REINFORCEME	NT (FRONT)	1	Replace
			12	16002601	BUMPER EMBLEM (FRONT)	1	Replace
			13	16003201	BUMPER GRILLE (FRONT)	1	Unconfirm
			14	41300101	SUPPORT PANEL (F	RONT)	1	Replace
			15	15600101	BRACE PANEL (FR	RONT)	1	Unconfirm
			16	112023	AIR CON CONDE	NSER	1	Unconfirm
			17	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Unconfirm
			18	149001	BONNET		1	Replace
			19	344008	RADIATOR FA	N =	1	Unconfirm
			20	344011	RADIATOR FAN CI	UTCH	1	Unconfirm

Save Submit

· Task Transfer · Exit

Claim Handling LOS SAL SUB Accident MT/0989266 GST Registration No. Policy No. 5088919658 Vehicle No. SKC2216K Policyholder NRIC \$11865383 SIAH HANG CHONG Policyholder Name Loading 0 Product Code PRIVATE CAR INSURANCE Cover Type drivo CLASSIC Contact No.(Home) 0 Contact No.(Mobile) 97322177 Contact No.(Office) 0 Special Remark eCode No ₹ Email Address - No Yes eCode Reason KFK . No Yes NCD Entitlement(%) Private Hire No NCD Protection 50 Yes Accident Details Accident Report Within 24 hrs Yes Accident Type Collision - Head to Rear 06/04/2018 11:02 Report Date 05/04/2018 Time of Accident hh:mm 09:45 Country of Accident Singapore Date of Accident ICM No. NATIONAL ASSESSMENT CENTR Orange Force Reporting Centre No Accident Location GEYLANG ROAD → Benefits **▽** Excess Additional Excess 600.00 0.00 Windscreen Excess 100.00 Own damage Excess Outside Singapore OD 600,00 Unnamed Driver Excess 0.00 Outside Singapore TP Third Party Excess 0.00 0.00 Excess GST Registered Information **GST Registration Date** GST Registered No. GST Status Verified GST Registration No. Yes Modification History Policyholder Mailing Address SINGAPORE 469374 Address 3 94 BEDOK ROAD Address 2 Address 1 Post Code 469374 Singapore address Address 4 Address Type Related Policy Number Unit No. 5088919658 SIAH HANG CHONG Driver Type Main Driver Driver Name Driver NRIC S1186538J Driver DOB 03/12/1956 Unnamed driver Name Register Date of Driver Driving Experience 01/04/1984 Driver Age 61 34 License Contact No.(Mobile) 97322177 Contact No.(Office) Contact No.(Home) 0 0 94 BEDDK ROAD Address 2 Address 3 Address 1 Post Code Address 4 Address Type Singapore address 469374 Unit No Does he own a Singapore Registered car? Yes - No Driver Vehicle No. Driver Insurer Company **▽** Declaration Breathalyser or Blood Any injury? Yes . No 0 mg Test Reading? Modification History Claim 001 OD-MD OD-MD Insured Name SIAH HANG CHONG Insured NRIC \$11865381 Claim Type Contact No.(Mobile) Contact No.(Home) 67854255 Contact No.(Office) 97322177 OI Vehicle Number TP Vehicle Number G8849238 Email Address SKC2216K weichuan87@gmail.com Name of Preferred Workshop SKC2216K / GBB4923B ON 5 Apr 2018 Claim Description Preferred Workshop Contact Insured Liability Partially at Fault Received Require Finalisation Yes Preferered Repair Option Preferred Workshop, Name unknown GIA report Date Registered 06/04/2018 11:10 Claim Close Date Date Received 06/04/2018 KRISHNASAMY Workshop Repairer Total Loss but Repaired Report Taken By Print AK letter

Modification History

Reason

7									
cident No.	MT/098926	5	Claim No.		001	nae			
st Doc, Receive	ed Yes	No	Upload Date		06/04/2018 13	:12			
		Path *			Category	- Laboratoria	Confidential	2007	-
Choose File	No file chosen			Clear	Please Select	*	NO	▼ Normal	•
Choose File	No file chosen			Clear	Please Select	•	NO	▼ Normal	7.1
Choose File	No file chosen			Clear	Please Select	•	NO	▼ Normal	*
Choose File	No file chosen			Clear	Please Select	•	NO	▼ Normal	*
Choose File	No file chosen			Clear	Please Select	7	NO	▼ Normal	
Choose File	No file chosen			Clear	Please Select	•	NO	▼ Normal	¥:
Message Read									
	nt List								
Attachment		Uploaded By/Date		Category	9	Urgency		De	scription
	NAC_PAYA_UB1_800601	NATIONAL ASSESSMENT CENTRE n 06 Apr 2018 13:12	E SERVICES) o	Photos		Normal		Photo	s 2018-4
4	NAC_PAYA_UBI_800601	NATIONAL ASSESSMENT CENTRE n 06 Apr 2018 13:12	E SERVICES) o	Photos		Normal		Photo	s 2018-4
43	NAC_PAYA_UBI_800601	NATIONAL ASSESSMENT CENTRE n 06 Apr 2018 13:12	E SERVICES) o	Photos		Normal		Photo	s 2018-4
	NAC_PAYA_UBI_800601	NATIONAL ASSESSMENT CENTRI n 06 Apr 2018 13:11	E SERVICES) o	Photos		Normal		Photo	s 2018-4
震致	NAC_PAYA_UBI_800601	NATIONAL ASSESSMENT CENTRI n 06 Apr 2018 13:11	E SERVICES) o	Photos		Normal		Photo	s 2018-
	NAC_PAYA_UBI_800601	NATIONAL ASSESSMENT CENTR n 06 Apr 2018 13:11	E SERVICES) o	Photos		Normal		Photo	os 2018-
S	NAC_PAYA_UBI_800601	NATIONAL ASSESSMENT CENTRO n 06 Apr 2018 13:11	E SERVICES) o	Photos		Normal		Photo	os 2018-4
	NAC_PAYA_UBI_800601	NATIONAL ASSESSMENT CENTRI n 06 Apr 2018 13:11	E SERVICES) o	Photos		Normal		Photo	os 2018-4
	NAC_PAYA_UBI_800601	NATIONAL ASSESSMENT CENTR n 06 Apr 2018 13:11	E SERVICES) o	Photos		Normal		Photo	os 2018-4
(a)	NAC_PAYA_UB1_800601	(NATIONAL ASSESSMENT CENTR n 06 Apr 2018 13:10	E SERVICES) o	Photos		Normal		Photo	s 2018-4
	NAC_PAYA_UBI_800601	(NATIONAL ASSESSMENT CENTR n 06 Apr 2018 13:10	E SERVICES) o	Photos		Normal		Photo	os 2018-
17	NAC_PAYA_UBI_800601	(NATIONAL ASSESSMENT CENTR n 06 Apr 2018 13:10	E SERVICES) o	Photos		Normal		Photo	os 2018-4
10	NAC_PAYA_UB1_800601	(NATIONAL ASSESSMENT CENTR n 06 Apr 2018 13:10	E SERVICES) o	Photos		Normal		Photo	os 2018-
	NAC_PAYA_UBI_800601	(NATIONAL ASSESSMENT CENTR n 06 Apr 2018 13:10	E SERVICES) 0	Photos		Normal		Photo	os 2018
TATE OF	NAC_PAYA_UBI_800601	(NATIONAL ASSESSMENT CENTR in 06 Apr 2018 13:10	E SERVICES) o	Photos		Normal		Photo	os 2018
7	NAC_PAYA_UB1_800601	(NATIONAL ASSESSMENT CENTR n 06 Apr 2018 13:09	E SERVICES) o	Photos		Normal		Photo	os 2018→
	NAC_PAYA_UBI_800601	(NATIONAL ASSESSMENT CENTR n 06 Apr 2018 13:09	E SERVICES) o	Photos		Normal		Photo	os 2018-
	NAC_PAYA_UBI_800601	(NATIONAL ASSESSMENT CENTR n 06 Apr 2018 13:09	E SERVICES) o	Photos		Normal		Photo	os 2018-

018	Claim Handling (damage assessment	Claim rask wirrosco.	out old in	
3	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:09	Photos	Normal	Photos 2018-4-6
O	NAC_PAYA_UBI_80D601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:09	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:09	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:09	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) 0 n 06 Apr 2018 13:09	Photos	Normal	Photos 2018-4-6
-22	NAC_PAYA_UBI_B00601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:09	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UBI_BDD601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:09	Photos	Normal	Photos 2018-4-6
-	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n D6 Apr 2018 13:09	Photos	Normal	Photos 2018-4-6
450	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:09	Photos	Normal	Photos 2018-4-6
1	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:08	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n D6 Apr 2018 13:08	Photos	Normal	Photos 2018-4-6
9032X	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:08	Photos	Normal	Photos 2018-4-6
CHAN	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:08	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:08	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:08	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:07	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:07	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UBI_BD0601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:07	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:07	Photos	Normal	Photos 2018-4-6
-	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:07	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 13:07	Photos	Normal	Photos 2018-4-5
A- (25)	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:09	NRIC/ Driving License	Normal	NRIC/ Driving License 201i
1	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:07	SAS	Normal	SAS 2018-4-6
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:07	Photos	Normal	Photos 2018-4-5
	NAC_PAYA_UBL_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:07 NAC_PAYA_UBL_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o	Photos	Normal	Photos 2018-4-6
	n 06 Apr 2018 11:07	and the second s		400 W-144-E000

	Uploaded By/Date	Folder Date	File Name	?	Source
				-	
	NAC_PAYA_UB1_800601	NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:06	Photos	Normal	Photos 2018-4-6
53	NAC_PAYA_UB1_800601{	NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:06	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:06	Photos	Normal	Photos 2018-4-6
1	NAC_PAYA_UBI_BD0601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:06	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:06	Photos	Normal	Photos 2018-4-6
1	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:06	Photos	Normal	Photos 2018-4-5
(T)	NAC_PAYA_UBI_BDD601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:07	Photos	Normal	Photos 2018-4-6
5	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:07	Photos	Normal	Photos 2018-4-6
6	NAC_PAYA_UB1_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:07	Photos	Normal	Photos 2018-4-6
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 06 Apr 2018 11:07	Photos	Normal	Photos 2018-4-6

Display in New Window Scan and uploading

LKK Paya Ubi

From:

Tan Siew Choo <siewchoo.tan@income.com.sg>

Sent:

Friday, 13 April 2018 10:36 AM

To:

'City Auto'; NAC

Subject:

SGD3232Z, OD claim no : MT/0989266

Importance:

High

Dear City Auto,

Veh is still with owner Mr Siah (tel: 97322177).

Owner is overseas at the moment and he will only be back to Singapore tonight.

OD excess of \$600/- is applicable.

FOR PAYMENT: Please forward the Invoice & Discharge Voucher within 14 days after the repair has been done to my email, cc a copy to Yap Chee Ling at cheeling.yap@income.com.sg

Regards.

Without Prejudice

Tan Siew Choo

Senior Claims Executive Motor Insurance 7+65 6430 7882 www.income.com.sg











Our Ref: MT/CA/OD/051/0989266-001/TSC

13 Apr 2018

CITY AUTO PTE LTD

BLK 8 #01-58TO66

SIN MING INDUSTRIAL EST SECTOR C

SINGAPORE 575643

Dear Sir

CLAIM NUMBER: MT/0989266-001

REPAIR OF VEHICLE NUMBER: SGD3232Z

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as

follows:

Award Date: 13 Apr 2018

Make: BMW Model: 523i Estimated Repair Days: 5

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Tan Siew Choo at 64307882 or email us at motor@income.com.sg.

Yours sincerely Low Choo Mee Senior Manager Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

LKK Paya Ubi

From: Tan Siew Choo <siewchoo.tan@income.com.sg>

Sent: Tuesday, 10 April 2018 11:13 AM

To: NA

Subject: SKC2216K (new veh nos : SGD3232Z), OD claim no : MT/0989266

Importance: High

Dear IDAC,

I had been calling owner Mr Siah at his handphone no: 97322177 since yesterday, but I am not able to get hold of him (phone always not available).

Is this veh in your compound? Is owner overseas? any other tel nos to call him instead?

Regards.

Without Prejudice

Tan Siew Choo Senior Claims Executive Motor Insurance T+65 6430 7882 www.income.com.sg











Not in idac

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

LKK Paya Ubi

From:

Tan Siew Choo <siewchoo.tan@income.com.sg>

Sent:

Friday, 13 April 2018 10:36 AM

To:

'City Auto'; NAC

Subject:

SGD3232Z, OD claim no: MT/0989266

Importance:

High

Dear City Auto,

Veh is still with owner Mr Siah (tel: 97322177).

Owner is overseas at the moment and he will only be back to Singapore tonight.

OD excess of \$600/- is applicable.

FOR PAYMENT: Please forward the Invoice & Discharge Voucher within 14 days after the repair has been done to my email, cc a copy to Yap Chee Ling at cheeling.yap@income.com.sg

Regards.

Without Prejudice

Tan Siew Choo Senior Claims Executive Motor Insurance T+65 6430 7882 www.income.com.sg











Our Ref: MT/CA/OD/051/0989266-001/TSC

13 Apr 2018

CITY AUTO PTE LTD

BLK 8 #01-58TO66

SIN MING INDUSTRIAL EST SECTOR C

SINGAPORE 575643

Dear Sir

CLAIM NUMBER: MT/0989266-001

REPAIR OF VEHICLE NUMBER: SGD3232Z

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as

follows:

Award Date: 13 Apr 2018

Make: BMW Model: 523i Estimated Repair Days: 5

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Tan Siew Choo at 64307882 or email us at motor@income.com.sg.

Yours sincerely Low Choo Mee Senior Manager Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.