

Surveyor

## ASSIGNMENT (Office)

From (Person): julie mengubat of AGI Date/Time: 5/4/18 @ 3:59pm

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No: SLB 9821K Insured: SKR 8617T

at Workshop m/: TC Autoclinic Tel: 67038515 / 9645 0023

of 25 Leng Kee Rd

Policy No: Claim No: C10001479

Sum Insured: Excess:

Make of Veh: D.O.A. 02/04/18

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 4:29pm @ 5/4/18 Person Contacted: shawn

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 9821K - X
	SKR 8617T - X
	Confirm final figure \$3639.96

Signature: *Tammy*

REF: AGI

# ASSIGNMENT

From: \_\_\_\_\_ Date: 12/04/2018

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLB 9821K  
at Workshop m/s TC Autoclinic  
of 25 Leng Kee Rd

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record) 2pm - 4pm @ owner waiting  
Make of Veh: Shawn @ 96450023

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>(up)</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT  
Shawn

Veh No: SLB 9821K Yr Regn: 2016 / Apr / 1  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Note. cc. 1198

Colour: Black. A/C: Insured / Std / NI / NA

Sp. Reading: 17483 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: SN17BVE1220982539

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Confrontal

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 12/4/182/5/5

Survey held at TC Autoclinic Leng Kee.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/Top or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 27 APR 2018

Date/Time. File Pass to?

☐ : Preli. Report  
☒ : Final Report

1) 27/4/18 TUPIST  
Date/Time. File Return to?

2) \_\_\_\_\_

Report Format :

Lump Sum / I.B.I: (\$ 3689.96)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

\_\_\_\_ \$ + RS \_\_\_\_ \$

Photos

Others

TOTAL

250

**Nivitha (LKK Auto)**

---

**From:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Sent:** Thursday, 5 April 2018 3:59 PM  
**To:** sur@lkkauto.com; assignments@lkkauto.com  
**Subject:** FW: Accident Involving SLB9821K & SKR8617T On 02/04/18 | Claim ref: C10001479  
**Attachments:** SLB9821K GIA Report.PDF; Estimate Before Survey.pdf

Hi Team

Please survey TP vehicle on a without prejudice basis.

Thank you,  
-Julie

---

**From:** Shawn Chua <shawnychua@tanchong.com>  
**Sent:** Thursday, 5 April, 2018 1:44 PM  
**To:** Claims <claims@budgetdirect.com.sg>  
**Cc:** Heng Kwang Liang <kelvinheng@tanchong.com>  
**Subject:** Accident Involving SLB9821K & SKR8617T On 02/04/18

Dear Sir/Madam,

Our customer holds your insured driver, **SKR8617T** liable for the accident on **02/04/18** and would like to claim against your insured driver. We hereby inquire whether you would like to have a direct settlement with our customer, **SLB9821K**.

If you minded to reach an amicable direct settlement with our customer, please let us have your substantive reply strictly by **10/04/18**. Otherwise our customer will proceed in a manner that he deems fit.

Kindly let me know when can I arrange for a survey so that I'll be able to arrange an appointment with my customer.

Attached herewith the **GIA Report** and **estimate of repair cost** for **SLB9821K**.

Regards,

Shawn Chua  
Service Executive  
TC AutoClinic Pte Ltd  
25 Leng Kee Road  
Singapore 159097  
DID: +65 67038515  
HP: +65 96450023  
Fax: +65 64795019

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/04/2018 08:50
Date Of Accident	02/04/2018 12:20
Exact Location Of Accident	PEOPLE'S PARK CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB9821K
-----------------------------	----------

### Insured/Policyholder

Name Of Registered Owner	XU HUI YUN MARSHA
NRIC No	S1421659F
Email Address	MARSHAXHY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92310409
Alternative Phone No	OTHERS-92310409

### Vehicle Particulars

Manufacturer	NISSAN
Model	NOTE-1.2 DIG-S CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100463639-01000
Cover Note Number	28/04/2017 - 27/04/2018

### Driver

Name of Driver	XU HUI YUN MARSHA
NRIC No	S1421659F
Date Of Birth	04/09/1960
Occupation	INDOOR
Date Of Driving Pass	02/10/1978
Driving Experience	39 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92310409
Fax Number	
Contact Number	OTHERS-92310409
Email Address	MARSHAXHY@GMAIL.COM

Address	1005 LOWER DELTA RD #08-02
Postcode	S099309
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer to attached sketch plan

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR8617T
Vehicle Make/Model/Colour	PEUGEOT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NASYITAL TAN WAH LING
NRIC/Passport Number	
Contact Number	90291411
Address	
Postcode	
Insurance Company Name	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

3/4/18 12pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At People's park car park in Chinnor, SKR 8617T was reversing her car to park, as she ~~re~~ reversed in, I drove past, suddenly her car surged forward to ~~not~~ hit the second part of my car body.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO : 67038511  
REFERENCE : 084/IC/TCAC/CCR/2018  
DATE : 04-FEB-2018

BUDGET DIRECT INSURANCE  
190 CLEMENCEAU AVENUE  
#03-01 SINGAPORE SHOPPING CENTRE  
S(239924)  
TEL : 62212111  
FAX :

OWNER'S NAME : XU HUI YUN MARSHA  
ADDRESS : 1005 LOWER DELTA ROAD  
#08-02  
S(099309)  
TELEPHONE NO : 92310409

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100463639-01000  
VEHICLE NO : SLB9821K  
MODEL CODE : TDWAREZE12VDAY406Z  
MODEL/YEAR : NISSAN NOTE 1.2 SUPER CHARGE  
ENGINE NO : HR121864398  
CHASSIS NO : JN1TBAE12Z0982539  
MILEAGE : 17156 KM  
DATE IN : 04/02/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : SHAWN CHUA CHU RONG  
ACCIDENT DATE : 02/04/2018

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495746  
12/1/18 R1515  
WP  
\* Resurvey before paint  
sur@lkkauto.com  
6 days

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLB9821K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	360.00	✓
2	SEAL	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	300.00	100 ✓
3	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	✓
4	ZZ/001	RENEW FRONT LEFT DOOR, REAR LEFT DOOR, REAR LEFT FENDER ETC. PANELS & REPAIR	1950.00	290 1170 ✓
5	ZZ/002	RENEW REAR LEFT RIM	50.00	✓
6	ZZ/003	RENEW REAR LEFT QUARTER GLASS TO FACILITATE REPAIR	150.00	X
7	ZZ/004	INSTALL SOLAR FILM ON REAR LEFT QUARTER GLASS	32.00	X
8	ZZ/005	TRANSFER FRONT LEFT & REAR LEFT DOORS COMPONENTS TO FACILITATE REPAIR	240.00	120 ✓
9	ZZ/006	REMOVE & INSTALL HEADLINER, SEATS, SIDE PANELS TO FACILITATE REPAIR	120.00	X
10	ZZ/007	RESPRAY FRONT LEFT DOOR, REAR LEFT DOOR, REAR LEFT FENDER, SIDE SILL, MUDGUARD ETC	1500.00	250 750 ✓
11	ZZ/008	QC, RETUNE & CONSULT CHECK		
12	ZZ/009	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	120.00	X
TOTAL LABOUR CHARGES:			4915.00	

ATC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SL89821K

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	ALLOY RIM(E12)	40300-SH08		apt ✓ 350.00 X
2	SEALANT - SIDE	SEALANT - 2		nn X 80.00 Y
3	REAR LEFT QUARTER GLASS	83301-3VA08		nn X 608.00 Y
4	REAR DOOR CENTRE MOULDING	82821-3VADA	122.80	? X nn
5	REAR LEFT DOOR	H210A-3VAMA	871.20	bt ✓
6	FRONT LEFT DOOR CENTRE MOULDING	80821-3WC1A	85.10	X X nn
7	FRONT LEFT DOOR	H010A-3VAMA	871.20	Rp X
8	REAR LEFT FENDER	G8101-3VAMA	863.50	Rp X
9	LEFT SIDE SILL	G6411-3VAMA	852.60	Rp X
SUB TOTAL			3666.40	0.00 1038.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			733.28	0.00 0.00
GRAND TOTAL			2933.12	0.00 1038.00
OVERALL TOTAL			3971.12	

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLB9B21K

TOTAL LABOUR CHARGES	4915.00
TOTAL SPARE PARTS CHARGES	3971.12
	-----
GRAND TOTAL	8886.12 *
	-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO : 67038511  
REFERENCE : 084/IC/TCAC/CCR/2018  
DATE : 04-FEB-2018

BUDGET DIRECT INSURANCE  
190 CLEMENCEAU AVENUE  
#03-01 SINGAPORE SHOPPING CENTRE  
S(239924)  
TEL : 62212111  
FAX :

OWNER'S NAME : XU HUI YUN MARSHA  
ADDRESS : 1005 LOWER DELTA ROAD  
#08-02  
S(099309)  
TELEPHONE NO : 92310409

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100463639-01000  
VEHICLE NO : SL89821K  
MODEL CODE : TDWAREZE12V0AY406Z  
MODEL/YEAR : NISSAN NOTE 1.2 SUPER CHARGE  
ENGINE NO : HR121864398  
CHASSIS NO : JN1TBAE12Z0982539  
MILEAGE : 17156 KM  
DATE IN : 04/02/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : SHAWN CHUA CHU RONG  
ACCIDENT DATE : 02/04/2018

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLB9821K

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	360.00	360.00
2 SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	300.00	100.00
3 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	93.00
4 ZZ/001	RENEW REAR LEFT DOOR REPAIR FRONT LEFT DOOR, REAR LEFT FENDER, LEFT SILL	1950.00	1170.00
5 ZZ/002	RENEW REAR LEFT RIM	50.00	50.00
6 ZZ/003	RENEW REAR LEFT QUARTER GLASS TO FACILITATE REPAIR	150.00	.00
7 ZZ/004	INSTALL SOLAR FILM ON REAR LEFT QUARTER GLASS	32.00	.00
8 ZZ/005	TRANSFER FRONT LEFT & REAR LEFT DOORS COMPONENTS TO FACILITATE REPAIR	240.00	120.00
9 ZZ/006	REMOVE & INSTALL HEADLINER, SEATS, SIDE PANELS TO FACILITATE REPAIR	120.00	.00
10 ZZ/007	RESPRAY FRONT LEFT DOOR, REAR LEFT DOOR, REAR LEFT FENDER, SIDE SILL	1500.00	750.00
11 ZZ/008	QC, RETUNE & CONSULT CHECK		
12 ZZ/009	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	120.00	.00
	TOTAL LABOUR CHARGES	4915.00	2643.00

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLB9821K

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	REAR LEFT QUARTER GLASS	83301-3VA0B			608.00	X
2	ALLOY RIM(E12)	40300-SH08			350.00	OK
3	SEALANT - SIDE	SEALANT - 2			80.00	X
4	REAR DOOR CENTRE MOULDING	82821-3VA0A	122.80			X
5	REAR LEFT DOOR	H210A-3VAMA	871.20			OK
6	FRONT LEFT DOOR CENTRE MOULDING	80821-3WC1A	85.10			X
7	FRONT LEFT DOOR	H010A-3VAMA	871.20			X
8	REAR LEFT FENDER	G8101-3VAMA	863.50			X
9	LEFT SIDE SILL	G6411-3VAMA	852.60			X
SUB TOTAL			871.20	0.00	350.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			174.24	0.00	0.00	
GRAND TOTAL			696.96	0.00	350.00	
OVERALL TOTAL			1046.96			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLB9821K

NETT ITEM 871.20  
LESS 20.00%) -174.24  
NETT AMOUNT 696.96

LIST ITEM 0.00  
LESS 30.00%) 0.00  
LIST AMOUNT 0.00

SPECIAL NETT ITEM 350.00  
LESS .00%) 0.00  
SPECIAL NETT AMOUNT 350.00

TOTAL LABOUR CHARGES 2643.00  
TOTAL SPARE PARTS CHARGES 1046.96

TOTAL CHARGES 3689.96  
ADD 7 % GST 258.30

GRAND TOTAL 3948.26





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18006368/T1td3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRES SINGAPORE

239924

Date : 04-05-2018



Code : AGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKR 8617T	Veh. Inspected	SLB 9821K
Policy No.		Coverage (\$)	0.00
Claim No.	C10001479	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	05/04/2018

## 2. Vehicle Particulars & Condition

Make & Model	NISSAN NOTE	c.c	1198
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JN1TBAE12Z0982539	Colour	BLACK
Odometer	17483	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	CONTINENTAL	6 mm
L/H Front Tyre	185/65 R15	CONTINENTAL	6 mm
R/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm
L/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	02/04/2018	Inspection Date	12/04/2018
Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 9821K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR DOOR CENTRE MOULDING (N)	NOT NECESSARY	122.80	-
1	REAR LEFT DOOR (N)	BENT	871.20	871.20
1	FRONT LEFT DOOR CENTRE MOULDING (N)	NOT NECESSARY	85.10	-
1	FRONT LEFT DOOR (N)	TO REPAIR SEE LABOUR	871.20	-
1	REAR LEFT FENDER (N)	TO REPAIR SEE LABOUR	863.50	-
1	LEFT SIDE SILL (N)	TO REPAIR SEE LABOUR	852.60	-
	LESS 20% DISCOUNT		-733.28	-174.24
			2,933.12	696.96
<b>SPECIAL NETT ITEMS</b>				
1	ALLOY RIM (E12)(SN)	CUT	350.00	350.00
1	SEALANT-SIDE (SN)	NOT NECESSARY	80.00	-
1	REAR LEFT QUARTER GLASS (SN)	NOT NECESSARY	608.00	-
			1,038.00	350.00
<b>LABOUR</b>				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		360.00	360.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		300.00	100.00
	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION.		93.00	93.00
	RENEW FRONT LEFT DOOR, REAR LEFT DOOR, REAR LEFT FENDER ETC. PANELS & REPAIR. INCLUSIVE OF THE REPAIR OF LEFT SIDE SILL.		1,950.00	1,170.00
	RENEW REAR LEFT RIM.		50.00	50.00
	RENEW REAR LEFT QUARTER GLASS TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	INSTALL SOLAR FILM ON REAR LEFT QUARTER GLASS.	NOT NECESSARY	32.00	-
	TRANSFER FRONT LEFT & REAR LEFT DOORS COMPONENTS TO FACILITATE REPAIR.		240.00	120.00
	REMOVE & INSTALL HEADLINER, SEATS, SIDE PANELS TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-

Report Ref No. CS/AGI18006368/T1td3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY FRONT LEFT DOOR,REAR LEFT DOOR,REAR LEFT FENDER,SIDE SILL MUDGUARD ETC.	NOT NECESSARY	1,500.00	750.00
	WASH A& VACUUM,POLISH & WAX,SHINE ALL TYRES.		120.00	-
			4,915.00	2,643.00
GRAND TOTAL			8,886.12	3,689.96
RECOMMENDED COST OF REPAIRS				3,689.96

Report Ref No. CS/AGI18006368/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.