

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315



Reg. No: 52983356E GST Reg. No. 20-0405911-H

| NTUC INCOME INSURANCE CO-OPERATIVE LTD                                 |  |                          | Ref:         | NS/INC18006375/Svbn2 |            |  |
|--|--|--------------------------|--------------|----------------------|------------|--|
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556 |  |                          | Date:        | 02-05-2018<br>INC4   |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                             |  |                          |              |                      |            |  |
|  | Insured Veh.   | SLV 3014H                | Veh. Ir      | spected              | SHB 668T   |  |
|  | Policy No.   | 5096979944               | Covera       | age (\$)             | 0.00       |  |
|  | Claim No.  | MT/0989010-002           | Exces        | s (\$)               | 0.00       |  |
|  | Assign From  |                          | Assigr       | n Date               | 05/04/2018 |  |
| 2. Vehicle Particulars & Condition                                     |  |                          |              |                      |            |  |
|  | Make & Model   | TOYOTA PRIUS 4           | c.c          |                      | 1798       |  |
|  | Engine No.   | HIDDEN                   | Year o       | f Reg.               | 2017       |  |
|  | Chassis No.  | JTDKB3FU803579722        | Colour       | •                    | MAROON     |  |
|  | Odometer   | 25703                    | Steerin      | ng                   | IN ORDER   |  |
|  | Brakes   | IN ORDER                 | Modifi       | cation               | NIL        |  |
|  | General  | FAIR                     |              |                      |            |  |
| 3. Conditions of Tyres   |  |                          |              |                      |            |  |
|  |  | Size                     | Make         |                      | Balance    |  |
|  | R/H Front Tyre   | 195/65 R15               | YOKOH        | IAMA                 | 7 mm       |  |
|  | L/H Front Tyre   | 195/65 R15               | YOKOH        | IAMA                 | 7 mm       |  |
|  | R/H Rear Tyre  | 195/65 R15               | YOKOH        | IAMA                 | 7 mm       |  |
|  | L/H Rear Tyre  | 195/65 R15               | YOKOH        | IAMA                 | 7 mm       |  |
| 4. Description of Damages  |  |                          |              |                      |            |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |                          |              |                      |            |  |
|  | DAMAGES SEE DETAILS.   |                          |              |                      |            |  |
| 5.   | 5. General Information   |                          |              |                      |            |  |
|  | Accident Date  | 04/04/2018               | Inspec       | tion Date            | 05/04/2018 |  |
|  | Survey held at   | SMRT AUTOMOTIVE SERVICES | ICES PTE LTD |                      |            |  |
|  | 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705   |                          |              |                      |            |  |
| 5a.  | Remarks  |                          |              |                      |            |  |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                          |              |                      |            |  |
| 5b.  | Estimate Days of Repair  |                          |              |                      |            |  |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days   |                          |              |                      |            |  |