

22/03/2001

ASS. REC. BY:

REF: CS/MSG18006379/4+0307 Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Elaine Nguof MSIGDate/Time: 6/4/18 @ 11:17am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 5061JInsured: SDY 2210Tat Workshop m/s Ban Hock HinTel: 62816520of No. 6 Defu Lane 4Policy No: 27320685 SMPClaim No: 554656

Sum Insured:

Excess:

Make of Veh:
(Client's Record)D.O.A. 02/04/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:49am @ 6/4/18

Person Contacted:

KhalidVehicle: IN OUT

Date/Time

Action/Instruction (✓) Estimate

FBK 5061J - X

SDY 2210T - X

10/04/18

@ 10.08am. revised to Elaine Ngu Sau Mei via member.

MS16/**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / ☒ VS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: F3K5061Jat Workshop m/s Bri/H

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: F3K5061J Yr Regn: 10 / 15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha / BR125 c.c. 124Colour: orange A/C: Insured / Std / NI / NASp. Reading: 38373 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LBPRG101000055563Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 2.75-18R: 3.00-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or metze/rFront 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 2/4/18 D.O.I. 8/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & n/s. o/s only.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/4/18 Conf. and final by 398 with Raymond. (Red. 368, 439)

RECEIVED 20 APR 2018

Date/Time, File Pass to?

1) 20/4 Typist ☐ : Prel. Report☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 39820010210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18006379/Utd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 06-04-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDY 2210T	Veh. Inspected	FBK 5061J	
Policy No.	27320685SMP	Coverage (\$)	0.00	
Claim No.	554656	Excess (\$)	0.00	
Assign From	MERIMEN (ELAINE NGU)	Assign Date	06/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/04/2018	Inspection Date	06/04/2018	
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth ed	Status
Main	02 Apr 2018		06 Apr 2018 11:17 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	K,ASOKAN, ID: S1606578A		
Main Claimant:	MAGIX FOOD ENTERPRISE, Co. Reg. No.: 53065880A		
Vehicle Reg. No.:	FBK5061J	Date of Loss:	02/04/2018 11:00 - :59 [29 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 554656	Policy/Cover Note No.:	27320685SMP (Comprehensive) Coverage: 10/05/2017 - 09/05/2018
Vehicle Reg. No. (Insured):	SDY2210T	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/04/2018]		
Adj Asg. Remarks:	THERE IS A BIKE ALSO SAME SHOP -554646- ALREADY ASSIGN TO LKK		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 10 Apr 2018

Preliminary Advice

Insured Vehicle No : SDY2210T
TP Vehicle No : FBK5061J
Make : YAMAHA YBR125
Date of Inspection : 06/04/2018
Inspection At : Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Accident Date : 02/04/2018
Assignment Date : 06/04/2018
Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear, n/s and o/s body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	706.00
Revised Amount	:S\$	398.00
Check Items (Estimated)	:S\$	1.50
Total	:S\$	399.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBK5061J		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	YBR125		
Chassis No. :	LBPREF101000055563		
Propellant :	Petrol		
Engine No. :	E3F5E040671		
Engine Capacity :	124 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	320 kg		
Unladen Weight :	114 kg		
Year Of Manufacture :	2015		
Original Registration Date :	03 Oct 2015		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$6,112.00		
COE Expiry Date :	02 Oct 2025		
Road Tax Expiry Date :	02 Oct 2018		
Inspection Due Date :	02 Oct 2018		
Intended Transfer Date :	06 Apr 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5880A
Vehicle Details	
Vehicle No.:	FBK5061J
Vehicle to be Exported:	No
Intended De-registration Date:	06 Apr 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	E3F5E040671
Chassis No.:	LBPREF101000055563
Maximum Power Output:	-
Open Market Value:	\$1,941.00
Original Registration Date:	03 Oct 2015
First Registration Date:	03 Oct 2015
Transfer Count:	1
Actual ARF Paid:	\$292.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Oct 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,112.00
COE Rebate Amount:	\$4,577.00
Total Rebate Amount:	\$4,577.00

The information contained herein is correct as at 06 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/04/2018 17:31
Date Of Accident	02/04/2018 11:55
Exact Location Of Accident	206A CHUA CU KANG AVE 1(OUTSIDE RITE PIZZA)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK5061J
Insured/Policyholder	
Name Of Registered Owner	MAGIX FOOD ENTERPRISE
Co Reg No	53065880A
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96904979

Vehicle Particulars

Manufacturer	YAMAHA
Model	YBR125
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	MSD/VMT/17-986208-WTT
Cover Note Number	

Driver

Name of Driver	ANDIAN BIN ZAINAL
NRIC No	S9022381Z
Date Of Birth	22/06/1990
Occupation	OUTDOOR
Date Of Driving Pass	19/06/2017
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96904979
Fax Number	
Contact Number	
EEmail Address	YEOQIN@HOTMAIL.COM

Address

BLK 119 BUKIT BATOK WEST AVENUE 6 #02-254 SINGAPORE 650119

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

The bike FBK6061J was stationary in front of the shop, suddenly the other party SDY2210T reversed back and bang onto the bike. No injuries involved

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDY2210T
Vehicle Make/Model/Colour	B.M.W./520I/BROWN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	K ASOKAN
NRIC/Passport Number	S1606578A
Contact Number	94880635
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (i) I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MAI
REPORTING OFFICER
MUHAMMAD SUMARDI
MOHD AFFANDI

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Officer
Personnel

Sketch Plan

ACCIDENT STATEMENT (2000 characters)

The bike FBK6061J was stationary in front of the shop, suddenly the other party SDY2210T reversed back and bang onto the bike. No injuries involved

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

2 April 2018 3:14 pm

Date/Time:

2 April 2018 3:15 pm



MSIG Insurance (Singapore) Pte. Ltd. (Incorporated in Singapore)
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel: +65 5827 7888, Fax: +65 5827 7800
www.msig.com.sg

CERTIFICATE OF INSURANCE

Road Transport Act, 1987 (Malaysia)
The Motor Vehicles (Third Party Risks) Rules, 1987 (Federation of Malaysia)
Motor Vehicles (Third Party Risks and Compensation) Act (CAP. 189) of the Revised Edition) (Republic of Singapore)
The Motor Vehicles (Third Party Risks and Compensation) Rules, 1986 (Federation of Malaysia)
Or any Amendment, Act or Acts passed in substitution thereof.

CERTIFICATE NO : MSD/VMP/17-986268-VTF A0533-081/W0801

MINURED : TPL
CLASS : NIL

Index mark and Registration Number of Vehicle : 51065880A
YK5061J 124 C.C.

Name of Policyholder : YAMAHA
MAGIX F000 ENTERPRISE

Effective date of the Commencement of Insurance : 08/11/2017
for the purposes of the Act
Date of Expiry of Insurance : 05/11/2018

Persons or Classes of Persons entitled to drive

1. Any person who is driving on the Policyholder's order

OR with their permission
provided that the person driving is permitted in accordance with the licensing
other laws or regulations to drive the Motor Vehicle or has been so permitted
and is not disqualified by order of a Court of Law or by reason of any enactment
regulation in that behalf from driving the Motor Vehicle. And provided further that
the Motor Vehicle is registered and licensed under the Road Traffic Act and its
regulation and licensing under the Road Traffic Act has not been cancelled at the
time of the accident loss or damage.

Limitation as to Use
Use for social domestic and pleasure purposes and in
connection with the Policyholder's business or profession.

The Policy does not cover
.. Use for hire or reward.

1. Use for racing, pace-making, reliability trial or speed-testing.
1. Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party
Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport
Act, 1987 (Malaysia), are not to be included under these headings.*

WE HEREBY CERTIFY that the Policy to which this Certificate relates is
issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks
and Compensation) Act (Chapter 189) and the Road Transport Act,
1987 (Malaysia).

WTT INSURANCE AGENCIES PTE LTD

LIST ITEMS

<u>PAY</u>	<u>UNPAID</u>
5.00	195.00
50.00	2.50
20.00	15.00
48.00	10.00
35.00	1.50
60.00	14.00
180.00	30.00
	40.00

NETT ITEMS

<u>PAY</u>	<u>UNPAID</u>
------------	---------------

LABOUR

<u>PAY</u>	<u>UNPAID</u>
------------	---------------

0.00

0.00

398.00

0.00

308.00

0.00

706.00

0.00

0.00

398.00

0.00

0.00

308.00

0.00

0.00

0.00

0.00 (25% DISC)

0.00 LIST ITEM AFTER DISC (PAY)

0.00 NETT ITEM (PAY)

398.00 ITEM (PAY)

398.00

1.50



CHECK ITEM

1.50

TOTAL = 399.50 (PAY ITEM + CHECK ITEM)



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

MSIG INSURANCE (S) PTE LTD
4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

NO. : 32504

DATE : 03/04/2018
CLAIM NO. : 11125
POLICY NO. : MSD/MT/17-986208-WT
FROM : RAYMOND

VEHICLE NO. : FBK5061J
MAKE/MODEL : YAM / YBR125

*Not Allowed
to be photo taken
3 days.
6/4/18*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00 X
2	DAMPER FOOTREST P/N: 52712	REPLACE	1.00	\$2.50	2.50 X
3	FOOTREST REAR ASSY LH P/N: 25348	REPLACE	1.00	\$15.00	15.00 X
4	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	2.00	\$35.00	70.00
5	PLATE P/N: 52713	REPLACE	1.00	\$1.50	1.50 X
6	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00 X
7	SPRAY PAINT ON FIBER BOX	Spray	1.00	\$210.00	210.00
8	STAND MAIN P/N: 26847	REPLACE	1.00	\$40.00	40.00 X
9	STICKER (HALAL) 9CM P/N: 29313	REPLACE	2.00	\$2.50	5.00
10	STICKER (RITE PIZZA) BOX REAR 17" X 23" P/N: 29117	REPLACE	1.00	\$50.00	50.00
11	STICKER (RITE PIZZA) FUEL TANK P/N: 29118	REPLACE	2.00	\$10.00	20.00
12	STICKER (RITE PIZZA) TEL NO:68993838 - SMALL P/N: 29195	REPLACE	3.00	\$16.00	48.00



S/N	Description	Action	Qty	Unit Price	Amount
13	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		1.00	\$35.00	35.00

SUB TOTAL	\$706.00
GST @ 7 %	\$49.42
GRAND TOTAL	\$755.42

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

398





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32504

- Rev. 1

MSIG INSURANCE (S) PTE LTD
4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

DATE : 03/04/2018
CLAIM NO. : 11125
POLICY NO. : MSD/VMT/17-986208-WT
FROM : RAYMOND

VEHICLE NO. : FBK5061J
MAKE/MODEL : YAM / YBR125

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	2.00	\$30.00	60.00
2	SPRAY PAINT ON FIBER BOX	Spray	1.00	\$180.00	180.00
3	STICKER (RITE PIZZA) BOX REAR 17" X 23" P/N: 29117	REPLACE	1.00	\$50.00	50.00
4	STICKER (RITE PIZZA) FUEL TANK P/N: 29118	REPLACE	2.00	\$10.00	20.00
5	STICKER (RITE PIZZA) TEL NO:68993838 - SMALL P/N: 29195	REPLACE	3.00	\$16.00	48.00
6	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		1.00	\$35.00	35.00
7	STICKER (HALAL) 9CM P/N: 29313		2.00	\$2.50	5.00

SUB TOTAL
GST @ 7 %

\$398.00
\$27.86

GRAND TOTAL

\$425.86

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0303
ISO 9001: 2008

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2018		06 Apr 2018 11:17 Edit Adj Rpt	\$398.00 Edit Estimates	\$398.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS [Created by Insurer] Insured: K,ASOKAN, ID: S1606578A Main Claimant: MAGIX FOOD ENTERPRISE, Co. Reg. No.: 53065880A Vehicle Reg. No.: FBK5061J Date of Loss: 02/04/2018 11:00 - :59 [29 Months and 30 Days From LTA Reg Date (Man Yr)] Claim Type: TP / 554656 Policy/Cover Note No.: 27320685SMP (Comprehensive) Coverage: 10/05/2017 - 09/05/2018 Vehicle Reg. No. (Insured): SDY2210T Policy No. (Claimant): Excess: S\$750.00 Repairer: Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520 Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540] Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 06/05/2018] Adj Asg. Remarks: THERE IS A BIKE ALSO SAME SHOP -554646- ALREADY ASSIGN TO LKK				

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBK5061J (554656)
[SDY2210T]
TP
MAGIX FOOD ENTERPRISE
Apr 2 2018 11:00AM
[K,ASOKAN]
Ban Hock Hin Co. Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page 1 ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	10/04/18 10:08	Adjuster Immediate Advice	1 Load HTM	
Photos/Images			3 per page 3 ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	07/04/18 10:38	General View	1 Load JPG ☒	
2	07/04/18 10:38	General View	1 Load JPG ☒	
3	07/04/18 10:38	General View	1 Load JPG ☒	
4	07/04/18 10:38	General View	1 Load JPG ☒	
5	07/04/18 10:38	General View	1 Load JPG ☒	
6	07/04/18 10:38	General View	1 Load JPG ☒	
7	07/04/18 10:38	General View	1 Load JPG ☒	
8	07/04/18 10:38	General View	1 Load JPG ☒	
9	07/04/18 10:38	General View	1 Load JPG ☒	
10	07/04/18 10:38	General View	1 Load JPG ☒	
11	07/04/18 10:38	General View	1 Load JPG ☒	
12	07/04/18 10:38	General View	1 Load JPG ☒	
13	07/04/18 10:38	General View	1 Load JPG ☒	
14	07/04/18 10:38	General View	1 Load JPG ☒	
15	07/04/18 10:38	General View	1 Load JPG ☒	
16	07/04/18 10:38	General View	1 Load JPG ☒	
17	07/04/18 10:38	General View	1 Load JPG ☒	
18	07/04/18 10:38	General View	1 Load JPG ☒	
19	07/04/18 10:38	General View	1 Load JPG ☒	
20	07/04/18 10:38	General View	1 Load JPG ☒	
21	18/04/18 19:12	Reinspection Photo	1 Load JPG ☒	
22	18/04/18 19:12	Reinspection Photo	1 Load JPG ☒	
23	18/04/18 19:12	Reinspection Photo	1 Load JPG ☒	
24	18/04/18 19:12	Reinspection Photo	1 Load JPG ☒	
25	18/04/18 19:12	Reinspection Photo	1 Load JPG ☒	
26	18/04/18 19:12	Reinspection Photo	1 Load JPG ☒	
27	18/04/18 19:12	Reinspection Photo	1 Load JPG ☒	
28	18/04/18 19:12	Reinspection Photo	1 Load JPG ☒	
Documentation			1 per page 1 ☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print	
1	06/04/18 11:14	TPD FBK5061J EST & PRI & GIA REPORT.pdf	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006379/UTD3E2

Date: 20/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27320685SMP

Claimant Vehicle No : FBK5061J

Insured Vehicle No : SDY2210T

Date of Loss: 02/04/2018

Nature of Claim: TP

Claim No: 554656

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBK5061J

Make & Model: YAMAHA YBR125, 124cc (M)

Engine No: E3F5E040671

Reg. Date: 03/10/2015 (Man. Year: 2015)

Chassis No: LBPREF101000055563

Colour: Orange

Odometer: 38373 km

Engine Capacity: 124 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.75-18

Rear Tyre Size: 3.00-18

Front Left Side: Metzeler 6 mm

Rear Left Side: Metzeler 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	391.00	123.00	268.00	68.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	315.00	275.00	40.00	12.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	706.00	398.00	308.00	43.63
+ GST 7.00/7.00% (S\$)	49.42	27.86	21.56	43.63
Nett Amount (S\$)	755.42	425.86	329.56	43.63

INSPECTION

Date of Assignment: 06/04/2018

Date Inspected: 06/04/2018 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Apr 2018)	
Parts:	N/A	YAMAHA YBR125 124cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK5061J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CRASH BAR (DENTED)	Not Consistent With The Impact	195.00 F	*- F
2	1		*DAMPER FOOTREST	Not Necessary	2.50 F	*- F
3	1		*FOOTREST REAR ASSY LH	Not Necessary	15.00 F	*- F
4	1		*PLATE	Not Necessary	1.50 F	*- F
5	1		*RUBBER FOOTREST FRONT (TORN)	Not Consistent With The Impact	14.00 F	*- F
6	1		*STAND MAIN	Not Necessary	40.00 F	*- F
7	2		*STICKER (HALAL) 9CM	Necessary	5.00 F	*5.00 F
8	1		*STICKER (RITE PIZZA) BOX REAR 17 X 23	Necessary	50.00 F	*50.00 F
9	2		*STICKER (RITE PIZZA) FUEL TANK	Necessary	20.00 F	*20.00 F
10	3		*STICKER (RITE PIZZA) TEL NO:68993838-SMALL	Necessary	48.00 F	*48.00 F

F=Franchise part.

Total Parts (S\$) **391.00** **123.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR - FOR DISMANTLING AND ASSEMBLING OF PARTS	New	70.00	60.00
2	SPRAY PAINT ON FIBER BOX	New	210.00	180.00
3	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER)	New	35.00	35.00
Gross Labour Cost (S\$)			315.00	275.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >