

ASS. REC. BY:

REF

CS3/MSG18006383/GZAD3

Special Instructions:

Surveyor

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSG

Date/Time:

06/04/18 @ 12:05 pm

Estimated Cost:

Bill to:

OD (11) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JKJ 6769

Insured:

SJJ 4606E

at Workshop m/s

Motor Intel Automo

Tel:

8838 3318

of

13 Kaki Bkt Road 4 #01-20

Policy No:

S288136308MP

Claim No:

554389

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/04/2018

CA / REV / REP. / REV 24 HRS (wp)

09/04/2018

H.O.D. Endorsement:

Date/Time:

12:52pm @ 6/4/18

Person Contacted:

Wilson

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	JKJ 6769 -X
	SJJ 4606E -X
10/4/18	Dismantled

PR5
Xhl.

REF: MSIG

ASSIGNMENT

From: Date: 09/04/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JKJ 6769

at Workshop m/s Motor Intel
of 13 Kaki Bkt Rd 4 # 01-20

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: JKJ6769

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota

G.C

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 241555

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50ZR18

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Joy road

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 09-04-18

Survey held at w/s 5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$7,800 - \$9,500

20/6/2018

Date/Time. File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

☐ : S + RS, SI

☐ : Photos

☐ : Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS3/MSG18006383/Gz4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 06-04-2018	
			Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SJJ 4606E	Veh. Inspected	JKJ 6769	
Policy No.	S28813630SMP	Coverage (\$)	0.00	
Claim No.	554389	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	06/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/04/2018	Inspection Date		
Survey held at	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018		06 Apr 2018 12:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KANG KAI, ID: S7975531A, Tel: +6598525522, Email: kangkai24@yahoo.com		
Main Claimant:	Bok Chik Fu, ID: F7418579R		
Vehicle Reg. No.:	JKJ6769	Date of Loss:	03/04/2018 16:00 - :59 [219 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 554389	Policy/Cover Note No.:	S28813630SMP (Comprehensive) Coverage: 15/09/2017 - 14/09/2018
Vehicle Reg. No. (Insured):	SJJ4606E	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/04/2018]		
Driver/Custodian (Insured):	KANG KAI (38 / Female), NRIC: S7975531A, Tel: +6598525522		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



AMY LIM LAW PRACTICE

High Street Centre
1 North Bridge Road
#08-08
Singapore 179094
T: 9625 8742 / 9639 3110
F: 6491 5638
UEN: 53361230J
We do not accept service by fax

Our Ref: 2018.1158.PD.MIA (JKJ6769)
Your Ref: SJJ4606E

4 April 2018

MSIG Insurance (Singapore) Pte Ltd
(Motor Claims Dept)
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581
Attn: Motor Claims Department

BY EMAIL ONLY
claims@sg.msig-asia.com

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: BOK CHIK FU
TRAFFIC ACCIDENT ON 2 APRIL 2018 AT 18:30 HRS AT THE JUNCTION OF
WOODLANDS AVENUE 1 AND WOODLANDS AVENUE 12 INVOLVING
VEHICLES NO. JKJ6769 & SJJ4606E

We are instructed by **Bok Chik Fu** to notify you of a road accident on 2 April 2018 at about 18:30 hrs at the junction of Woodlands Avenue 1 and Woodlands Avenue 12 involving our client's vehicle registration number JKJ6769 and vehicle registration number SJJ4606E driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: **Motor Intel Automo Pte Ltd**
Address: 13 Kaki Bukit Road 4,
#01-20, Bartley Biz Centre
Singapore 417807
Contact: Wilson Ong @ 8838 3318

Please liaise with the above workshop directly.

Yours faithfully

Esther Moey

Email: claims@esthermoey.com

encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

.....



SINGAPORE POLICE FORCE



T/20180403/2102

1 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunus Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20180403/2102

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/04/2018 17:24		Vide Report No.:		Station Diary No.: 33	
Informant's Particulars					
Name of Informant: BOK CHIK FU			Address: APT BLK 6001 BEACH ROAD #02-14 GOLDEN MILE TOWER SINGAPORE 199589		
ID Type / ID No.: FIN NO / F7418579R			Contact No.: Home/Office: Mobile: 9422 5744		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 41	Date of Birth: 10/02/1977	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Furniture Contractor			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 02/04/2018 18:30	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 WOODLANDS AVENUE 12 WOODLANDS AVENUE 1 TOWARDS SLE, JUNCTION OF WOODLANDS AVENUE 1				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JKJ6769	Car	TOYOTA		White	Slightly Damaged	0
SJJ4606E	Car	MERCEDES BENZ		White	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180403/2102

2 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20180403/2102

CONTINUATION OF REPORT

Driver			
Name	BOK CHIK FU	ID No.	F7418579R
Related Vehicle	JKJ6769 (Car)	Contact No.	9422 5744
Hospital/Clinic	PARKWAY EAST HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	03/04/2018	Date Discharge	03/04/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	KANG KAI	ID No.	S7975531A
Related Vehicle	SJJ4606E (Car)	Contact No.	9112 3353
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 02/04/2018 at about 1830hrs, I was driving my vehicle, a white coloured Toyota, bearing the licence plate of JKJ6769. I was approaching the T-junction of Woodlands Avenue 12, and Woodlands Avenue 1, heading towards SLE.

As the traffic there was very heavy, I had to slow down, and eventually stopped at the junction, and waited for the traffic to pass. When my vehicle was stationary at the junction, I suddenly felt an impact from the rear of my vehicle.

After the accident, I went out of my vehicle to see what had happened. Apparently, a white Mercedes bearing the licence plate of SJJ4606E, had collided into the rear of my vehicle. I then exchanged particulars with the other driver, and we decided to settle the matter through insurance claim.

On 03/04/2018 at about 1000hrs, I woke up and felt pain on the left rear side of my neck. I then went to the Parkway East Hospital to get checked up, and received three days of medical leave.
I do not have in-car camera installed in my vehicle.



SINGAPORE
POLICE FORCE



T/20180403/2102

3 of 3

Report No. T/20180403/2102

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt LUQMAN MOHD MANSOR

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Staff Sgt TANG SIEW PING
Contact No.: 65476430

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
03/04/2018 17:24

Classification Of Case:



SINGAPORE
POLICE FORCE

SIGNATURE


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A - 3KJ 6769

B-535 4606 E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report no. T	20180403	202
----------------------------	----------	-----

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018		06 Apr 2018 12:05 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
<div style="text-align: right;">[Created by insurer]</div> CLAIM SUBFOLDER DETAILS Insured: KANG KAI , ID: S7975531A, Tel: +6598525522, Email: kangkai24@yahoo.com Main Claimant: Bok Chik Fu , ID: F7418579R Vehicle Reg. No.: JKJ6769 Date of Loss: 03/04/2018 16:00 - :59 Claim Type: TP / 554389 Policy/Cover Note No.: S28813630SMP (Comprehensive) Coverage: 15/09/2017 - 14/09/2018 Vehicle Reg. No. (Insured): SJJ4606E Policy No. (Claimant): Excess: S\$500.00 Repairer: Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel: Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545] Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 07/04/2018] Driver/Custodian (Insured): KANG KAI (38 / Female), NRIC: S7975531A, Tel: +6598525522																								
ASSOCIATED MAIL RECEIVED <div style="text-align: right;"> View All Compose Case Mail </div> There are no mail for this case.																								
ALL ASSOCIATED TASKS <div style="text-align: right;"> View All Search Tasks Create New Task Complete </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*JKJ6769 (554389)

[SJJ4606E]

TP

Bok Chik Fu

Apr 3 2018 4:00PM

[KANG KAI]

Motor Intel Automo Pte Ltd - Kaki Bukit

Upload Documents

Upload Photos

Compose New Letter

View

























View in Browser

1 per page

Assessment Reports			Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		
1	06/04/18 12:03	Accident Statement From: SC - Reg. No: SJJ4606E, Claimant: KANG KAI	1 Load HTM	

3 per page

Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	18/04/18 12:23	General View	1 Load JPG	
2	18/04/18 12:23	General View	1 Load JPG	
3	18/04/18 12:23	General View	1 Load JPG	
4	18/04/18 12:23	General View	1 Load JPG	
5	18/04/18 12:23	General View	1 Load JPG	
6	18/04/18 12:23	General View	1 Load JPG	
7	18/04/18 12:23	General View	1 Load JPG	
8	18/04/18 12:23	General View	1 Load JPG	
9	18/04/18 12:23	General View	1 Load JPG	
10	18/04/18 12:23	General View	1 Load JPG	
11	18/04/18 12:23	General View	1 Load JPG	
12	18/04/18 12:23	General View	1 Load JPG	
13	18/04/18 12:24	General View	1 Load JPG	
14	18/04/18 12:24	General View	1 Load JPG	
15	18/04/18 12:24	General View	1 Load JPG	
16	18/04/18 12:24	General View	1 Load JPG	
17	18/04/18 12:24	General View	1 Load JPG	
18	18/04/18 12:24	General View	1 Load JPG	
19	18/04/18 12:24	General View	1 Load JPG	
20	18/04/18 12:24	General View	1 Load JPG	
21	18/04/18 12:24	General View	1 Load JPG	
22	18/04/18 12:24	General View	1 Load JPG	
23	18/04/18 12:24	General View	1 Load JPG	
24	18/04/18 12:24	General View	1 Load JPG	
25	18/04/18 12:24	Dismantled Parts	1 Load JPG	
26	18/04/18 12:24	Dismantled Parts	1 Load JPG	
27	18/04/18 12:24	Dismantled Parts	1 Load JPG	
28	18/04/18 12:24	Dismantled Parts	1 Load JPG	
29	18/04/18 12:24	Dismantled Parts	1 Load JPG	
30	18/04/18 12:24	Dismantled Parts	1 Load JPG	
31	18/04/18 12:24	Dismantled Parts	1 Load JPG	
32	18/04/18 12:24	Dismantled Parts	1 Load JPG	
33	18/04/18 12:24	Dismantled Parts	1 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	18/04/18 12:24	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	18/04/18 12:24	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	18/04/18 12:24	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	18/04/18 12:24	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	18/04/18 12:24	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	18/04/18 12:24	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	18/04/18 12:24	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	18/04/18 12:24	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	18/04/18 12:24	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	18/04/18 12:24	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	18/04/18 12:24	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	18/04/18 12:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	18/04/18 12:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	18/04/18 12:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	18/04/18 12:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	18/04/18 12:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	18/04/18 12:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	18/04/18 12:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	18/04/18 12:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	18/04/18 12:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	18/04/18 12:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	18/04/18 12:25	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/04/18 12:04	TP PRI Request	 Load PDF	
2	06/04/18 12:05	TP reject SJE - assign LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18006383/GZ4D3E2
Date: 27/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: S28813630SMP

Claimant Vehicle No: JKKJ6769

Insured Vehicle No: SJJ4606E

Date of Loss: 03/04/2018

Nature of Claim: TP Claim No: 554389

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JKKJ6769
Make & Model: TOYOTA CORONA, 1.6 GLi (A)
Reg. Date: (Man. Year:)
Colour: White
Engine Capacity: 0 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price
Engine No: HIDDEN
Chassis No: HIDDEN
Odometer: 241555 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50Z R18 Rear Tyre Size: 235/50Z R18
Front Left Side: Joy Road 6 mm Rear Left Side: Joy Road 6 mm
Front Right Side: Joy Road 6 mm Rear Right Side: Joy Road 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/04/2018
Date Inspected: 09/04/2018 Inspected At:

Motor Intel Automo Pte Ltd - Kaki Bukit (HQ)
13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre
Singapore 417807

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 27/6/2018

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,800.00 - \$9,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2018)
Parts: 143	TOYOTA CORONA 1.6 GLI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JKJ6769)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >