

Your Ref: BK.17784.17

Date: 19th April 2018

Our Ref: CS1/LAW18006384/Lvbs2

M/s Bonnie Kwok LLC
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
PC 3229H INSURED VEHICLE: SJX 8533G ACCIDENT DATE: 07/03/2017**

We thank you for your instruction on 28/02/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of PC 3229H from M/s FormTeam Consultancy Pte Ltd.
- b) Survey report by Automax Survey with colour photographs.
- c) Singapore Accident Statement of Vehicles PC 3229H and SJX 8533G.
- d) Colour damaged vehicle photographs of PC 3229H.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: PC 3229H
Make & Model	: Toyota Hiace
Year of Registration	: 2014
Chassis Number	: KDH2230021745
Engine Capacity	: 2982 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.