

ASS. REC. BY:

REF: CS3/ICS18006392/GZ4d35<sup>2</sup>

Special Instruction:

Surveyor  
m/min

GQ

ASSIGNMENT (Office)

From (Person): Janice Goh

of

ECICS

Date/Time: 6/4/18 @ 2:25pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No: SGR 8829X

Insured: SKZ 4116G

at Workshop n/s: Motor Intel

Tel: 88 38 3318

of Blkaki Bkt Rd 4 #01-20

Policy No: MPC18A0053000

Claim No: DMPC1800122H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 01/04/2018

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 2:27pm @ 6/4/18

Person Contacted:

Wilson

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SGR 8829X - CC6/CTI18006221/Aug 3 D.O.A: 1/4/18
	SKZ 4116G - CS/ICS18006364/Rlg d3 D.O.A: 01/04/18
16/4/18	After repair

PR5 xml REF: Tcs

(-2022)

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Motor Intel

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SGR 8829X Yr Regn: 22 Feb 2007

Type: M Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Mazda 3 lux cc 1598

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 223907 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6BK106270 334125

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A Rim or

Tyre Size: F: 205/55 2 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 06-04-18

Survey held at w/s 4pm

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
	* Repair Estimate : S\$ 7000 - 8000
	* 5 days
27/4/18	Submit PRS Report
RECEIVED 30 APR 2018	

Date/Time: File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time: File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\_\_\_\_\_ S + RS \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

Weekend (\$) \_\_\_\_\_

TOTAL \_\_\_\_\_

## Nivitha (LKK Auto)

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Friday, 6 April 2018 2:25 PM  
**To:** Claims; 'assignments'  
**Cc:** ECICS Claims  
**Subject:** RE: Our client's vehicle no. SGR8829X; Your insured's vehicle no. SKZ4116G - PRI Notice  
**Attachments:** MIA - Pre-Repair Inspection Notice (ECICS)(SGR8829X).pdf

### Without Prejudice

Hi Justine

Thank you for your email.  
We are not agreed with your list of surveyor and we will appoint LKK for PRI.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,  
Janice Goh  
Claims Division  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.**

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

---

**From:** Claims [mailto:claims@esthermoey.com]  
**Sent:** Friday, 6 April, 2018 12:20 PM  
**To:** ECICS Claims  
**Subject:** RE: Our client's vehicle no. SGR8829X; Your insured's vehicle no. SKZ4116G - PRI Notice

Your Attention is Drawn to the Confidentiality Notice Below:

=====

Dear sirs,

We refer to your email of even date.

Our client objects appointing your surveyors as a single joint expert.

We propose on the following surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. Ho Joo Loong, Danny
2. Lee Kok Weng
3. Seah Kwang Boon
4. Winson Goh

Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Thank you.

Yours sincerely,

*Justin Yap*

Secretary to Esther Moey  
Amy Lim Law Practice  
[office@esthermoey.com](mailto:office@esthermoey.com)

Tel: (+65) 9625 8742 (Justin) / (+65) 9639 3110 (Esther)  
Fax: (+65) 6491 5638

**CONFIDENTIALITY NOTICE**

This e-mail from Amy Lim Law Practice (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

Amy Lim Law Practice DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

---

**From:** ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)>  
**Sent:** Friday, 6 April, 2018 12:09 PM  
**To:** Claims <[claims@esthermoey.com](mailto:claims@esthermoey.com)>; ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)>  
**Subject:** RE: Our client's vehicle no. SGR8829X; Your insured's vehicle no. SKZ4116G - PRI Notice

**Without prejudice**

Dear Justine

Thank you for your email with attachment.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.**

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

---

**From:** Claims [<mailto:claims@esthermoey.com>]  
**Sent:** Wednesday, 4 April, 2018 4:39 PM  
**To:** ECICS Claims  
**Subject:** Our client's vehicle no. SGR8829X; Your insured's vehicle no. SKZ4116G - PRI Notice  
**Importance:** High

Your Attention is Drawn to the Confidentiality Notice Below:  
=====

Dear Sirs,

We refer to our attached PRI Notice dated 4 April 2018 for your urgent attention.

Thank you.

Yours sincerely,

*Justin Yap*  
Secretary to Esther Moey  
Amy Lim Law Practice  
[office@esthermoey.com](mailto:office@esthermoey.com)

Tel: (+65) 9625 8742 (Justin) / (+65) 9639 3110 (Esther)  
Fax: (+65) 6491 5638

**CONFIDENTIALITY NOTICE**

This e-mail from Amy Lim Law Practice (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

Amy Lim Law Practice DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

follow us on  facebook  follow us on twitter  visit our website [ecics.com.sg](http://ecics.com.sg)

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



AMY LIM LAW PRACTICE

High Street Centre  
1 North Bridge Road  
#08-08  
Singapore 179094  
T: 9625 8742 / 9639 3110  
F: 6491 5638  
UEN: 53361230J  
We do not accept service by fax

Our Ref: 2018.1157.PD.MIA (SGR8829X)  
Your Ref: SKZ4116G

4 April 2018

ECICS Limited  
(Motor Claims Dept)  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987  
Attn: Motor Claims Department

BY EMAIL ONLY  
[claims@ecics.com.sg](mailto:claims@ecics.com.sg)

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION**  
**CLAIMANT: HUA CHENG FOOK, DESMONG**  
**TRAFFIC ACCIDENT ON 1 APRIL 2018 AT 14:25 HRS ALONG BRADDELL**  
**ROAD SLIP ROAD INTO TOA PAYOH LORONG 6 INVOLVING VEHICLES NO.**  
**SGR8829X & SKZ4116G**

We are instructed by **Hua Cheng Fook, Desmond** to notify you of a road accident on 1 April 2018 at about 14:25 hrs along Braddell Road slip road into Toa Payoh Lorong 6 involving our client's vehicle registration number SGR8829X and vehicle registration number SKZ4116G driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: **Motor Intel Automo Pte Ltd**  
Address: 13 Kaki Bukit Road 4,  
#01-20, Bartley Biz Centre  
Singapore 417807  
Contact: Wilson Ong @ 8838 3318

Please liaise with the above workshop directly.

Yours faithfully

Esther Moey

Email: [claims@esthermoey.com](mailto:claims@esthermoey.com)

encs

**PLEASE LET US KNOW THE DATE  
OF THE PRE-REPAIR INSPECTION**

.....

Injury (3 fac) Amy PRI

Date of Accident : 01/04/18 Accident Time: 1425 (24-HR-Format)  
Accident Place : Braddell Road (slip Road into Lot 6 TUA PAUOH)  
Vehicle No. (Car Plate No.) : SGR 8829X Make/Model: MAZDA 3 SP  
Insurance Company : Ching Teiping Policy No: DMPCSN 3013021802  
Owner or Company Name / IC No. : HUA CHUNG FOOK, DESMOND 881399533  
Owner or Company Contact No. : \_\_\_\_\_ Owner's Hp 92304433 Company Tel \_\_\_\_\_  
DRIVER'S Name / IC No. : \_\_\_\_\_  
DRIVER'S Date Of Birth : 19/12/1981 DRIVER'S License Pass Date 29/04/2004  
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: \_\_\_\_\_  
DRIVER'S Address : BIK 79C TUA PAUOH CENTRAL #27-39 S (313079)  
DRIVER'S Contact No./ Alt No. : (1) \_\_\_\_\_ 2) \_\_\_\_\_  
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
Email Address : desmond.hua@gmail.com  
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
Number of Passengers (Including Driver): 4  
Was there any video Captured by car camera: YES \ NO  
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
Any Injury (If YES, Pls state): \_\_\_\_\_

Other Party Driver's Particular (if any)

Vehicle No: (B) SK2 4116G	Vehicle No: GBG 12028 CC
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: 9339 0625	IC No. Driver/Contact: 9633 9861

\* NEW - Passenger's name & gender:




## SKETCH PLAN


### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SKETCH PLAN



A = SGR 8829X

B = SKZ 4116 G

C = GBG 12102S

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As my front vehicle stopped due to give way to top Payoh lor G vehicle, I follow suit. As my vehicle is still in a stationary position, suddenly I feel an impact from my vehicle rear and the huge impact forces my vehicle to surge forward and hit onto the infant car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9953J
Vehicle Details	
Vehicle No.:	SGR8829X
Vehicle to be Exported:	No
Intended De-registration Date:	09 Apr 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3SP LUX
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	Z6525242
Chassis No.:	JM6BK106270334125
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$15,280.00
Original Registration Date:	22 Feb 2007
First Registration Date:	22 Feb 2007
Transfer Count:	0
Actual ARF Paid:	\$16,808.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,197.00
COE Rebate Amount:	\$19,497.00
<b>Total Rebate Amount:</b>	<b>\$19,497.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 09 Apr 2018

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2018 10:18 <a href="#">Edit Reg</a>		06 Apr 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -, Email: j@gmail.com		
Main Claimant:	-		
Vehicle Reg. No.:	<b>SGR8829X</b>	Date of Loss:	01/04/2018 14:00 - :59 [133 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	<b>SKZ4116G</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Motor Intel Automo Pte Ltd - Kaki Bukit (HQ)</b> 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	<b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Nivitha Govindasamy</b> ] ... [Final Rpt due 07/05/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SGR8829X

[SKZ4116G]

TP

-













Apr 1 2018 2:00PM























[-]

Motor Intel Automo Pte Ltd - Kaki Bukit

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View**
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
32	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
33	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
34	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
35	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
38	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
40	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
41	25/04/18 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
42	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	25/04/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	25/04/18 12:14	Photo After Spray	 Load JPG	✓
85	25/04/18 12:14	Photo After Spray	 Load JPG	✓
86	25/04/18 12:15	Photo After Spray	 Load JPG	✓
87	25/04/18 12:15	Photo After Spray	 Load JPG	✓
88	25/04/18 12:15	Photo After Spray	 Load JPG	✓
89	25/04/18 12:15	Photo After Spray	 Load JPG	✓
90	25/04/18 12:15	Photo After Spray	 Load JPG	✓
91	25/04/18 12:15	Photo After Spray	 Load JPG	✓
92	25/04/18 12:15	Photo After Spray	 Load JPG	✓
93	25/04/18 12:15	Photo After Spray	 Load JPG	✓
94	25/04/18 12:15	Photo After Spray	 Load JPG	✓
95	25/04/18 12:15	Photo After Spray	 Load JPG	✓
96	25/04/18 12:15	Photo After Spray	 Load JPG	✓

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18006392/GZ4D3S2  
Date: 07/05/2018

## REFERENCE

Handling Insurer: ECICS Limited Policy No:  
Claimant Vehicle No: SGR8829X Insured Vehicle No: SKZ4116G  
Date of Loss: 01/04/2018 Nature of Claim: TP Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGR8829X Engine No: Z6525242  
Make & Model: MAZDA 3, 1.6 LUX (A) Chassis No: JM6BK106270334125  
Reg. Date: 22/02/2007 (Man. Year: 2006) Odometer: 223907 km  
Colour: Black  
Engine Capacity: 1598 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55ZR16 Rear Tyre Size: 205/55ZR16  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 06/04/2018  
Date Inspected: 06/04/2018 Inspected At: Motor Intel Automo Pte Ltd - Kaki Bukit (HQ)  
13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre  
Singapore 417807  
Estimated Period of Repair: 5.0 days

Adjuster: Nivitha Govindasamy

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/7/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
<b>Parts:</b>	143	MAZDA 3 1.6 LUX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGR8829X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >