

Study

CC 4/KM
AXA1800

6399, S 2639

Surveyor:

YWR

DOI:

ASSIGNMENT

6/4/18

Date / Time:

6/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLW 1438B

Name of Insured:

ADEL ETO

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

2/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TOM DET SEE BEKEMLE

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

C8M00 D5W / 38558

Policy No.:

CNSHT69

Make / Model:

MERCEDES

Place of Accident:

MIL OF LEANER K &
O RUMARDUNT

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SMB 1600g



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMRT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

11/6/18
TH

SMB 1600g

SMB 1600g

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:


26/11/18

AXA APPROVING REJECTION.

08/12/18

BANK TO TP TO RESORT CLAIM
TO CLAR CLAR.
NO SETTLEMENT

RECEIVED 07 DEC 2018



PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

PIP

SS

465.00 (1/2 days)

Reduction:

A1 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

(5 x days)

Loss of Income (LOI):

SS

(5 x days)

LOR only ☐ LOU only ☐

LOR + LOU

☐ LOR + LOI☐ [Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

RESORT TP CLAIM
SPEAK TO OI REPORTING CLAR.
JULIA MURDO DOH ON THERE
QWER.

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4350.00

REF:

Signature

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured.

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

0.5

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Flp b 465.00 (LABOUR ONLY)
 Rev. b 529.00 (41%)

Veh No.

SM6 1600J

Yr Regn:

13/1/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazd NL 3200

C.C

10518

Colour

Green

A/C: Insured / Std / NI / NA

Sp. Reading

301946

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WMAA 2226.81-7002576

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 275/70R225

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgesto

Front

Rear

R/Bal.

6

mm

R/Bal.

6/16

mm

L/Bal.

6

mm

L/Bal.

6/16

mm

D.O.A.

L/S/18

D.O.I.

6/4/18

Survey held at

SMR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 1/6

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time. File Pass to?

☐

Prel. Report

1)

Date/Time. File Return to?

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation.

) \$ + RS \$

) Photos

) Other

TOTAL

Report Format :

Lump Sum / I.B.I. (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18006399/Sub3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811			Date : 06-04-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLW 1438B	Veh. Inspected	SMB 1600Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	06/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/03/2018	Inspection Date	06/04/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1600Y
 Ref. No : BUS/03/18/1008
 Reg. Date : 12/03/2018
 Vehicle Type : BUS -12M
 Make : MAN
 Model : MAN
 Name of Driver : David Rajendran S/O Ramasamy
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 02/03/2018 04:12:00 PM
 Accident Reported Date / Time : 06/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : AXA
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 SMB1600Y - LEFT REAR PORTION
 SLW1438B (TP) - INSURED WITH AXA.
 Prepared Date : 12/03/2018 02:46:17 PM



LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Sebastian
 6/4/18
 - Lump Sum Repair
 - Photos After Paint

Chassis No : Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	530.00	0.00
Total Spray Painting Charges	262.00	0.00
Total Material Charges	0.00	0.00
Other Charges	0.00	0.00
TOTAL	792.00	0.00
Lum Sum Total	800.00	0.00
No. of Repair Days	1.00	0.60
Prepared / Adjusted By		05
Arc / Surveyor Sing Off Date	05/04/2018 05:55:40 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/04/2018 05:55:40 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	530.00	0.00 265
Total Labour	530.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	262.00	0.00 262
Total Spray Painting & Panel Beating	262.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discouted)								0.00	0.00	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	L.T. Check
TOTAL SUPPLEMENTARY MATERIALS									

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2292D
Vehicle Details	
Vehicle No.:	SMB1600Y
Vehicle to be Exported:	No
Intended De-registration Date:	09 Apr 2018
Vehicle Make:	MAN
Vehicle Model:	NL 320F (A22) 11L AUTO ABS TURBO
Primary Colour:	Multi-Colour
Manufacturing Year:	2014
Engine No.:	50339480753946
Chassis No.:	WMAA22ZZ8F7002576
Maximum Power Output:	-
Open Market Value:	\$248,623.00
Original Registration Date:	13 Jan 2015
First Registration Date:	13 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

OK



Service Request Details

Claim

S8M00D5W

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Reference

None

Loss Date

March 2, 2018

Request Date

April 6, 2018

Due Date

April 13, 2018

06042018 @ 10500m

Sunny veh in.

Sebastian.

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SMB1600Y

Make

TPVD MERCEDES-BENZ

Service Address

...

Primary Contact/Insured

ADEL EID

130 TANJONG RHU ROAD, #11-11 PEBBLE BAY LOBBY M, 436918, Singapore

BERENICE128@GMAIL.COM

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Vic (LKKAuto)

From: Ashley Nguyen <Ashley.Nguyen@ethozgroup.com>
Sent: Thursday, 6 December, 2018 2:01 PM
To: Jonathan Lim
Cc: Vic (LKKAuto)
Subject: Wrong DOA for SLW1438B
Attachments: SAS2391829.pdf

Importance: High

Hi Jonathan,

Kindly assist to amend DOA 02/04/2018 to 02/03/2018 in Merimen for the above vehicle. Attached for your reference.

Warmest Regards,
Ashley Nguyen
Claims Settlement

ETHOZ

ETHOZ GROUP LTD

22 Tampines St 92 S(528876)
DID: 6654 7920 | Fax: 6654 7699
Website: www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Wednesday, 5 December, 2018 10:46 AM
To: Audrey Woo (Auto Svcs/Ext Biz Svcs/Claims & IA/Buses)
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: Urgent Reminder to AXA - BUS/03/18/1008/AW - SMB1600Y & SLW1438B - DOA 2 MARCH 2018 LKK REF CC4/ASM18006399/Shb3
Attachments: STATEMENT.pdf

Without Prejudice

Dear Audrey,

We refer further to the below email.

Please be informed that our principal had further reviewed the matter and based on the available information provided, our principal is in the view that our Insured is not liable of this accident. Based on both accident report, our Insured was stationary along the main road when your client from the minor road made a turn and grazed the front portion of our Insured's vehicle. Kindly refer to the attached statement.

As such, we have our principal's instruction and we are unable to look further into your client's claim.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Audrey Woo (Auto Svcs/Ext Biz Svcs/Claims & IA/Buses) [<mailto:audrey@smrt.com.sg>]
Sent: Friday, 9 November, 2018 2:44 PM
To: Thin Thin (LKKAUTO); NG Stacey
Cc: Admin A; cts@axa.com.sg
Subject: Urgent Reminder to AXA - BUS/03/18/1008/AW - SMB1600Y & SLW1438B - DOA 2 MARCH 2018
Importance: High

Urgent Reminder

SMRT : BUS/03/18/1008/AW

AXA : S8M00D5WMC/NPS/StaceyNg

LKK : CC4/ASM18006399/SUB3/ThinThin

Dear Thin Thin (LKK) and Stacey (AXA),

LOD had been issued to AXA c/o LKK on 1 June 2018. Have been 5 months since and we have yet to hear from AXA or LKK to date. Kindly let us have your offer to settle without further ado.

This is a case of SMRT bus turning with green light in bus's favour but AXA insured car SLW1438B positioned itself inside the Yellow Box obstructing the way. It is a traffic offence to station one's car inside a yellow box obstruction the way, especially when green light is not in SLW1438B's favour.

Liability is clear and irrefutable with accident scene photographic evidence. Quantum is tiny in this case, only \$609.50. We therefore seek AXA's speedy offer/DV soon, to close off this small case quickly.



Audrey Woo | DID : 6556 3521 | FAX : 6481 9221 | Email : audrey@smrt.com.sg | Claims Department | 6 Ang Mo Kio Street 62 Singapore 569140



From: Audrey Woo (Auto Svcs/Ext Biz Svcs/Claims & IA/Buses)
Sent: Friday, 1 June, 2018 10:51 AM
To: 'motor.survey@axa.com.sg'; 'cts@axa.com.sg'; Admin A (admin-a@lkkauto.com)
Subject: LOD to AXA - BUS/03/18/1008/AW - SMB1600Y & SLW1438B - DOA 2 MARCH 2018

BUS/03/18/1008/AW
AXA : SLW1438B

Dear Motor Claims Officer,

We claim on behalf of SMRT BUSES LTD, owner of the vehicle registration number SMB1600Y. Your client's negligent driving has caused the above accident. As a result, my client has suffered the following losses,

Cost of Repair	\$465.00
----------------	----------

Loss of Use (3 Days x \$275, 12m Bus)	\$ 137.50
LTA search fee	\$7.00
Total	\$ 609.50

We enclose the following documents,

- Repair Invoice
- GIA report
- LTA Search
- Survey Report and Bus Photos to be furnished by AXA's own appointed surveyor LKK.

We look forward to your confirmation to settle our claims within 15 days from the date of this email. Payment by cheque shall be crossed and made payable to SMRT BUSES LTD.

Audrey Woo | DID : 6556 3521 | FAX : 6368 7421 | Email : audrey@smrt.com.sg | Claims
Department | SMRT BUSES LTD | 6 Ang Mo Kio Street 62 Singapore 569140





Re:Seek instruction S8M00D5W

Type

🔗 Question

Message

Pls proceed to reject and submit final report.

Reply




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18006399/Shb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Date : 12-12-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLW 1438B	Veh. Inspected	SMB 1600Y	
Policy No.	CN873769	Coverage (\$)	0.00	
Claim No.	S8M00D5W	Excess (\$)	0.00	
Assign From		Assign Date	06/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAN NL 320F	c.c	10518	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WMAA22ZZ8F7002576	Colour	GREEN	
Odometer	301446	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/03/2018	Inspection Date	06/04/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		0.500 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1600Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPAIR LH REAR PORTION .		530.00	265.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		262.00	200.00
			792.00	465.00
GRAND TOTAL			792.00	465.00

RECOMMENDED COST OF REPAIRS			465.00
------------------------------------	--	--	---------------

Report Ref No. CC4/ASM18006399/Shb3q2

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

58M0003W

Reference

CCA/ASM1006399/5H6J62

Loss Date

2 March 2018

Request Date

6 April 2018

Due Date

Vendor Name

LUX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

5MB1400Y

Make

TPVO MERCEDES-BENZ

Model

BUS

Service Address

Primary Contact/Insured

ADEL EID

130 TANJONG BHU ROAD, #11-11 PEBBLE BAY LOBBY M, 436918, Singapore

BERENICE128@GMAIL.COM

Claim Handler

NG Stacy

6568804351

stacey.ng@axa.com.sg

Actions












Next Step

Wait for Approve Invoice

Add Payment

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Policies
<div>Document Type: <div>Document SubType</div></div>						
<div>+ Upload Documents</div>						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
<div><div>LUXInvoice1.pdf</div></div>	Invoice	Surveyor/ Assessor expense	LUX AUTO CONSULTANTS PTE LTD (TP)	19 December 2018		

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018
 LKKAdjustment 1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018
 Email from TP dd 071218.pdf	Letters and Correspondence	Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)	17 December 2018
 LKK INSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 December 2018
 Email to TP Reject dd 051218.pdf	Letters and Correspondence	Third Party	LKK AUTO CONSULTANTS PTE LTD (TP)	5 December 2018
 Accident scene photos.jpg	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 November 2018
 Accident Location.jpg	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 November 2018
 Accident Location 1.jpg	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 November 2018
 TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	9 April 2018
 Preliminary Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	9 April 2018
 EMAIL FROM WORKSHOP INCLUDING ESTIMATE & SHB1600Y TP GUA.jpg	Letters and Correspondence	Workshop	NIKAM Santosh Pandurang	6 April 2018