

ASS. REC. BY:

REF: CS3 / FWD 18006406 / M124d3^{sr} Special Instruction

Surveyor

Ma

ASSIGNMENT (Office)

McGinn

From (Person):

Clara Li

of

FWD

Date/Time: 6/4/18 @ 3:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 3142Z

Insured:

SKJ 9348E

at Workshop m/s:

Guan Auto Service

Tel:

9388 4210

of BIK 7, Sin Ming Ind. Est. Sec. C #01-82 / 01-80

Policy No: 1201700005897-002

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/09/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

18042018 @ after 10am

H.O.D. Endorsement:

Date/Time:

3:21pm 06/4/18

Person Contacted:

jacky

Vehicle IN

(OUT)

Date/Time	Action/Instruction (x) Estimate
	GBF 3142Z -x
	SKJ 9348E -x

PRS

REF: FWD

ASSIGNMENT

From: Date: 18042018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBF 3142Z

at Workshop m/s

Guan Motor

of

176 Sim Ming DR #01-82

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

after 10am

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBF3142Z, Yr Regn: AUG / 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN NV350 c.c 2488

Colour:

Black.

A/C: Insured / Std / NI / NA

Sp. Reading

37728

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1MC2626Z0006329.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ order / Jammed / Leaked / Burnt orBrake: ☒ order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

YOKO.

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

16/12/17

D.O.I.

18/14/2018.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

OS FR.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No est upon Survey.

800-1000k.

2 w days

4/5/18

submit PRS Report

RECEIVED 07 MAY 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD18006406/M1z4d3

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 06-04-2018



Code : FWD

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKJ 9348E	Veh. Inspected	GBF 3142Z
Policy No.	1201700005897-002	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CLARA LI	Assign Date	06/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/09/2017	Inspection Date
Survey held at	BLK 7 SIN MING IND.EST.SEC.C #01-82	
Repairer	GUAN AUTO SERVICE	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Nivitha (LKK Auto)

From: motorclaims.sg@fwd.com
Sent: Friday, 6 April 2018 3:15 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Subject: FW: Our Ref: CY.GBF3142Z.18.GA(HW).wp(Lh); Your Ref: SKJ 9348E Our Ref: 1201700005897-002
Attachments: GIA REPORT - GBF3142Z.PDF

Hi LKK team,

Please refer to the email below and liaise with TP repairer for survey arrangement.

Please create the case in Merimen.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
---	--	--	--

From: Motor Claims SG - SG Common

Sent: Friday, 6 April, 2018 3:14 PM

To: 'Lheny'; winnie@yoga-legal.com

Subject: RE: Our Ref: CY.GBF3142Z.18.GA(HW).wp(Lh); Your Ref: SKJ 9348E Our Ref: 1201700005897-002

WITHOUT PREJUDICE

Dear Lheny,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK AUTO CONSULTANTS PTE LTD, to conduct the pre-repair survey (PRS) on your

client's vehicle, GBF3142Z. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
---	--	--	--

From: Lheny [<mailto:lheny@yoga-legal.com>]

Sent: Friday, 6 April, 2018 3:12 PM

To: Motor Claims SG - SG Common; winnie@yoga-legal.com

Subject: RE: Our Ref: CY.GBF3142Z.18.GA(HW).wp(Lh); Your Ref: SKJ 9348E Our Ref: 1201700005897-002

WITHOUT PREJUDICE

Dear Clara Li

We refer to your email on the even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

1. Winson Goh
2. Amas Ong Poh Meng
3. Ong Ah Keng, Kent

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "single joint expert".

We will accordingly inform you who the "single joint expert" is to facilitate your conduct of a pre-repair survey.

Best regards,

Lheny

M/s C YOGARAJAH LLC
883 North Bridge Road
#19-05 Southbank
Singapore 198785

Tel: 6292 5838
Fax: 6292 5938

Email: lheny@yoga-legal.com

From: motorclaims.sg@fwd.com [<mailto:motorclaims.sg@fwd.com>]

Sent: Friday, 6 April, 2018 2:34 PM

To: lheny@yoga-legal.com; winnie@yoga-legal.com

Subject: RE: Our Ref: CY.GBF3142Z.18.GA(HW).wp(Lh); Your Ref: SKJ 9348E Our Ref: 1201700005897-002

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

WITHOUT PREJUDICE

Dear Lheny

We refer to your letter dated 06 April 2018 of the PRI Notice of your client's vehicle GBF3142Z.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

Kind Regards

Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!	 2.02% p.a. fwd.com.sg save now
--	---	---

From: Lheny [<mailto:lheny@yoga-legal.com>]

Sent: Friday, 6 April, 2018 12:21 PM

To: SG Corporate Contact

Cc: winnie@yoga-legal.com

Subject: Our Ref: CY.GBF3142Z.18.GA(HW).wp(Lh); Your Ref: SKJ 9348E

Importance: High

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES GBF 3142Z & SKJ 9348E ON 16.09.2017 @ 16:30HRS ALONG CARPARK EAST COAST PARK

We are instructed by TKR EZIM PTE LTD to notify you of a road traffic accident on 16.09.2017 @ 16:30hrs along Carpark East Coast Park involving our client's customer's vehicle registration number GBF 3142Z and vehicle registration number SKJ 9348E driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that our client's vehicle can be inspected at:

M/s. Guan Auto Service

Block 7 Sin Ming Industrial Estate Sector C

#01-82 / #01-80 Singapore 575642

Mr. Jacky Fong (9388 4210)

Fax no : 6451 1706

Best regards,

Lheny

M/s C YOGARAJAH LLC

883 North Bridge Road

#19-05 Southbank

Singapore 198785

Tel: 6292 5838

Fax: 6292 5938

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/09/2017 10:03
Date Of Accident	16/09/2017 16:30
Exact Location Of Accident	CARPARK OF EAST COAST PARK (PARKLAND GREEN)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF3142Z
Insured/Policyholder	
Name Of Registered Owner	TKR EZIM PTE LTD
Co Reg No	197903960C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94508775

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350 PANEL VAN

Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
--	------------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCV17S017605
Cover Note Number	

Driver

Name of Driver	ISHWAR GENIMAL DADLANI
NRIC No	S2007866I
Date Of Birth	24/02/1950
Occupation	OUTDOOR
Date Of Driving Pass	27/12/2007
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94508775
Fax Number	
Contact Number	
Email Address	BOBDADLANI@GMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

I was at carpark of East Coast Park (Former Big Splash). I stopped my vehicle on the left side of the one way road to dropped off my wife before i reverse into carpark lot. After my wife alighted out from the vehicle, as i was about to reverse, car SKJ9348E from behind drove past my vehicle at a fast speed and its left rear side collided onto my vehicle front right side. Damages to my vehicle were on the front right side. No injuries were involved.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKJ9348E
Vehicle Make/Model/Colour AUDI/A4 1.8
Details Of Properties
Name of Driver ALTON
NRIC/Passport Number S8979179J
Contact Number 96497489
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 4

Details of Witness

Name
Phone Number
Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicles involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER

Muhammad Faizal


Bin Pabla

Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was at carpark of East Coast Park(Former Big Splash). I stopped my vehicle on the left side of the one way road to dropped off my wife before i reverse into carpark lot. After my wife alighted out from the vehicle, as i was about to reverse, car SKJ9348E from behind drove past my vehicle at a fast speed and its left rear side collided onto my vehicle front right side. Damages to my vehicle were on the front right side. No injuries were involved.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer:



Registered Owner or Driver's Signature

Job Complete Date/Time

18 September 2017 at 9:32 AM

Date/Time:

18 September 2017 at 9:32 AM

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Apr 2018 Edit Reg		06 Apr 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Ho Xiu Jin Zoe, ID: S8922429B		
Main Claimant:	TKR EZIM PTE LTD, Co. Reg. No.: 197903960C		
Vehicle Reg. No.:	GBF3142Z	Date of Loss:	16/09/2017 16:00 - :59 [12 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201700005897	Policy/Cover Note No.:	PNPV2017-00004957 (Comprehensive)
Vehicle Reg. No. (Insured):	SKJ9348E	Policy No. (Claimant):	
		Excess:	
Repairer:	Guan Auto Service (Sin Ming) Block 7 Sin Ming Industrial Estate Sector C, #01-80/ # 01-82, 575642 Sin Ming - Tel: 93884210		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 27/04/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBF3142Z (1201700005897)**
[SKJ9348E]













TP
TKR EZIM PTE LTD
Sep 16 2017 4:00PM
[Ho Xiu Jin Zoe]
Guan Auto Service

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
2	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
3	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
4	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
5	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
6	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
7	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
8	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
9	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
10	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
11	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
12	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
13	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
14	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
15	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
16	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
17	19/04/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page ▼

No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	19/04/18 10:22	OI GIA Report	 Load PDF	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18006406/M1Z4D3S2
 Date: 09/05/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00004957
 Claimant Vehicle No: GBF3142Z Insured Vehicle No: SKJ9348E
 Date of Loss: 16/09/2017 Nature of Claim: TP Claim No: 1201700005897

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF3142Z Engine No: YD25392432A
 Make & Model: NISSAN NV350, 2.5 (A) Chassis No: JN1MC2E26Z0006329
 Reg. Date: 31/08/2016 (Man. Year: 2016) Odometer: 37728 km
 Colour: Black
 Engine Capacity: 2488 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/04/2018
 Date Inspected: 18/04/2018 Inspected At: Guan Auto Service (Sin Ming)
 Block 7 Sin Ming Industrial Estate Sector C, #01-80/ #01-82
 Singapore 575642
 Estimated Period of Repair: 2.0 days

Adjuster: MA CHIN FOOK

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/9/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$800.00 - \$1,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 May 2018)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF3142Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >