

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/04/2018 16:21
Date Of Accident	03/04/2018 23:30
Exact Location Of Accident	CAVENDISH PARK (20 PINE GROVE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGH3095G
Insured/Policyholder	
Name Of Registered Owner	CHIN YIN KEONG
NRIC No	S2549954I
Email Address	DARYL.CHIN.SHI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91918093
Alternative Phone No	HOME-62554540

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	DRIVING HOME
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091479752
Cover Note Number	

Driver

Name of Driver	CHIN SHICHANG ,DARYL(CHEN SHICHANG, DARYL)
NRIC No	S8121249Z
Date Of Birth	04/08/1981
Occupation	INDOOR
Date Of Driving Pass	16/12/2008
Driving Experience	9 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91918093
Fax Number	
Contact Number	HOME-62554540
Email Address	DARYL.CHIN.SHI@GMAIL.COM

Address	20 PINE GROVE #05-04
Postcode	597595
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: SON GENDER: MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	DOVER NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 3 DOVER ROAD , POSTCODE: 130003 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7788999 - FAX NO: 67762859
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT D/20180406/2058

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF5887B
Vehicle Make/Model/Colour	TOYOTA SIENTA
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	LIM SEOK KHENG
NRIC/Passport Number	S1151358A
Contact Number	90538848
Address	

SSS 1600 01

R377

17/07/2018

V-1: 170

ASSIGNMENT TRACKBy Assessor- 1) Vehicle Information:

- 1) Vehicle hit Vehicle: ☐ 2) Vehicle hit by:
- a) Motorcycle ☐ a) Pedestrian ☐
- b) Motorcycle ☐ b) Animal ☐
- c) Bicycle ☐
- 3) Vehicle hit Road Side Objects:
- a) Govn Property ☐ b) Road Work Object ☐
- (Ex: signposts, lights, trees etc)
- c) Private Property ☐
- 4) Vehicle drop into drain ☐
- 5) Damage due to Act of God:
- a) Fallen Object ☐ b) Flood ☐
- c) Other: _____
- 6) Parked & Found Damaged:
- a) Vandalism ☐ b) Hit by Moving Object ☐
- 7) Theft Case
- a) Stolen ☐ b) Damage found ☐
- when recovered
- 8) Fire
- a) Whilst driving ☐ b) Parked ☐
- 9) Accident date more than 24hrs ☐

Remarks for internal informationRemarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ☐
- 2) SSS Light on ☐
- 3) ABS Light on ☐

By Assessor- 1) Vehicle Information:

Veh No: SGH 3095 G Yr Reg: JUN / 2006

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / ☐

/ Truck / Trailer or

Make & Model: HONDA CIVIC 1.8L 4 1999

Colour: Grey Transmission Type: Auto / Manual

Eng/No: R18A11027883 Sp Reading: 135171

C/Nr: JHMF016306820846

Gen. Cond: Good / Fair / Poor / Burnt or

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: R/R / S/Rim / STD. A/Rim or

Tyre Size: F: 185/65 R15

R: 185/65 R15

BS: DUNLOP / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	mm	Rear	mm
R/Bul. <u>6</u>		R/Rc. <u>6</u>	
L/Bul. <u>6</u>		L/Bul. <u>6</u>	

Parallel Import: Yes / No Towed-In: Yes / No

Repair Type: LS / I.B.I Towing Required: Yes / No

No of Repair Days: Vehicle In Idoc: Yes / No

D.O.L: 11/05/2018 Time: 1740

By Assessor- 2) Currency

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
- a) Vehicle ☐ b) Motorcycle ☐ c) Bicycle ☐ d) Pedestrian ☐
- e) Animal ☐ f) Govn Object ☐ g) Road Work Object ☐
- h) Private Property ☐ i) Drain ☐ j) Road Kerb/Grass verge ☐
- 3) Vehicle does not seem damaged as a result of:
- a) Fallen Object ☐ b) Flood ☐ c) Vandalism ☐ d) Fire ☐
- e) Moving Object ☐ f) Stolen ☐ g) Stolen & Recovered ☐

17/07/2018

17/07/2018

17/07/2018

17/07/2018

17/07/2018

MOTOR CAR (Frt)

Front Portion

NAC	INC	Item	CON	ACQTY
1001	991886	Frt Number Plate	87	✓
1002	991887	Frt Number Plate Base		
1003	991889	Frt Number Plate Garnish		
1004	991300	Frt Bumper	88	✓
1005	992341	Frt Bumper Clips	1111	✓
1006	991325	Frt Bumper Bracket	132	✓
1007	991462	Frt Bumper Side Retainer	1111	✓
1008	991433	Frt Bumper Reinforcement		✓
1009	991318	Frt Bumper Beam		✓
1010	991468	Frt Bumper Sponge		
1011	991427	Frt Bumper Protector		
1012	991420	Frt Bumper Pad		
1013	991363	Frt Bumper Grille		
1014	991301	Frt Bumper Moulding		
1015	991407	Frt Bumper Lower Spoiler		
1016	991438	Frt Bumper Sensor		
1017	995100	Frt LH Bumper Fog Lamp Cover		✓
1018	991355	Frt RH Bumper Fog Lamp Cover		✓
1019	995079	Frt LH Bumper Fog Lamp		
1020	995080	Frt RH Bumper Fog Lamp		✓
1021	991793	Frt Grille		
1022	991328	Frt Grille Emblem		
1023	991799	Frt Grille Chrome Moulding		
1024	991222	Frt Apron Panel		
1025	992013	Frt Support Panel		
1026	992025	Frt Support Panel Top Garnish Cover		
1027	992416	Horn		
1028	991277	Frt Brace Panel		
1029	995153	Frt LH Headlamp Assy		✓
1030	991821	Frt RH Headlamp Assy	SCIL	✓
1031	995088	Frt LH Side Lamp		
1032	995089	Frt RH Side Lamp		
1033	990248	Bonnet		
1034	991328	Bonnet Emblem		
1035	990287	Bonnet Lock		
1036	990285	Bonnet Insulator		
1037	990273	Bonnet Hinge		
1038	990261	Bonnet Damper		
1039	990305	Bonnet Rubber		
1040	990252	Bonnet Cable		
1041	990311	Bonnet Stand		
1042	990119	Air Con Condenser		✓
1043	990122	Air Con Fan Assy		
1044	990134	Air Con Suction Pipe (Low Pressure)		
1045	990118	Air Con Suction Hose		
1046	990133	Air Con Discharge Pipe (High Pressure)		
1047	990114	Air Con Discharge Hose		
1048	990149	Air Con Liquid Pipe		
1049	995066	Air Con Receiver Drier		
1050	990111	Air Con Compressor Assy		
1051	995294	Air Con Belt		
1052	995074	Radiator		✓
1053	992738	Radiator Cowling		
1054	992742	Radiator Fan Assy		
1055	992745	Radiator Fan Clutch		
1056	992758	Radiator Hose Top		
1057	992757	Radiator Hose Bottom		
1058	992741	Radiator Expansion Tank		
1059	990151	Air Duct		
1060	990070	Air Cleaner Assy		
1061	990056	Air Cleaner Hose		
1062	990089	Air Cleaner Resonator		
1063	991712	Frt Exhaust Manifold		
1064	991713	Frt Exhaust Manifold Cover		
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)		
1066	991714	Front Exhaust Pipe		
1067	990219	Battery		
1068	990224	Battery Cover		
1069	990223	Battery Bracket		
1070	990229	Battery Tray		

NAC	INC	Item	CON	ACQ	QTY
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: _____

ASSessor:

original copy

Claim Handling

Task Transfer Exit

Accident MT/0989332

LTP SAL SUB

Policy No.	SGH1479752	Vehicle No.	SGH3095G	GST Registration No.	
Policyholder Name	CHIN VIN KEONG			Policyholder NRIC	525499541
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	91918093	Contact No.(Office)		Contact No.(Home)	62594540
Email Address		Special Remark		eCode	No
KPK	+ No Yes	TCA	+ No Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	20	Private Hire	No

Accident Details

Report Date	06/04/2018 16:40	Accident Report Within 24 hrs	No	Accident Type	Collision - Head to Rear
Date of Accident	03/04/2018	Time of Accident (hh:mm)	21:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	CAVENDISH PARK (20 PINE GROVE)				

Benefits

Coverage	Sum Insured
Transport Allowance	9999999999.99

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	11 JALAN NOVENA TIMOR	Address 2	ENG AUN PARK	Address 3	SINGAPORE 308533
Address 4		Address Type	Singapore address	Post Code	308533
Unit No.		Related Policy Number	SGH1479752		

OI Driver Info

Driver Name	DARYL CHEN SHICHANG	Driver Type	Named Driver		
Unnamed driver Name		Driver NRIC	S8121249Z	Driver DOB	04/08/1981
Register Date of Driver License	16/12/2008	Driver Age	36	Driving Experience	9
Contact No.(Mobile)		Contact No.(Office)		Contact No.(Home)	
Address 1		Address 2		Address 3	
Address 4		Address Type	Foreign address	Post Code	
Unit No.					
Does he own a Singapore Registered car?	Yes + No	Driver Vehicle No.	SGH3095G	Driver Insurer Company	NTUC

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	Yes + No
Modification History	09/04/2018 15:50 s029755 Modify Accident Report Within 24 hrs(Yes-->No)		

Investigation

Claim 001 OD-MD

Claim Case Officer Ng Hak Joo

LTP SAL SUB

Claim Type	OD-MD	Insured Name	CHIN VIN KEONG	Insured NRIC	525499541
Contact No.(Mobile)		Contact No.(Home)	62594540	Contact No.(Office)	82830611
Email Address	racyin@hotmail.com	OI Vehicle Number	SGH3095G	TP Vehicle Number	SLF5887B
Claim Description	SGH3095G / SLF5887B ON 3 Apr 2018			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability	Partially at Fault	GIA report	Received
Require finalisation	Yes	Preferred Repair Option	Preferred Workshop, Name unknown	Date Received	14/05/2018 08:36
Date Registered	06/04/2018 16:46	Claim Close Date		Total Loss but Repaired	
Report Taken By	ROSLI WAHAB	Workshop Repaired		OD Excess Collected by Workshop	

Print AK letter

Modification History 14/05/2018 08:36 s069588 Modify Claim Type(OD-MX-->OD-MD)

Special Claim Creation Approval

Approval	Reason
Remarks	

Damage assessment

Attachment

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	CTVIC	Engine Capacity	
Date of Registration	06/06/2006	Classis No.	SHMF0163065208413		
Towing Required *	☐ Yes ☒ No	Vehicle in IDAC *	☐ Yes ☒ No	Parallel Import *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	ROSLI WAHAB	Survey Current Status	

5/14/2018

Claim Handling (damage assessment Claim Task MT/0989332 / Claim 001 OD-MD)

IDAC/Workshop Name NATIONAL ASSESSMENT CENTRE

IDAC/Workshop Location

51 UBI AVENUE 1 #01-25 PAYA

Windscreen
Parts & Labour
Cost

Total Loss *

Yes * No

Market
Value(\$)

Scrap Value(\$)

Economical Repair Value(\$)

Remark

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
Not Applicable	1	32200101	NUMBER PLATE (FRONT)	1	Replace	X
ABS	2	16000101	BUMPER (FRONT)	1	Replace	X
ABSORBER	3	16001301	BUMPER BRACKET (FRONT LEFT)	1	Replace	X
ACCELERATOR	4	16001302	BUMPER BRACKET (FRONT RIGHT)	1	Replace	X
ACTUATOR	5	16002401	BUMPER CLIPS (FRONT)	1	Replace	X
ADVERTISEMENT STICKER	6	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm	X
	7	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Unconfirm	X
	8	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm	X
	9	16005001	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm	X
	10	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
	11	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
	12	16005601	BUMPER SPONGE (FRONT)	1	Unconfirm	X
	13	27700101	HEAD LAMP (LEFT)	1	Unconfirm	X
	14	27700102	HEAD LAMP (RIGHT)	1	Replace	X
	15	112023	AIR COIL CONDENSER	1	Unconfirm	X
	16	364001	RADIATOR	1	Unconfirm	X
	17	454012	WIPER WASHER TANK	1	Unconfirm	X
	18	25400103	FENDER (FRONT RIGHT)	1	Replace	X
	19	25400802	FENDER INNER PANEL (FRONT RIGHT)	1	Unconfirm	X
	20	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Unconfirm	X

Save

Submit

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : 2 MAY 18 046106 Vehicle Registration No : SGH 30956
Name (as shown in NRIC) : CHIN SHICHANG DARYL NRIC/FIN/Passport No : SP121249Z
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : 11 JALAN NOVENA TIMOR Singapore : 308533
Contact (Tel) : 91918093 Mobile No. : _____
Email Address : daryl.chin.chi@gmail.com
Date of Accident : 3/4/2018 Time of Accident : 2330
Place of Accident : CAVEN DISH PARK, 18 PING GROVE, PORCH.
Insurance Company : NTUC INCOME

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To change from REPORTER to own DAMAGE CLAIMS

Policyholder / Driver's Signature
Date: 11/5/18

Reporting Centre Personnel's Signature
Name: [Signature]
NRIC/FIN No.: _____
Date: 11/05/2018

rsbm

From: Ng Hak Joo <hakjoo.ng@income.com.sg>
Sent: Tuesday, 15 May, 2018 3:15 PM
To: IEPL DF12 Workshop; Tan Cheng Huat
Cc: rsbm
Subject: MT/0989332-001, VEHICLE NUMBER: SGH3095G

Importance: High

Dear Indeco

Please liaise with owner Mr Chin yinKeong at 91918093 as the vehicle is with him, excess \$642 and TA

Our Ref: MT/CA/OD/051/0989332-001/NHJ

15 May 2018

INDECO ENGINEERS (PTE) LTD

BLK 39 DEFU LANE 12

SINGAPORE 539139

Dear Sir

CLAIM NUMBER: MT/0989332-001

REPAIR OF VEHICLE NUMBER: SGH3095G

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 15 May 2018

Make: HONDA

Model: CIVIC

Estimated Repair Days: 4

Location: NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)

Address: BLK 1007 #1 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE INDUSTRIAL ESTATE SINGAPORE 159721

Benefits Applicable: Transport Allowance

Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Ng Hak Joo at 64307890 or email us at motor@income.com.sg.

Yours sincerely

Low Choo Mee

Senior Manager

Motor Insurance

Ng Hak Joo

Claims Executive, Motor Insurance

T +65 6430 7890

www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the

recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.