

22/03/2007

ASS. REC. BY:

REF: CS/lpc18006418 / GHD3<sup>72</sup>

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person): Gerald poh

of

Lpc

Date/Time: 6/4/18 @ 4:52pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 3580 D

Insured:

SGX8598E

at Workshop m/s

KGC workshop

Tel:

8189 2986

of BLK 176 Sin Ming Drive #02-04

Policy No:

Claim No:

17/18/18 / VP05/020516

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp/

09/04/2018

H.O.D. Endorsement:

Date/Time: 5:09pm 06/4/18

Person Contacted:

joyce

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLX 3580 D - x
	SGX 8598E - CC4 / lpc18002396 / Area 3 D.O.A: 3/2/18
	lump Sum \$1150+ (Red: 3970.16 : 77%)






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS/LPC18006418/Gtd3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 06-04-2018		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGX 8598E	Veh. Inspected	SLX 3580D	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020516	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	06/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	04/04/2018	Inspection Date		
Survey held at	KGC WORKSHOP PTE LTD 176 SIN MING DRIVE, SIN MING AUTOCARE #02-04 SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**Nivitha (LKK Auto)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Friday, 6 April 2018 4:52 PM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** FW: PRI - L18.0572.AT / SLX 3580D & SGX 8598E ON 04.04.18//Your ref: 17/18/18/VP05/020516

Dear Catherine,

Kindly note and proceed accordingly

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Kuru & Co [mailto:kurulegal@yahoo.com.sg]  
**Sent:** Friday, 6 April, 2018 4:46 PM  
**To:** ONG LI LI  
**Cc:** MT\_Claim\_SG  
**Subject:** Re: PRI - L18.0572.AT / SLX 3580D & SGX 8598E ON 04.04.18//Your ref: 17/18/18/VP05/020516

Dear Sirs

Our client is agreeable to the following surveyor as the SJE: Ma Chin Fook

Please arrange for your surveyor to survey our client's vehicle at the following address:

KGC WORKSHOP PTE LTD  
Blk 176 Sin Ming Drive  
#02-04 Sin Ming Autocare  
Singapore 575721  
Contact: Joyce/8189 2986

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards  
Anne  
Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

---

**From:** ONG LI LI <llong@lonpac.com>

**To:** "kurulegal@yahoo.com.sg" <kurulegal@yahoo.com.sg>

**Cc:** MT\_Claim\_SG <mt\_claim@lonpac.com>

**Sent:** Friday, 6 April 2018, 14:12

**Subject:** RE: PRI - L18.0572.cj / SLX 3580D & SGX 8598E ON 04.04.18 Our ref: 17/18/18/VP05/020516

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No	Name of Surveyor	Please tick <input type="checkbox"/>
1	Wilson Teo	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Kalvin Ang	
5	Sebastian Yeang	
6	Adrian Ling	
7	Mohammed Rasul	
8	Marcus Chua	
9	Kenneth Kong	
10	Ma Chin Fook	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]  
**Sent:** Friday, 6 April, 2018 12:52 PM  
**To:** MT\_Claim\_SG  
**Subject:** PRI - L18.0572.cj / SLX 3580D & SGX 8598E ON 04.04.18

Dear Sirs

We enclose our PRI's letter dated 06.04.18, the content of which is self-explanatory for your attention.

Regards  
Irene  
Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/04/2018 14:48
Date Of Accident	04/04/2018 19:50
Exact Location Of Accident	AMK AVE 5 TWRDS CTE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX3580D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KANG HOCK SENG
NRIC No	S1586540G
Email Address	KANGHOCKSENG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97912267
Alternative Phone No	OTHERS-NOPHONE

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN884631
Cover Note Number	

### Driver

Name of Driver	KANG HOCK SENG
NRIC No	S1586540G
Date Of Birth	27/07/1963
Occupation	INDOOR
Date Of Driving Pass	03/08/1987
Driving Experience	30 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97912267
Fax Number	
Contact Number	OTHERS-NOPHONE
Email Address	KANGHOCKSENG@HOTMAIL.COM

Address	BLK 519 WOODLANDS DR 14 #09-277
Postcode	730519
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : JIMMY GENDER: : MALE
Passenger 2	NAME: : AH SOON GENDER: : MALE
Passenger 3	NAME: : WANG KIN FA GENDER: : MALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO ATTACHED

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE IS TOO LARGE
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGX8598E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	



Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:


  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN

Accident Date: 04/04/18 Time: 1950 Location: AMK Ave S toward CTE  
 My Vehicle A: SLX 3580D Vehicle B: SGX 8592E Vehicle C/Others: Nil



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When the traffic turn green, I was travelling to enter the highway.  
 Suddenly hear a bang from the rear.  
 Review the video footage, notice the veh (B) cut from the  
 right most lane into my lane.

( ) Claim OD / TP at Ah Lim Motor ☒ Claim OD / TP at other workshop ( ) Reporting Only

Remarks : Please forward a copy of my efile accident report to

My workshop : Kgc workshop Pte Ltd.  
 Email Address : Joyee@kgcworkshop.com.sg / dj@kgcworkshop.com.sg  
 & Myself :  
 Email Address : kanghock.song@hotmail.com.

Note : Please take note that your insurer have **14 days timeframe** for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Kcy 5/4/18 11:00 AM  
 Policyholder's Signature  
 Date & Time:

Kcy  
 Driver's Signature (If driver is not the policyholder)  
 Date & Time

Witnessed by Reporting Centre  
 Personnel

# Sketch Plan Pg. 3

## AXA INSURANCE PTE LTD

8 Shenton Way, #24-01  
AXA Tower, Singapore 068811  
Customer Service Centre #B1-01  
Tel: 6338 7288 Fax: 6338 2522  
Website: www.axa.com.sg  
GST Registration Number: 199903512M



Original

Agent Code: **08260**

Policy No. (if any):

**New Business**

SmartDrive Quote Ref:

## MOTOR COVER NOTE

No. **CN884631**

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) - Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements

The insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby HELD COVERED under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

## SCHEDULE

THE COMPANY	AXA INSURANCE PTE LTD
INSURED	KANG HOCK SENG
MAKE AND DESCRIPTION OF VEHICLE	HYUNDAI ELANTRA 1.6 GLS A 'S'
VEHICLE REGISTRATION NO.	SLX3580D
YEAR OF MANUFACTURE	2018
ENGINE NO.	G4FGJU150284
CHASSIS NO.	KMHD841CMJU646319
ENGINE CAPACITY/TONNAGE	1591
COVER TYPE	COMPREHENSIVE
HIRE PURCHASE	MALAYAN BANKING BERHAD
VALUE (\$)	AS PER MARKET VALUE
PERIOD OF INSURANCE	FROM: 26/03/2018 TO: 25/03/2019
EXCESS (\$)	AS PER POLICY
AXA PREMIUM WORKSHOP?	NO

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).

AXA INSURANCE PTE LTD

Issued by HOCK MOH NELSON on 26/03/2018 11:39am  
TEO

Authorised Signature

**Note :** This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.

- Premium for time on risk will be charged subject to minimum of S\$53.50 (inclusive of GST), if the policy is cancelled after the inception date.
- An administrative fee of S\$26.75 (inclusive of GST) will be charged:
  - Cover note issued and cancelled before inception.
  - Retaining the old registration number for a new vehicle insuring with AXA.

### PREMIUM WARRANTY

**For Individual Customers:**

Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.

**For Non-Individual Customers:**

Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days on inception / renewal / endorsement. For all other cases, the premium in full should be paid before inception.

MTR/C/NOTE/V01/03



Co.Reg.No.: 201719986M

# KGC WORKSHOP PTE LTD

Sincere • Secure • Satisfaction

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: TP 180405

Date: 10/4/2018

No of Page: 1/2

Kang Hock Seng  
176 Sin Ming Drive, Sin Ming Autocare  
# 02-04  
Singapore 575721

4 Days.  
Kumpsin Repairs.  
After repair photos.  
Gm. Qiang.  
09/4/18.

Registration No: SLX 3580 D

Model: Hyundai Elantra

Accident Date: 4-Apr-18

Chassis No: -

Our Ref: TP180405

Engine Capacity: -

S/No	Qty	Items	Unit Price	Amount
1	1	Tail Lamp X NN	\$ 362.60	\$ 362.60
2	1	Rear Bumper - OA	\$ 479.80	\$ 479.80
3	1	Rear Bumper Retainer - MC	\$ 46.30	\$ 46.30
4	1	RHS Rear Fender X Repair	\$ 1,788.50	\$ 1,788.50
5	1	RHS Rear Fender Shield X NN	\$ 98.00	\$ 98.00

\$ 2,775.20 526.1

-20% \$ 555.04

Total for spare parts \$ 2,220.16 420.88

## Special Nett

1	10	Rear Bumper Clips /	\$ 5.00	\$ 50.00 20
2	1	RHS Rear Fender Shield Clips / MC	\$ 4.00	\$ 40.00 20

Total for SP \$ 90.00

Sub-Total for Parts: \$ 2,310.16

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts	500	1,500.00
2		To putty and spray paint on all accident damage parts and other accident affected areas	400	1,000.00
3		To check wiring system to facilitate repair and refit the same	30	50.00
4		Apply rust proofing on the adjacent panels	NN X	200.00
5		To remove and refit bumper sensors KGC Workshop Pte Ltd	40.	60.00

176 Sin Ming Drive, Sin Ming Autocare #02-04 (575721)

Office : 6453 6279 Fax : 6456 5410

TOTAL AMOUNT: 2,810.00

OVERALL COST: 5,120.16

430.88  
20% 1150



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18006418/Gtd3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 25-04-2018

Code : LPC2



## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGX 8598E	Veh. Inspected	SLX 3580D
Policy No.		Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020516	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	06/04/2018

## 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHD841CMJU646319	Colour	GREY
Odometer	208	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEXEN	6 mm
L/H Front Tyre	195/65 R15	NEXEN	6 mm
R/H Rear Tyre	195/65 R15	NEXEN	6 mm
L/H Rear Tyre	195/65 R15	NEXEN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	04/04/2018	Inspection Date	09/04/2018
Survey held at	KGC WORKSHOP PTE LTD 176 SIN MING DRIVE, SIN MING AUTOCARE #02-04 SINGAPORE 575721		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 3580D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAIL LAMP	NOT NECESSARY	362.60	-
1	REAR BUMPER	CRACKED	479.80	479.80
1	REAR BUMPER RETAINER	NECESSARY	46.30	46.30
1	RHS REAR FENDER	TO REPAIR SEE LABOUR	1,788.50	-
1	RHS REAR FENDER SHIELD	NOT NECESSARY	98.00	-
	LESS 20% DISCOUNT		-555.04	-105.22
			2,220.16	420.88
<b>SPECIAL NETT ITEMS</b>				
10	REAR BUMPER CLIPS @\$5.00 (SN)	NECESSARY	50.00	20.00
1	RHS REAR FENDER SHIELD CLIPS (SN)	NECESSARY	40.00	20.00
			90.00	40.00
<b>LABOUR</b>				
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF RHS REAR FENDER.		1,500.00	500.00
	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS.		1,000.00	400.00
	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME.		50.00	30.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.	NOT NECESSARY	200.00	-
	TO REMOVE AND REFIT BUMPER SENSORS.		60.00	40.00
			2,810.00	970.00
<b>GRAND TOTAL</b>			<b>5,120.16</b>	<b>1,430.88</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,150.00</b>

Report Ref No. CS/LPC18006418/Gtd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.