

(08/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: _____

at Work stop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 42234 Yr Regn: 10 May / 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Sonata C.C. 1991Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 68880 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 1CMHETXIVMCA825071

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WettkFront 2 mm Rear 2 mmR/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 5/4/8 D.O.I. 6/4/8Survey held at CDGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>9/6/8</u>	<u>Call U/S \$550/2 hrs.</u>

Date/Time, File Pass to?



: Preli. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

1)



: Final Report

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Signature

member of COMFORTDELGRO

Date/Time: 06.04.2018 08:59 Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305138978

OMER	REGN NO : SHD4223G	MILEAGE
S OMER NO ESS	MAKE : HYUNDAI	FUEL E.....1/2.....F
COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755	MODEL SONATA	DATE/TIME IN 05.04.2018 16:10
(R) (P)	YR OF MANU 10.05.2012	TARGET DATE
DUNT CARD NO.	CHASSIS CODE KMHET41VMCA825071	COMPLETION DATE/TIME:

Accident Date: 05.04.2018
 ATURE: 3P 05.04.18

NO	LABOR CODE	DESCRIPTION
----	------------	-------------

WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE _____

ledgement Slip

Exit Pass

No.: SHD4223G JU AXA

Vehicle No.: SHD4223G

f Service Advisor

Signature/Date

Name of Service Advisor

Date _____

Returned to Service Reception upon collection

To be kept by Security Guard