

ASS. REC. BY:

REF: CS/CTI18006450/ R1 qd3 n2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

Mennen

From (Person): shennan tan of CTI Date/Time: 09/04/18 @ 10:13am

Estimated Cost: Bill to:

OD ~~TP~~ AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 692K Insured: SGH 9232M

at Workshop m/s cheng Auto Bodyworks Tel: 6631 0707

of 5800N Lee Street #01-62

Policy No: DMPes N 3051101701 Claim No: SNM18 D01798C02

Sum Insured: Excess:

Make of Veh: D.O.A. 04/04/2018

(Client's Record)

10/04/2018

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 10:34am @ 9/4/18 Person Contacted: Muri

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKZ 692K-X
	SGH 9232M-CE6 / CTI 16013552 / 11eb3n2 DOA: 19/7/16
02/6/18 @ 11.03m	Panel finalised with Muri LS \$3000. 5 days.
	Chd @ 7175.12, 712.

Shirley

Form

REF:

5466I

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 692K

at Workshop m/s: CHERK AUTO

of S, SUDN LEE ST #01-62

Insured: CTI/TP

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SKZ 692K Yr Regn: 2016 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ C180 AV c.c. 1595

Colour: GRAY A/C: Insured / Std / NI / NA

Sp.Reading: 70557 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W80 205 04 02 R130754

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 04/04/18 D.O.I. 10/04/18

Survey held at CHERK AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 08 JUN 2016

Date/Time, File Pass to?

1) 08/6/18

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

220

Report Format :

Lump Sum / I.B.I: (\$)

WER-TP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Apr 2018 Sendback Est	06 Apr 2018 15:45 \$10,175.12	09 Apr 2018 10:13 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NARAYANAN S/O BATUMALAI, ID: S2502989E		
Main Claimant:	LIM HUNG QUEE, ID: S1655466I		
Vehicle Reg. No.:	SKZ692K	Date of Loss:	04/04/2018 12:00 - :59 [26 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D01798C02	Policy/Cover Note No.:	DMPCSN3051101701
Vehicle Reg. No. (Insured):	SGH9232M	Policy No. (Claimant):	GA146190
		Excess:	\$0.00
Repairer:	Cheng Auto Bodyworks (HQ) 5 Soon Lee Street #01-62 Pioneer Point, 627607 Pioneer - Tel: 6631 0707		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/04/2018]		
Driver/Custodian (Insured):	NARAYANAN S/O BATUMALAI (/ Male), NRIC: S2502989E		
Adj Asg. Remarks:	EST \$10,175.12, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: CLAIMS@CHENGAUTO.COM
Sent: Thursday, 7 June 2018 11:03 AM
To: Rasul (LKKAUTO)
Cc: SUR
Subject: Re: SKZ 692K - LIM HUNG QUEE | DOA : 04/04/2018 | POLICY NO. : GA146190 | REF. NO. SNM18D01798C02

Dear Mr. Rasul,

Your Claim Ref. No.	: SNM18D01798C02
CHENG AUTO Ref. No.	: SKZ692K / LIM HUNG QUEE
Insured Name	: LIM HUNG QUEE
Policy Number	: GA146190
Insurer/Policy Type	: AXA INSURANCE / COMPREHENSIVE
Date of Loss	: 04/04/2018
Our Vehicle No.	: SKZ692K
TP Vehicle No.	: SGH9232M / CHINA TAIPING INSURANCE

We refer to your offer of \$3,000.00 / 05 days Lumpsum & before GST. We accept your offer sir.

Thanks & Best Regards,

Muru
Claims Department



CHENG AUTO BODYWORKS

HP: 8666 7775 | Office-Tel: 6631 0707 | Fax: 6316 2431

Reporting Centre

Address: 5 Soon Lee Street #01-60 Pioneer Point, Singapore 627607

Email: claims@chengauto.com

Workshop

Address: 5 Soon Lee Street #01-62 Pioneer Point, Singapore 627607

Email: cab@chengauto.com

Windscreen

Address: 5 Soon Lee Street #01-41 Pioneer Point, Singapore 627607

Email: windscreen@chengauto.com

Spraypainting

Address: 1 Soon Lee Street #06-41 Pioneer Centre, Singapore 627605

Email: cab@chengauto.com

On 7/6/2018 10:53 AM, Rasul (LKKAUTO) wrote:

Hi,

Kindly confirm the finalised amount

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/04/2018 18:28
Date Of Accident	04/04/2018 12:30
Exact Location Of Accident	CARPARK BLK 161 WOODLANDS ST 13
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ692K
Insured/Policyholder	
Name Of Registered Owner	LIM HUNG QUEE
NRIC No	S1655466I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98336585
Alternative Phone No	OFFICE-98336585

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180-1.6 AVANTGARDE (R17 LED) (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA146190
Cover Note Number	

Driver

Name of Driver	LIM HUNG QUEE
NRIC No	S1655466I
Date Of Birth	30/08/1964
Occupation	INDOOR
Date Of Driving Pass	17/12/1982
Driving Experience	35 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98336585
Fax Number	
Contact Number	OFFICE-98336585
E-Mail Address	NOEMAIL

Address	SINGAPORE
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On the 4/4/18 at 1230Hrs, I was driving at the carpark of Blk 161, Woodlands st 13. Vehicle B (SGH9232M) reversed out of his parking lot and hit the left portion of my car. he reversed out without any warning thereby not giving me any chance to react.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGH9232M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NARAYANAN S/O BATUMALAI
NRIC/Passport Number	S2502989E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I am fully aware that my insurer may have a 14-day period for me to decide on filing an Own Damage Claim.

Accident Sketch Plan

Date of Accident:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 4/4/8 at 030hrs, I was driving at the corner of Blk 161 Woodlands St 13 Vehicle B (SGH 4232M) reversed out of his parking lot and hit the left portion of my car. He reversed out without any warning, thereby not giving me any chance to react.

- ☐ Own Damage Claim
- ☒ Third Party Claim
- ☐ OD/TP Claim at another workshop
- ☐ Reporting Only

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

林江松

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRC/SIN No.:



Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-62 Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**NARAYANAN S/O BATUMALAI**

BLK 161 WOODLANDS STREET 13

#11-621

Singapore 730161

Claimant Insurer: AXA Insurance Pte Ltd**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	04/04/2018
Vehicle Reg. No.:	SKZ692K	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LIM HUNG QUEE	Driver (Insured):	NARAYANAN S/O BATUMALAI
Make/Model:	MERCEDES-BENZ C180, 1.6 AVANTGARDE (R17 LED) (A)	Vehicle Reg. Date:	08/01/2016
Vehicle Colour:	SILVER	Chassis No:	WDD2050402R130754
Engine No:	27491030497435		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	ON THE 4/4/18 AT 1230HRS, I WAS DRIVING AT THE CARPARK OF BLK 161, WOODLANDS ST 13. VEHICLE B (SGH9232M) REVERSED OUT OF HIS PARKING LOT AND HIT THE LEFT PORTION OF MY CAR. HE REVERSED OUT WITHOUT ANY WARNING THEREBY NOT GIVING ME ANY CHANCE TO REACT.		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS

	Amount
Parts	7,575.12
Miscellaneous Items	0.00
Labour	2,600.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (\$\$)	10,175.12

This claim is handled by: LAI JIA WEN RACHEL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Apr 2018)

Parts: 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) (2015)

Print Code: Cheng Auto Bodyworks/SKZ692K/06/04/2018 15:45

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Handwritten notes and signatures:

- Top right: "TP- / Chinataiping"
- Below it: "f1p"
- Below that: "Rmshuf" with a checkmark.
- Below that: "llcc"
- Bottom right: "45 / 8/8"

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*L/F DOOR	10.00	0.00	(R) Repair 2,066.40 FL
2	1		*L/R DOOR	10.00	0.00	PA 2,558.85 FL
3	1		*FRONT DOOR CHROME	10.00	0.00	SLC X *134.40 FL
4	1		*REAR DOOR CHROME	10.00	0.00	SLC X *85.05 FL
5	1		*REAR FENDER	10.00	0.00	(R) Repair 2,655.45 FL
6	1		*DOOR LOCK ASSY FRONT	10.00	0.00	SLC X *557.55 FL
7	1		*DOOR LOCK ASSY REAR	10.00	0.00	SLC X *359.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

8,416.80

- List Item Discount on L Items (S\$)

841.68

Total Parts (S\$)

7,575.12

Cheng Auto Bodyworks/SKZ692K/06/04/2018 15:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR	New	400 400 1,000.00
2	SPRAYPAINTING	New	750 750 1,000.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	60 60 100.00
4	DISMANTLE AND TRANSFER LEFT FRONT DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	New	80 80 250.00
5	DISMANTLE AND TRANSFER LEFT REAR DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	New	80 80 250.00
Gross Labour Cost (\$)			2,600.00

Cheng Auto Bodyworks/SKZ692K/06/04/2018 15:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Resue

Hp 90010068

5 days

4/5 ~~HP~~ P/P

2/5/18

10/04/18 @ 1740

after

Res after repair
by part

Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-62 Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**NARAYANAN S/O BATUMALAI**

BLK 161 WOODLANDS STREET 13

#11-621

Singapore 730161

Claimant Insurer: AXA Insurance Pte Ltd**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	04/04/2018
Vehicle Reg. No.:	SKZ692K	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LIM HUNG QUEE	Driver (Insured):	NARAYANAN S/O BATUMALAI
Make/Model:	MERCEDES-BENZ C180, 1.6 AVANTGARDE (R17 LED) (A)	Vehicle Reg. Date:	08/01/2016
Vehicle Colour:	SILVER	Chassis No:	WDD2050402R130754
Engine No:	27491030497435		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	ON THE 4/4/18 AT 1230HRS, I WAS DRIVING AT THE CARPARK OF BLK 161, WOODLANDS ST 13. VEHICLE B (SGH9232M) REVERSED OUT OF HIS PARKING LOT AND HIT THE LEFT PORTION OF MY CAR. HE REVERSED OUT WITHOUT ANY WARNING THEREBY NOT GIVING ME ANY CHANCE TO REACT.		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS	Amount
Parts	7,575.12
Miscellaneous Items	0.00
Labour	2,600.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	10,175.12

This claim is handled by: LAI JIA WEN RACHEL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Apr 2018)

Parts: 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) (2015)

Print Code: Cheng Auto Bodyworks/SKZ692K/06/04/2018 15:45

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*L/F DOOR	10.00	0.00	(R) Repair 2,066.40 FL
2	1		*L/R DOOR	10.00	0.00	2,558.85 FL
3	1		*FRONT DOOR CHROME	10.00	0.00	X *134.40 FL
4	1		*REAR DOOR CHROME	10.00	0.00	X *85.05 FL
5	1		*REAR FENDER	10.00	0.00	(R) Repair 2,655.45 FL
6	1		*DOOR LOCK ASSY FRONT	10.00	0.00	X *557.55 FL
7	1		*DOOR LOCK ASSY REAR	10.00	0.00	X *359.10 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$) 2,643.90 ~~8,416.80~~- List Item Discount on L Items (\$\$) 264.39 ~~841.68~~Total Parts (\$\$) 2,379.51 ~~7,575.12~~

Cheng Auto Bodyworks/SKZ692K/06/04/2018 15:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR	New	400 1,000.00
2	SPRAYPAINTING	New	750 1,000.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	60 100.00
4	DISMANTLE AND TRANSFER LEFT FRONT DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	New	80 250.00
5	DISMANTLE AND TRANSFER LEFT REAR DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	New	80 250.00
Gross Labour Cost (S\$)			1,370.00 2,600.00

Cheng Auto Bodyworks/SKZ692K/06/04/2018 15:45. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FINALIZATION CALCULATION

Total Parts	S\$ 2,379.51 ✓
Total Supplementary	S\$ -
Total Labour	S\$ 1,370.00
Total Miscellaneous	S\$ -
Total	S\$ 3,749.51
Lumpsum 20%	S\$ 749.90
Grand Total	S\$ 2,999.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

5 days

4/5

10/04/18 @ 1740

Res after repair

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18006450/R1QD3N2

Date: 13/06/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3051101701
Claimant Vehicle No :	SKZ692K	Insured Vehicle No :	SGH9232M
Date of Loss:	04/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01798C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ692K	Engine No:	27491030497435
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Chassis No:	WDD2050402R130754
Reg. Date:	08/01/2016 (Man. Year: 2015)	Odometer:	70557 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,575.12	2,908.29	4,666.83	61.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,370.00	1,230.00	47.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,175.12	4,278.29	5,896.83	57.95
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	10,175.12	3,000.00	7,175.12	70.52

INSPECTION

Date of Assignment:	09/04/2018	Present Location:	Cheng Auto Bodyworks (HQ)
Date Inspected:	10/04/2018	Inspected At:	Cheng Auto Bodyworks (HQ) 5 Soon Lee Street #01-62 Pioneer Point Singapore 627607
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2018)
Parts:	143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ692K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/F DOOR (WCP)	Repair	2,066.40 FL	*- F
2	1		*L/R DOOR (WCP)	Bent	2,558.85 FL	*2,558.85 F
3	1		*FRONT DOOR CHROME (WCP)	Serviceable	134.40 FL	*- F
4	1		*REAR DOOR CHROME (WCP)	Necessary	85.05 FL	*85.05 F
5	1		*REAR FENDER (WCP)	Repair	2,655.45 FL	*- F
6	1		*DOOR LOCK ASSY FRONT (WCP)	Serviceable	557.55 FL	*- F
7	1		*DOOR LOCK ASSY REAR (WCP)	Serviceable	359.10 FL	*- F
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					8,416.80	2,643.90
- List Item Discount on L Items 10.00/0.00% (\$\$)					841.68	0.00
+ Margin on L,N Items 0.00/10.00% (\$\$)					0.00	264.39
Total Parts (\$\$)					7,575.12	2,908.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	1,000.00	400.00
2	SPRAYPAINTING	New	1,000.00	750.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	100.00	60.00
4	DISMANTLE AND TRANSFER LEFT FRONT DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	New	250.00	80.00
5	DISMANTLE AND TRANSFER LEFT REAR DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	New	250.00	80.00
Gross Labour Cost (\$\$)			2,600.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >