

Form No. 1

Insured By

REP CS/11918006463/ Kqd302

Special Instruction

Survivor
Mentem

Kenneth
chin lee ying

ASSIGNMENT (Office)

of ALG

Date/Time 9/4/18 @ 10:25am

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No. SLW 692P

Insured

at Workshop (s) Motor Image

Tel. 9090 3323

of 19 Lorong 8 Toa Payoh

Policy No. 180008942

Claim No. 634576422789

Sum Insured

Excess: 400 of 05

Make of Veh.
(Client's Record)

D.O.A. 09/04/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time 11:01am 9/4/18

Person Contacted: Khan

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLW 692P-X
10/4/18 @	1.33pm Informed Wei Long c/A to EX: TBA by email. (CORL < 5.5K)
20/4/18 @	11.58am Informed Wei Leang EX: \$400 by email.
	Kenneth confirmed final fig \$2767.80 (Red \$4073.34, 60%)
15/Jul/18 @	1.30pm Tony Shing (L&K) called to inform that they success to contact the owner & owner willing to pay the ex: \$400. He said when all in order He will re-open the Mentem case and mentioned the W&SP invoice can proceed.

ASS. REC. BY:

REF: 1161

Kenneth

ASSIGNMENT

lw

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s Note Inq
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: ?
 (Client's Record)
 Make of Veh: _____

Veh No: SZE 692P Yr Regn: 01, 18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or A1 Wagon
 Make: Subaru Forester c.o. 1995
 Colour: N. P. White AC: Insured / Std / NI / NA
 Sp. Reading: 2879 T/Radio: Insured / Std / NI / NA

Eng No: _____
 C/No: JF1JJ5KC5J6 103457
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rlm / STD / Rlm or
 Tyre Size: F: 225/60R17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear
R/Bal. <u>9</u> mm		R/Bal. <u>9</u> mm
L/Bal. <u>9</u> mm		L/Bal. <u>9</u> mm
D.O.A. <u>5/4/18</u>		D.O.I. <u>9/4/18</u>

Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
M O/S

The UIC / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$119k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 2-3 days Res.: Yes or No
 Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
<u>10/9</u>	<u>File pass to Catherine</u>
<u>→</u>	<u>the excess as \$0f.</u>
<u>21/11/19 @ 8.40am</u>	<u>S. Chan Tong Shing (MIS) informed they already settle the excess with the owner. ask us to submit our report asap.</u>
<u>21/11/19 @ 8.50am</u>	<u>informed motor manage, say accordingly.</u>

RECEIVED 21 NOV 2019

Date/Time, File Pass to? : Prell. Report
 : Final Report
 Date/Time, File Return to? _____

Days Of Repair: 2
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	<u>200</u>
Transportation:	_____
S - RS - St	_____
Photos	_____
Others	<u>11</u>
TOTAL	<u>211</u>

Report Format: MEER-OD
 Lump Sum / I.B.I. (\$): 2367.80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18006463/Kqd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 09-04-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLW 692P
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From CHIN LEE YING	Assign Date	09/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 09/04/2018	Inspection Date 09/04/2018
Survey held at MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

- FW: SLW692P-OD CLAIM-AIG-SURVEY-09/04/2018-AFTER 1000 HRS

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 9/4/2018 10:25:15 AM

Attachments:  4107_004.jpg  4107_003.jpg  SLW692P_ESTIMATE.pdf
 SLW692P_GIA_REPORT.PDF
 20180405_191118_EF (online-video-cutter.com).mp4

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Kuan Wei Loong [<mailto:welloong@motorimage.net>]
Sent: Saturday, April 07, 2018 2:42 PM
To: AIG SGP, Claims-Survey
Cc: Sayedinah Ali; Daniel Lim; Chin, Lee-Ying
Subject: SLW692P-OD CLAIM-AIG-SURVEY-09/04/2018-AFTER 1000 HRS
Importance: High

Hi Claims Team,
Kindly arrange survey of the above mentioned vehicle.
(09/04/2018-AFTER 1000 HRS)

Regards
Kuan Wei Loong
Claims Advisor
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:90903323
Email:welloong@motorimage.net
Website:www.tanchong.com :: www.motorimage.net




Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 20 April 2018 11:54 AM
To: weiloong@motorimage.net
Cc: SUR
Subject: FW: SLW692P OD / 6345764227SG

Dear Wei Loong,

Please take note that the excess of above vehicle is \$400.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loo, Tong Shing [<mailto:TongShing.Loo@aig.com>]
Sent: Tuesday, 17 April 2018 2:05 PM
To: SUR <sur@lkkauto.com>
Cc: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Subject: SLW692P OD / 6345764227SG

Hi LKK,

Please be informed after further review the case.

We had decided to amended OI is at fault.

Kindly forward this email to workshop PIC as I have amended OI excess from \$0.00 to \$400.00.

Thank you.

Loo Tong Shing
AIG

Express Claims Adjuster
Claims Operations | AIG Shared Services

TongShing.Loo@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 10 April 2018 1:33 PM
To: weiloong@motorimage.net
Cc: SUR
Subject: VEHICLE SLW 692P (DOA: 09/04/2018)

Dear Wei Loong,

Please proceed to repair the insured vehicle **SLW 692P (Excess TBA)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8263C
Vehicle Details	
Vehicle No.:	SLW692P
Vehicle to be Exported:	No
Intended De-registration Date:	10 Apr 2018
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0I-L CVT AWD SR
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	FB20YC29508
Chassis No.:	JF1SJ5KC5JG103457
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,108.00
Original Registration Date:	29 Jan 2018
First Registration Date:	29 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$13,108.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2028
PARF Rebate Amount:	\$9,831.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,661.00
COE Rebate Amount:	\$41,800.00
Total Rebate Amount:	\$51,631.00

The information contained herein is correct as at 10 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/04/2018 10:05
Date Of Accident	05/04/2018 19:10
Exact Location Of Accident	UPPER CHANGI AIR PORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW692P
Insured/Policyholder	
Name Of Registered Owner	TAN WEE KEONG DARREN
NRIC No	S1328263C
Email Address	DARRENTANWK@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97715444
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 AWD (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800008942
Cover Note Number	

Driver

Name of Driver	TAN WEE KEONG DARREN
NRIC No	S1328263C
Date Of Birth	10/02/1958
Occupation	INDOOR
Date Of Driving Pass	28/04/2003
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97715444
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	DARRENTANWK@YAHOO.COM.SG

Address	1
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : 1 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

KINDLY REFER TO DOCUMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 1910 hrs, I was travelling towards Upper Chayji Rd from Townh which Kachil rd. I turn right and a car SP# 86264 turn right at Upper Chayji rd, but my front right tyre stop & rolled left to inspect damages and exchange particulars

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time: 6/5/2018


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The **issue and acceptance** of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 6/1/2018

Driver's Signature

(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/IN No.:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0721/2018
DATE : 07-APR-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : TAN WEE KEONG DARREN
ADDRESS : BLK 803 UPPER SERANGOON ROAD #02-07
S(534163)
TELEPHONE NO : 97715444

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 1800008942
VEHICLE NO : 8LW692P
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AND CVT
ENGINE NO : FB20YC29508
CHASSIS NO : JF18J5KC5JG103457
MILEAGE : 1 KM
DATE IN : 07/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 07/04/2018

Print Date : 07/04/2018
Print Time : 14:34:58

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO 8LM692P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	22/001	CONDUCT OD CLAIM AIG LOCATION:UPPER CHANGI AIRPORT DATE:05/04/2018 TIME:1910HRS		
3	22/002	REPLACE/REPAIR FRONT BUMPER,FRONT SPOILER AND FRONT PANEL	1000.00	2401
4	22/003	RESPRAY FRONT BUMPER AND FRONT PANEL	600.00	2001
5	22/004	TO CONDUCT FRONT LIGHTING TEST	20.00	✓
6	22/005	TO CONDUCT FRONT PROTECTANT COATING	250.00	1501
7	22/006	SUNDRIES	100.00	X
TOTAL LABOUR CHARGES			1970.00	

NOTORINAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SIN692P

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
		NETT	LIST	S/NETT	S/LIST REMARKS
1 RAD PHL COMPL RPR	53029SG0009P			R	360.00 X
2 BRKT CORNER F RH	57707SG000			Dis	36.00 ✓
3 BRKT CORNER F LH	57707SG010			Sm	36.00 X
4 BRKT SD F RH	57707SG020				12.60 TXR
5 BRKT SD F LH	57707SG030			Sm	12.60 X
6 BUMPER COVER FRT (FOR BL/W)	57709SG011			C/A	594.00 ✓
7 BACK BEAM CPL F	577118G0009P				288.00 TXR
8 ENERGY ABSOR F	577228G020				126.00 TXSVC
9 COVER HOOK F SP	577318G070			Sm	5.40 X
10 COVER FOG F SP RH	577318G080				43.20 TXSVC
11 COVER SD F SP RH	577318G120				12.60 TXSVC
12 COVER SD F SP LH	577318G130			Sm	12.60 X
13 PACKING RAD	577808G010			Sm	9.00 X
14 PACKING RAD	577808G020			Sm	9.00 X
15 LAMP ASSY HEAD EOP RH	84002SG220			Gr	2380.00 ✓
16 FOG LAMP ASSY F	84501AJ040			Sm	272.00 X
17 NOZZLE COVER ASSYRH	866368G340Q1			Sm	54.00 ✓
18 NOZZLE H L WASHERRH	866368G361				79.20 TXSVC
19 FRONT GRILLE BK	J10108G100			Sm	1200.00 X
20 FORESTER 2.0i-S KIT FRONT UNDER SPOILER (TCS)	TCS-FJB-FL-002			Sm	1398.00 X
SUB TOTAL		0.00	0.00	0.00	6940.20
LESS DISCOUNT (S/LIST-30 %)		0.00	0.00	0.00	2082.06
GRAND TOTAL		0.00	0.00	0.00	4858.14
OVERALL TOTAL		4858.14			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO 5LW692P

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
		NETT	LIST	S/NETT	S/LIST REMARKS

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SIN692P

TOTAL LABOUR CHARGES	1978.00
TOTAL SPARE PARTS CHARGES	4858.14
GRAND TOTAL	6836.14 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Not Authored
Li: Bil
Resurvey B4 paint
M 015


PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kg

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LOHONG 6, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0721/2018
DATE : 07-APR-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SEVENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : TAN WEE KEONG DARREN
ADDRESS : BLK 803 UPPER SERANGOON ROAD #02-07

S(534163)
TELEPHONE NO : 97715444

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 1800008942
VEHICLE NO : SLM692P
MODEL CODE : S.5EX7C
MODEL/YEAR : FORESTER 2.0I-L AND CVT
ENGINE NO : FB20YC29508
CHASSIS NO : JF1SJSWC5JG103457
MILEAGE : 2880 KM
DATE IN : 07/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KIMAN WEE LOONG**
ACCIDENT DATE : 07/04/2018

Print Date : 10/08/2018
Print Time : 19:15:24

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LOHONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SL2692P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	00CLAIM	CONDUCT BOOTWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM AIG LOCATION:UPPER CHANGI AIRPORT DATE:05/04/2018 TIME:1910HRS		
3	ZZ/002	REPLACE/REPAIR FRONT BUMPER,FRONT SPOILER AND FRONT PANEL	1000.00	240.00
4	ZZ/003	RESPRAY FRONT BUMPER AND FRONT PANEL	600.00	200.00
5	ZZ/004	TO CONDUCT FRONT LIGHTING TEST	28.00	28.00
6	ZZ/005	TO CONDUCT FRONT PROTECTANT COATING	250.00	150.00
7	ZZ/006	SUNDRIES	100.00	.00
		TOTAL LABOUR CHARGES	1978.00	618.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW692P

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 RAD PNL COMPL RPR	53029SG0009P				360.00 X
2 BRKT CORNER F RH	57707SG000				36.00 OK
3 BRKT CORNER F LH	57707SG010				36.00 X
4 BRKT SD F RH	57707SG020			R	12.60 X
5 BRKT SD F LH	57707SG030				12.60 X
6 BUMPER COVER FRT (FOR HL/W)	57709SG011				594.00 OK
7 BACK BEAM CPL F	57711SG0009P			R	288.00 X
8 ENERGY ABSOR F	57722SG020			Sm	126.00 X
9 COVER HOOK F SP	57731SG070				5.40 X
10 COVER FOG F SP RH	57731SG080				43.20 X
11 COVER SD F SP RH	57731SG120			Sm	12.60 X
12 COVER SD F SP LH	57731SG130				12.60 X
13 PACKING RAD	57780SG010				9.00 X
14 PACKING RAD	57780SG020				9.00 X
15 LAMP ASSY HEAD EDF RH	84002SG220				2380.00 OK
16 FOG LAMP ASSY F	84501AJ060				272.00 X
17 NOZZLE COVER ASSTPH	86636SG340Q1				54.00 OK
18 NOZZLE H L WASHERH	86636SG361			Sm	79.20 X
19 FRONT GRILLE BK	J1010SG100				1200.00 X
20 FORESTER 2.0I-S KIT FRONT UNDER SPOILER (TCS)	TCS-FJ8-PL-002				1398.00 X
SUB TOTAL					
LESS DISCOUNT (S/LIST-30 %)		0.00	0.00	0.00	3064.00
		0.00	0.00	0.00	919.20
GRAND TOTAL		0.00	0.00	0.00	2144.80
OVERALL TOTAL		2144.80			

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW692P

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	

LEGEND: REMARKS(CK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TDA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLW692P

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	3064.00
LESS 30 %	-919.20
S/LIST AMOUNT	2144.80
TOTAL LABOUR CHARGES	618.00
TOTAL SPARE PARTS CHARGES	2144.80
TOTAL CHARGES	2762.80
ADD 7 % GST	193.40
GRAND TOTAL	2956.20



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh Singapore 319255
 Service Centre Tel: (65) 6703 8101 / 102 Fax: (65) 6253 5535
 25 Leng Kee Road Singapore 159097
 Service Centre Tel: (65) 6703 8163 Fax : (65) 6479 1137
 Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L507178

For cash sales, payment will be endorsed on this invoice and no separate receipt will be issued.

DATE REC'D: 09-Apr-2018

SERVICE ADVISOR: HOOI

JOB No.: L478440

MILEAGE: 2880

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
 #07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: FORESTER 2.0I-L AWD CVT
ENGINE No.: FB20YC29508
CHASSIS No.: JF1SJSKC5JG103457
REGISTRATION No.: SLW692P

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
1	ODCLAI CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)	
2	REMARK CONDUCT OD CLAIM AIG LOCATION:UPPER CHANGI AIRPORT DATE:05/04/2018 TIME:1910HRS	
3	INS01 FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE	
4	INS02 IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338).	
5	INS03 STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE	
6	INS04 SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD.	
7	INS05 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM	
8	INS06 THE OWNER IS REQUIRED.	
9	INS07 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING:	
10	INS08 NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED	
11	INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY.	
12	REMARK EXCESS WAIVED BY AIG	
13	REMARK REPLACE/REPAIR FRT BUMPER,FRT SPOILER & FRT PANEL	240.00
14	REMARK RESPRAY FRT BUMPER & FRT PANEL	200.00
15	REMARK TO CONDUCT FRONT LIGHTING TEST	28.00
16	REMARK TO CONDUCT FRONT PROTECTANT COATING	150.00
	TOTAL(LABOUR)	618.00
1	BRKT CORNER F RH 57707SG000(Qty : 1 @ 36.00 each(Discount 30.00%))	25.20

Certified True Copy



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh Singapore 319255
 Service Centre Tel (65) 64170100/101 Fax (65) 62535535
 25 Leng Kee Road Singapore 159097
 Service Centre Tel (65) 64764776 Fax (65) 64791137
 Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER
Invoice No: L507178
For cash sales, payment will be endorsed on this invoice and no separate receipt will be issued.
DATE REC'D: 09-Apr-2018
SERVICE ADVISOR: HOOI
JOB No.: L478440
MILEAGE: 2880
ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
 #07-16 AIG BUILDING, S(079120)
TELEPHONE: 91007211
MODEL: FORESTER 2.0I-L AWD CVT
ENGINE No.: FB20YC29508
CHASSIS No.: JF1S35KC5JG103457
REGISTRATION No.: SLW692P

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
2	BUMPER COVER FRT (FOR HL/W) 57709SG011(Qty : 1 @ 594.00 each(Discount 30.00%))	415.80
3	LAMP ASSY HEAD EOF RH 84002SG220(Qty : 1 @ 2380.00 each(Discount 30.00%))	1,666.00
4	NOZZLE COVER ASSYRH 86636SG340Q1(Qty : 1 @ 54.00 each(Discount 30.00%))	37.80
	TOTAL(SPARE PARTS)	2,144.80

Subtotal 2,762.80
 GST(7%) 193.40
TOTAL \$2,956.20

DATE : 21-Nov-2019

 CUSTOMER



 MANAGER

The customer acknowledges and confirms by taking delivery of the vehicle and/or upon receipt of this invoice, either personally or by an agent that his/her complaints relating to the vehicle have been rectified to his/her satisfaction and that the Company's liability for defective work and/or materials will be limited to rectification works and/or replacement of parts without charge or at discounted charge, at the Company's option. The customer further acknowledges that any discrepancy in this invoice (with the exception of errors and omissions) must be brought to the Company's attention in writing within three(3) days from the date of this invoice failing which it will be deemed correct.

CUSTOMER

Not yet a DUO Member? Join us now at www.DUO.com.sg and start accumulating your points for your invoice today!

Certified True Copy



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
T (65) 6417 0333 F (65) 6252 5655
W www.motorimage.net
Co Reg No: 196702032R

DISCHARGE VOUCHER

Name of Insured: TAN WEE KEONG DARREN
Address of Insured: BLK 803 UPPER SERANGOON ROAD #02-07 S(534163)
Name of Repairs: MOTOR IMAGE ENTERPRISES PTE LTD / WORKSHOP
Address of Repairs: NO. 19 LORONG 8 TOA PAYOH SINGAPORE 319225
Place of Accident: UPPER CHANGI AIRPORT
Date of Accident: 05/04/2018 Vehicle No: SLW692P
Policy No: 1800008942 Claim No: _____

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of AIG ASIA PACIFIC INS L.P. settling the repair costs stated above with the said repairers. I/We hereby release and discharge the said insurers from all further obligations and liabilities under the aforesaid policy in respect on and accident involving my/our said motor vehicle on or about the abovementioned date and place.

I/We agree that by virtue of such payment, all my/our rights and remedies in respect of the damages to the said Motor Vehicle are subrogated to the said Insurers in accordance with the laws governing such matters.

I/We hereby grant the said insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefore. I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their parts they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:



Company's Chop & Signature

KUAN WEI LOONG

Name

13/04/2018

Date

INSURED:



IC No. & Signature/Company's Chop S1328263C

TAN WEE KEONG DARREN

Name

13/04/2018

Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Apr 2018		10 Apr 2018 10:06 Edit Adj Rpt	\$2,762.80 Edit Estimates	\$2,762.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS		[Created by insurer]		
Insured:	TAN WEE KEONG DARREN , ID: S1328263C, Tel: +6597715444, Email: darrentanwk@yahoo.com.sg			
Vehicle Reg. No.:	SLW692P	Date of Loss:	05/04/2018 19:00 - :59 [2 Months and 7 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 6345764227SG	Policy/Cover. Note No.:	1800008942 (Comprehensive)	
		Excess:	S\$0.00	
Repairer:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038101			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 19/04/2018]			
Driver/Custodian:	TAN WEE KEONG DARREN (60 / Male), NRIC: S1328263C, Tel: +6597715444 Email: darrentanwk@yahoo.com.sg			
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
<ul style="list-style-type: none"> • AIG_SG (21/11/2019): SLW692P / OD / 05/04/2018 / Coverage & Excess update • AIG_SG (17/04/2018): SLW692P / OD / 05/04/2018 / Coverage & Excess update • AIG_SG (12/04/2018): SLW692P / OD / 05/04/2018 / Coverage & Excess update 				
ALL ASSOCIATED TASKS			View All	Search Tasks
			Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject
			Handler	Assigned By
			Completed On	Created On
			Done?	
No results.				

Claim Documents

*SLW692P (6345764227SG)
OD
Apr 5 2018 7:00PM
[TAN WEE KEONG DARREN]
Motor Image Enterprises Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Video											1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)							Thumbnail	Print		
1	07/04/18 10:20	Video - Accident <small>[Linked Accident Report Documents]</small>								Load MP4		
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	10/04/18 12:12	General View								Load JPG	<input checked="" type="checkbox"/>	
2	10/04/18 12:12	General View								Load JPG	<input checked="" type="checkbox"/>	
3	10/04/18 12:12	General View								Load JPG	<input checked="" type="checkbox"/>	
4	10/04/18 12:12	General View								Load JPG	<input checked="" type="checkbox"/>	
5	10/04/18 12:12	General View								Load JPG	<input checked="" type="checkbox"/>	
6	10/04/18 12:12	General View								Load JPG	<input checked="" type="checkbox"/>	
7	10/04/18 12:12	General View								Load JPG	<input checked="" type="checkbox"/>	
8	10/04/18 12:12	General View								Load JPG	<input checked="" type="checkbox"/>	
9	10/04/18 12:12	General View								Load JPG	<input checked="" type="checkbox"/>	
10	10/04/18 12:12	General View								Load JPG	<input checked="" type="checkbox"/>	
11	10/04/18 12:12	Odometer Reading								Load JPG	<input checked="" type="checkbox"/>	
12	10/04/18 12:12	General View								Load JPG	<input checked="" type="checkbox"/>	
13	10/04/18 12:12	Chassis Number								Load JPG	<input checked="" type="checkbox"/>	
14	16/08/18 15:59	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>	
15	16/08/18 15:59	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>	
Documentation											1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	10/04/18 12:12	ESTIMATE								Load PDF		
2	21/11/19 15:56	Workshop Invoice								Load PDF		
3	21/11/19 15:56	Discharge Voucher								Load PDF		

Linked Accident Report Documents

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Video											1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)							Thumbnail	Print		
1	07/04/18 10:20	Video - Accident								Load MP4		
Assessment Reports											1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)							Thumbnail	Print		
1	07/04/18 10:21	Accident Statement								Load HTM		
2	19/06/18 20:29	Addendum Sheet								Load JPG	<input checked="" type="checkbox"/>	
3	19/06/18 20:29	Accident Statement Adm. #1								Load HTM		
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)							Thumbnail	Print		
1	07/04/18 10:20	Accident Photo								Load JPG	<input checked="" type="checkbox"/>	
2	07/04/18 10:20	Accident Photo								Load JPG	<input checked="" type="checkbox"/>	
3	07/04/18 10:20	Accident Photo								Load JPG	<input checked="" type="checkbox"/>	
4	07/04/18 10:20	Accident Photo								Load JPG	<input checked="" type="checkbox"/>	
5	07/04/18 10:20	Accident Photo								Load JPG	<input checked="" type="checkbox"/>	
6	07/04/18 10:20	Accident Photo								Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
7	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
20	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
21	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
22	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
23	07/04/18 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	07/04/18 10:16	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	07/04/18 10:16	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	19/06/18 20:28	Common Statement	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG18006463/KQD3E2

Date: 21/11/2019

REFERENCE

Insured/Claimant:	TAN WEE KEONG DARREN	Policy No:	1800008942
Date of Loss:	05/04/2018	Nature of Claim:	OD
			Claim No: 6345764227SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW692P	Engine No:	FB20YC29508
Make & Model:	SUBARU FORESTER, 2.0 AWD (A)	Chassis No:	JF1SJ5KC5JG103457
Reg. Date:	29/01/2018 (Man. Year: 2017)	Odometer:	2879 km
Colour:	Metallic Pearl White		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$119,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,958.14	2,144.80	2,813.34	56.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,878.00	618.00	1,260.00	67.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,836.14	2,762.80	4,073.34	59.59
+ GST 7.00/7.00% (S\$)	478.53	193.40	285.13	59.58
Nett Amount (S\$)	7,314.67	2,956.20	4,358.47	59.59

INSPECTION

Date of Assignment: 10/04/2018

Date Inspected: 09/04/2018 Inspected At:

Motor Image Enterprises Pte Ltd (Toa Payoh)
19 Lorong 8 Toa Payoh
Singapore 319255

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS
2	1		*RAD PNL COMPL RPR	Repair	360.00 FL	*- FL
3	1		*BRKT CORNER F RH	Distorted	36.00 FL	*36.00 FL
4	1		*BRKT CORNER F LH	Serviceable	36.00 FL	*- FL
5	1		*BRKT SD F RH	Repair	12.60 FL	*- FL
6	1		*BRKT SD F LH	Serviceable	12.60 FL	*- FL
7	1		*BUMPER COVER FRT (FOR HL/W)	Cracked	594.00 FL	*594.00 FL
8	1		*BACK BEAM CPL F	Repair	288.00 FL	*- FL
9	1		*ENERGY ABSOR F	Serviceable	126.00 FL	*- FL
10	1		*COVER HOOK F SP	Serviceable	5.40 FL	*- FL
11	1		*COVER FOG F SP RH	Serviceable	43.20 FL	*- FL
12	1		*COVER SD F SP RH	Serviceable	12.60 FL	*- FL
13	1		*COVER SD F SP LH	Serviceable	12.60 FL	*- FL
14	1		*PACKING RAD	Serviceable	9.00 FL	*- FL
15	1		*PACKING RAD	Serviceable	9.00 FL	*- FL
16	1		*LAMP ASSY HEAD E0F RH	Cut	2,380.00 FL	*2,380.00 FL
17	1		*FOG LAMP ASSY F	Serviceable	272.00 FL	*- FL
18	1		*NOZZLE COVER ASSYRH	Missing	54.00 FL	*54.00 FL
19	1		*NOZZLE H L WASHERRH	Serviceable	79.20 FL	*- FL
20	1		*FRONT GRILLE BK	Serviceable	1,200.00 FL	*- FL
21	1		*FORESTER 2.0i-S KIT FRONT UNDER SPOILER (TCS)	Serviceable	1,398.00 FL	*- FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	7,040.20	3,064.00
- List Item Discount on L Items 30.00/30.00% (S\$)	2,082.06	919.20
Total Parts (S\$)	4,958.14	2,144.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE / REPAIR FRONT BUMPER, FRONT SPOILER AND FRONT PANEL	New	1,000.00	240.00
2	RESPRAY FRONT BUMPER AND FRONT PANEL	New	600.00	200.00
3	TO CONDUCT FRONT LIGHTING TEST	New	28.00	28.00
4	TO CONDUCT FRONT PROTECTANT COATING	New	250.00	150.00
Gross Labour Cost (S\$)			1,878.00	618.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >