



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2016 PEUGEOT 308 5DR ALLURE PURETECH (SLQ2429C)

Date of Loss

4 April 2018

Time of Loss

17.50

Loss Description

SLQ2429C (INSD) HIT IN REAR OF GBE8868K

Comment

Workshop Details

Total Rebate Amount

47320

Nett Loss Amount

\$40,680.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

30/07/2018



Days of work completion *

112



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SLQ2429C

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

30/06/2017



Mileage

14373

Age of Vehicle

0

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2016

ASSESSMENT INFO...

2016

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

M THIRUCHITTAMPALAM T RAMANAN
S/O

CATEGORY Make

POLICY INFORMAT... PEUGEOT

ASSESSMENT INFO...
PEUGEOT

CATEGORY Model

POLICY INFORMAT... 308 5DR ALLURE PURETECH

ASSESSMENT INFO...
308 5DR ALLURE PURETECH 1.2 A/T 2

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...
▼

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... VF3LPHNYWGS259197

POST SURVEY INF...

CATEGORY

Date of Birth

FNOL INFORMATI... 31 December 1965

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Age

FNOL INFORMATI... 52

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY

Driving Experience

ASSESSMENT INFO... VF3LPHNYWGS259197

CATEGORY Engine No

POLICY INFORMAT... 10XTA40462839

ASSESSMENT INFO... 10XTA40462839

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1199

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 88000

FNOL INFORMATI... 6

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI...BLK 141 LORONG AH SOO, #10-265,
530141, Singapore

POST SURVEY INF...

CATEGORYAddress type

FNOL INFORMATI...Residential

POST SURVEY INF...

CATEGORYGender

FNOL INFORMATI...Male

POST SURVEY INF...

CATEGORYMarital status

FNOL INFORMATI...Married

POST SURVEY INF...

CATEGORYIdentification #

FNOL INFORMATI...S2583704E

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

09/04/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/45ZR17

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

225/45ZR17

Front left side

MICHELIN6MM

Front right side

MICHELIN6MM

Rear left side

MICHELIN6MM

Rear right side

MICHELIN6MM



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes ☐ No

Part Supplied by AXA

Yes No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			FRT BUMPER			Deformed	630		0		630	Review
		2	1			RECESS DOOR FRT			Serviceable	0	0	0	0	0	Deny
		3	1			FRT BUMPER F-LAMP MOULDING			Necessary	135		0		135	Review
		4	1			FRT BPR CTRL GRILLE BRACKET			Cracked	201.6		0		201.6	Review
		5	1			RADIATOR GRILL FRAME MDLG			Cracked	216		0		216	Review
		6	1			FRT BUMPER ABSORBER			Deformed	40.5		0		40.5	Review
		7	1			DETECTOR SENSOR SUPPORT SET			Necessary	81.9		0		81.9	Review
		8	1			FRT GUARD GRILLE			Serviceable	0	0	0	0	0	Deny
		9	1			BRACKET SET			Serviceable	0	0	0	0	0	Deny
		10	1			FRT BUMPER LWR MOULDING			Serviceable	0	0	0	0	0	Deny
		11	1			FRT BUMPER C-FINISHER			Serviceable	0	0	0	0	0	Deny
		12	1			FINISHER BUMPER			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		13	1			FRT BUMPER PLUG			Serviceable	0	0	0	0	0	Deny
		14	1			SET PROXIMITY SENSOR SUPPORTS FRT			Necessary	61.2		0		61.2	Review
		15	1			FRT BUMPER TOP RANGE			Serviceable	0	0	0	0	0	Deny
		16	1			FRT BUMPER RANGE			Cracked	61.2		0		61.2	Review
		17	1			FRT BPR REINFORCEMENT			Bent	252		0		252	Review
		18	1			MKT LWR FRT BPR PANEL FIXINGS			Necessary	54.9		0		54.9	Review
		19	1			FRT FACE TOP CROSSMEMBER			Serviceable	0	0	0	0	0	Deny
		20	1			FRT FENDER LH			Repair	0	0	0	0	0	Deny
		21	1			FRT FENDER RH			Repair	0	0	0	0	0	Deny
		22	1			FRT WING ACCOUSTIC SEAL LH			Serviceable	0	0	0	0	0	Deny
		23	1			FRT WING ACCOUSTIC SEAL RH			Serviceable	0	0	0	0	0	Deny
		24	1			ENGINE BONNET-ALUM			Bent	675		0		675	Review
		25	1			BONNET HINGE LH			Bent	36		0		36	Review
		26	1			BONNET HINGE RH			Bent	36		0		36	Review

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		27	1			HEADLAMP ASSY LH			Cracked	1197		0		1197	Review
		28	1			BARE HEADLAMP RH ADD DRIVER KIT			Serviceable	0	0	0	0	0	Deny
		29	1			RADIATOR ASSY			Serviceable	0	0	0	0	0	Deny
		30	1			CONDENSER			Serviceable	0	0	0	0	0	Deny
		31	1			GRILLE MOULDING			Cracked	90		0		90	Review

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		1		TO REPLACE/REPAIR FRT BUMPER,FRT PANEL,FRT BONNET,FRT LHS FENDER,FRT RHS FENDER	1800	0	0	Reviewing		1
		2		RESPRAY FRT BUMPER,FRT BONNET,FRT LHS FENDER,FRT RHS FENDER	2400	0	0	Reviewing		1
		3		WIRING CONNECTION & CHECK	150	0	0	Reviewing		1
		4		REMOVE & REPLACE RADIATOR INCLUDING BLEEDING,PRESSURE TEST & CHECK LEAKAGE	0	0	0	Deny		1
		5		REMOVE & REPLACE A/C CONDENSER INCLUDING REFILL A/C GAS,PRESSURE TEST & TEST LEAKAGE	0	0	0	Deny		1
		6		REMOVE & REPLACE FRT HEADLAMP SYSTEM INCLUDING REALIGN HEADLAMP BEAM LEVEL	200	0	0	Reviewing		1

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
 	7		TO REMOVE & REPLACE FRT PARKING SENSOR	150	0	0	Reviewing		1
 	8		TUFF KOTE	60	0	0	Reviewing		1
 	9		SEALANT FOR FRT BONNET	90	0	0	Reviewing		1
 	10		TO CONDUCT ECU COMPUTER DIAGNOSTIC CHECK INCLUDING CLEAR FAULT CODE	600	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR:6
DAYS

Reviewing



2

SUNDRIES

Reviewing

30

NECESSARY



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount\$7,848.30

Claim Amount\$7,848.30

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$5,450.00	\$5,450.00
Miscellaneous	\$30.00	\$30.00
Excess	-\$1,400.00	-\$1,400.00

Submit for Review